File	No.	191065

Committee Item No.	<u>3</u>	
Board Item No.		

## **COMMITTEE/BOARD OF SUPERVISORS**

AGENDA PACKET CONTENTS LIST

Committee: Government Audit and Oversige Board of Supervisors Meeting:	ht Date: Nov. 21, 2019 Date:
Cmte Board	
Motion   Resolution   Ordinance   Legislative Digest   Budget and Legislative Analys   Youth Commission Report   Introduction Form   Department/Agency Cover Lett   MOU   Grant Information Form   Grant Budget   Subcontract Budget   DRAFT Mills Act Agreement   Form 126 – Ethics Commission   Award Letter   Mills Act Application Docs   Public Correspondence	ter and/or Report
OTHER	
Planning Case Report – October	
HPC Reso No. 1091 – October  Assessor's Mills Act Valuation	2, 2019
Assessor's Updated Estimated	Tax Savings Chart
Transmittal Letter – October 15	
Prepared by: John Carroll Prepared by: John Carroll	Date: Nov. 15, 2019 Date:

[Mills Act Historical Property Contract - 1401 Howard Street]

Resolution approving an historical property contract between 1401 Howard LLC, the owner of 1401 Howard Street, and the City and County of San Francisco, under Administrative Code, Chapter 71; and authorizing the Planning Director and the Assessor-Recorder to execute and record the historical property contract.

WHEREAS, The California Mills Act (Government Code, Sections 50280 et seq.) authorizes local governments to enter into a contract with the owners of a qualified historical property who agree to rehabilitate, restore, preserve, and maintain the property in return for property tax reductions under the California Revenue and Taxation Code; and

WHEREAS, The Planning Department has determined that the actions contemplated in this Resolution comply with the California Environmental Quality Act (California Public Resources Code, Sections 21000 et seq.), and

WHEREAS, Said determination is on file with the Clerk of the Board of Supervisors in File No. 191065, is incorporated herein by reference, and the Board herein affirms it; and

WHEREAS, San Francisco contains many historic buildings that add to its character and international reputation and that have not been adequately maintained, may be structurally deficient, or may need rehabilitation, and the costs of properly rehabilitating, restoring, and preserving these historic buildings may be prohibitive for property owners; and

WHEREAS, Administrative Code, Chapter 71, was adopted to implement the provisions of the Mills Act and to preserve these historic buildings; and

WHEREAS, 1401 Howard Street is designated as Article 10 individual Landmark

Number 120 and is listed on the National Register of Historic Places and thus qualifies as an historical property as defined in Administrative Code, Section 71.2; and

WHEREAS, A Mills Act application for an historical property contract has been submitted by 1401 Howard LLC, the owner of 1401 Howard Street, detailing rehabilitation work and proposing a maintenance plan for the property; and

WHEREAS, As required by Administrative Code, Section 71.4(a), the application for the historical property contract for 1401 Howard Street was reviewed by the Assessor's Office and the Historic Preservation Commission; and

WHEREAS, The Assessor-Recorder has reviewed the historical property contract and has provided the Board of Supervisors with an estimate of the property tax calculations and the difference in property tax assessments under the different valuation methods permitted by the Mills Act in its report transmitted to the Board of Supervisors on October 15, 2019, which report is on file with the Clerk of the Board of Supervisors in File No. 191065 and is hereby declared to be a part of this Resolution as if set forth fully herein; and

WHEREAS, The Historic Preservation Commission recommended approval of the historical property contract in its Resolution No. 1091, including approval of the Rehabilitation Program and Maintenance Plan, attached to said Resolution, which is on file with the Clerk of the Board of Supervisors in File No. 191065 and is hereby declared to be a part of this Resolution as if set forth fully herein; and

WHEREAS, The draft historical property contract between 1401 Howard LLC, the owner of 1401 Howard Street, and the City and County of San Francisco is on file with the Clerk of the Board of Supervisors in File No. 191065 and is hereby declared to be a part of this Resolution as if set forth fully herein; and

WHEREAS, The Board of Supervisors has conducted a public hearing pursuant to Administrative Code, Section 71.4(d), to review the Historic Preservation Commission's recommendation and the information provided by the Assessor's Office in order to determine whether the City should execute the historical property contract for 1401 Howard Street; and

WHEREAS, The Board of Supervisors has balanced the benefits of the Mills Act to the owner of 1401 Howard Street with the cost to the City of providing the property tax reductions authorized by the Mills Act, as well as the historical value of 1401 Howard Street and the resultant property tax reductions, and has determined that it is in the public interest to enter into a historical property contract with the applicants; now, therefore, be it

RESOLVED, That the Board of Supervisors hereby approves the historical property contract between 1401 Howard LLC, the owner of 1401 Howard Street, and the City and County of San Francisco; and, be it

FURTHER RESOLVED, That the Board of Supervisors hereby authorizes the Planning Director and the Assessor-Recorder to execute the historical property contract and record the historical property contract.

Recording Requested by, and when recorded, send notice to: Michelle Taylor 1650 Mission Street, Suite 400 San Francisco, CA 94103-2414

#### CALIFORNIA MILLS ACT HISTORIC PROPERTY AGREEMENT

THIS AGREEMENT is entered into by and between the City and County of San Francisco, a California municipal corporation ("City") and 1401 Howard, LLC ("Owner").

#### RECITALS

Owner is the owner of the property located at 1401 Howard Street, in San Francisco, California (Block 3517, Lot 035). The building located at 1401 Howard Street is designated as individual landmark No. 120 pursuant to Article 10 of the Planning Code, and is also known as the "Historic Property". The Historic Property is a Qualified Historic Property, as defined under California Government Code Section 50280.1.

Owner desires to execute a rehabilitation and ongoing maintenance project for the Historic Property. Owner's application calls for the rehabilitation and restoration of the Historic Property according to established preservation standards, which it estimates will cost two hundred ninety-one thousand and sixty-five dollars (\$291,065.00) (See Rehabilitation Plan, Exhibit A.) Owner's application calls for the maintenance of the Historic Property according to established preservation standards, which is estimated will cost approximately thirty-one thousand and forty dollars (\$31,040.00) annually (See Maintenance Plan, Exhibit B).

The State of California has adopted the "Mills Act" (California Government Code Sections 50280-50290, and California Revenue & Taxation Code, Article 1.9 [Section 439 et seq.]) authorizing local governments to enter into agreements with property Owner to reduce their property taxes, or to prevent increases in their property taxes, in return for improvement to and maintenance of historic properties. The City has adopted enabling legislation, San Francisco Administrative Code Chapter 71, authorizing it to participate in the Mills Act program.

Owner desires to enter into a Mills Act Agreement (also referred to as a "Historic Property Agreement") with the City to help mitigate anticipated expenditures to restore and maintain the Historic Property. The City is willing to enter into such Agreement to mitigate these expenditures and to induce Owner to restore and maintain the Historic Property in excellent condition in the future.

NOW, THEREFORE, in consideration of the mutual obligations, covenants, and conditions contained herein, the parties hereto do agree as follows:

- 1. <u>Application of Mills Act.</u> The benefits, privileges, restrictions and obligations provided for in the Mills Act shall be applied to the Historic Property during the time that this Agreement is in effect commencing from the date of recordation of this Agreement.
- 2. <u>Rehabilitation of the Historic Property.</u> Owner shall undertake and complete the work set forth in Exhibit A ("Rehabilitation Plan") attached hereto according to certain standards and

requirements. Such standards and requirements shall include, but not be limited to: the Secretary of the Interior's Standards for the Treatment of Historic Properties ("Secretary's Standards"); the rules and regulations of the Office of Historic Preservation of the California Department of Parks and Recreation ("OHP Rules and Regulations"); the State Historical Building Code as determined applicable by the City; all applicable building safety standards; and the requirements of the Historic Preservation Commission, the Planning Commission, and the Board of Supervisors, including but not limited to any Certificates of Appropriateness approved under Planning Code Article 10. The Owner shall proceed diligently in applying for any necessary permits for the work and shall apply for such permits within no more than six (6) months after recordation of this Agreement, shall commence the work within six (6) months of receipt of necessary permits, and shall complete the work within three (3) years from the date of receipt of permits. Upon written request by the Owner, the Zoning Administrator, at his or her discretion, may grant an extension of the time periods set forth in this paragraph. Owner may apply for an extension by a letter to the Zoning Administrator, and the Zoning Administrator may grant the extension by letter without a hearing. Work shall be deemed complete when the Director of Planning determines that the Historic Property has been rehabilitated in accordance with the standards set forth in this Paragraph. Failure to timely complete the work shall result in cancellation of this Agreement as set forth in Paragraphs 12 and 13 herein.

- 3. <u>Maintenance</u>. Owner shall maintain the Historic Property during the time this Agreement is in effect in accordance with the standards for maintenance set forth in Exhibit B ("Maintenance Plan"), the Secretary's Standards; the OHP Rules and Regulations; the State Historical Building Code as determined applicable by the City; all applicable building safety standards; and the requirements of the Historic Preservation Commission, the Planning Commission, and the Board of Supervisors, including but not limited to any Certificates of Appropriateness approved under Planning Code Article 10.
- Damage. Should the Historic Property incur damage from any cause whatsoever, which damages fifty percent (50%) or less of the Historic Property, Owner shall replace and repair the damaged area(s) of the Historic Property. For repairs that do not require a permit, Owner shall commence the repair work within thirty (30) days of incurring the damage and shall diligently prosecute the repair to completion within a reasonable period of time, as determined by the City. Where specialized services are required due to the nature of the work and the historic character of the features damaged, "commence the repair work" within the meaning of this paragraph may include contracting for repair services. For repairs that require a permit(s), Owner shall proceed diligently in applying for any necessary permits for the work and shall apply for such permits within no more than sixty (60) days after the damage has been incurred, commence the repair work within one hundred twenty (120) days of receipt of the required permit(s), and shall diligently prosecute the repair to completion within a reasonable period of time, as determined by the City. Upon written request by the Owner, the Zoning Administrator, at his or her discretion, may grant an extension of the time periods set forth in this paragraph. Owner may apply for an extension by a letter to the Zoning Administrator, and the Zoning Administrator may grant the extension by letter without a hearing. All repair work shall comply with the design and standards established for the Historic Property in Exhibits A and B attached hereto and Paragraph 3 herein. In the case of damage to twenty percent (20%) or more of the Historic Property due to a catastrophic event, such as an earthquake, or in the case of damage from any cause whatsoever that destroys more than fifty percent (50%) of the Historic Property, the City and Owner may mutually agree to terminate this Agreement. Upon such termination, Owner shall not be obligated to pay the cancellation fee set forth in Paragraph 13 of this Agreement. Upon such termination, the City shall assess the full value of the Historic Property without regard to any restriction imposed upon the Historic Property by this Agreement and Owner shall pay property taxes to the City based upon the valuation of the Historic Property as of the date of termination.

- 5. <u>Insurance</u>. Owner shall secure adequate property insurance to meet Owner's repair and replacement obligations under this Agreement and shall submit evidence of such insurance to the City upon request.
- 6. <u>Inspections and Compliance Monitoring.</u> Prior to entering into this Agreement and every five years thereafter, and upon seventy-two (72) hours advance notice, Owner shall permit any representative of the City, the Office of Historic Preservation of the California Department of Parks and Recreation, or the State Board of Equalization, to inspect of the interior and exterior of the Historic Property, to determine Owner's compliance with this Agreement. Throughout the duration of this Agreement, Owner shall provide all reasonable information and documentation about the Historic Property demonstrating compliance with this Agreement, as requested by any of the above-referenced representatives.
- 7. <u>Term.</u> This Agreement shall be effective upon the date of its recordation and shall be in effect for a term of ten years from such date ("Term"). As provided in Government Code section 50282, one year shall be added automatically to the Term, on each anniversary date of this Agreement, unless notice of nonrenewal is given as set forth in Paragraph 9 herein.
- 8. <u>Valuation</u>. Pursuant to Section 439.4 of the California Revenue and Taxation Code, as amended from time to time, this Agreement must have been signed, accepted and recorded on or before the lien date (January 1) for a fiscal year (the following July 1-June 30) for the Historic Property to be valued under the taxation provisions of the Mills Act for that fiscal year.
- 9. Notice of Nonrenewal. If in any year of this Agreement either the Owner or the City desire not to renew this Agreement, that party shall serve written notice on the other party in advance of the annual renewal date. Unless the Owner serves written notice to the City at least ninety (90) days prior to the date of renewal or the City serves written notice to the Owner sixty (60) days prior to the date of renewal, one year shall be automatically added to the Term of the Agreement. The Board of Supervisors shall make the City's determination that this Agreement shall not be renewed and shall send a notice of nonrenewal to the Owner. Upon receipt by the Owner of a notice of nonrenewal from the City, Owner may make a written protest. At any time prior to the renewal date, City may withdraw its notice of nonrenewal. If either party serves notice of nonrenewal of this Agreement, this Agreement shall remain in effect for the balance of the period remaining since the original execution or the last renewal of the Agreement, as the case may be. Thereafter, the Owner shall pay property taxes to the City without regard to any restriction imposed on the Historic Property by this Agreement, and based upon the Assessor's determination of the fair market value of the Historic Property as of expiration of this Agreement.
- 10. Payment of Fees. As provided for in Government Code Section 50281.1 and San Francisco Administrative Code Section 71.6, upon filing an application to enter into a Mills Act Agreement with the City, Owner shall pay the City the reasonable costs related to the preparation and approval of the Agreement. In addition, Owner shall pay the City for the actual costs of inspecting the Historic Property, as set forth in Paragraph 6 herein.
- 11. Default. An event of default under this Agreement may be any one of the following:
- (a) Owner's failure to timely complete the rehabilitation work set forth in Exhibit A, in accordance with the standards set forth in Paragraph 2 herein;
- (b) Owner's failure to maintain the Historic Property as set forth in Exhibit B, in accordance with the requirements of Paragraph 3 herein;
- (c) Owner's failure to repair any damage to the Historic Property in a timely manner, as provided in Paragraph 4 herein;

(d) Owner's failure to allow any inspections or requests for information, as provided in Paragraph 6 herein;

(e) Owner's failure to pay any fees requested by the City as provided in Paragraph 10

herein;

(f) Owner's failure to maintain adequate insurance for the replacement cost of the Historic Property, as required by Paragraph 5 herein; or

(g) Owner's failure to comply with any other provision of this Agreement.

An event of default shall result in Cancellation of this Agreement as set forth in Paragraphs 12 and 13 herein, and payment of the Cancellation Fee and all property taxes due upon the Assessor's determination of the full value of the Historic Property as set forth in Paragraph 13 herein. In order to determine whether an event of default has occurred, the Board of Supervisors shall conduct a public hearing as set forth in Paragraph 12 herein prior to cancellation of this Agreement.

- 12. <u>Cancellation.</u> As provided for in Government Code Section 50284, City may initiate proceedings to cancel this Agreement if it makes a reasonable determination that Owner has breached any condition or covenant contained in this Agreement, has defaulted as provided in Paragraph 11 herein, or has allowed the Historic Property to deteriorate such that the safety and integrity of the Historic Property is threatened or it would no longer meet the standards for a Qualified Historic Property. In order to cancel this Agreement, City shall provide notice to the Owner and to the public and conduct a public hearing before the Board of Supervisors as provided for in Government Code Section 50285. The Board of Supervisors shall determine whether this Agreement should be cancelled.
- 13. <u>Cancellation Fee.</u> If the City cancels this Agreement as set forth in Paragraph 12 above, and as required by Government Code Section 50286, Owner shall pay a Cancellation Fee of twelve and one-half percent (12.5%) of the fair market value of the Historic Property at the time of cancellation. The City Assessor shall determine fair market value of the Historic Property without regard to any restriction imposed on the Historic Property by this Agreement. The Cancellation Fee shall be paid to the City Tax Collector at such time and in such manner as the City shall prescribe. As of the date of cancellation, the Owner shall pay property taxes to the City without regard to any restriction imposed on the Historic Property by this Agreement and based upon the Assessor's determination of the fair market value of the Historic Property as of the date of cancellation.
- 14. <u>Enforcement of Agreement.</u> In lieu of the above provision to cancel the Agreement, the City may bring an action to specifically enforce or to enjoin any breach of any condition or covenant of this Agreement. Should the City determine that the Owner has breached this Agreement, the City shall give the Owner written notice by registered or certified mail setting forth the grounds for the breach. If the Owner do not correct the breach, or do not undertake and diligently pursue corrective action to the reasonable satisfaction of the City within thirty (30) days from the date of receipt of the notice, then the City may, without further notice, initiate default procedures under this Agreement as set forth in Paragraph 12 and bring any action necessary to enforce the obligations of the Owner set forth in this Agreement. The City does not waive any claim of default by the Owner if it does not enforce or cancel this Agreement.
- 15. <u>Indemnification</u>. The Owner shall indemnify, defend, and hold harmless the City and all of its boards, commissions, departments, agencies, agents and employees (individually and collectively, the "City") from and against any and all liabilities, losses, costs, claims, judgments, settlements, damages, liens, fines, penalties and expenses incurred in connection with or arising in whole or in part from: (a) any accident, injury to or death of a person, loss of or damage to property occurring in or about the Historic Property; (b) the use or occupancy of the Historic Property by the Owner, their Agents or Invitees; (c) the condition of the Historic Property; (d)

any construction or other work undertaken by Owner on the Historic Property; or (e) any claims by unit or interval Owner for property tax reductions in excess those provided for under this Agreement. This indemnification shall include, without limitation, reasonable fees for attorneys, consultants, and experts and related costs that may be incurred by the City and all indemnified parties specified in this Paragraph and the City's cost of investigating any claim. In addition to Owner's obligation to indemnify City, Owner specifically acknowledge and agree that they have an immediate and independent obligation to defend City from any claim that actually or potentially falls within this indemnification provision, even if the allegations are or may be groundless, false, or fraudulent, which obligation arises at the time such claim is tendered to Owner by City, and continues at all times thereafter. The Owner's obligations under this Paragraph shall survive termination of this Agreement.

- 16. <u>Eminent Domain.</u> In the event that a public agency acquires the Historic Property in whole or part by eminent domain or other similar action, this Agreement shall be cancelled and no cancellation fee imposed as provided by Government Code Section 50288.
- 17. <u>Binding on Successors and Assigns.</u> The covenants, benefits, restrictions, and obligations contained in this Agreement shall run with the land and shall be binding upon and inure to the benefit of all successors in interest and assigns of the Owner. Successors in interest and assigns shall have the same rights and obligations under this Agreement as the original Owner who entered into the Agreement.
- 18. <u>Legal Fees.</u> In the event that either the City or the Owner fail to perform any of their obligations under this Agreement or in the event a dispute arises concerning the meaning or interpretation of any provision of this Agreement, the prevailing party may recover all costs and expenses incurred in enforcing or establishing its rights hereunder, including reasonable attorneys' fees, in addition to court costs and any other relief ordered by a court of competent jurisdiction. Reasonable attorneys' fees of the City's Office of the City Attorney shall be based on the fees regularly charged by private attorneys with the equivalent number of years of experience who practice in the City of San Francisco in law firms with approximately the same number of attorneys as employed by the Office of the City Attorney.
- 19. <u>Governing Law.</u> This Agreement shall be construed and enforced in accordance with the laws of the State of California.
- 20. Recordation. Within 20 days from the date of execution of this Agreement, the parties shall cause this Agreement to be recorded with the Office of the Recorder of the City and County of San Francisco. From and after the time of the recordation, this recorded Agreement shall impart notice to all persons of the parties' rights and obligations under the Agreement, as is afforded by the recording laws of this state.
- 21. <u>Amendments.</u> This Agreement may be amended in whole or in part only by a written recorded instrument executed by the parties hereto in the same manner as this Agreement.
- 22. <u>No Implied Waiver</u>. No failure by the City to insist on the strict performance of any obligation of the Owner under this Agreement or to exercise any right, power, or remedy arising out of a breach hereof shall constitute a waiver of such breach or of the City's right to demand strict compliance with any terms of this Agreement.
- 23. <u>Authority.</u> If the Owner signs as a corporation or a partnership, each of the persons executing this Agreement on behalf of the Owner does hereby covenant and warrant that such entity is a duly authorized and existing entity, that such entity has and is qualified to do business in California, that the Owner has full right and authority to enter into this Agreement, and that each and all of the persons signing on behalf of the Owners are authorized to do so.

- 24. <u>Severability</u>. If any provision of this Agreement is determined to be invalid or unenforceable, the remainder of this Agreement shall not be affected thereby, and each other provision of this Agreement shall be valid and enforceable to the fullest extent permitted by law.
- 25. <u>Tropical Hardwood Ban.</u> The City urges companies not to import, purchase, obtain or use for any purpose, any tropical hardwood or tropical hardwood product.
- 26. <u>Charter Provisions.</u> This Agreement is governed by and subject to the provisions of the Charter of the City.
- 27. <u>Signatures.</u> This Agreement may be signed and dated in parts

IN WITNESS WHEREOF, the parties hereto have executed this Agreement as follows:

#### CITY AND COUNTY OF SAN FRANCISCO:

By:Carmen Chu, Assessor-Recorder	DATE:
By:John Rahaim, Director of Planning	DATE:
APPROVED AS TO FORM: DENNIS J. HERRERA CITY ATTORNEY	
By:Andrea Ruiz-Esquide, Deputy City Attorney	DATE:
OWNER(S)	
By:Christopher Foley, 1401 Howard Street, LLC,	DATE:

OWNER(S)' SIGNATURE(S) MUST BE NOTARIZED. ATTACH PUBLIC NOTARY FORMS HERE.

### REHABILITATION / RESTORATION & MAINTENANCE PLAN (CONTINUED/ ATTACHMENT)

Exhibit A. Rehabilitation/Restoration Plan

Scope: #1				
Building Feature: Ext	erior (	Gates, Curbs, Fence, P	iers, Granite Steps	
Rehab/Restoration	X	Maintenance	Completed X	Proposed
Contract year work co	omple	etion: 2018		
Total Cost: \$25,000.0	00 <b>S</b> o	urce SOV #2920		
Description of work: F	Resto	ration and Repair of Ex	terior Gates, Curbs, Fe	nces, Piers and Granite
Stone		·		

- The direction of the swing of all gates was reversed in the direction of egress. The gates were prepared, primed, and painted, and latch and lock sets were provided. At the two existing double gateways, the existing gates were reinstalled on new freestanding supports similar to the existing. The original hinges were retained at the original piers. The displaced sections of the piers were reset in the original locations and grouted. The cement plaster parge was repaired as required to match the original.
- The iron fence was prepared, primed, and painted. The gaps and voids were filled with mortar at the base and pier attachments. Where the fence is set into the curb and is corroded, the metal was repaired, painted, and set into lead or sealant as required to prevent future damage to the fence or curb.
- The cement plaster parge on the piers was cleaned and graffiti was removed or painted over. The cement plaster parge was repaired to match the existing adjacent color and texture as required.
- Existing joints were raked out and the granite steps were cleared of debris. Joints were repaired with mortar. Algae, moss, and other biological growth was removed. Soil and paint spatters were removed. New code-required bronze handrails were installed.

Scope: #2 Building Feature: Exte	erior	Paint and Stucco Rep	air	
Rehab/Restoration	X	Maintenance	Completed X	Proposed
Contract year work co	mp	letion: 2018 Phase 1, F	Phase 2 scheduled for 20	026
Total Cost: \$146,950.	So	urce SOV #9900 (half	), \$293850/2=\$146,950.	

Description of work: Façade Restoration and Full Repainting

- The existing stucco was analyzed to determine if it was lime or Portland cement-based. These tests were performed by an architectural conservator.
- Staining and soiling was removed by the gentlest means possible, this included light brushing and water washing, and cleaning with a commercial agent.
- Areas of significant hairline cracking were repaired based on analysis to determine the root cause of the condition. Investigation included testing for underlying detachment of the stucco layer, moisture intrusion, structural movement, or other causes.
- Climbing vegetation such as ivy was removed.
- Spalls and cracks through cement plaster were repaired. The cracks were routed and patched to match the existing adjacent texture, profile, and appearance.
- The existing deteriorated or detached cement plaster was removed. Graffiti and stains were removed.
- Unsound paint was removed and coated with a new breathable paint coating.

Scope: #3						
Building Feature: Ext	erior	Sheet Metal Element	s, including dome:	s on t	owers, column capitals,	
decorative moldings,	gutte	rs and down spouts.				
Rehab/Restoration	X	Maintenance	Completed	X	Proposed	
Contract year work o	omple	etion: 2018				
Total Cost: \$424,323	Sou	rce SOV #7600 = \$434	1,323			

Description of work: Repair and Restoration of Exterior Sheet Metal Elements

- Peeling or blistering paint was scraped or sanded.
- Corrosion was removed with hand scrapers or a wire brush.
- For panels with heavy corrosion and resulting perforation of the sheet metal unit, there were three options, dependent on severity and size:
  - 1. Corroded panels were removed and the unit was replaced with a new piece of sheet metal cut to the appropriate dimension and profile,
  - 2. The corroded area was cut out of existing sheet metal, a new piece was brazewelded and the joint was ground flat; or
  - 3. The corroded area was cut out of existing sheet metal and steel-filled epoxy compound was installed to patch small holes.
- All exposed metal was painted with a rust-inhibiting primer and two coats of color-appropriate outdoor paint.
- Missing elements were replaced to maintain visual consistency.

Scope: #4			
Building Feature: Exterior _ V	Vood-sash Windows and	Steel Tracery	
Rehab/Restoration X	Maintenance	Completed X	Proposed
Contract year work completio			
Total Cost: \$366,443. Source	SOV #6150 and # 8050	) for \$96,867 and \$	269,576 = 366,443
Description of Work: Repair, I	Restoration and Replace	ment of Windows	
determine the extent	assessment of windows of deterioration and apprection and documentation to diagnostic tests.	opriate treatments a	at each window. This
while providing adequ	frames attempted to reta late moisture protection elements in areas of sev	for the building, and	included paint removal,

Ħ	The wood frames were prepared and painted, all the existing ribbed glass that could be
	preserved was reused. Ribbed glass that matched the original was installed in selected
	locations.

Scope: # 5 Building Feature: Ext	erior _ Stained Glass Windows			
Rehab/Restoration	X Maintenance	Completed	Х	Proposed
Contract year work co	ompletion: 2018			
Total Cost: \$81,260.0	00 Source SOV #8070	A CONTRACTOR OF THE PARTY OF TH		
				<del></del>

Description of work: Repair and Restoration of Stained Glass Windows

glazing compound.

- Documentation and restoration of the windows was performed by a professional conservator. Restoration included removal, transport, restoration, and reinstallation of the stained glass.
- The wood and steel armatures remaining from the previous stained glass window installation were prepared and painted.
- The remaining stained glass in the south wall of the kitchen was removed, salvaged, and reinstalled in the office on the first floor.

Scope: #6			
Building Feature: Exterio	r Skylight	100	
Rehab/Restoration X	Maintenance	Completed X	Proposed
Contract year work comp	oletion: 2018	, .	
Total Cost: \$39,010.00 S	Source SOV #8080		
Description of work: Rep	air and Restoration of Ext	terior Skylight	
The steel skyligh	nt remained in place and v	vas repaired and clean	ed.
<ul><li>New tempered g</li></ul>	lazing and sealant was in	stalled, and all work an	d flashing details were
coordinated with	the roof strengthening ar	nd re-roofing work.	

Scope: #7 Building Feature: Inte	rior St	ructural Steel for Seisi	mic	
Rehab/Restoration			Completed X	Proposed
Contract year work co	omplet	ion: 2018		
Total Cost: \$571,841	Source	e SOV 8 items #5050	), 5070 and 5120	
Description of work: S	Seismi	Strengthening		
<ul> <li>Steel was fab</li> </ul>	ricated	d and installed for seis	mic strengthening.	

Scope: #8			
Building Feature: Interior D	ecorative Plaster		
Rehab/Restoration X	Maintenance	Completed X	Proposed
Contract year work comple	tion: 2018		
Total Cost: \$1,350,577.00	Source SOV #9050 , \$	1,350,577	
Description of work: Repair	and Restoration of Int	erior Decorative Plaster	
<ul> <li>Detached or cracket</li> </ul>	ed plaster elements we	re repaired, if in otherw	rise sound condition, with
an injected epoxy o	or gypsum-based grout	. Testing was conducte	d to determine the most
effective adhesive.		_	

- Non-historic wood veneer was removed so that plaster at the base of the wall could be restored and painted. Further testing of the plaster was conducted to determine the extent of deterioration. This
- determined the treatment method: patching and reshaping damaged elements when possible, or replacement in kind.

Scope: # 9 Building Feature: Interi	or Woodwork, Doors and F	Finish Hardware	
Rehab/Restoration	X Maintenance	Completed X	Proposed
Contract year work cor	npletion: 2018		
Total Cost: \$269,000.0	0 Source SOV #8200		

Description of work: Repair and Restoration of Interior Woodwork, Doors and Finish Hardware

- Soiling was cleaned with the gentlest means possible, using a soft bristle brush to remove loose dust and a damp cloth for tenacious soiling.
- Blistered varnish was treated with the gentlest means possible in order to preserve the existing finish. Treatments included lightly scraping blistered areas of varnish and spottreating with fine steel wool or cotton, alcohol and a compatible varnish or shellac.
- White stains were tested to determine the cause Paint and guano were removed mechanically with a scraper so as not to damage the existing wood finish.
- Where required by the level of damage, select areas of woodwork were refinished to match the original.

- Wood was replaced where missing to match the original.
- At exterior doors, deteriorated wood was repaired with wood Dutchman and matched the original species, grade, grain, and profile. The exterior surface was prepped and painted. The interior was cleaned and touched up or refinished to match the original stain or clear coat
- Door hardware was replaced or repaired to match existing and to meet current code.

Scope: #10 Building Feature: Interior M	larble Wainscoting and	l Tiles	
Rehab/Restoration X	Maintenance	Completed X	Proposed
Contract year work comple	tion: 2018		
Total Cost: \$5,000.00 Soul	ce From KFI (3/28/19	email)	
Description of work: Restor	ation of Interior Marble	)	

- Tape residue and soiling was removed with a gentle stone cleaner. Mock-ups were conducted to determine the most effective product.
- Vinyl tiles and mastic were removed in the vestibule without causing damage to underlying marble, which was cleaned with a gentle stone cleaner to remove staining and adhesive. Mockups were conducted to determine the most effective product.
- Vinyl tiles and mastic were removed from the vestibule floor and cleaned using the gentlest means possible.
- The marble floors were polished to restore luster

Scope: #11			
Building Feature: Inte	rior Nave Floor Cor	ncrete	
Rehab/Restoration	X Maintena	ince Completed 🖸	K Proposed
Contract year work co	mpletion: 2018		
Total Cost: \$207,357	Source (4 items) ?	SOV #2050, #2250, #2300 ai	nd KFI, \$30,000 \$7,500
\$79,847 \$45,410 and	d \$44,600	•	<u> </u>
Description of work:			
<ul><li>The existing (</li></ul>	non historic) slab v	vas removed	,
<ul><li>Soil was exca</li></ul>	vated and the surr	ounding soil was underpinne	d.
<ul><li>New foundation</li></ul>	ons, with piers and	grade beams were installed	•
<ul> <li>New stage ov</li> </ul>	er the grade beam	s was installed in the apse.	

Scope: # 12 Building Feature: Interior	Towar Floor Caparata		
Rehab/Restoration X		Completed X	Proposed
Contract year work compl		. Completed [X]	1 1000000
Total Cost: \$573,000.00 \$		#2460 and KFI	
Description of work:			
<ul> <li>The concrete slop</li> </ul>	ed floor was replaced w	rith a new flat structural	concrete slab.
<ul> <li>New micropile fou</li> </ul>	ndations were installed	in the towers.	
<ul> <li>The top 10 feet of</li> </ul>	the micro piles were ca	sed in concrete.	
	proed in concrete and co		

Scope: #13		Pane		
Building Feature: Ex	derior	Lighting		
Rehab/Restoration	X	Maintenance	Completed X	Proposed
Contract year work	comp	etion: 2018		

Total Cost: \$92,625.00 Source SOV #16080

Lead paint was abated.

# Description of work: The missing original fixtures on the main entry façade were replicated based on historic documentation. Building façade lighting was replaced with LED fixtures to save energy.

Scope: # 14 Building Feature: Interior Li	ghting		
Rehab/Restoration X	Maintenance	Completed X	Proposed
Contract year work comple	tion: 2018		
Total Cost: \$135,281.00 Sc	ource SOV #16070		
Description of work: Repair			oric light fixtures:
<ul> <li>The historic light fix</li> </ul>	ctures were cleaned an	d relamped.	
The missing fixture	s in the main sanctuary	were replicated	

Scope: #15 Building Feature: Roof / Bu	ıilt-up Roof		
Rehab/Restoration X	Maintenance	Completed X	Proposed
Contract year work comple	tion: 2018		
Total Cost: \$28,110.00 So	urce SOV #7500		
Description of work:			,
<ul> <li>Existing built-up ro</li> </ul>	ofing was removed at t	he lower roofs.	
	g was installed over ne		

Scope: #16 Building Feature: Roof / S	late Roof		
Rehab/Restoration X	Maintenance	Completed X	Proposed
Contract year work compl	etion: 2018		
Total Cost: \$258,950.00 \$	ource SOV #7300		
Description of work:			
to allow access for	r structural stabilization	of the roof structure.	salvaged, and reinstalled or new tile to match the

New felt underlayment and galvanized flashing was installed.

Scope: #17	and the second s		
Building Feature: Interior	Painting		
Rehab/Restoration X	Maintenance	Completed X	Proposed
Contract year work comp	letion: 2018 Phase 1, Ph	ase 2 scheduled for 20	26
Total Cost: \$146,950.00	Source SOV #9900 (half	f), \$293850/2=\$146,950	· ·
Description of work:			
<ul> <li>Tested bottom la</li> </ul>	yer of paint to find origina	al colors.	
<ul> <li>Interior plaster w</li> </ul>	as painted, interior wood	was refinished, and wir	ndow mullions were
repainted.			

Scope: # 18				
Building Feature: Roof / Sheet	Metal Dome and Sheet	: Metal Crosses		
Rehab/Restoration X	Maintenance	Completed X	Propose	d
Contract year work completion	ı: 2018			
Total Cost: \$60,000.00 Source	e SOV #9950			
Description of work:				
<ul> <li>Gold leaf was reapplied</li> </ul>	ed to the domes and cros	sses.		
Scope: #19				
Building Feature: ADA Upgrad	les _ Exterior Ramp			1000
Rehab/Restoration X	Maintenance	Completed X	Propose	d
Contract year work completion	ı: 2018			
Total Cost: 12,000.00 Convers	sation with contractor			
Description of work:				
<ul><li>Ramp provided at tran</li></ul>				
<ul> <li>Auto operator provided</li> </ul>	d at existing door.			
were analysis (000 page using planting and 100 page and 1		00 - 1		
Scope: #20				
Building Feature: Interior Paint				
Rehab/Restoration X	Maintenance	Completed	Proposed	X
Contract year work completion				
Total Cost: \$50,000.00 See See	ource SOV #9900			
Description of work:				
<ul><li>Partial repainting of int</li></ul>	erior walls.			
	pro-100-100 per 100-100 per			
Scope: # 21	Annual Commence			
Building Feature: Exterior Pain				
Rehab/Restoration X	Maintenance	Completed	Proposed	X
Contract year work completion				24440
Total Cost: \$241,065.00 (Exter				
	r any new cracks. All rep			npatible
materials and in accord	dance with the Secretary	v of the Interior's	Standards.	

### Exhibit B Maintenance Plan

Scope: #1						
Building Feature: Site_L	andscape					
Rehab/Restoration	Maintenance	X	Completed	Proposed	X	
Contract year work comp	oletion: 2028 and eve	ery 1	0 years thereafter		,	
Total Cost: \$120,000.00	(\$1,000/month x 12r	no x	(10 yrs)			
Description of work: Was	hing of sidewalks ar	nd gr	ranite entry steps. Grar	ite steps will be	e cle	aned
using the gentlest means	s possible as recomn	nend	ded in NPS Preservatio	n Brief No. 1: A	sse	ssing
Cleaning and Water-Rep	ellent Treatments fo	r His	storic Masonry Building	s. All work will l	be p	erformed
in conformance with the	Secretary of the Inte	rior	Standards.		•	

Building Feature: Exteri	or_Stucco				
Rehab/Restoration	Maintenance	X	Completed	Proposed	X
Contract year work com	pletion: 2019 and ar	nually t	hereafter		
Total Cost: \$40,000 (ma	aintenance of 4,000/	yr x10yr	S) .		
Description of work: Re	gular repainting of ex	kterior st	ucco as needed to a	address graffiti.	Perform
visual inspection annua	lly for signs of blister	ing or pe	eeling paint.	_	

Scope: #3					-
Building Feature: Roof					
Rehab/Restoration	Maintenance	X	Completed	Proposed	X
Contract year work com	pletion: 2019 and ar	nually	thereafter		
Total Cost: \$30,000.00	(maintenance of \$3,	000 x	10yrs)		
Description of work: Insp and repair caulking and and discourage roosting	flashing. Clear drain				

Scope: # 4 Building Feature: Exterior decorative moldings, gu			ncluding domes on tov	wers, column capitals,			
Rehab/Restoration	Maintenance		Completed	Proposed X			
Contract year work com	oletion: 2019 and ar	nually	thereafter				
Total Cost: \$12,000.00 (	\$1200 per year)						
Description of work: Perform visual inspection annually for rust, holes and signs of water where it							
shouldn't be. Clean gutters, replace screens, check down spouts and clean drains. Repair damaged							
pieces to match existing using appropriate materials and methods. All repairs will be performed in							
conformance with the Secretary of the Interior Standards.							

Scope: # 5 Building Feature: Exteri	or Wood-sash Windo	ws and	Steel Tracery.	
Rehab/Restoration	Maintenance		Completed	Proposed X
Contract year work com	pletion: 2019 and an	nually t	hereafter.	
Total Cost: \$10,000.00	(\$1000 per year)			
Description of work: Per	form visual inspection	n annua	ally for signs of caull	king failure, check operab
				. All window repairs will b
performed in accordanc			•	·

Scope: #6								
Building Feature: Exterior	Skylight							
Rehab/Restoration	Maintenance	X	Completed	Proposed X				
Contract year work comp	letion: 2019 and an	nua	lly thereafter					
Total Cost: \$5,000.00 (\$5								
Description of work: Perfo	orm visual inspection	n ar	nnually for signs of caull	king failure, condensation				
problems that might comp								
kind. All repairs will be pe	rformed in conform	anc	e with the Secretary of t	he Interior Standards.				
Scope: #7								
Building Feature: Exterior	Stained Glass Wir	idov	VS					
Rehab/Restoration	Maintenance	X	Completed	Proposed X				
Contract year work comp		nua	lly thereafter					
Total Cost: \$16,000.00 (\$								
Description of work: Inspect stained glass and replace any cracked or missing pieces with glass that								
matches original glass in color and texture. Inspect and repair lead cames.								
All work will be performed in conformance with the Secretary of the Interior's Standards and in								
accordance with NPS Pre	servation Brief No.	33:	The Preservation and F	Repair of Historic Stained				
and Leaded Glass	•							

Scope: #8	A MARKET				
Building Feature: Exteri	or Wood Doors				
Rehab/Restoration	Maintenance	Χ	Completed	Proposed	X
Contract year work com	pletion: 2019 and ar	nually t	hereafter		
Total Cost: \$7,900.00 (\$	790 per year)				
Description of work: The	face of the wood do	oors ha	ve extreme exposure	to rain and sun	n. They
suffered significant dete					
work will be performed i					J

Scope: #9 Building Feature: Interio	or Decorative Plaster	in a			
Rehab/Restoration	Maintenance		Completed	Proposed	X
Contract year work com	pletion: 2019 and ev	ery 10	0 years thereafter		
Total Cost: \$20,000.00	(\$2000 per year)				
Description of work: The behind the decorative p damage was done insid must look inside the atti All work will be performe accordance with NPS P	laster ceiling. Probler e the concealed space c for signs of water ded in conformance wi	ms on ces, the amag ith the	n the surface appeared herefore there will be ge and make needed r e Secretary of the Intel	d only after consi visual inspection epairs. rior's Standards	iderable s annually and in

Scope: #10 Building Feature: Interio	r Woodwork				
Rehab/Restoration	Maintenance	X	Completed	Proposed [	X
Contract year work com	pletion: 2019 and an	nually t	hereafter		
Total Cost: \$16,000.00	(\$1600 per year)				
Description of work: Per	form visual inspection	n annu	ally for damage and	repair in the gent	lest means
possible. All work will be	performed in confor	rmance	with the Secretary o	f the Interior's Sta	andards.

Scope: #11				Regulation of the second of th
Building Feature: Bell To	wer			
Rehab/Restoration	Maintenance	X	Completed	Proposed X
Contract year work comp	oletion: 2019 and ar	nually	y thereafter	
Total Cost: \$18,500.00 (	\$1850 per year)			
Description of work: Ann	ual visual inspection	n of b	ell rope and hanging r	nechanism. Climb the
ladders and go into the a	ittic spaces and rem	nove b	oirds and close up any	gaps in the screens and
louvers.				·

Building Feature: Site D					
Rehab/Restoration	Maintenance	<u>X</u>	Completed	Proposed	X
Contract year work com	oletion: 2019 and an	nually t	hereafter	-	
Total Cost: \$11,500 (\$1,	500 per year)				
Description of work: Insp	ect drywells in gard	en area	s and verify site drai	nage is functio	ning to
remove standing water.					

Scope: #13 Building Feature: Interio	r plaster				
Rehab/Restoration	Maintenance	Χ	Completed	Proposed	Χ
Contract year work com	oletion: 2023 and bi	-annual	ly thereafter		
Total Cost: \$80,000					
Description of work; Repperformed in conforman					
NPS Preservation Brief I					
Historic Flat Plaster Wal		,	•		. 0

Scope: #14 Building Feature: Interio	r Marble Floors				
Rehab/Restoration	Maintenance	X	Completed	Proposed	X
Contract year work comp	oletion: 2022 and ar	nually	thereafter		
Total Cost: \$8,000	_				
Description of work: Clea	an and reseal marbl	e floor	s and wainscot. All m	arble will be cle	aned using
the gentlest means poss	ible as recommende	ed in N	IPS Preservation Brie	of No. 1: Assess	ing Cleaning
and Water-Repellent Tre	eatments for Historic	Maso	nry Buildings		

Rehab/Restoration	Maintenance	X	Completed	Proposed	Χ
Contract year work com	pletion: 2022 and an	nually th	nereafter		
Total Cost: \$12,000					



## Mills Act Historical Property Contracts Case Report

Hearing Date:

October 2, 2019

Staff Contact:

Michelle Taylor - (415) 575-9197

Michelle Taylor@sfgov.org

Reviewed By:

Elizabeth Gordon-Jonckheer – (415) 575-8728

Elizabeth Gordon-Jonckheer @sfgov.org

a. Filing Date:

May 1, 2019

Case No.:

2019-006323MLS

Project Address:

2251 Webster Street (District 2)

Landmark District:

Contributor to the Webster Street Historic District

Zoning:

RH-2 (Residential-House, Two-Family District)

Height &Bulk:

40-X

Block/Lot:

0612/001A

Applicant:

Sally A. Sadosky Revocable Trust

2251 Webster Street

San Francisco, CA 94115

**b.** Filing Date:

May 1, 2019

Case No.:

2019-006384MLS

Project Address:

1401 Howard Street (District 6)

Landmark No.:

120

Zoning:

RCD - Regional Commercial District

Height and Bulk:

55/65-X

Block/Lot:

3517/035

Applicant:

1401 Howard LLC

1401 Howard Street

San Francisco, CA 94103

c. Filing Date:

May 1, 2019

Case No.:

2019-006322MLS

Project Address:

64 Potomac Street (District 8)

Landmark District:

Contributor to the Duboce Park Historic District

Zoning:

RH-2 (Residential-House, Two-Family District)

Height and Bulk:

40-X

Block/Lot:

0866/014

Applicant:

Gustav Lindquist & Caroline Ingeborn

64 Potomac Street

San Francisco, CA 94117

www.sfplanning.org

1650 Mission St. Suite 400 San Francisco, CA 94103-2479

Reception: 415.558.6378

Fax:

415.558.6409

Planning Information: 415.558.6377

#### Mill Act Applications October 2, 2019

2019-006323MLS (2251 Webster Street); 2019-006384MLS (1401 Howard Street); 2019-006323MLS (64 Potomac Street); 2019-005831MLS (2168 Market Street); 2019-006455MLS (2731-2735 Folsom Street);

**d.** Filing Date:

May 1, 2019

Case No.:

2019-005831MLS

Project Address:

2168 Market Street (District 8)

Landmark No.:

267

Zoning:

NCT – Upper Market Neighborhood Commercial Transit

Height and Bulk:

40/50-X

Block/Lot:

3542/062

Applicant:

Swedish Society of San Francisco

2168 Market Street

San Francisco, CA 94114

e. Filing Date:

May 1, 2019

Case No.:

2019-006455MLS

Project Address:

2731-2735 Folsom Street (District 9)

Landmark No.:

276

Zoning:

RH-2 – Residential-House, Two-Family

Height and Bulk:

40-X

Block/Lot:

3640/031 Adele Feng

Applicant:

2733 Folsom Street

San Francisco, CA 94110

#### PROPERTY DESCRIPTIONS

a. <u>2251 Webster Street:</u> The subject property is located on the west side of Webster Street between Washington and Clay streets, Assessor's Block 0612, Lot 001A. The subject property is located within a RH-2 (Residential-House, Two-Family District) zoning district and a 40-X Height and Bulk district. The subject property is a contributing building to the Webster Street Historic District. It is a two-story, plus basement, wood-frame, single-family dwelling designed in the Italianate style and built in circa 1900.

- b. 1401 Howard Street: The subject property is located on the south corner of Howard and 10th Streets, Assessor's Block 3517, Lot 035. The subject property is located within an RCD (Regional Commercial District) zoning district and a 55/65-X Height and Bulk district. The subject property, historically known as St. Joseph's Church, is an Article 10 individual landmark (No. 120), located in the California Register Western SOMA Light Industrial and Residential Historic District, and added to the National Register of Historic Places in 1982. The subject property is a former Catholic church constructed in 1913 and designed in the Romanesque Revival style by architect John J. Foley.
- c. 64 Potomac Street: The subject property is located on the east side of Potomac Street between Waller Street and Duboce Park, Assessor's Block 0866 Lot 014. The subject property is located within a RH-2 (Residential-House, Two-Family District) zoning district and a 40-X Height and

Bulk district. The subject property is a contributing building to the Article 10 Duboce Park Historic District. It is a two story over garage, wood-frame, single-family dwelling built in 1899 and features a gable roof and bay window.

- d. <u>2168 Market Street:</u> The subject property is located on the north side of Market Street between Sanchez and Church streets, Assessor's Block 3542 Lot 062. The subject property is located within an NCT (Upper Market Neighborhood Commercial Transit) zoning district and a 40/50-X Height and Bulk district. The subject property is an Article 10 individual landmark (No. 267). It is a three-story wood-frame commercial building constructed in 1907 and designed by master architect August Noridn.
- e. <u>2731-2735 Folsom Street</u>: The subject property is located on the west side of Folsom Street between 23rd and 24th streets, Assessor's Block 3640, Lot 031. The subject property is located within the RH-2 (Residential House, Two Family) zoning district and 40-X Height and Bulk district. The subject property is a three-story, wood frame, three-unit residential building with a rectangular plan. The subject property is an Article 10 individual landmark building (No. 276). The subject property was designed in the Beaux-Arts style by architect James Francis Dunn (1874-1921) and constructed in 1900 for James Gaughran.

#### PROJECT DESCRIPTION

This project is a Mills Act Historical Property Contract application.

#### MILLS ACT REVIEW PROCESS

Once a Mills Act application is received, the matter is referred to the Historic Preservation Commission (HPC) for review. The HPC shall conduct a public hearing on the Mills Act application, historical property contract, and proposed rehabilitation and maintenance plan, and make a recommendation for approval or disapproval to the Board of Supervisors.

The Board of Supervisors will hold a public hearing to review and approve or disapprove the Mills Act application and contract. The Board of Supervisors shall conduct a public hearing to review the Historic Preservation Commission recommendation, information provided by the Assessor's Office, and any other information the Board requires in order to determine whether the City should execute a historical property contract for the subject property.

The Board of Supervisors shall have full discretion to determine whether it is in the public interest to enter into a Mills Act contract and may approve, disapprove, or modify and approve the terms of the contract. Upon approval, the Board of Supervisors shall authorize the Director of Planning and the Assessor-Recorder's Office to execute the historical property contract.

#### MILLS ACT REVIEW PROCEDURES

The Historic Preservation Commission is requested to review and make recommendations on the following:

- The draft Mills Act Historical Property Contract between the property owner and the City and County of San Francisco.
- The proposed rehabilitation and maintenance plan.

The Historic Preservation Commission may also comment in making a determination as to whether the public benefit gained through restoration, continued maintenance and preservation of the property is sufficient to outweigh the subsequent loss of property taxes to the City.

#### APPLICABLE PRESERVATION STANDARDS

Ordinance No. 191-96 amended the San Francisco Administrative Code by adding Chapter 71 to implement the California Mills Act, California Government Code Sections 50280 *et seq.* The Mills Act authorizes local governments to enter into contracts with private property owners who will rehabilitate, restore, preserve, and maintain a "qualified historical property." In return, the property owner enjoys a reduction in property taxes for a given period. The property tax reductions must be made in accordance with Article 1.9 (commencing with Section 439) of Chapter 3 of Part 2 of Division 1 of the California Revenue and Taxation Code.

#### **TERM**

Mills Act contracts must be made for a minimum term of ten years. The ten-year period is automatically renewed by one year annually to create a rolling ten-year term. One year is added automatically to the initial term of the contract on the anniversary date of the contract, unless notice of nonrenewal is given or the contract is terminated. If the City issues a notice of nonrenewal, then one year will no longer be added to the term of the contract on its anniversary date and the contract will only remain in effect for the remainder of its term. The City must monitor the provisions of the contract until its expiration and may terminate the Mills Act contract at any time if it determines that the owner is not complying with the terms of the contract or the legislation. Termination due to default immediately ends the contract term. Mills Act contracts remain in force when a property is sold.

#### **ELIGIBILITY**

San Francisco Administrative Code Chapter 71, Section 71.2, defines a "qualified historic property" as one that is not exempt from property taxation and that is one of the following:

- (a) Individually listed in the National Register of Historic Places;
- (b) Listed as a contributor to an historic district included on the National Register of Historic Places;
- (c) Designated as a City landmark pursuant to San Francisco Planning Code Article 10;
- (d) Designated as contributory to a landmark district designated pursuant to San Francisco Planning Code Article 10; or
- (e) Designated as significant (Categories I or II) or contributory (Categories III or IV) to a conservation district designated pursuant to San Francisco Planning Code Article 11.

#### Mill Act Applications October 2, 2019

2019-006323MLS (2251 Webster Street); 2019-006384MLS (1401 Howard Street); 2019-006323MLS (64 Potomac Street); 2019-005831MLS (2168 Market Street); 2019-006455MLS (2731-2735 Folsom Street);

All properties that are eligible under the criteria listed above must also meet a tax assessment value to be eligible for a Mills Act Contract. The tax assessment limits are listed below:

#### Residential Buildings

Eligibility is limited to a property tax assessment value of not more than \$3,000,000.

#### Commercial, Industrial or Mixed-Use Buildings

Eligibility is limited to a property tax assessment value of not more than \$5,000,000.

Properties may be exempt from the tax assessment values if it meets any one of the following criteria:

- The qualified historic property is an exceptional example of architectural style or represents a work of a master architect or is associated with the lives of persons important to local or national history; or
- Granting the exemption will assist in the preservation and rehabilitation of a historic structure (including unusual and/or excessive maintenance requirements) that would otherwise be in danger of demolition, deterioration, or abandonment;

Properties applying for a valuation exemption must provide evidence that it meets the exemption criteria, including a historic structure report to substantiate the exceptional circumstances for granting the exemption. The Historic Preservation Commission shall make specific findings in determining whether to recommend to the Board of Supervisors that the valuation exemption should be approved. Final approval of this exemption is under the purview of the Board of Supervisors.

#### PRIORITY CRITERIA CONSIDERATIONS

Staff reviewed all applications on the merits of five Priority Consideration. The five priority considerations are:

**Necessity:** The project will require a financial incentive to help ensure the preservation of the property. This criterion will establish that the property is in danger of deterioration and in need of substantial rehabilitation and restoration that has significant associated costs. Properties with open complaints, enforcement cases or violations will not meet this criterion.

**Investment:** The project will result in additional private investment in the property other than for routine maintenance. This may include seismic retrofitting and substantial rehabilitation and restoration work. This criterion will establish that the owner is committed to investing in the restoration, rehabilitation and maintenance the property.

**Distinctiveness:** The project preserves a distinctive example of a property that is especially deserving of a contract due to its exceptional nature.

**Recently Designated City Landmarks**: properties that have been recently designated landmarks will be given priority consideration.

Legacy Business: The project will preserve a property at which a business included in the Legacy Business Registry is located. This criterion will establish that the owner is committed to preserving the property, including physical features that define the existing Legacy Business.

#### PUBLIC/NEIGHBORHOOD INPUT

The Department has not received any public comment regarding the Mills Act Historical Property Contract.

#### STAFF ANAYLSIS

The Department received five Mills Act applications by the May 1, 2019 filing date. The Project Sponsors, Planning Department Staff, and the Office of the City Attorney have negotiated the five attached draft historical property contracts, which include a draft rehabilitation and maintenance plan for the historic building. Department Staff believes the draft historical property contracts and plans are adequate. Please see below for complete analysis.

a. <u>2251 Webster Street</u>: As detailed in the Mills Act application, the applicant proposes to rehabilitate and maintain the historic property. Staff determined that the proposed work, detailed in the attachments, is consistent with the Secretary of Interior's Standards for Rehabilitation.

The subject property is currently valued by the Assessor's Office as under \$3,000,000 (see attached Market Analysis and Income Approach reports) and did not require a Historic Structure Report.

The applicant completed some rehabilitation of the building in 2019, including dry rot repair and painting with an estimated cost of \$12,650. The proposed Rehabilitation Plan includes in kind window replacement, interior plaster and lathe repair from and exterior leak, in-kind replacement of the front and rear doors, roof repair and replacement, painting. Rehabilitation work is estimated to cost \$113,610 over ten years.

The proposed Maintenance Plan includes annual inspection of the wood siding, windows, and roof. Maintenance work is estimated to cost \$2,880 annually. Any needed repairs will be made in kind and will avoid altering, removing or obscuring character-defining features of the building.

No changes to the use of the property are proposed. Please refer to the attached Rehabilitation and Maintenance Plan for a full description of the proposed work. The attached draft historical property contract will help the applicant mitigate these expenditures and will induce the applicant to maintain the property in excellent condition in the future.

The subject property meets three of the five Priority Considerations: Necessity, Investment and Distinctiveness. The proposed rehabilitation will require significant associated costs to ensure the preservation of the subject property. The property owner will invest additional money towards

the rehabilitation other than for routine maintenance. Finally, the proposed rehabilitation project will preserve a distinctive example of a grouping of Italianate homes constructed circa 1900. The subject property does not meet the Recently Designated City Landmarks or the Legacy Business criteria. The building was designated an Article 10 landmark district in 1991 and therefore is not a recent landmark. A Legacy Business is not located at the subject property.

b. <u>1401 Howard Street</u>: As detailed in the Mills Act application, the applicant proposes to rehabilitate and maintain the historic property. Staff determined that the proposed work, detailed in the attachments, is consistent with the Secretary of Interior's Standards for Rehabilitation.

The subject property is currently valued by the Assessor's Office at over \$5,000,000 (see attached Market Analysis and Income Approach reports); therefore, an exemption from the tax assessment value is required. The subject property qualifies for an exemption as it is designated an individual landmark under Article 10 of the Planning Code. A Historic Structure Report was required in order to demonstrate that granting the exemption would assist in the preservation of a property that might otherwise be in danger of demolition, deterioration or abandonment.

In 2018, the applicant completed a full rehabilitation and restoration of the building and received final approval for the Federal Historic Preservation Tax Incentive in September 2018. Work included the restoration of exterior and interior finishes, seismic strengthening, repair of the slate roof, and restoration of the sheet metal domes. The cost of the completed work was approximately \$3,962,310.00.

Future rehabilitation and restoration scope items include full repainting of the interior and exterior. The estimated cost of the proposed rehabilitation work is \$291,065.00 over ten years.

The proposed Maintenance Plan includes annual inspection of exterior stucco, metal roof elements, windows, doors, and roof on a regular basis. The applicant will be maintaining interior character defining features identified in the National Register nomination, such as the entry lobby floors, plaster detailing, and woodwork. Maintenance work is estimated to cost \$31,040 annually. Any needed repairs will be made in kind and will avoid altering, removing or obscuring character-defining features of the building.

No changes to the use of the property are proposed. Please refer to the attached Rehabilitation and Maintenance Plan for a full description of the proposed work. The attached draft historical property contract will help the applicant mitigate these expenditures and will induce the applicant to maintain the property in excellent condition in the future.

The subject property meets two of the five Priority Considerations: Distinctiveness and Investment. The building represents a distinctive example of the Romanesque Revival architectural style. Completed in 2018, the applicant has invested in a full building restoration and rehabilitation scope, including seismic strengthening. The subject application does not meet the Necessity, Recently Designated Landmark, and Legacy Business criteria. The applicant completed a full building rehabilitation and restoration scope in 2018 and the building is in excellent condition; therefore, the application does not meet the Necessity criteria. The building

was designated an Article 10 landmark in 1980 and therefore is not a recent landmark. A Legacy Business is not located at the subject property.

c. 64 Potomac Street: As detailed in the Mills Act application, the applicant proposes to rehabilitate and maintain the historic property. Staff determined that the proposed work, detailed in the attachments, is consistent with the Secretary of Interior's Standards for Rehabilitation.

The subject property is currently valued by the Assessor's Office as under \$3,000,000 (see attached Market Analysis and Income Approach reports) and did not require a Historic Structure Report.

The proposed Rehabilitation Plan includes seismic strengthening, roof replacement, wood siding repair and painting, front façade window repair, restoration of front stairs, front door and garage door replacement. Rehabilitation work is estimated to cost \$126,035 over ten years.

The proposed Maintenance Plan includes annual inspection of roof, gutters and downspouts, windows, doors, foundation, and wood siding and trim. Any needed repairs will be made in kind and will avoid altering, removing or obscuring character-defining features of the building. Maintenance work is estimated to cost approximately \$4,000 annually.

No changes to the use of the property are proposed. Please refer to the attached Rehabilitation and Maintenance Plan for a full description of the proposed work. The attached draft historical property contract will help the applicant mitigate these expenditures and will induce the applicant to maintain the property in excellent condition in the future.

The subject property meets three of the five Priority Considerations: Necessity, Investment and Distinctiveness. The proposed rehabilitation will require significant associated costs to ensure the preservation of the subject property. The property owner will invest additional money towards the rehabilitation other than for routine maintenance. Finally, the proposed rehabilitation project will preserve a distinctive example of Victorian style home. The subject property does not meet the Recently Designated City Landmarks or the Legacy Business criteria. The building was designated an Article 10 landmark district in 2013 and therefore is not a recent landmark. A Legacy Business is not located at the subject property.

d. <u>2168 Market Street:</u> As detailed in the Mills Act application, the applicant proposes to rehabilitate and maintain the historic property. Staff determined that the proposed work, detailed in the attachments, is consistent with the Secretary of Interior's Standards for Rehabilitation.

The subject property is currently valued by the Assessor's Office as under \$5,000,000 (see attached Market Analysis and Income Approach reports) and did not require a Historic Structure Report.

The proposed Rehabilitation Plan includes repair and restoration of the exterior front entry features such as terrazzo, doors, windows, and brick. Rehabilitation work is estimated to cost \$95,160 over ten years.

The proposed Maintenance Plan includes annual inspection of front façade, windows, interior wood elements, and roof. Any needed repairs resulting from inspection will be made in kind and will avoid altering, removing or obscuring character-defining features of the building. Maintenance work is estimated to cost approximately \$7,500 annually.

No changes to the use of the property are proposed. Please refer to the attached Rehabilitation and Maintenance Plan for a full description of the proposed work. The attached draft historical property contract will help the applicant mitigate these expenditures and will induce the applicant to maintain the property in excellent condition in the future. A Certificate of Appropriateness has been submitted for the following scopes to be completed in the next two to three years: replace existing non historic main doors and supporting framework; replace non-historic glass window facing market street with leaded glass window to match the historic nature of the façade.

The subject property meets three of the five Priority Considerations. It represents an exceptional example of the Arts & Crafts architectural style and therefore meets the Distinctiveness priority consideration. The building was designated an Article 10 landmark in 2015 and was designated on the National Register of Historic Places in 2019 and therefore is a recent landmark. In 2015 the applicant performed a full building rehabilitation, including seismic strengthening and elevator upgrades, at the subject property; therefore, the subject property not meet the Necessity or Investment criteria. Café du Nord, a registered Legacy Business ca. 2016, is located at the subject property and will continue to operate as such.

e. <u>2731-2735 Folsom Street:</u> As detailed in the Mills Act application, the applicant proposes to rehabilitate and maintain the historic property. Staff determined that the proposed work, detailed in the attachments, is consistent with the Secretary of Interior's Standards for Rehabilitation.

The subject property is currently valued by the Assessor's Office at over \$3,000,000 (see attached Market Analysis and Income Approach reports); therefore, an exemption from the tax assessment value is required. The subject property qualifies for an exemption as it is designated an individual landmark under Article 10 of the Planning Code. A Historic Structure Report was required in order to demonstrate that granting the exemption would assist in the preservation of a property that might otherwise be in danger of demolition, deterioration or abandonment.

The building underwent a full rehabilitation c.2014 which included full re-painting of all elevations, façade restoration, structural strengthening, and re-roofing. The proposed Rehabilitation Plan includes dry rot repair of wood elements at the base of the building, repair and restoration of windows, improve site drainage against foundation of building, repaint exterior, replace roof flashing, and fully re-roof the building. Rehabilitation work is estimated to cost \$305,573 over ten years.

The proposed Maintenance Plan includes annual inspection of gutters and downspouts, windows, front facade, and roof. Any needed repairs resulting from inspection will be made in

kind and will avoid altering, removing or obscuring character-defining features of the building. Maintenance work is estimated to cost approximately \$5,148 annually.

No changes to the use of the property are proposed. Please refer to the attached Rehabilitation and Maintenance Plan for a full description of the proposed work. The attached draft historical property contract will help the applicant mitigate these expenditures and will induce the applicant to maintain the property in excellent condition in the future.

The subject property meets three of the five Priority Considerations: Distinctiveness, Investment and Recently Designated City Landmark. The subject property represents a distinctive and well-preserved example of the Beaux-Arts style architecture. The property owner will be investing additional money towards the rehabilitation other than for routine maintenance. Additionally, in 2017 the City of San Francisco designated the subject building as an individual landmark under Article 10. The subject property does not meet the Necessity and Legacy Business criteria. In 2014, a full building rehabilitation, including seismic strengthening, was performed therefore the building is in good condition. Furthermore, the building is fully occupied and is not in danger of deterioration or abandonment. A Legacy Business is not located at the subject property.

#### ASSESSOR-RECORDER INFORMATION

Based on information received from the Assessor-Recorder, the following properties will receive an estimated first year reduction as a result of the Mills Act Contract. Please refer to the attached Preliminary Valuation spreadsheet prepared by the Assessor for detailed information about each property.

- a) <u>2251 Webster Street:</u> Estimated Property Tax Savings of <u>\$14,184</u> (a 66.37% reduction from factored base year value)
- b) <u>1401 Howard Street:</u> Estimated Property Tax Savings of <u>\$66,974</u> (a 31.20% reduction from factored base year value)
- c) <u>64 Potomac Street:</u> Estimated Property Tax Savings of <u>\$22,679</u> (a 76.47% reduction from factored base year value)
- d) <u>2168 Market Street:</u> Estimated Property Tax Savings of \$0 (a 0.00% reduction from factored base year value). The property owner is aware that they will not receive a tax savings but would like to move forward with the Mills Act knowing that the property will be re-evaluated in the future.
- e) <u>2731-2735 Folsom Street:</u> Estimated Property Tax Savings of \$35,495 (a 49.46% reduction from factored base year value)

#### PLANNING DEPARTMENT RECOMMENDATION

- The Planning Department recommends that the Historic Preservation Commission adopt a resolution recommending approval of the Mills Act Historical Property Contracts and Rehabilitation and Maintenance Plans to the Board of Supervisors for the following properties:
  - a. 2251 Webster Street
  - b. 1401 Howard Street
  - c. 64 Potomac Street
  - d. 2168 Market Street
  - e. 2731-2735 Folsom Street

#### ISSUES AND OTHER CONSIDERATIONS

Mills Act Contract property owners are required to submit an annual affidavit demonstrating compliance with Rehabilitation and Maintenance Plans.

#### HISTORIC PRESERVATION COMMISSION ACTIONS

Review and adopt a resolution for each property:

- 1. Recommending to the Board of Supervisors approval of the proposed Mills Act Historical Property Contract between the property owner(s) and the City and County of San Francisco;
- 2. Approving the proposed Mills Act Rehabilitation and Maintenance Plan for each property.

#### Attachments:

#### a. 2251 Webster Street:

Site & Aerial Photos

**Draft Resolution** 

Draft Mills Act Historical Property Contract

Draft Rehabilitation Program& Maintenance Plan

Draft Mills Act Valuation provided by the Assessor-Recorder's Office

Pre-Approval Inspection Report

Mills Act Application

#### b. 1401 Howard Street:

Site & Aerial Photos

**Draft Resolution** 

Draft Mills Act Historical Property Contract

Draft Rehabilitation Program & Maintenance Plan

Draft Mills Act Valuation provided by the Assessor-Recorder's Office

Pre-Approval Inspection Report

Mills Act Application

#### Mill Act Applications October 2, 2019

2019-006323MLS (2251 Webster Street); 2019-006384MLS (1401 Howard Street); 2019-006323MLS (64 Potomac Street); 2019-005831MLS (2168 Market Street); 2019-006455MLS (2731-2735 Folsom Street);

Historic Structure Report

#### c. 64 Potomac Street:

Site & Aerial Photos
Draft Resolution
Draft Mills Act Historical Property Contract
Draft Rehabilitation Program & Maintenance Plan
Draft Mills Act Valuation provided by the Assessor-Recorder's Office
Pre-Approval Inspection Report
Mills Act Application

#### d. 2168 Market Street:

Site & Aerial Photos
Draft Resolution
Draft Mills Act Historical Property Contract
Draft Rehabilitation Program & Maintenance Plan
Draft Mills Act Valuation provided by the Assessor-Recorder's Office
Pre-Approval Inspection Report
Mills Act Application

#### e. 2731-2735 Folsom Street:

Site & Aerial Photos
Draft Resolution
Draft Mills Act Historical Property Contract
Draft Rehabilitation Program & Maintenance Plan
Draft Mills Act Valuation provided by the Assessor-Recorder's Office
Pre-Approval Inspection Report
Mills Act Application
Historic Structure Report

Case No.:

2019-006384MLS

Project Address:

1401 Howard Street (District 6)

Landmark District:

Article 10 Landmark Number 120

Zoning:

RCD (Regional Commercial)

Height and Bulk:

55/65-X 3517/035

Block/Lot:
Applicant:

1401 Howard Street, LLC


1401 Howard Street

San Francisco, CA 94103

## SITE PHOTO



## **AERIAL PHOTO**





## Historic Preservation Commission Resolution No. 1091

HEARING DATE OCTOBER 2, 2019

Case No.:

2019-006384MLS

Project Address:

1401 Howard Street (District 6)

Eligibility:

Article 10 Landmark No. 120: Saint Joseph's Church

National Register listed property

Zoning:

RCD - Regional Commercial

Height and Bulk:

55/65-X 3517/035

Block/Lot: Staff Contact:

Michelle Taylor – (415) 575-9197

Michelle.Taylor@sfgov.org

Reviewed By:

Elizabeth Gordon-Jonckheer - (415) 575-8728

Elizabeth.Gordon-Jonckheer@sfgov.org

ADOPTING FINDINGS RECOMMENDING TO THE BOARD OF SUPERVISORS APPROVAL OF THE DRAFT MILLS ACT HISTORICAL PROPERTY CONTRACT, REHABILITATION PROGRAM, AND MAINTENANCE PLAN FOR 1401 HOWARD STREET.

WHEREAS, The Mills Act, California Government Code Sections 50280 et seq. ("the Mills Act") authorizes local governments to enter into contracts with owners of private historical property who assure the rehabilitation, restoration, preservation and maintenance of a qualified historical property; and

WHEREAS, In accordance with Article 1.9 (commencing with Section 439) of Chapter 3 of Part 2 of Division 1 of the California Revenue and Taxation Code, the City and County of San Francisco may provide certain property tax reductions, such as those provided for in the Mills Act; and

WHEREAS, Ordinance No. 191-96 amended the San Francisco Administrative Code by adding Chapter 71, to implement Mills Act locally; and

WHEREAS, The Planning Department has determined that the actions contemplated in this Resolution are categorically exempt from with the California Environmental Quality Act (California Public Resources Code Sections 21000 et seq.) under section 15331; and

WHEREAS, The existing building located at 1401 Howard Street is listed under Article 10 as Landmark Number 120 and listed on the National Register of Historic Places and thus qualifies as a historical property for the purposes of the Mills Act; and

WHEREAS, The Planning Department has reviewed the Mills Act Application, draft Historical Property Contract, Rehabilitation Program, and Maintenance Plan for 1401 Howard Street, which are located in

1650 Mission St. Suite 400 San Francisco, CA 94103-2479

Reception: 415.558.6378

Fax:

415.558.6409

Planning Information: 415.558.6377 Case Docket No. 2019-006384MLS. The Planning Department recommends approval of the draft Mills Act historical property contract, rehabilitation program, and maintenance plan; and

WHEREAS, The Historic Preservation Commission (HPC) recognizes the historic building at 1401 Howard Street as an historical resource and believes the Rehabilitation Program and Maintenance Plan are appropriate for the property; and

WHEREAS, At a duly noticed public hearing held on October 2, 2019, the HPC reviewed documents, correspondence and heard oral testimony on the Mills Act Application, Historical Property Contract, Rehabilitation Program, and Maintenance Plan for 1401 Howard Street, which are located in Case Docket No. 2019-006384MLS.

THEREFORE BE IT RESOLVED that the HPC hereby recommends that the Board of Supervisors approve the draft Mills Act Historical Property Contract, including the Rehabilitation Program and Maintenance Plan for the historic building located at 1401 Howard Street, attached herein as Exhibits A and B, and fully incorporated by this reference.

BE IT FURTHER RESOLVED That the HPC hereby directs its Commission Secretary to transmit this Resolution, the draft Mills Act Historical Property Contract, including the Rehabilitation Program, and Maintenance Plan for 1401 Howard Street, and other pertinent materials in the case file 2019-006384MLS to the Board of Supervisors.

I hereby certify that the foregoing Resolution was ADOPTED by the Historic Preservation Commission on October 2, 2019.

Jonas P. Jonin

Commissions Secretary

AYES:

Johns, Pearlman, So, Hyland, Matsuda, Black

NOES:

None

ABSENT:

None

RECUSED:

Foley

ADOPTED:

October 2, 2019

### REHABILITATION / RESTORATION & MAINTENANCE PLAN (CONTINUED/ ATTACHMENT)

Exhibit A. Rehabilitation/Restoration Plan

Scope: # 1
Building Feature: Exterior Gates, Curbs, Fence, Piers, Granite Steps
Rehab/Restoration X Maintenance Completed X Proposed
Contract year work completion: 2018
Total Cost: \$25,000.00 Source SOV #2920
Description of work: Restoration and Repair of Exterior Gates, Curbs, Fences, Piers and Granite

Description of work: Restoration and Repair of Exterior Gates, Curbs, Fences, Piers and Granite Steps

- The direction of the swing of all gates was reversed in the direction of egress. The gates were prepared, primed, and painted, and latch and lock sets were provided. At the two existing double gateways, the existing gates were reinstalled on new freestanding supports similar to the existing. The original hinges were retained at the original piers. The displaced sections of the piers were reset in the original locations and grouted. The cement plaster parge was repaired as required to match the original.
- The iron fence was prepared, primed, and painted. The gaps and voids were filled with mortar at the base and pier attachments. Where the fence is set into the curb and is corroded, the metal was repaired, painted, and set into lead or sealant as required to prevent future damage to the fence or curb.
- The cement plaster parge on the piers was cleaned and graffiti was removed or painted over. The cement plaster parge was repaired to match the existing adjacent color and texture as required.
- Existing joints were raked out and the granite steps were cleared of debris. Joints were repaired with mortar. Algae, moss, and other biological growth was removed. Soil and paint spatters were removed. New code-required bronze handrails were installed.

Scope: # 2 Building Feature: Ext	erior Pai	nt and Stucco Re	pair		
Rehab/Restoration	X	Maintenance	Completed	X	Proposed
Contract year work c	ompletio	n: 2018 Phase 1,	Phase 2 scheduled 1	for 2	026
Total Cost: \$146,950	. Source	e SOV #9900 (ha	f), \$293850/2=\$146,	950.	•

Description of work: Façade Restoration and Full Repainting

- The existing stucco was analyzed to determine if it was lime or Portland cement-based. These tests were performed by an architectural conservator.
- Staining and soiling was removed by the gentlest means possible, this included light brushing and water washing, and cleaning with a commercial agent.
- Areas of significant hairline cracking were repaired based on analysis to determine the root cause of the condition. Investigation included testing for underlying detachment of the stucco layer, moisture intrusion, structural movement, or other causes.
- Climbing vegetation such as ivy was removed.
- Spalls and cracks through cement plaster were repaired. The cracks were routed and patched to match the existing adjacent texture, profile, and appearance.
- The existing deteriorated or detached cement plaster was removed. Graffiti and stains were removed.
- Unsound paint was removed and coated with a new breathable paint coating.

Scope: #3 Building Feature: Exterior	Sheet Motal Floments	including domes on t	owers column capita	ile
decorative moldings, gutte		s, including domes on t	owers, column capite	us,
Rehab/Restoration X	Maintenance	Completed X	Proposed	_
Contract year work comple	etion: 2018			_
Total Cost: \$424,323. Sou	rce SOV #7600 = \$434	,323		
Description of work: Renai	r and Restoration of Ev	terior Sheet Metal Elen	nante	

ork: Repair and Restoration of Exterior Sheet Metal Elements

- Peeling or blistering paint was scraped or sanded.
- Corrosion was removed with hand scrapers or a wire brush.
- For panels with heavy corrosion and resulting perforation of the sheet metal unit, there were three options, dependent on severity and size:
  - 1. Corroded panels were removed and the unit was replaced with a new piece of sheet metal cut to the appropriate dimension and profile,
  - 2. The corroded area was cut out of existing sheet metal, a new piece was brazewelded and the joint was ground flat; or
  - 3. The corroded area was cut out of existing sheet metal and steel-filled epoxy compound was installed to patch small holes.
- All exposed metal was painted with a rust-inhibiting primer and two coats of colorappropriate outdoor paint.
- Missing elements were replaced to maintain visual consistency.

Scope: Building	# 4 g Feature: Exterio	or Wood-sash Window	s and Steel Tracery	
Rehab	Restoration X	Maintenance	Completed X	Proposed
Contrac	ct year work com	pletion: 2018		
Total C	ost: \$366,443. S	ource SOV #6150 and #	8050 for \$96,867 and	\$269,576 = 366,443
Descrip	otion of Work: Re	pair, Restoration and Re	placement of Windows	
# #	determine the e included careful and other non-in	tions assessment of win ktent of deterioration and inspection and documen avasive diagnostic tests. Indow frames attempted	d appropriate treatments ntation of each window f	at each window. This rame and its conditions,
-	while providing	-	ction for the building, an	id included paint removal,

glazing compound. The wood frames were prepared and painted, all the existing ribbed glass that could be preserved was reused. Ribbed glass that matched the original was installed in selected locations.

Scope: # 5 Building Feature: Exterior	_ Stained Glass Windo	ows		
Rehab/Restoration X	Maintenance	Completed X	Proposed	
Contract year work comple	etion: 2018			
Total Cost: \$81,260,00 So	urce SOV #8070			

Description of work: Repair and Restoration of Stained Glass Windows

- Documentation and restoration of the windows was performed by a professional conservator. Restoration included removal, transport, restoration, and reinstallation of the stained glass.
- The wood and steel armatures remaining from the previous stained glass window installation were prepared and painted.
- The remaining stained glass in the south wall of the kitchen was removed, salvaged, and reinstalled in the office on the first floor.

Scope: #6		199		
Building Feature: Ext	erior S	kylight		
Rehab/Restoration	X	Maintenance	Completed X	Proposed
Contract year work c	omplet	ion: 2018		
Total Cost: \$39,010.0	00 Sou	rce SOV #8080		
Description of work: I	Repair	and Restoration of Ex	terior Skylight	
■ The steel sky	/light re	emained in place and	was repaired and clean	ied.
<ul> <li>New tempered</li> </ul>	ed glaz	ing and sealant was ir	istalled, and all work ar	nd flashing details were
coordinated	with the	e roof strengthening a	nd re-roofing work.	•

Scope: #7 Building Feature: Inte	rior Str	uctural Steel for Seisr	mic		
Rehab/Restoration	X	Maintenance	Completed X	Proposed ·	
Contract year work co	ompleti	on: 2018			
Total Cost: \$571,841 Source SOV 8 items #5050, 5070 and 5120					
Description of work: Seismic Strengthening					
Steel was fabricated and installed for seismic strengthening.					

Building Feature: Inter	ior Deco	rative Plaster			
Rehab/Restoration	X	Maintenance	Completed [2	Χ	Proposed
Contract year work cor	mpletion	: 2018			
Total Cost: \$1,350,577	7.00 SQL	rce SOV #9050,\$	1.350.577		

- Detached or cracked plaster elements were repaired, if in otherwise sound condition, with an injected epoxy or gypsum-based grout. Testing was conducted to determine the most effective adhesive.
- Non-historic wood veneer was removed so that plaster at the base of the wall could be restored and painted.
- Further testing of the plaster was conducted to determine the extent of deterioration. This
  determined the treatment method: patching and reshaping damaged elements when
  possible, or replacement in kind.

Scope: # 9		·		
Building Feature: Interior	Woodwork, Doors and F	inish Hardware		
Rehab/Restoration X	Maintenance	Completed X	Proposed	
Contract year work comp	etion: 2018			
T	0 001/ //0000			

Total Cost: \$269,000.00 Source SOV #8200

Description of work: Repair and Restoration of Interior Woodwork, Doors and Finish Hardware

- Soiling was cleaned with the gentlest means possible, using a soft bristle brush to remove loose dust and a damp cloth for tenacious soiling.
- Blistered varnish was treated with the gentlest means possible in order to preserve the
  existing finish. Treatments included lightly scraping blistered areas of varnish and spottreating with fine steel wool or cotton, alcohol and a compatible varnish or shellac.
- White stains were tested to determine the cause Paint and guano were removed mechanically with a scraper so as not to damage the existing wood finish.
- Where required by the level of damage, select areas of woodwork were refinished to match the original.

- Wood was replaced where missing to match the original.
- At exterior doors, deteriorated wood was repaired with wood Dutchman and matched the original species, grade, grain, and profile. The exterior surface was prepped and painted. The interior was cleaned and touched up or refinished to match the original stain or clear coat.
- Door hardware was replaced or repaired to match existing and to meet current code.

Scope: #10				
Building Feature: Inte	erior N	Narble Wainscoting and	Tiles	
Rehab/Restoration	X	Maintenance	Completed X	Proposed
Contract year work of	omple	etion: 2018		
Total Cost: \$5,000.00	) Sou	rce From KFI (3/28/19	email)	

Description of work: Restoration of Interior Marble

- Tape residue and soiling was removed with a gentle stone cleaner. Mock-ups were conducted to determine the most effective product.
- Vinyl tiles and mastic were removed in the vestibule without causing damage to underlying marble, which was cleaned with a gentle stone cleaner to remove staining and adhesive. Mockups were conducted to determine the most effective product.
- Vinyl tiles and mastic were removed from the vestibule floor and cleaned using the gentlest means possible.
- The marble floors were polished to restore luster

New stage over the grade beams was installed in the apse.

Tower walls reinforced in concrete and covered in plaster.

Scope: #11						44.0
Building Feature: Inte	erior Na	ave Floor Concrete				
Rehab/Restoration	X	Maintenance	Completed	X	Proposed	
Contract year work c	omplet	ion: 2018				
Total Cost: \$207,357	Sour	ce (4 items) SOV #20:	50, #2250, #2300	and	KFI, \$30,000 \$7,500	
\$79,847 \$45,410 ar	nd \$44	,600				
Description of work:						
<ul><li>The existing</li></ul>	(non h	istoric) slab was remo	ved			
<ul> <li>Soil was exc</li> </ul>	avated	and the surrounding s	soil was underpinr	red.		
<ul> <li>New foundat</li> </ul>	ions. v	ith piers and grade be	ams were installe	d		

Scope: # 12
Building Feature: Interior Tower Floor Concrete

Rehab/Restoration X Maintenance Completed X Proposed

Contract year work completion: 2018

Total Cost: \$573,000.00 Source SOV #2450 and #2460 and KFI

Description of work:

The concrete sloped floor was replaced with a new flat structural concrete slab.

New micropile foundations were installed in the towers.

The top 10 feet of the micro piles were cased in concrete.

Scope: # 13				
Building Feature: Ext	erior	Lighting		
Rehab/Restoration	X	Maintenance	Completed X	Proposed
Contract year work o	ompl	etion: 2018		

#### Total Cost: \$92,625.00 Source SOV #16080

#### Description of work:

- The missing original fixtures on the main entry façade were replicated based on historic documentation.
- Building façade lighting was replaced with LED fixtures to save energy.

The missing fixtures in the main sanctuary were replicated.

New built-up roofing was installed over new structural decking.

Scope: # 14 Building Feature: Int	erior Li	ighting		e dan e	
Rehab/Restoration	X	Maintenance	Completed	X	Proposed
Contract year work of	comple	tion: 2018			
Total Cost: \$135,28	1.00 Sc	ource SOV #16070			
Description of work:	Repair	, Restoration and Repl	acement in kind o	of hist	oric light fixtures:
<ul><li>The historic</li></ul>	light fix	ctures were cleaned an	d relamped.		

Scope: # 15
Building Feature: Roof / Built-up Roof
Rehab/Restoration X Maintenance Completed X Proposed
Contract year work completion: 2018
Total Cost: \$28,110.00 Source SOV #7500
Description of work:

Existing built-up roofing was removed at the lower roofs.

Scope: # 16
Building Feature: Roof / Slate Roof
Rehab/Restoration X Maintenance Completed X Proposed
Contract year work completion: 2018
Total Cost: \$258,950.00 Source SOV #7300

#### Description of work:

- Existing slate roof tile was removed at the main roof and portals, salvaged, and reinstalled to allow access for structural stabilization of the roof structure.
- Deteriorated and broken tiles were replaced with salvaged stock or new tile to match the existing.
- New felt underlayment and galvanized flashing was installed.

# Scope: # 17 Building Feature: Interior Painting Rehab/Restoration X Maintenance Completed X Proposed Contract year work completion: 2018 Phase 1, Phase 2 scheduled for 2026 Total Cost: \$146,950.00 Source SOV #9900 (half), \$293850/2=\$146,950 Description of work:

- Tested bottom layer of paint to find original colors.
- Interior plaster was painted, interior wood was refinished, and window mullions were repainted.
- Lead paint was abated.

Scope: #18		Property of the Control of the Contr			
Building Feature: Roo	of / Shee	t Metal Dome and Sheet	Metal Crosses		
Rehab/Restoration	<u>X</u>	Maintenance	Completed X	Propose	d
Contract year work co	mpletio	n: 2018	-		
Total Cost: \$60,000.0	0 Source	e SOV #9950			
Description of work:					
Gold leaf was	; reappli	ed to the domes and cros	sses.		
002506	Kirkatha etaka aya L				
Scope: #19					
Building Feature: AD/					
Rehab/Restoration	[X]	Maintenance	Completed X	Propose	<b>d</b>
Contract year work co					***************************************
	Convei	rsation with contractor			
Description of work:					
Ramp provide					
Auto operator	provide	ed at existing door.		,	
Scope: #20					
Building Feature: Inte	rior Pair	ting			
Rehab/Restoration	X	Maintenance	Completed	Proposed	X
Contract year work co			Completed	Troposed	
Total Cost: \$50,000.0					
Description of work:	0 0000				
■ Partial repain	ting of in	nterior walls			
Scope: #21					
	erior Pai	nting of Cement Plaster			
Rehab/Restoration	[X]	Maintenance	Completed	Proposed	X
Contract year work co	mpletio	n: 2026			
		erior painting costs in 201	8 escalated 5%/	yr for 8 years	)
		ir any new cracks. All re			
		rdance with the Secretar			•

# Exhibit B Maintenance Plan

Scope: # 1 Building Feature: Site_L	andscape					1.2
Rehab/Restoration	Maintenance	X	Completed	Proposed	X	
Contract year work comp	oletion: 2028 and ev	ery	10 years thereafter			
Total Cost: \$120,000.00	(\$1,000/month x 12	mo :	x 10 yrs)			
Description of work: Was	shing of sidewalks ar	nd g	ranite entry steps. Gran	ite steps will be	e clea	aned
using the gentlest means	s possible as recomr	men	ded in NPS Preservation	n Brief No. 1: A	lsses	ssing
Cleaning and Water-Rep	ellent Treatments fo	or Hi	storic Masonry Building	s. All work will	be pe	erformed
in conformance with the	Secretary of the Inte	erior	Standards.			

Building Feature: Exteri	or_Stucco				
Rehab/Restoration	Maintenance	X	Completed	Proposed	X
Contract year work com	pletion: 2019 and ar	nually th	nereafter		
Total Cost: \$40,000 (ma	intenance of 4,000/	yr x10yrs	3)		
Description of work: Re	gular repainting of ex	cterior st	ucco as needed to a	address graffiti.	Perform
visual inspection annua				Ü	

Scope:#3					
Building Feature: Roof					
Rehab/Restoration	Maintenance	X	Completed	Proposed	X
Contract year work comp	oletion: 2019 and ar	nually	y thereafter		
Total Cost: \$30,000.00 (	maintenance of \$3	,000 x	10yrs)		
Description of work: Insp and repair caulking and t and discourage roosting.	fashing. Clear drair				

Scope: # 4 Building Feature: Exterior decorative moldings, gu			cluding domes on to	wers, column c	apitals,
Rehab/Restoration	Maintenance		Completed	Proposed	X
Contract year work com	pletion: 2019 and ar	nually tl	nereafter	-	
Total Cost: \$12,000.00 (	\$1200 per year)				
Description of work: Per shouldn't be. Clean gutt pieces to match existing conformance with the So	ers, replace screens using appropriate n	, check naterials	down spouts and cle and methods. All re	ean drains. Rep	air damaged

Scope: #5						
Building Feature: Exterio	or Wood-sash Winde	ows ar	nd Steel Tracery.	10 mg		
Rehab/Restoration	Maintenance	X	Completed	Proposed	X	
Contract year work com	pletion: 2019 and ar	nnually	thereafter.			
Total Cost: \$10,000.00 (	\$1000 per year)					
Description of work: Per	form visual inspection	on ann	ually for signs of caul	king failure, che	ck operable	
windows, window locks a	and replace any cra	cked c	r broken glass in kind	l. All window rep	pairs will be	
performed in accordance	with the Secretary	of the	Interior Standards.			

Scope: #6					
Building Feature: Exterio	r Skylight		The state of the s		
Rehab/Restoration	Maintenance	X	Completed	Proposed	X
Contract year work comp	letion: 2019 and ar	nually th	ereafter		
Total Cost: \$5,000.00 (\$5	500 per year)	,			
Description of work: Perf	orm visual inspection	on annua	lly for signs of caul	king failure, con	densation
problems that might com	promise structure o	f skyligh	t and replace any c	racked or broke	n glass in
kind. All repairs will be be	erformed in conform	nance wit	th the Secretary of t	the Interior Star	ndards.

Building Feature: Exterio	r Stained Glass Wir	ndows	S		9.00
Rehab/Restoration	Maintenance	X	Completed	Proposed	X
Contract year work comp	oletion: 2019 and an	nuall	y thereafter	•	
Total Cost: \$16,000.00 (	\$1600 per year)				
Description of work: Insp matches original glass in All work will be performe accordance with NPS Pr and Leaded Glass	color and texture. I d in conformance w	nspec	ct and repair lead came e Secretary of the Inter	es. ior's Standards	s and in

Scope:#8					
Building Feature: Exterior	or Wood Doors				
Rehab/Restoration	Maintenance	<u>X</u>	Completed	Proposed	X
Contract year work com	pletion: 2019 and ar	nually	thereafter		
Total Cost: \$7,900.00 (\$	790 per year)	-			
Description of work: The	face of the wood do	ors ha	ve extreme exposure	to rain and sur	n. They
suffered significant dete	rioration in the past.	They n	eed regular cleaning	and regular ref	finishing. All
work will be performed i	n conformance with	the Sec	cretary of the Interior	's Standards	•

Scope: # 9 Building Feature: Interio	r Decorative Plaster				
Rehab/Restoration	Maintenance	X	Completed	Proposed	X
Contract year work com	pletion: 2019 and ev	ery 10	years thereafter	,	
Total Cost: \$20,000.00	(\$2000 per year)			-	
Description of work: The	e existing plaster was	s previo	ously damaged when	water got into	the attic and
behind the decorative p	aster ceiling. Proble	ms on	the surface appeared	only after cons	siderable
damage was done insid	e the concealed spa	ces, th	erefore there will be v	isual inspectio	ns annually
must look inside the atti	c for signs of water o	lamage	e and make needed re	epairs.	
All work will be performe	ed in conformance w	ith the	Secretary of the Inter	ior's Standards	s and in
accordance with NPS P	reservation Brief No.	23: Pi	eserving Historic Orn	amental Plaste	er.

Scope: #10 Building Feature: Interio	r Woodwork				
Rehab/Restoration	Maintenance	X	Completed	Proposed	X
Contract year work com	pletion: 2019 and ar	nually t	hereafter		
Total Cost: \$16,000.00 (	(\$1600 per year)				· ·
Description of work: Per	form visual inspection	on annu	ally for damage and	repair in the ge	ntlest means
possible. All work will be	-		-		

Scope: # 11

Building Feature: Bell Tower

Rehab/Restoration Maintenance X Completed Proposed X

Contract year work completion: 2019 and annually thereafter

Total Cost: \$18,500.00 (\$1850 per year)

Description of work: Annual visual inspection of bell rope and hanging mechanism. Climb the ladders and go into the attic spaces and remove birds and close up any gaps in the screens and louvers.

Scope: # 12

Building Feature: Site Drainage

Rehab/Restoration Maintenance X Completed Proposed X

Contract year work completion: 2019 and annually thereafter

Total Cost: \$11,500 (\$1,500 per year)

Description of work: Inspect drywells in garden areas and verify site drainage is functioning to remove standing water. Repair if needed if water is not being completely absorbed as intended.

Scope: # 13

Building Feature: Interior plaster

Rehab/Restoration Maintenance X Completed Proposed X

Contract year work completion: 2023 and bi-annually thereafter

Total Cost: \$80,000

Description of work; Repaint public spaces and repair plaster work as necessary. All work will be performed in conformance with the Secretary of the Interior's Standards and in accordance with NPS Preservation Brief No. 23: Preserving Historic Ornamental Plaster and No. 21: Repairing Historic Flat Plaster Walls and Ceilings

Scope: # 14

Building Feature: Interior Marble Floors

Rehab/Restoration Maintenance X Completed Proposed X

Contract year work completion: 2022 and annually thereafter

Total Cost: \$8,000

Description of work: Clean and reseal marble floors and wainscot. All marble will be cleaned using the gentlest means possible as recommended in NPS Preservation Brief No. 1: Assessing Cleaning and Water-Repellent Treatments for Historic Masonry Buildings

Scope: # 15

Building Feature: Interior wood floors, wood doors and wood paneling

Rehab/Restoration Maintenance X Completed Proposed X


Contract year work completion: 2022 and annually thereafter


Total Cost: \$12,000

Description of work: Conduct a visual inspection and repair as needed to match original. All work will meet the Secretary of the Interior's Standards.



# Office of the Assessor / Recorder - City and County of San Francisco Mills Act Valuation







## SUBJECT PHOTOGRAPH AND LOCATOR MAP

Address: 1401 Howard Street

APN: 3517-035





#### OFFICE OF THE ASSESSOR-RECORDER - CITY & COUNTY OF SAN FRANCISCO MILLS ACT VALUATION

APN:

3517-035

Lien Date:

7/1/2019

Address:

1401 Howard Street

**Application Date:** 

5/24/2019

SF Landmark No.:

4/29/1900

**Application Term:** 

10 years

Applicant's Name:

1401 Howard LLC

Last Sale Date:

3/26/2008

Agt\_/Tax Rep\_/Atty:

Unknown

Last Sale Price:

\$500,000

Fee Appraisal Provided:

No

(Assessment Appeals Board Value)

FACTORED BASE Y	PEAR (Roll) VALUE	INCOME CAPITALIZATION	ON APPROACH	SALES COMPARISON	N APPROACH
Land	\$553,421	Land	\$7,620,000	Land	\$8,220,000
Imps.	\$17,905,319	Imps.	\$5,080,000	Imps.	\$5;480,000
Personal Prop	\$0	Personal Prop	\$0	Personal Prop	\$0
Total	\$18,458,740	Total	\$12,700,000	Total	\$ 13,700,000

#### **Property Description**

Property Type:

Commercial

Year Built:

1913 / 2017

Neighborhood:

Soma

Type of Use:

Interior Design Firm (Total) Rentable Area:

21,943

Land Area:

26,811

Owner-Occupied:

Stories:

4

Zoning:

RCD - Regional Commercial

Unit Types:

Commercial

Parking Spaces:

Surface / 6

Total No. of Units: 1

#### Special Conditions (Where Applicable)

Conclusions and Recommendations	Per Unit	PerSF	Total
Factored Base Year Roll	\$18,458,740	\$841	\$ 18,458,740
Income Approach - Direct Capitalization	\$12,700,000	\$579	\$ 12,700,000
Sales Comparison Approach	\$13,700,000	\$624	\$ 13,700,000
Recommended Value Estimate	\$ 12,700,000 \$	579	\$ 12,700,000

Appraiser:

Jody Scott Reichel

Principal Appraiser: Orla Fahy

Hearing Date: Unknown

	1401 Howard Street 7/1/2019					
		Sq. Ft.		Annual Rent/SF		Comments
Potential Gross	s Income	21,943	x	\$61.06	\$1,339,800	Based on actual
Less: Vaca	ancy & Collection Loss		,	3%	(\$40,194)	lease amount
Effective Gross	Income				\$1,299,606	
Less: Antic	ipated Operating Expenses (Pre-	Property Tax)*		3%	(\$38,988)	
Net Operating	Income (Pre-Property Tax)				\$1,260,618	
		•				
2019 interest Risk rate (4% 2019 propert	pitalization Rate rate per State Board of Equalization owner occuped / 2% all other projects y tax rate * rate for improvements only			4.7500% 2.0000% 1.1630%		
	g economic life (in years) ents constitute % of total property	<u>30</u> ∕ value	0.0333 60%	<u>2.0000%</u>	9.9130%	

INCOME APPROACH

**RESTRICTED VALUE ESTIMATE** 

\$12,716,815 \$12,700,000 RD

<sup>\*</sup> The 2019 property tax rate will be determined in September 2019. Rate utilized is from 2018.

Comparable improve APN:	ed Sales Adjustment 3517-035		a, un campagnica property diagram Calebra (n. 1800 1806 1806 1800 1800 1800 1804 1806 1806 1806 1806 1806 1806 1806 1806	ang yang ng ketilah di Kili Myelahay 20. Dengan di Kapadan di Kili Kapadan Ciran.	ina de la composição do la composição de l La composição de la compo
ਪਾਸ. Address:	1401 Howard Street				
Sale No	One	Two	Three	Four	SUBJECT
APt	V: 0839-032	3502-013	0637-015 & -016	1080-035	3517-035
Addres		170 Valencia Street	2395 Sacramento St.	2398 Geary Blvd.	1401 Howard St.
Sale Dat		12/31/2018	12/8/2017	3/11/2016	7/1/2019
Sale Prio		\$9,600,000	\$9,500,000	\$4,400,000	04.040
Size (Si		23,270 1931	20,110 1912	7,937 1906	21,943
Year Bui Price/S		\$413	\$472	\$554	1913 / 2017
PIICE/S	\$300	D412	Ψ41Z	\$304	
Us	e Former Church	Former Religious Hall	Former Library	Former Church	Former Church
Site Zonin		RTO	RM1	RH3	SLR
Site Size (SI		8,250	15,105	5,031	26,811
Land: Bldg. Rat		0.35	0.75	0.63	1.22
On Site Parkin	g			•	
Ratio/1,000 SF NR	A 0.23	0.00	0.00	0,00	0.00
Mos. Since Effective Dat		6	19	. 39	
Time Adjustmer	nt 0%	3%	10%	15%	
	- december 1				
Size Adjustment ( SI	-5%	0%	0%	-5%	
Location Ad	ij. 5%	5%	5%	5%	STREET .
Age / Condition Ad	ij. 10%	20%	10%	20%	
Land: Bldg. Rati	5%	10%	5%	5%	<del>vone</del>
Zoning Ac	j. 5%	5%	5%	5%	TYPHAGANATARA
Parkin	9 -3%	0%	0%	0%	amontonios.
NILA A JI: Duiz - JO					1
Net Adj. Price/Gros Office S		43%	35%	45%	
		4370	3376	40/6	Concluded Value/S
Adjusted Price/S	1				
Site Are	sa \$592	\$590	\$638	\$804	\$625 \$625/SF X 21,943 SF
Indicated Value/ S	. 1			:	\$13,714,375
Indicated Value/ S	1				
ROUNDE	וט	1			\$13,700,000

The subject property is a former church that had a complete renovation including seismic upgrade. It is now fully leased to an interior design firm. Sales One, Two and Four are also religious facilities and Sale Three is a former library. The subject property was significantly superior in age/condition due to the recent renovation. After adjustment the price per square feet range is \$592 to \$804/SF with \$625/SF considered to be supported by the sales comparables. The subject property is considered to be an investment property given it is fully leased on NNN basis with the tenant paying for expenses. The Income Capitalization Approach is typically the most applicable valuation approach for investment properties. Given the Restricted Capitalization Rate for Mills Act properties the Income Capitalization Approach for the subject property results in the lowest valuation.


# Comparable Improved Sales Adjustment Grid

APN:

3517-035

Address:

1401 Howard Street



**IMPROVED SALES MAP** 



# PRE-APPROVAL INSPECTION REPORT

Report Date:

May 24, 2019

Inspection Date:

May 22, 2019; 11:00am

Filing Date:

May 1, 2018

Case No.:

2019-006384MLS

Project Address:

1401 Howard Street

Block/Lot:

3517/035

Eligibility

Article 10 Landmark No. 120: Saint Joseph's Church

National Register listed property

Zoning:

RCD – Regional Commercial District

Height &Bulk:

40-X

Supervisor District: District 6 (Matt Haney)

Project Sponsor:

Christopher Foley of 1401 Howard LLC

Address:

1401 Howard Street

San Francisco, CA 94103

415-305-4600

cfoley@groundmatrix.com

Staff Contact:

Michelle Taylor - (415) 575-9197

michelle.taylor@sfgov.org

Reviewed By:

Tim Frye – (415) 575-6822

tim.frye@sfgov.org

#### PRE-INSPECTION

☑ Application fee paid

☑ Record of calls or e-mails to applicant to schedule pre-contract inspection

5/7/2019: Email applicant to schedule site visit.

5/14/2019: Email applicant to reschedule site visit.

1650 Mission St. Suite 400 San Francisco, CA 94103-2479

Reception: 415.558.6378

Fax:

415.558.6409

Planning Information: 415.558.6377

# Mills Act Pre-Approval Inspection Report May 24, 2019

Case Number: 2019-006384MLS 1401 Howard Street

# INSPECTION OVERVIEW

Date and	time of ins	spection: Wednesday, May 22, 2019, 11:00am
Parties pr	esent: Mic	helle Taylor, Shannon Ferguson, Chris Foley, Rick Feldman
☑ Provid	e applican	t with business cards
☑ Inform	applicant	of contract cancellation policy
☑ Inform	applicant	of monitoring process
Inspect p	roperty. If	multi-family or commercial building, inspection included a:
<u>-</u>	<b>I</b> Thorough	n sample of units/spaces
	<b>]</b> Represen	tative
	I Limited	
☑ Reviev	v any recer	atly completed and in progress work to confirm compliance with Contract.
☑ Reviev	v areas of p	proposed work to ensure compliance with Contract.
☑ Reviev	v proposed	maintenance work to ensure compliance with Contract.
	y and phot	tograph any existing, non-compliant features to be returned to original condition od. N/A
☑ Yes	□ No	Does the application and documentation accurately reflect the property's existing condition? If no, items/issues noted:
☑ Yes	П №	Does the proposed scope of work appear to meet the Secretary of the Interior's Standards? If no, items/issues noted: See below
☑ Yes	□ No	Does the property meet the exemption criteria, including architectural style, work of a master architect, important persons or danger of deterioration or demolition without rehabilitation? If no, items/issues noted:
☑ Yes	□ No	Conditions for approval? If yes, see below.

#### **NOTES**

1401 Howard Street (District 6) 1401 Howard Street is located on the south corner of Howard and 10th Streets, Assessor's Block 3517, Lots 39. The subject property is located within an RCD (Regional Commercial District) zoning district and a 55/65-X Height and Bulk district. The subject property is an Article 10 individual landmark No. 120 and added to the National Register of Historic Places in 1982. Formerly Saint Joseph's Church, the subject property is a former Catholic church constructed in 1913 and designed in the Romanesque Revival style by architect John J. Foley.

The subject property is currently valued by the Assessor's Office at over \$5,000,000; therefore, an exemption from the tax assessment value is required. The application includes a Historic Structure Report prepared by Page & Turnbull that provides evidence that the property meets the exemption criteria for tax assessment value.

At the preliminary inspection visit, the applicant was informed that some proposed scope items would not be considered qualifying scopes of work, such as maintenance of landscaping at the exterior and maintenance of the new concrete floor in the interior. The applicant was advised to include regular inspection and repairs of interior character defining features in the proposed maintenance plan.

In 2018, the applicant completed a full rehabilitation and restoration of the building and received Final approval for the Federal Historic Preservation Tax Incentive in September 2018. Work included the restoration of exterior and interior finishes, seismic strengthening, repair of the slate roof, restoration of the sheet metal domes, and addition of an accessibility ramp.


Future rehabilitation and restoration scope items include full repainting of the interior and exterior. The estimated cost of the proposed rehabilitation work is \$291,065.

The applicant has provided a revised maintenance plan which proposes to inspect and make any necessary repairs to the exterior stucco, metal roof elements, windows, doors, and roof on a regular basis. The applicant will be maintaining interior character defining features identified in the National Register nomination, such as the entry lobby floors, plaster detailing, and woodwork. The estimated cost of maintenance work is \$30,040 annually


# **PHOTOGRAPHS**




Front and side elevations of 1401 Howard Street



Primary interior volume facing northwest



Detail of restored decorative plaster elements



MILLS ACT APPLICATION
1401 HOWARD STREET
SAN FRANCISCO, CALIFORNIA

PREPARED FOR: 1401 HOWARD LLC PRIMARY PROJECT CONTACT: Ruth Todd Page & Turnbull, 170 Maiden Lane, 5th Floor San Francisco, CA 94108 415.593.3234/415.362.5560 fax ruthtodd@page-turnbull.com

#### TABLE OF CONTENTS

# I. APPLICATION FORMS REHABILITATION / RESTORATION & MAINTENANCE PLAN (CONTINUED/ ATTACHMENT)......14 REHABILITATION/ RESTORATION PLANS SUPPORTING DOCUMENTATION.......24 II. EXEMPTION STATEMENT AND SIGNIFICANCE EVALUATION ......29 III. HISTORIC STRUCTURE REPORT ......31 EXISTING CONDITIONS IMAGES PRIOR TO REHABILITATION/RESTORATION ......62 IV. 1401 HOWARD STREET ADDITIONAL PHOTOGRAPHY.......76 VLTAX BILL 90 VII. RENTAL INCOME INFORMATION......91

# MILLS ACT HISTORICAL PROPERTY CONTRACT Application Checklist:

Applicant should complete this checklist and submit along with the application to ensure that all necessary materials have been provided. Saying "No" to any of the following questions may nullify the timelines established in this application.

1	Mills Act Application	YES 🛚	№ □
	Has each property owner signed? Has each signature been notarized?		
2	High Property Value Exemption Form & Historic Structure Report	YES X	NO 🗌
	Required for Residential properties with an assessed value over \$3,000,000 and Commercial/Industrial properties with an assessed value over \$5,000,000. Have you included a copy of the Historic Structures Report completed by a qualified consultant?		N/A 🗌
3	Draft Mills Act Historical Property Contract	YES X	NO 🗌
***************************************	Are you using the Planning Department's standard "Historical Property Contract?" Have all owners signed and dated the contract? Have all signatures been notarized?	-	
4	Notary Acknowledgement Form	YES X	NO 🗌
	Is the Acknowledgement Form complete?  Do the signatures match the names and capacities of signers?		
5	Draft Rehabilitation/Restoration/Maintenance Plan	YES 🗵	NO 🗌
	Have you identified and completed the Rehabilitation, Restoration, and Maintenance Plan organized by contract year, including all supporting documentation related to the scopes of work?		
6	Photographic Documentation	YES 🛚	NO 🗌
	Have you provided both interior and exterior images (either digital, printed, or on a CD)? Are the images properly labeled?		
7	Site Plan	YES X	NO 🗌
	Does your site plan show all buildings on the property including lot boundary lines, street name(s), north arrow and dimensions?		-
8	Tax Bill	YĖS 🏻	№ 🗆
	Did you include a copy of your most recent tax bill?	***************************************	
9	Rental Income Information	YES X	ΝО □
	Did you include information regarding any rental income on the property, including anticipated annual expenses, such as utilities, garage, insurance, building maintenance, etc.?		,
10	Payment	YES X	№ 🗌
***************************************	Did you include a check payable to the San Francisco Planning Department?  Current application fees can be found on the Planning Department Fee Schedule under Preservation Applications.		
11	Recordation Requirements	YES 🗌	№ 🗌
	A Board of Supervisors approved and fully executed Mills Act Historical Property contract must be recorded with the Assessor-Recorder. The contract must be <a href="mailto:accompanied">accompanied</a> by the following in order to meet recording requirements:	٠	
	- All approvals, signatures, recordation attachments		
	<ul> <li>Fee: Check payable to the Office of the Assessor-Recorder" in the appropriate recording fee amount Please visit www.sfassessor.org for an up-to-date fee schedule for property contracts.</li> </ul>		
	Preliminary Change of Ownership Report (PCOR). Please visit www.sfassessor.org for an up-to-date     PCOR (see example on page 20)		

# APPLICATION FOR Mills Act Historical Property Contract

Applications must be submitted in both hard copy and digital copy form to the Planning Department at 1650 Mission St., Suite 400 by May 1st in order to comply with the timelines established in the Application Guide. Please submit only the Application and required documents.

Owner/Applicant Information (If more than three owners, att	ach additiona	l sheets as necessary.)			
PROPERTY OWNER 1 NAME:		TELEPHONE:			
1401 HOWARD LLC		(415) 640 - 0567			
PROPERTY OWNER 1 ADDRESS:	EMAIL:				
810 7TH STREET		sean@visitthemarket.com			
PROPERTY OWNER 2 NAME:		TELEPHONE:			
		( )			
PROPERTY OWNER 2 ADDRESS:		EMAIL:			
PROPERTY OWNER AND A		TELEDIONE			
PROPERTY OWNER 3 NAME:		TELEPHONE:			
PROPERTY ON THE A APPROPRIA		( )			
PROPERTY OWNER 3 ADDRESS:		EMAIL:			
2. Subject Property Information					
PROPERTY ADDRESS:			ZIP CODE:		
1401 HOWARD STREET		,	94103		
PROPERTY PURCHASE DATE:	PROPERTY PURCHASE DATE: ASSESSOR BLOCK/LOT(S):				
	3517 / 035	5			
MOST RECENT ASSESSED VALUE:	ZONING DISTRI	ICT:			
\$ 15,797,197	RCD				
Are taxes on all property owned within the City and County of	San Francis	sco paid to date?	YES X	NO 🗌	
Is the entire property owner-occupied?			YES 🗌	NO X	
If No, please provide an approximate square footage for own income (non-owner-occupied areas) on a separate sheet of processing the state of processing the state of processing the square footage for own income (non-owner-occupied areas) on a separate sheet of processing the state of processing		l areas vs. rental			
	<del>-</del>				
Do you own other property in the City and County of San Fra If Yes, please list the addresses for all other property owned	Incisco?	ity of Can	YES 🗌	NO X	
Francisco on a separate sheet of paper.	WILLIII LITE C	ity of Sair			
Are there any outstanding enforcement cases on the propert	v from the S	San Francisco	VEC 🗆	NO W	
Planning Department or the Department of Building Inspection		an i ranoisoo	YES 🗌	NO X	
If Yes, all outstanding enforcement cases must be abated an		eligibility for			
the Mills Act.					
L		***************************************			
I/we am/are the present owner(s) of the property described above					
contract. By signing below, I affirm that all information provided swear and affirm that false information will be subject to penalty				tner	
	and it vocat				
Owner Signature:	V=V,,	Date:			
Owner Signature:		Date:		-	
Owner Signature:	Date:				

Mills Act Application

# 3. Property Value Eligibility: Choose one of the following options: The property is a Residential Building valued at less than \$3,000,000. YES NO X The property is a Commercial/Industrial Building valued at less than \$5,000,000. YES NO X \*If the property value exceeds these options, please complete the following: Application of Exemption. Application for Exemption from Property Tax Valuation If answered "no" to either question above please explain on a separate sheet of paper, how the property meets the following two criteria and why it should be exempt from the property tax valuations. 1. The site, building, or object, or structure is a particularly significant resource and represents an exceptional example of an architectural style, the work of a master, or is associated with the lives of significant persons or events important to local or natural history; or 2. Granting the exemption will assist in the preservation of a site, building, or object, or structure that would otherwise be in danger of demolition, substantial alteration, or disrepair. (A Historic Structures Report, completed by a qualified historic preservation consultant, must be submitted in order to meet this requirement.) 4. Property Tax Bill All property owners are required to attach a copy of their recent property tax bill. PROPERTY OWNER NAMES: 1401 HOWARD LLC MOST RECENT ASSESSED PROPERTY VALUE: \$ 15,797,197 PROPERTY ADDRESS: 1401 HOWARD ST, SAN FRANCISCO, CA 5. Other Information All property owners are required to attach a copy of all other information as outlined in the checklist on page 7 of this application. By signing below, I/we acknowledge that I/we am/are the owner(s) of the structure referenced above and by applying for exemption from the limitations certify, under the penalty of perjury, that the information attached and provided is accurate. Owner Signature: Date:

Date:

Owner Signature:

Owner Signature:

5. Rehabilitation/Restoration & Maintenance Plan					
A 10 Year Rehabilitation/Restoration Plan has been submitted detailing work to be performed on the subject property	YES 🗵	NO 🗆			
A 10 Year Maintenance Plan has been submitted detailing work to be performed on the subject property	YES X	NO 🗌			
Proposed work will meet the Secretary of the Interior's Standards for the Treatment of Historic Properties and/or the California Historic Building Code.	YES 🗓	NO 🗌			
Property owner will ensure that a portion of the Mills Act tax savings will be used to finance the preservation, rehabilitation, and maintenance of the property	YES X	NO 🗌			
Use this form to outline your rehabilitation/restoration plan. Copy this page as necessary to include all items that apply to your property. Begin by listing recently completed rehabilitation work (if applicable) and continue with work you propose to complete within the next ten years, followed by your proposed maintenance work. Arranging all scopes of work in order of priority.					
Please note that all applicable Codes and Guidelines apply to all work, including the Planning Code an components of the proposed Plan require approvals by the Historic Preservation Commission, Pla Zoning Administrator, or any other government body, these approvals must be secured prior to Mills Act Historical Property Contract. This plan will be included along with any other supporting part of the Mills Act Historical Property contract.	anning Cor applying f	mmission, or a			
#(Provide a scope number) BUILDING FEATURE:					
Rehab/Restoration Maintenance Completed Proposed					
CONTRACT YEAR FOR WORK COMPLETION:					
TOTAL COST (rounded to nearest dollar):					
ALL OF THE RESTORATION/ REHABILITATION, AND MAINTENANCE WORK IS DESCRIPTION PAGES.	RIBED IN	ГНЕ			

#### 6. Draft Mills Act Historical Property Agreement

Please complete the following Draft Mills Act Historical Property Agreement and submit with your application. A final Mills Act Historical Property Agreement will be issued by the City Attorney once the Board of Supervisors approves the contract. The contract is not in effect until it is fully executed and recorded with the Office of the Assessor-Recorder.

Any modifications made to this standard City contract by the applicant or if an independently-prepared contract is used, it shall be subject to approval by the City Attorney prior to consideration by the Historic Preservation Commission and the Board of Supervisors. This will result in additional application processing time and the timeline provided in the application will be nullified.

Recording Requested by, and when recorded, send notice to: Director of Planning 1650 Mission Street San Francisco, California 94103-2414

### California Mills Act Historical Property Agreement

	Camorna	wills / tot i listorioari roperty	7 Igroofficht
	ST.	OSEPH'S ART SOCIETY	
	PROPE	RTY NAME (IF ANY)	
	140	1 HOWARD STREET	
	PROPE	RTY ADDRESS	
		San Francisco, California	
THIS AGREEMEN	IT is entered into by and bet	ween the City and County of San I	Francisco, a California municipal corporation
("City") and	1401 HOWARD LLC	("Owner/s").	
		RECITALS	
Owners are the ow	vners of the property located	I at1401 HOWARD STREET	in San Francisco California
3517	/ 035	. The building located at	1401 HOWARD STREET
BLOCK NUMBER	LOT NUMBER		PROPERTY ADDRESS
is designated as	SF CITY LANDMARK #120,	FODIO DI ACEC #02002250	(e.g. "a City Landmark pursuant to Artic
	NATIONAL REGISTER OF HIS Code") and is also known a		SEPHS CHURCH
		HISTORIC NAME OF	PROPERTY (IF ANY)
		ne Historic Property according to extend to the Historic Property according to extend the Housand of the Housan	ne Historic Property. Owners' application stablished preservation standards, which it (\$ 5,725,874). See Rehabilitation Plan,
	on calls for the maintenance will cost approximately ntenance Plan, Exhibit B.	of the Historic Property according SIX HUNDRED SEVENTY THOUSAND, NINE HUNDRED SIXTY FIVE AMOUNT IN WORD FORMAT	to established preservation standards,  (\$ 670,965  AMOUNT IN NUMERICAL FORMAT
Revenue & Taxatic property owners to properties. The Cit participate in the M	on Code, Article 1.9 [Section or potentially reduce their proby has adopted enabling leginals act program.	439 et seq.) authorizing local gover operty taxes in return for improver islation, San Francisco Administrat	e Sections 50280-50290, and California rnments to enter into agreements with ment to and maintenance of historic ive Code Chapter 71, authorizing it to
Owners desire to e	nter into a Mills Act Agreer	nent (also referred to as a "Historic	Property Agreement") with the City to help

NOW, THEREFORE, in consideration of the mutual obligations, covenants, and conditions contained herein, the parties hereto do agree as follows:

mitigate its anticipated expenditures to restore and maintain the Historic Property. The City is willing to enter into such Agreement to mitigate these expenditures and to induce Owners to restore and maintain the Historic Property in excellent

Mills Act Application

condition in the future.

#### 1. Application of Mills Act.

The benefits, privileges, restrictions and obligations provided for in the Mills Act shall be applied to the Historic Property during the time that this Agreement is in effect commencing from the date of recordation of this Agreement.

#### 2. Rehabilitation of the Historic Property.

Owners shall undertake and complete the work set forth in Exhibit A ("Rehabilitation Plan") attached hereto according to certain standards and requirements. Such standards and requirements shall include, but not be limited to: the Secretary of the Interior's Standards for the Treatment of Historic Properties ("Secretary's Standards"); the rules and regulations of the Office of Historic Preservation of the California Department of Parks and Recreation ("OHP Rules and Regulations"); the State Historical Building Code as determined applicable by the City; all applicable building safety standards; and the requirements of the Historic Preservation Commission, the Planning Commission, and the Board of Supervisors, including but not limited to any Certificates of Appropriateness approved under Planning Code Article 10. The Owners shall proceed diligently in applying for any necessary permits for the work and shall apply for such permits not less than six (6) months after recordation of this Agreement, shall commence the work within six (6) months of receipt of necessary permits, and shall complete the work within three (3) years from the date of receipt of permits. Upon written request by the Owners, the Zoning Administrator, at his or her discretion, may grant an extension of the time periods set forth in this paragraph. Owners may apply for an extension by a letter to the Zoning Administrator, and the Zoning Administrator may grant the extension by letter without a hearing. Work shall be deemed complete when the Director of Planning determines that the Historic Property has been rehabilitated in accordance with the standards set forth in this Paragraph. Failure to timely complete the work shall result in cancellation of this Agreement as set forth in Paragraphs 13 and 14 herein.

#### 3. Maintenance.

Owners shall maintain the Historic Property during the time this Agreement is in effect in accordance with the standards for maintenance set forth in Exhibit B ("Maintenance Plan"), the Secretary's Standards; the OHP Rules and Regulations; the State Historical Building Code as determined applicable by the City; all applicable building safety standards; and the requirements of the Historic Preservation Commission, the Planning Commission, and the Board of Supervisors, including but not limited to any Certificates of Appropriateness approved under Planning Code Article 10.

#### 4. Damage.

Should the Historic Property incur damage from any cause whatsoever, which damages fifty percent (50%) or less of the Historic Property, Owners shall replace and repair the damaged area(s) of the Historic Property. For repairs that do not require a permit, Owners shall commence the repair work within thirty (30) days of incurring the damage and shall diligently prosecute the repair to completion within a reasonable period of time, as determined by the City. Where specialized services are required due to the nature of the work and the historic character of the features damaged, "commence the repair work" within the meaning of this paragraph may include contracting for repair services. For repairs that require a permit(s), Owners shall proceed diligently in applying for any necessary permits for the work and shall apply for such permits not less than sixty (60) days after the damage has been incurred, commence the repair work within one hundred twenty (120) days of receipt of the required permit(s), and shall diligently prosecute the repair to completion within a reasonable period of time, as determined by the City. Upon written request by the Owners, the Zoning Administrator, at his or her discretion, may grant an extension of the time periods set forth in this paragraph. Owners may apply for an extension by a letter to the Zoning Administrator, and the Zoning Administrator may grant the extension by letter without a hearing. All repair work shall comply with the design and standards established for the Historic Property in Exhibits A and B attached hereto and Paragraph 3 herein. In the case of damage to twenty percent (20%) or more of the Historic Property due to a catastrophic event, such as an earthquake, or in the case of damage from any cause whatsoever that destroys more than fifty percent (50%) of the Historic Property, the City and Owners may mutually agree to terminate this Agreement. Upon such termination, Owners shall not be obligated to pay the cancellation fee set forth in Paragraph 14 of this Agreement. Upon such termination, the City shall assess the full value of the Historic Property without regard to any restriction imposed upon the Historic Property by this Agreement and Owners shall pay property taxes to the City based upon the valuation of the Historic Property as of the date of termination.

#### 5. Insurance.

Owners shall secure adequate property insurance to meet Owners' repair and replacement obligations under this Agreement and shall submit evidence of such insurance to the City upon request.

#### 6. Inspections.

Owners shall permit periodic examination of the exterior and interior of the Historic Property by representatives of the Historic Preservation Commission, the City's Assessor, the Department of Building Inspection, the Planning Department, the Office of Historic Preservation of the California Department of Parks and Recreation, and the State Board of Equalization, upon seventy-two (72) hours advance notice, to monitor Owners' compliance with the terms of this Agreement. Owners shall provide all reasonable information and documentation about the Historic Property demonstrating compliance with this Agreement as requested by any of the above-referenced representatives.

#### 7. Term.

This Agreement shall be effective upon the date of its recordation and shall be in effect for a term of ten years from such date ("Initial Term"). As provided in Government Code section 50282, one year shall be added automatically to the Initial Term, on each anniversary date of this Agreement, unless notice of nonrenewal is given as set forth in Paragraph 10 herein.

#### 8. Valuation.

Pursuant to Section 439.4 of the California Revenue and Taxation Code, as amended from time to time, this Agreement must have been signed, accepted and recorded on or before the lien date (January 1) for a fiscal year (the following July 1-June 30) for the Historic Property to be valued under the taxation provisions of the Mills Act for that fiscal year.

#### 9. Termination.

In the event Owners terminates this Agreement during the Initial Term, Owners shall pay the Cancellation Fee as set forth in Paragraph 15 herein. In addition, the City Assessor-Recorder shall determine the fair market value of the Historic Property without regard to any restriction imposed on the Historic Property by this Agreement and shall reassess the property taxes payable for the fair market value of the Historic Property as of the date of Termination without regard to any restrictions imposed on the Historic Property by this Agreement. Such reassessment of the property taxes for the Historic Property shall be effective and payable six (6) months from the date of Termination.

#### 10. Notice of Nonrenewal.

If in any year after the Initial Term of this Agreement has expired either the Owners or the City desires not to renew this Agreement that party shall serve written notice on the other party in advance of the annual renewal date. Unless the Owners serves written notice to the City at least ninety (90) days prior to the date of renewal or the City serves written notice to the Owners sixty (60) days prior to the date of renewal, one year shall be automatically added to the term of the Agreement. The Board of Supervisors shall make the City's determination that this Agreement shall not be renewed and shall send a notice of nonrenewal to the Owners. Upon receipt by the Owners of a notice of nonrenewal from the City, Owners may make a written protest. At any time prior to the renewal date, City may withdraw its notice of nonrenewal. If in any year after the expiration of the Initial Term of the Agreement, either party serves notice of nonrenewal of this Agreement, this Agreement shall remain in effect for the balance of the period remaining since the execution of the last renewal of the Agreement.

#### 11. Payment of Fees.

Within one month of the execution of this Agreement, City shall tender to Owners a written accounting of its reasonable costs related to the preparation and approval of the Agreement as provided for in Government Code Section 50281.1 and San Francisco Administrative Code Section 71.6. Owners shall promptly pay the requested amount within forty-five (45) days of receipt.

#### 12. Default.

An event of default under this Agreement may be any one of the following:

- (a) Owners' failure to timely complete the rehabilitation work set forth in Exhibit A in accordance with the standards set forth in Paragraph 2 herein;
- (b) Owners' failure to maintain the Historic Property in accordance with the requirements of Paragraph 3 herein;
- (c) Owners' failure to repair any damage to the Historic Property in a timely manner as provided in Paragraph 4 herein;
- (d) Owners' failure to allow any inspections as provided in Paragraph 6 herein;
- (e) Owners' termination of this Agreement during the Initial Term;
- (f) Owners' failure to pay any fees requested by the City as provided in Paragraph 11 herein;
- (g) Owners' failure to maintain adequate insurance for the replacement cost of the Historic Property; or
- (h) Owners' failure to comply with any other provision of this Agreement.

An event of default shall result in cancellation of this Agreement as set forth in Paragraphs 13 and 14 herein and payment of the cancellation fee and all property taxes due upon the Assessor's determination of the full value of the Historic Property as set forth in Paragraph 14 herein. In order to determine whether an event of default has occurred, the Board of Supervisors shall conduct a public hearing as set forth in Paragraph 13 herein prior to cancellation of this Agreement.

#### 13. Cancellation.

As provided for in Government Code Section 50284, City may initiate proceedings to cancel this Agreement if it makes a reasonable determination that Owners have breached any condition or covenant contained in this Agreement, has defaulted as provided in Paragraph 12 herein, or has allowed the Historic Property to deteriorate such that the safety and integrity of the Historic Property is threatened or it would no longer meet the standards for a Qualified Historic Property. In order to cancel this Agreement, City shall provide notice to the Owners and to the public and conduct a public hearing before the Board of Supervisors as provided for in Government Code Section 50285. The Board of Supervisors shall determine whether this Agreement should be cancelled. The cancellation must be provided to the Office of the Assessor-Recorder for recordation.

#### 14. Cancellation Fee.

If the City cancels this Agreement as set forth in Paragraph 13 above, Owners shall pay a cancellation fee of twelve and one-half percent (12.5%) of the fair market value of the Historic Property at the time of cancellation. The City Assessor shall determine fair market value of the Historic Property without regard to any restriction imposed on the Historic Property by this Agreement. The cancellation fee shall be paid to the City Tax Collector at such time and in such manner as the City shall prescribe. As of the date of cancellation, the Owners shall pay property taxes to the City without regard to any restriction imposed on the Historic Property by this Agreement and based upon the Assessor's determination of the fair market value of the Historic Property as of the date of cancellation.

#### 15. Enforcement of Agreement.

In lieu of the above provision to cancel the Agreement, the City may bring an action to specifically enforce or to enjoin any breach of any condition or covenant of this Agreement. Should the City determine that the Owners has breached this Agreement, the City shall give the Owners written notice by registered or certified mail setting forth the grounds for the breach. If the Owners do not correct the breach, or if it does not undertake and diligently pursue corrective action, to the reasonable satisfaction of the City within thirty (30) days from the date of receipt of the notice, then the City may, without further notice, initiate default procedures under this Agreement as set forth in Paragraph 13 and bring any action necessary to enforce the obligations of the Owners set forth in this Agreement. The City does not waive any claim of default by the Owners if it does not enforce or cancel this Agreement.

#### 16. Indemnification.

The Owners shall indemnify, defend, and hold harmless the City and all of its boards, commissions, departments, agencies, agents and employees (individually and collectively, the "City") from and against any and all liabilities, losses, costs, claims, judgments, settlements, damages, liens, fines, penalties and expenses incurred in connection with or arising in whole or in part from: (a) any accident, injury to or death of a person, loss of or damage to property occurring in or about the Historic Property; (b) the use or occupancy of the Historic Property by the Owners, their Agents or Invitees; (c) the condition of the Historic Property; (d) any construction or other work undertaken by Owners on the Historic Property; or (e) any claims by unit or interval Owners for property tax reductions in excess those provided for under this Agreement. This indemnification shall include, without limitation, reasonable fees for attorneys, consultants, and experts and related costs that may be incurred by the City and all indemnified parties specified in this Paragraph and the City's cost of investigating any claim. In addition to Owners' obligation to indemnify City, Owners specifically acknowledge and agree that they have an immediate and independent obligation to defend City from any claim that actually or potentially falls within this indemnification provision, even if the allegations are or may be groundless, false, or fraudulent, which obligation arises at the time such claim is tendered to Owners by City, and continues at all times thereafter. The Owners' obligations under this Paragraph shall survive termination of this Agreement.

#### 17. Eminent Domain.

In the event that a public agency acquires the Historic Property in whole or part by eminent domain or other similar action, this Agreement shall be cancelled and no cancellation fee imposed as provided by Government Code Section 50288.

#### 18. Binding on Successors and Assigns.

The covenants, benefits, restrictions, and obligations contained in this Agreement shall be deemed to run with the land and shall be binding upon and inure to the benefit of all successors and assigns in interest of the Owners.

#### 19. Legal Fees.

In the event that either the City or the Owners fail to perform any of their obligations under this Agreement or in the event a dispute arises concerning the meaning or interpretation of any provision of this Agreement, the prevailing party may recover all costs and expenses incurred in enforcing or establishing its rights hereunder, including reasonable attorneys' fees, in addition to court costs and any other relief ordered by a court of competent jurisdiction. Reasonable attorneys fees of the City's Office of the City Attorney shall be based on the fees regularly charged by private attorneys with the equivalent number of years of experience who practice in the City of San Francisco in law firms with approximately the same number of attorneys as employed by the Office of the City Attorney.

#### 20. Governing Law.

This Agreement shall be construed and enforced in accordance with the laws of the State of California.

#### 21. Recordation.

The contract will not be considered final until this agreement has been recorded with the Office of the Assessor-Recorder of the City and County of San Francisco.

#### 22. Amendments.

This Agreement may be amended in whole or in part only by a written recorded instrument executed by the parties hereto in the same manner as this Agreement.

#### 23. No Implied Waiver.

No failure by the City to insist on the strict performance of any obligation of the Owners under this Agreement or to exercise any right, power, or remedy arising out of a breach hereof shall constitute a waiver of such breach or of the City's right to demand strict compliance with any terms of this Agreement.

#### 24. Authority.

If the Owners sign as a corporation or a partnership, each of the persons executing this Agreement on behalf of the Owners does hereby covenant and warrant that such entity is a duly authorized and existing entity, that such entity has and is qualified to do business in California, that the Owner has full right and authority to enter into this Agreement, and that each and all of the persons signing on behalf of the Owners are authorized to do so.

#### 25. Severability.

If any provision of this Agreement is determined to be invalid or unenforceable, the remainder of this Agreement shall not be affected thereby, and each other provision of this Agreement shall be valid and enforceable to the fullest extent permitted by law.

#### 26. Tropical Hardwood Ban.

The City urges companies not to import, purchase, obtain or use for any purpose, any tropical hardwood or tropical hardwood product.

#### 27. Charter Provisions.

This Agreement is governed by and subject to the provisions of the Charter of the City.

# 28. Signatures.

This Agreement may be signed and dated in parts

IN WITNESS WHEREOF, the parties hereto have executed this Agreement as follows:

CARMEN CHU ASSESSOR-RECORDER CITY & COUNTY OF SAN FRANCISCO	Date	JOHN RAHAIM DIRECTOR OF PLANNING CITY & COUNTY OF SAN FRANCISCO	Date
APPROVED AS PER FORM: DENNIS HERRERA	anno mora	Signature	 Date
CITY ATTORNEY CITY & COUNTY OF SAN FRANCISCO		Print name DEPUTY CITY ATTORNEY	
Signature	Date	Signature	Date
Print name OWNER		Print name OWNER	

Owner/s' signatures must be notarized. Attach notary forms to the end of this agreement. (If more than one owner, add additional signature lines. All owners must sign this agreement.)

### 7. Notary Acknowledgment Form

The notarized signature of the majority representative owner or owners, as established by deed or contract, of the subject property or properties is required for the filing of this application. (Additional sheets may be attached.)

State of California				
County of:				-
On:	before me,	SERT NAME OF THE OF	FICER	;
NOTARY PUBLIC personally	appeared:			
	NAME(S) OF SIGNER(S)			
the within instrument and acl	knowledged to me that he/s /her/their signature(s) on th	she/they execute	n(s) who name(s) is/are subscrib d the same in his/her/their author e person(s), or the entity upon be	orized
I certify under PENALTY OF I true and correct.	PERJURY under the laws o	f the State of Cali	ifornia that the foregoing paragra	aph is
WITNESS my hand and offic	ial seal.		·	
· · · · · · · · · · · · · · · · · · ·				
SIGNATURE		· · · · · · · · · · · · · · · · · · ·		
			( PLACE NOTARY SEAL ABOVE )	

# REHABILITATION / RESTORATION & MAINTENANCE PLAN (CONTINUED/ ATTACHMENT)

Exhibit A. Rehabilitation/Restoration Plan

Scope: #1				
Building Feature: Exte	erior	Gates, Curbs, Fence, P	iers, Granite Steps	
Rehab/Restoration	X	Maintenance	Completed X	Proposed
Contract year work co	ompl	etion: 2018		
Total Cost: \$25,000.0	0 Sc	ource SOV #2920		

Description of work: Restoration and Repair of Exterior Gates, Curbs, Fences, Piers and Granite Steps

- The direction of the swing of all gates was reversed in the direction of egress. The gates were prepared, primed, and painted, and latch and lock sets were provided. At the two existing double gateways, the existing gates were reinstalled on new freestanding supports similar to the existing. The original hinges were retained at the original piers. The displaced sections of the piers were reset in the original locations and grouted. The cement plaster parge was repaired as required to match the original.
- The iron fence was prepared, primed, and painted. The gaps and voids were filled with mortar at the base and pier attachments. Where the fence is set into the curb and is corroded, the metal was repaired, painted, and set into lead or sealant as required to prevent future damage to the fence or curb.
- The cement plaster parge on the piers was cleaned and graffiti was removed or painted over. The cement plaster parge was repaired to match the existing adjacent color and texture as required.
- Existing joints were raked out and the granite steps were cleared of debris. Joints were repaired with mortar. Algae, moss, and other biological growth was removed. Soil and paint spatters were removed. New code-required bronze handrails were installed.

Scope: #2				
Building Feature: Exterior Pa	int and Stucco Rep	oair		
Rehab/Restoration X	Maintenance	Completed	X	Proposed
Contract year work completion	n: 2018 Phase 1,	Phase 2 scheduled f	or 2026	3
Total Cost: \$146,950. Source	e SOV #9900 (half	f), \$293850/2=\$146,	950.	

- Description of work: Façade Restoration and Full Repainting
  - The existing stucco was analyzed to determine if it was lime or Portland cement-based. These tests were performed by an architectural conservator.
  - Staining and soiling was removed by the gentlest means possible, this included light brushing and water washing, and cleaning with a commercial agent.
  - Areas of significant hairline cracking were repaired based on analysis to determine the root cause of the condition. Investigation included testing for underlying detachment of the stucco layer, moisture intrusion, structural movement, or other causes.
  - Climbing vegetation such as ivy was removed.
  - Spalls and cracks through cement plaster were repaired. The cracks were routed and patched to match the existing adjacent texture, profile, and appearance.
  - The existing deteriorated or detached cement plaster was removed. Graffiti and stains were removed.
  - Unsound paint was removed and coated with a new breathable paint coating.

Scope: #3			
Building Feature: Exterio		s, including domes on to	owers, column capitals,
decorative moldings, gutt	ers and down spouts.		
Rehab/Restoration X	Maintenance	Completed X	Proposed
Contract year work comp	letion: 2018		
Total Cost: \$424,323. So	urce SOV #7600 = \$434	,323	

Description of work: Repair and Restoration of Exterior Sheet Metal Elements

- Peeling or blistering paint was scraped or sanded.
- Corrosion was removed with hand scrapers or a wire brush.
- For panels with heavy corrosion and resulting perforation of the sheet metal unit, there were three options, dependent on severity and size:
  - 1. Corroded panels were removed and the unit was replaced with a new piece of sheet metal cut to the appropriate dimension and profile,
  - 2. The corroded area was cut out of existing sheet metal, a new piece was brazewelded and the joint was ground flat; or
  - 3. The corroded area was cut out of existing sheet metal and steel-filled epoxy compound was installed to patch small holes.
- All exposed metal was painted with a rust-inhibiting primer and two coats of color-appropriate outdoor paint.
- Missing elements were replaced to maintain visual consistency.

Scope: #4				
Building Feature: Ext	erior_'	Wood-sash Window	s and Steel Tracery	
Rehab/Restoration	X	Maintenance	Completed X	Proposed
Contract year work c	ompleti	on: 2018		
Total Cost: \$366,443	. Sourc	e SOV #6150 and #	8050 for \$96,867 and \$	269,576 = 366,443
Description of Work:	Repair.	Restoration and Re	placement of Windows	

- A detailed conditions assessment of windows at St. Joseph's Church was conducted to determine the extent of deterioration and appropriate treatments at each window. This included careful inspection and documentation of each window frame and its conditions, and other non-invasive diagnostic tests.
- Repair of the window frames attempted to retain as much original material as possible, while providing adequate moisture protection for the building, and included paint removal, splicing of new wood elements in areas of severe deterioration, and replacement of all glazing compound.
- The wood frames were prepared and painted, all the existing ribbed glass that could be preserved was reused. Ribbed glass that matched the original was installed in selected locations.

Scope: # 5 Building Feature: Exterior	Stained Class Wind			
Rehab/Restoration X	Maintenance	Completed X	Proposed	<u> </u>
Contract year work comple	etion: 2018			
Total Cost: \$81,260,00 So	urce SOV #8070			

Description of work: Repair and Restoration of Stained Glass Windows

- Documentation and restoration of the windows was performed by a professional conservator. Restoration included removal, transport, restoration, and reinstallation of the stained glass.
- The wood and steel armatures remaining from the previous stained glass window installation were prepared and painted.
- The remaining stained glass in the south wall of the kitchen was removed, salvaged, and reinstalled in the office on the first floor.

Scope: #6			The second secon	
Building Feature: Ext	erior S	Skylight		
Rehab/Restoration	X	Maintenance	Completed X	Proposed
Contract year work co	omple	tion: 2018		
Total Cost: \$39,010.0	00 <b>S</b> ou	urce SOV #8080		
Description of work: f	Repair	and Restoration of Ex	terior Skylight	
<ul><li>The steel sky</li></ul>	light r	emained in place and v	was repaired and clean	ed.
<ul> <li>New tempered</li> </ul>	ed glaz	zing and sealant was ir	istalled, and all work ar	nd flashing details were
coordinated v	with th	e roof strengthening ar	nd re-roofing work.	

Scope: #7				
Building Feature: Inte	rior St	ructural Steel for Seisi	nic	
Rehab/Restoration	X	Maintenance	Completed X	Proposed
Contract year work co	omplet	on: 2018		·
Total Cost: \$571,841	Sourc	e SOV 8 items #5050	), 5070 and 5120	
Description of work: S	Seismi	Strengthening		
<ul> <li>Steel was fab</li> </ul>	oricated	d and installed for seis	mic strengthening.	

Scope: #8			
Building Feature: Interior D	ecorative Plaster		
Rehab/Restoration X	Maintenance	Completed X	Proposed
Contract year work complet	ion: 2018		
Total Cost: \$1,350,577.00 \$	Source SOV #9050 , \$	1,350,577	
Description of work: Repair	and Restoration of Int	erior Decorative Plaster	
<ul> <li>Detached or cracket</li> </ul>	ed plaster elements we	re repaired, if in otherwi	ise sound condition, with
an injected epoxy of	r gypsum-based grout	. Testing was conducted	d to determine the most
effective adhesive.		-	

restored and painted. Further testing of the plaster was conducted to determine the extent of deterioration. This determined the treatment method: patching and reshaping damaged elements when

Non-historic wood veneer was removed so that plaster at the base of the wall could be

possible, or replacement in kind.

Scope: #9 Building Feature: Inter	ior Woodwork, Doors and	Finish Hardware	
Rehab/Restoration	X Maintenance	Completed X	Proposed
Contract year work con	mpletion: 2018	·	
Total Cost: \$269,000.0	O Source SOV #8200	The state of the s	

Description of work: Repair and Restoration of Interior Woodwork, Doors and Finish Hardware

- Soiling was cleaned with the gentlest means possible, using a soft bristle brush to remove loose dust and a damp cloth for tenacious soiling.
- Blistered varnish was treated with the gentlest means possible in order to preserve the existing finish. Treatments included lightly scraping blistered areas of varnish and spottreating with fine steel wool or cotton, alcohol and a compatible varnish or shellac.
- White stains were tested to determine the cause Paint and guano were removed mechanically with a scraper so as not to damage the existing wood finish.
- Where required by the level of damage, select areas of woodwork were refinished to match the original.

- Wood was replaced where missing to match the original.
- At exterior doors, deteriorated wood was repaired with wood Dutchman and matched the original species, grade, grain, and profile. The exterior surface was prepped and painted. The interior was cleaned and touched up or refinished to match the original stain or clear
- Door hardware was replaced or repaired to match existing and to meet current code.

Scope: #10			
Building Feature: Interior	Marble Wainscoting and	Tiles	
Rehab/Restoration X	Maintenance	Completed X	Proposed
Contract year work comp	letion: 2018		
Total Cost: \$5,000.00 So	urce From KFI (3/28/19	email)	
Description of work: Rest	oration of Interior Marble		77

- Tape residue and soiling was removed with a gentle stone cleaner. Mock-ups were conducted to determine the most effective product.
- Vinyl tiles and mastic were removed in the vestibule without causing damage to underlying marble, which was cleaned with a gentle stone cleaner to remove staining and adhesive. Mockups were conducted to determine the most effective product.
- Vinyl tiles and mastic were removed from the vestibule floor and cleaned using the gentlest means possible.
- The marble floors were polished to restore luster

Scope: #11				ation (13) in	
Building Feature: Inte	erior N	ave Floor Concrete			
Rehab/Restoration	The state of the s	Maintenance	Completed	X	Proposed
Contract year work c	omplet	ion: 2018			
Total Cost: \$207,357	Source	ce (4 items) SOV #205	0, #2250, #2300	and K	(FI, \$30,000 \$7,500
\$79,847 \$45,410 ar	id \$44	,600			
Description of work:					
<ul><li>The existing</li></ul>	(non h	istoric) slab was remov	/ed		
<ul> <li>Soil was exc</li> </ul>	avated	and the surrounding s	oil was underpinn	ed.	
<ul> <li>New foundat</li> </ul>	ions, v	ith piers and grade be	ams were installe	d	
<ul> <li>New stage or</li> </ul>	ver the	e grade beams was ins	talled in the apse.		

Scope: #12			
Building Feature: Interior To	ower Floor Concrete		
Rehab/Restoration X	Maintenance	Completed X	Proposed
Contract year work complet	ion: 2018		
Total Cost: \$573,000.00 Sc	urce SOV #2450 and	#2460 and KFI	
Description of work:			
<ul> <li>The concrete slope</li> </ul>	d floor was replaced w	rith a new flat structural	l concrete slab.
<ul> <li>New micropile foun</li> </ul>	dations were installed	in the towers.	
The top 10 feet of t	he micro piles were ca	sed in concrete.	
	and in apparata and as		

Scope: #13			
Building Feature: Exterior I	_ighting		
Rehab/Restoration X	Maintenance	Completed X	Proposed
Contract year work comple	tion: 2018		

# Total Cost: \$92,625.00 Source SOV #16080

#### Description of work:

- The missing original fixtures on the main entry façade were replicated based on historic documentation.
- Building façade lighting was replaced with LED fixtures to save energy.

# Scope: # 14 Building Feature: Interior Lighting Rehab/Restoration X Maintenance Completed X Proposed Contract year work completion: 2018 Total Cost: \$135,281.00 Source SOV #16070 Description of work: Repair, Restoration and Replacement in kind of historic light fixtures: The historic light fixtures were cleaned and relamped.

The missing fixtures in the main sanctuary were replicated.

Scope: # 15 Building Feature: Ro	of / Bui	ilt-up Roof			
Rehab/Restoration		Maintenance	Completed X		Proposed
Contract year work	complet	ion: 2018			
Total Cost. \$28,110.	00 <b>So</b> u	rce SOV #7500			
Description of work:					
<ul><li>Existing buil</li></ul>	t-up roc	ofing was removed at t	ne lower roofs.		
<ul> <li>New built-up</li> </ul>	roofing	g was installed over ne	w structural decking	g.	

Scope: #16 Building Feature: Roof / S	Slate Roof		
Rehab/Restoration X	Maintenance	Completed X	Proposed
Contract year work comp	letion: 2018		
Total Cost: \$258,950.00	Source SOV #7300		
<u> </u>		· · · · · · · · · · · · · · · · · · ·	

# Description of work:

- Existing slate roof tile was removed at the main roof and portals, salvaged, and reinstalled to allow access for structural stabilization of the roof structure.
- Deteriorated and broken tiles were replaced with salvaged stock or new tile to match the existing.
- New felt underlayment and galvanized flashing was installed.

Scope: # 17		Painting			enter i de la compania del compania del compania de la compania del la compania de la compania del la compania de la compania de la compania del la compania de la compania del la compania
Rehab/Restoration		Maintenance	Completed [	<u>X</u> ]	Proposed
Contract year work c	omp	letion: 2018 Phase 1, Ph	nase 2 scheduled fo	or 20	)26
Total Cost: \$146,950	.00	Source SOV #9900 (hal	lf), \$293850/2=\$146	6,95	0
Description of work:					

- Tested bottom layer of paint to find original colors.
- Interior plaster was painted, interior wood was refinished, and window mullions were repainted.
- Lead paint was abated.

# Exhibit B Maintenance Plan

Scope: #1	The Art String Local String Local	200				
Building Feature: Site_ l	_andscape					X
Rehab/Restoration	Maintenance	X	Completed	Proposed	X	
Contract year work com	pletion: 2028 and ev	ery	10 years thereafter			
Total Cost: \$120,000.00	(\$1,000/month x 12	mo	x 10 yrs)			
Description of work: Wa	shing of sidewalks a	nd g	granite entry steps. Gran	ite steps will be	e clea	aned
using the gentlest mean	s possible as recomi	mer	ided in NPS Preservatio	n Brief No. 1: A	sses	ssing
Cleaning and Water-Rep	pellent Treatments for	or H	istoric Masonry Building	s. All work will b	ое ре	erformed
in conformance with the	Secretary of the Inte	erior	Standards.			

Scope: #2				
Building Feature: Exterio	r_Stucco			
Rehab/Restoration	Maintenance	X	Completed	Proposed X
Contract year work comp	letion: 2019 and ar	ınua	lly thereafter	
Total Cost: \$40,000 (mai	ntenance of 4,000/	yr x1	0yrs)	
Description of work: Reg	ular repainting of ex	cterio	or stucco as needed to	address graffiti. Perform
visual inspection annually	y for signs of blister	ing o	or peeling paint.	

Scope: #3				2-14-5-16	
Building Feature: Roof					Parameter and the second
Rehab/Restoration	Maintenance	X	Completed	Proposed	X .
Contract year work com	pletion: 2019 and a	nnuall	y thereafter		
Total Cost: \$30,000.00	(maintenance of \$3	,000 >	(10yrs)		
Description of work: Insp					
and repair caulking and		ns, ov	erflow drains and scup	opers. Remove b	irds nests
and discourage roosting	•				

Scope: #4		Bangai (C.)	And Street Street		
Building Feature: Exterior decorative moldings , gu			cluding domes on to	wers, column c	apitals,
Rehab/Restoration	Maintenance	X	Completed	Proposed	X
Contract year work com	pletion: 2019 and a	nnually t	hereafter		
Total Cost: \$12,000.00 (	(\$1200 per year)				
Description of work: Per	form visual inspecti	on annu	ally for rust, holes ar	nd signs of wate	er where it
shouldn't be. Clean gutte	ers, replace screens	s, check	down spouts and cle	ean drains. Rep	pair damaged
pieces to match existing	using appropriate r	naterials	and methods. All re	pairs will be pe	erformed in
conformance with the Se	ecretary of the Inter	ior Stand	dards.		

Scope: #5				
Building Feature: Exterior	or Wood-sash Windows and	Steel Tracery.		
Rehab/Restoration	Maintenance X	Completed	Proposed	X
Contract year work com	oletion: 2019 and annually t	thereafter.		
Total Cost: \$10,000.00 (	\$1000 per year)			
Description of work: Per	form visual inspection annu	ally for signs of caulk	ing failure, chec	k operable
windows, window locks	and replace any cracked or	broken glass in kind.	All window repa	airs will be
performed in accordance	with the Secretary of the I	nterior Standards	·	

Scope: #6			
Building Feature: Exterio	or Skylight		
Rehab/Restoration	Maintenance X	Completed	Proposed X
Contract year work com	oletion: 2019 and annually	thereafter	
Total Cost: \$5,000.00 (\$	500 per year)	4	
Description of work: Per	form visual inspection annu	ually for signs of caull	king failure, condensation
problems that might com	promise structure of skylig	ht and replace any c	racked or broken glass in
kind. All repairs will be p	erformed in conformance v	vith the Secretary of t	the Interior Standards.

Building Feature: Exterior Rehab/Restoration	Maintenance	X	Completed	Proposed	X
Contract year work comp	oletion: 2019 and an	nually t	hereafter		-
Total Cost: \$16,000.00 (	\$1600 per year)				
Description of work: Insp matches original glass in All work will be performe accordance with NPS Pr and Leaded Glass	color and texture. I d in conformance w	nspect a ith the S	and repair lead came Secretary of the Inter	es. ior's Standards	s and in

Scope: #8				
Building Feature: Exterior	or Wood Doors			
Rehab/Restoration	Maintenance	<u>X</u>	Completed	Proposed X
Contract year work com	pletion: 2019 and an	nually	thereafter	
Total Cost: \$7,900.00 (\$	790 per year)			
Description of work: The	face of the wood do	ors ha	ve extreme exposure	e to rain and sun. They
suffered significant dete	rioration in the past.	They n	eed regular cleaning	and regular refinishing. All
work will be performed in	n conformance with	the Sed	cretary of the Interior	's Standards

Scope: #9						
Building Feature: Interior	Decorative Plaster					
Rehab/Restoration	Maintenance	X	Completed	Proposed	X	
Contract year work comp	oletion: 2019 and ev	ery 10	0 years thereafter			
Total Cost: \$20,000.00 (	\$2000 per year)					
Description of work: The	existing plaster was	s prev	iously damaged when	water got into	the attic and	1
behind the decorative pla	aster ceiling. Proble	ms or	the surface appeared	d only after cons	siderable	
damage was done inside	the concealed spa	ces, t	herefore there will be	visual inspectio	ns annually	
must look inside the attic	for signs of water of	lamaç	ge and make needed r	epairs.		
All work will be performe	d in conformance w	ith the	e Secretary of the Inte	rior's Standards	and in	
accordance with NPS Pr	eservation Brief No.	23: F	Preserving Historic Orr	namental Plaste	er.	

Scope: #10				
Building Feature: Interio	or Woodwork			
Rehab/Restoration	Maintenance X	Completed	Proposed X	
Contract year work com	pletion: 2019 and annually	thereafter		
Total Cost: \$16,000.00	(\$1600 per year)			
Description of work: Per	form visual inspection annu	ually for damage and	repair in the gentlest n	neans
possible. All work will be	e performed in conformance	with the Secretary of	f the Interior's Standar	ds

Scope: # 11 Building Feature: Bell To	ower			
Rehab/Restoration	Maintenance	X	Completed	Proposed X
Contract year work com	pletion: 2019 and an	nually	thereafter	
Total Cost: \$18,500.00	\$1850 per year)			
Description of work: Ann ladders and go into the louvers.				mechanism. Climb the gaps in the screens and

Scope: # 12					
Building Feature: Site D	rainage				
Rehab/Restoration	Maintenance	X	Completed	Proposed	Χ
Contract year work com	pletion: 2019 and ar	nually t	hereafter		
Total Cost: \$11,500 (\$1	,500 per year)				
Description of work: Ins	pect drywells in gard	en area	is and verify site dra	nage is functio	ning to
remove standing water.	Repair if needed if v	vater is	not being completely	/ absorbed as i	ntended.

Scope: # 13					
Building Feature: Interior	plaster				
Rehab/Restoration	Maintenance	<u>X</u>	. Completed	Proposed	Χ
Contract year work comp	letion: 2023 and bi-	annua	Illy thereafter		
Total Cost: \$80,000					
Description of work; Representation performed in conformance					
NPS Preservation Brief N	lo. 23: Preserving I	- Historio	Ornamental Plaster	and No. 21: Re	pairing
Historic Flat Plaster Walls	s and Ceilings				<del>.</del>

Scope: # 14		THE VE			
Building Feature: Interio	r Marble Floors				
Rehab/Restoration	Maintenance	<u>X</u>	Completed	Proposed	Χ
Contract year work com	pletion: 2022 and ar	nually	thereafter		
Total Cost: \$8,000				-	
Description of work: Cle	an and reseal marbl	e floors	s and wainscot. All m	arble will be cle	aned using
the gentlest means poss	sible as recommende	ed in N	PS Preservation Brie	ef No. 1: Assess	ing Cleaning
and Water-Repellent Tre	eatments for Historic	Maso	nry Buildings		-

Rehab/Restoration	Maintenance	X	and wood paneling  Completed	Proposed	Χ
Contract year work com	pletion: 2022 and ar	nually th	nereafter		
Total Cost: \$12,000					

PAGE

1 OF 6 PAGES

# REHAI 000

TO OWNE	R: 1401 Howard, LLC.		PROJECT: 1401	Howard Street et, San Francisco, CA	APPLICATION NO: PERIOD TO:	22 1/31/2018
	NTRACTOR: Palisade Builde ascom Ave. #2400, Campbell,	•	140 t Howard Sire	iat, dan Handisto, da	CONTRACT DATE: PROJECT MANAGEI	
CONTR	RACTOR'S APPLICAT	FION FOR P	AYMENT	overnos Concestivos de Control de Indication de Concestion de Concestion de Control de Control de Control de C		Allyfolia (MA died af Adeil (Mag Har policianismo) - month of Grand (Mala Makelan Jaryan area monared
CHANGE	ORDER SUMMARY			Application is made for Paymen	t, as shown below, in connecti	ion with the Contract.
1	ges approved months By Owner Totals	ADDITIONS 2,001,881.73	DEDUCTIONS	1. ORIGINAL CONTRACT SUM 2. NET CHANGES BY CHANGI		\$ <u>11,111,908.00</u> \$ 2,001,881.73
Total appro	oved this Month  Approval Date	2,00 (,001.70		3. CONTRACT SUM TO DATE 4. TOTAL COMPLETED & STO	(Line 1 + 2)	\$ 13,113,789.73 \$ 12,825,585.66
	другочаг оасс			<ul><li>5. RETAÍNAGE:</li><li>6. TOTAL EARNED LESS RET</li><li>7. LESS PREVIOUS CERTIFIC</li></ul>	AINAGE	\$ 958,053,01 \$ 11,867,532.65 \$ 11,553,903.06
NET CHAI	NGES by Change Order	0.00	0:00	<ol> <li>CURRENT PAYMENT DUE</li> <li>BALANCE TO FINISH, INCL</li> </ol>	UDING RETAINAGE	\$ 313,629,59 \$ 1,246,257.08
previous Ce	unts have been paid by the Contr rilificates of Payment were issued and that the current payment sho CTOR:	I and payments rec	eived from			
By:		Date	•			
	R'S CERTIFICATE FO		•	AMOUNT CERTIFIED (Attach explanation if amount certific Owner: 1401 Howard, LLC		\$
data compri of his/her kr the quality of	sing the above application, the Ar	rchitect certifies to t the Work has progr the Contract Docun	he Owner to the best ressed as indicated,	Ву:		Date:
CONHECTOR	о вываеся to раушеня от те AIMO!	ONT OUNTHED.		Architect: Page & Turnball		
				Ву:		Date:

HARD COST APPLICATION AND CERTIFICATE FOR PAYMENT

APPLICATION AND CERTIFICATION FOR PAYMENT, CONTAINING CONTRACTOR'S SIGNED CERTIFICATION IS ATTACHED IN TABULATIONS BELOW, AMOUNTS ARE STATED TO THE NEAREST DOLLAR.

APPLICATION NO : APPLICATION DATE: 1/31/2018

PERIOD FROM :

1/1/2018 1/31/2018

PERIOD TO : JOB#:

1600

CONTRACT DATE:

JOB #1600 - 1401 Howard Street, 5	San Francisco.	CA
-----------------------------------	----------------	----

A	В		С		]				D	L	E	F	L	G	1		Н		1
					Change				Work Com	ple	ted	Materials		Total	%	Ī			
ITEM	Description of work		Scheduled		Orders		New		Previous		This	Presently		Completed	Complete		Balance to	F	Retainage
NO.			Value		То		Scheduled		Applications	ŀ	Period	Stored		and Stored			Finish		al 10%
					Date		Value			1	Nork In Place	(Not in D or	İ	to Date	Advantage of the Control of the Cont				
				(Th	ru PCCO#11)				(D + E)	L	(F-D)	E)	l	(D + E + F)	(G/C)	l	(C-G)		
1290	Weather Protection	\$	25,000.00			\$	25,000.00	\$	24,231.49	Π			\$	24,231.49	97%	\$	768.51	\$	2,423.15
1390	Hoisting/Equipment Rentals	\$	110,000.00	\$	(3,544.02)	\$	106,455.98	\$	100,000.00	\$	6,455.98		\$	106,455,98	100%	\$	-	\$	10,645.60
1800	General Conditions/Supervision	\$	800,000.00	\$	343,000.00	\$	1,143,000.00	\$	1,050,000.00	\$	73,321.77		\$	1,123,321.77	98%	\$	19,678.23	\$	-
2050	Demo Existing Concrete SOG	\$	37,500.00	\$	(7,500.00)	\$	30,000.00	\$	30,000.00	\$	-		\$	30,000.00	100%	\$	-	\$	
2070	Selective Demolition	\$	125,000.00	\$	92,298.53	\$	217,298.53	53	217,298.53	\$	-		\$	217,298,53	100%	\$	-	\$	15,479.85
2080	Core Drilling	\$	7,500.00			\$	7,500.00	\$	7,500.00				\$	7,500.00	100%	\$	-	\$	750.00
2250	Underpinning pits/misc.	\$	-	\$	79,847.59	\$	79,847.59	\$	79,847.59				\$	79,847.59	100%	\$	-	\$	(0.00)
2300	Spoils Removal	\$	13,280.00	\$	32,130.00	\$	45.410.00	\$	45,410.00	\$	-		\$	45,410.00	100%	\$	-	\$	4,541.00
2310	Excavation	\$	25,000.00	\$	5,906.00	\$	30,906.00	\$	30,906,00	\$	-		\$	30,906.00	100%	\$	-	\$	3,090.60
2450	Micropiles	\$	328,000.00			S	328,000.00	\$	328,000.00	\$	-		\$	328,000.00	100%	\$		\$	-
2460	Casing Upper 10' of each Micropile	\$	36,000.00	\$	24,000.00	\$	60,000.00	\$	60,000.00				S	60,000.00	100%	\$	-	\$	-
2510	Domestic Water Underground	\$	24,100.00	\$	(24,100.00)	\$		_					\$	-	100%	\$	-	\$	-
2520	Sanitary Sewer & SD	\$	143,440.00	\$	(36,000.00)	\$	107,440.00	ÇŞ.	107,440.00	\$	~		\$	107,440.00	100%	\$	-	\$	10,744.00
2800	Landscape; Irrigation & Planting	\$	46,000.00	\$	48,000.00	\$	94,000.00	\$	27,328.96	\$	40,301.93		\$	67,630.89	72%	\$	26,369.11	\$	6,763.09
2810	Site Lighting (excludes fixtures)	\$		\$	26,350.00	\$	26,350.00	\$	26,350.00	\$	-		\$	26,350.00	100%	\$	_	\$	2,635.00
2860	Landscape Arbors	\$	-	\$	15,000.00	\$	15,000.00						\$	-	0%	\$	15,000.00	\$	
2920	Fencing	\$	25,000.00	\$	25,000.00	\$	50,000.00			\$	30,000.00		\$	30,000.00	60%	\$	20,000.00	\$	3,000.00
	Landscape Gas Lights (piping	-							•										
2950	only)	\$		\$	12,500.00		12,500.00	\$	12,500.00				\$	12,500.00	100%	\$	-	\$	1,250.00
2960	Joint Trench	-\$	25,000.00	\$	60,000.00		85,000.00	\$	85,000.00	+	~	T	\$	85,000.00	100%	\$	-	\$	8,500.00
3050	Rebar/Mesh, Shotcrete & CIP	\$	1,245,000.00	\$	70,728.00		1,315,728.00	\$	1,315,728.00	\$	-		\$	1,315,728.00	100%	\$	-	\$	5,329.43
3070	Struct. Excavation, Backfill & Offhaul		151,000.00	\$	(4,721.36)	~~~	146,278.64	\$	146,278.64	\$	-		\$	146,278.64	100%	\$		\$	14,523.51
3100	On Grade Site Concrete (Hardscape)	\$	50,000.00	\$	25,000.00	\$	75,000.00	\$	70,815.67	\$			\$	70,815.67	94%	\$	4,184.33	\$	7,081.57
3200	Offsite Concrete	\$	50,000.00			\$	50,000.00	\$	28,864.00	\$			\$	28,864.00	58%	S	21,136.00	\$	2,886.40
3910	Misc. Concrete	\$	50,000.00	\$	(50,000.00)					\$			\$	-	100%	\$	- 1	\$	-
	SUBTOTALS PAGE 1	\$	3,316,820.00		733,894,74	\$.	4,050,714.74	\$	3,793,498:88	4	150.079.68	<b>\$</b>	\$	3,943,578.56	97%	\$	107,136:18	\$	99,643.20

APPLICATION AND CERTIFICATION FOR PAYMENT. CONTAINING CONTRACTOR'S SIGNED CERTIFICATION IS ATTACHED IN TABULATIONS BELOW, AMOUNTS ARE STATED TO THE NEAREST DOLLAR.

APPLICATION NO : APPLICATION DATE :

1/31/2018 PERIOD FROM : 1/1/2018 PERIOD TO : 1/31/2018

1600

JOB#: CONTRACT DATE:

JOB #1600 - 1401 Howard Street, San Francisco, CA

A	В	С			D	E	F	G		Н	1
			Change		Wark Cam	pleted	Materials	Total	%		
ITEM	Description of work	Scheduled	Orders	New	Previous	This	Presently	Completed	Complete	Balance to	Retainage
NO.	·	Value	To	Scheduled	Applications	Period	Stored	and Stored	j	Finish	at 10%
			Date	Value		Work In Place	(Not in D or	io Date			
	·		(Thru PCCO#11)		(D + E)	(F-D)	E)	(D+E+F)	(G/C)	(C-G)	
	1	2 00 000 00	A (20 000 00)					· c	40004	¢	T. A.

ITEM	Description of work	Scheduled	1	Orders	1	New		Previous	1	This	Presently		Completed	Complete	ĺ	Balance to	F	Retainage
NO.		Value	į .	To		Scheduled		Applications		Period	Stored		and Stored			Finish	-	at 10%
			1	Date	1	Value			W	ork in Place	(Not in D or		io Date					
			m	ru PCCO#11)				(D + E)		(F-D)	E)		(D + E + F)	(G/C)		(C-G)		
4900	Masonry	\$ 20,000.00	\$	(20,000.00)	Ş	-						\$	-	100%	\$	-	\$	- 1
5050	Structural Steel	\$ 275,000.00	\$	(40,000.00)	S	235,000.00	\$	235,000.00				\$	235,000.00	100% .	\$	-	\$	23,500.00
5070	Structural Steel Installation	\$ 400,000.00	\$	(88,158,91)	\$	311,841.09	\$	311,841.09	\$	-		\$	311,841.09	100%	\$	-	\$	31,184.11
5080	Mezzanine Steel	\$ 401,143.00	\$	(84,000.00)	\$	317,143.00	\$	317,143.00	\$	-		\$	317,143.00	100%	\$	-	\$	31,714.30
5090	Mezzanine Bridge	\$ 50,000.00			\$		\$	50,000.00				\$	50,000.00	100%	\$	-	\$	5,000.00
5100	Mezzanine Glass Rail System	\$ 205,000.00	\$	(117,500.00)	\$	87,500.00	\$	83,696.20	\$			S	83,696.20	96%	Ş	3,803.80	\$	8,369.62
5110	Stairs	\$ 80,000.00	\$	(17,500,00)	\$	62,500.00	\$	31,250.00	\$	-		\$	31,250.00	50%	\$	31,250.00	S	3,125.00
5120	Misc. Steel	\$ 25,000.00			\$	25,000.00	\$	11,812.50	\$	-		\$	11,812.50	47%	\$	13,187.50	53	1,181.25
5130	Supports for the 700 lb. Trough sink	\$ -	\$	7,500.00	\$	7,500.00	\$	7,500.00				\$	7,500.00	100%	\$	-	\$	750.00
6050	Cabinets	\$ 10,000.00	\$	(10,000.00)	\$	-						\$	-	100%	\$	_	\$	-
6100	Retrofit Carpentry	\$ 560,000.00	\$	77,701.97	\$	637,701.97	\$	568,219.74	\$	44,482.00		\$	612,701.74	96%	\$	25,000.23	\$	61,270.17
6150	Window Stop Repair	\$ 50,000.00	\$	46,867.00	\$	96,867.00	\$	96,867.00	\$			\$	96,867.00	100%	\$	-	\$	9,686.70
6160	Bell Tower Rot Repair	\$ -	\$	151,458.96	\$	151,458.96	\$	151,458.96	\$	-		\$	151,458.96	100%	\$		\$	15,145.90
6200	Trim Carpentry	\$ 50,000.00			\$	50,000.00	\$	21,895.57	\$	20,000.00		\$	41,895.57	84%	\$	8,104.43	\$	4,189.56
6250	Scaffolding	\$ 175,000.00	\$	174,060.84	\$	349,060.84	\$	349,060.84	\$	-		\$	349,060.84	100%	\$	-	\$	33,406.08
6250	Bell Tower Scaffolding	\$ -	\$	165,000.00	\$	165,000.00	\$	165,000.00	\$			S	165,000.00	100%	\$	-	\$	16,500.00
6500	Countertops	\$ 5,000.00	\$	(5,000.00)	\$	-						\$	-	100%	\$	-	\$	-
7200	Additional under slab insulation	\$ *	\$	35,000,00	\$	35,000.00	S	35,000.00		-		\$	35,000.00	100%	\$	-	\$	3,500,00
7300	Slate Tile Roof	\$ 267,950.00	\$	(9,000.00)	\$	258,950.00	\$	258,950.00	\$	-		\$	258,950.00	100%	\$		\$	25,895.00
7500	Lower Roof System	\$ 35,000.00	\$	(6,890.00)	\$_	28,110.00	\$	28,110.00				\$	28,110.00	100%	\$	-	\$	2,811.00
7600	Flashing & Sheetmetal	\$ 200,000.00	\$	234,323.47	\$	434,323.47	\$	434,323.47	\$	-		\$	434,323.47	100%	\$	-	\$	43,432.35
7900	Sealants & Caulking	\$ 10,000.00			\$		\$	10,000.00		-		\$	10,000.00	100%	\$		S	1,000.00
8050	Windows	\$ 545,000.00	S	(275,423.78)	\$	269,576.22		269,576.22		_		\$	269,576.22	100%	\$	-	\$	26,957.62
8070	Stain Glass Repair	\$ 120,000.00	\$	(38,739.33)	\$	81,260.67	\$	81,260.67	\$	-		\$	81,260.67	100%	Ş	-	\$	8,126.07
8080	Skylight Repair	\$ -	\$	39,010.06	\$	39,010.06	\$	39,010.06	\$	-		\$	39,010.06	100%	\$	~.	\$	3,901.01
8200	Doors/Millwork & Finish Hardware	\$ 284,000.00	\$	(15,000.00)	\$	269,000.00	\$	264,631.12	\$	-		\$	264,631.12	98%	\$	4,368.88	\$	26,463.11
9050	Plaster Repair	\$ 775,000.00	\$	575,577.80	\$	1,350,577.80	\$	1,350,577.80	\$			\$	1,350,577.80	100%	\$	-	\$ 1	135,057.78
9100	Metal Studs & Drywall	\$ 110,000.00	\$	(40,000.00)	\$	70,000.00	\$	70,000.00	\$	-		\$	70,000.00	100%	\$	-	S	7,000.00
	Soffitt below Transept Café,		T															
9200	Green Rm Stage Metal Framing	\$ -	\$	17,000.00	\$	17,000.00	\$	17,000.00	\$	-		\$	17,000.00	100%	\$		\$	1,700.00
9400	Ceramic Tile	\$ 30,000.00	\$	(30,000.00)	\$	-						\$	~	100%	S		\$	-
9630	Flooring - Carpet Tile	\$ 78,000.00	\$	(78,000.00)	\$	-						\$	-	100%	\$	-	\$	-
9900	Painting	\$ 234,900.00	\$	58,950.00	\$	293,850.00	\$	279,213.41	\$	-		\$	279,213.41	95%	\$	14,636.59	\$	27,921.34
9950	Gold Leaf at Dome	\$ 	\$	60,000.00	\$	60,000.00	\$	60,000.00	\$	-		\$	60,000.00	100%	\$		\$	6,000.00
13000	SUBTOTALS PAGE 2	\$ 8,312,813.00	\$	1,501,132.82	\$	9,813,945,82	\$	9,391,898.53	\$	214,561.68	<b>3</b>	\$	9,606,458,214	98%	\$	207,487,61	<b>5</b>	664,431.16

APPLICATION AND CERTIFICATION FOR PAYMENT, CONTAINING CONTRACTOR'S SIGNED CERTIFICATION IS ATTACHED IN TABULATIONS BELOW, AMOUNTS ARE STATED TO THE NEAREST DOLLAR.

APPLICATION DATE : PERIOD FROM:

APPLICATION NO :

1/31/2018 1/1/2018 1/31/2018

PERIOD TO:

JOB#: 1600

CONTRACT DATE:

JOB #1600 - 1401 Howard Street, San Francisco, CA

Α	В		C		I			)	D		E	F	Γ	G	Ι	$\neg$	Н		
					Change				Work Com	ıle:		Materials	-	Total	%	-			
ITEM	Description of work		Scheduled		Orders		New		Previous		This	Presently		Completed	Comple	te	Balance to	, E	Retainage
NO.	Description of Hom		Value .		To		Scheduled		Applications		Period	Stored		and Stored	Compro	``	Finish		at 10%
NO.			value .		Date		Value		/ upplications	V	Nork In Place	(Not in D or		to Date	1	1	1 (13)1		at 107g
•				(TTL	ru PCCO#11)		value		(D + E)	"	(F-D)	(1401 III 25 01 E)		(D + E + F)	(G/C	.	(C-G)		
10320	Fire Extinguishers	\$	1,600,00	. (11		\$	1,600.00	-		\$	1,600.00		\$	1,600.00	100%	\$		ŝ	160.00
10320		<u>\$</u>	6,500,00			\$	6,500,00	•	6,500.00				\$	6,500.00	100%			S	650.00
	Signage	\$	2,000.00			\$	2,000,00	φ.	0,500.00	\$	2,000.00		\$	2,000.00	100%	- <del>  3</del>			
10450	Mirrors Access Doors & Ladders	5	12,000,00			\$		\$	12,000.00	\$			\$	12,000.00	100%			\$	200.00
10530		S	11,500.00			\$	11,500.00		11,500.00				\$	11,500.00	100%	\$		\$	1,200.00
10600	Tollet Partitions	\$				\$		\$	1,500.00	<u>ф</u>					100%			\$	1,150.00
10800	Bath Accessories		1,500.00			\$		\$		_÷			\$	1,500.00		\$		\$	150.00
10910	Misc. Specialties/Bike Racks	\$	1,500.00		10,500,00				1,500.00	- 3				1,500.00	100%	\$		\$	150.00
	Appliances	\$	2,500.00	\$	(2,500.00)			_					\$		100%	\$		\$	
	Window Coverings	\$	- 400 000 00	-	(07,070,071	\$	0.400.70	-	0.400.70					0.400.770	100%	\$		\$	
13170		\$	100,000.00	, Þ	(97,870.27)			\$	2,129.73				\$	2,129.73	100%	\$		~~~~	212,97
13180	Bird Guano Abatement	\$	12,500.00	*	(3,200.00)		9,300.00		9,300.00	\$			\$	9,300.00	100%	\$		5	
13190	Asbestos Abatement	\$_		\$	(1,543.00)		14,457.00		14,457.00	\$			\$	14,457.00	100%	\$		<u>\$</u>	
14200	Wheel Chair Lift	\$	25,000.00	\$	20,000.00		45,000.00		45,000.00				\$	45,000.00	100%	\$		\$	4,500.00
15050	Plumbing	\$	105,000.00		(21,000.00)		84,000.00	~~~	80,000.00	\$			S	84,000.00	100%	\$		\$	8,400.00
15150	Radiant Floor Heat	\$	145,000.00	\$	7,500.00		152,500.00	\$	152,500.00			<u> </u>	\$	152,500.00	100%	\$		\$	15,250.00
15400	Ventilation	\$	185,000.00	\$	10,000.00		195,000.00			\$			\$	186,372.00	96%	\$		\$	18,637.20
	Electrical	\$	353,000.00	\$	643,000.00		996,000.00	\$		\$			\$	986,114.03	99%	\$		\$	98,611.40
-	Fixtures	\$	50,000.00	\$	85,281.00		135,281.00		126,327.00			************	\$	126,327.00	93%	\$		\$	12,632.70
16080	Site Lighting Fixtures	\$		\$	92,625.00		92,625.00			\$			\$	84,872.00	92%	- \$		\$	8,487.20
16090	Access Control / Intercom	\$		\$	27,469.00		27,469.00			\$			\$	27,469.00	100%	\$		\$	2,746.90
16100	CCTV System	\$	-	\$	15,484.00		15,484.00		4,645.20	\$	10,838.80		\$	15,484.00	100%	\$		\$	1,548.40
	WiFi System	\$	-	\$	18,360.00		18,360.00		9,180.00	\$	9,180.00		\$	18,360.00	100%	\$		\$	1,836.00
16160	Music Speaker System	\$		\$	51,248.00		51,248.00		51,248.00	_			\$	51,248,00	100%	\$		\$	5,124.80
	Commisary Service Upgrade	\$		\$	6,000.00		6,000.00		6,000.00				\$	6,000.00	100%	\$		\$	600.00
16180	Service Location Chg & Misc. Mods	\$	-	\$	9,975.00		9,975.00		9,975.00				\$	9,975.00	100%	\$	-	\$	997,50
16200	Low Voltage	\$	150,000.00	\$	(60,000,00)		90,000.00		83,072.13				\$	83,072.13	92%	\$	6,927.87	\$	8,307.21
16300	Telephone Data	\$		\$	6,248.00		6,248.00		6,248.00	\$			\$	6,248.00	100%	\$	-	S	624,80
16400	Lighting Control System	\$		\$	124,790.00		124,790.00	\$	109,637.10	\$	12,181.90		\$	121,819.00	98%	\$	2,971.00	\$	12,181.90
16500	Engineering	\$		\$	27,500.00		27,500.00	\$	27,500.00				\$	27,500,00	100%	\$	-	\$	2,750.00
17000	Additional Tenant Improvements	\$	240,000.00	\$	(240,000.00)	\$							\$	_	100%	\$	-	\$	-
17001	Red Room - Ceiling restoration	Ş	-	\$	40,749.25	\$	40,749.25	\$	40,749.25	S	-		\$	40,749.25	100%	. \$	-	\$	4,074.93
17002	West Tower - X brace & spiral stair	\$	-	\$	40,000.00	\$	40,000.00	\$	20,000.00	\$	10,000.00		\$	30,000.00	75%	\$	10,000.00	\$	3,000.00
17003	East Tower - X brace	\$	~	\$	20,000.00	\$	20,000.00	\$	20,000.00	\$	-		\$	20,000.00	100%	\$	-	\$	2,000.00
E E ES	SUBTOTALS PAGE 3	\$	9,733,413.00		2,321,248,80	\$	12,054,661.80	\$	11,479,698,22	\$	312,356,13	<b>\$</b> 250,000	\$	11,792,054,35	98	% 3	262,607,45	\$ 1	
The second	Wild the State of Market State of the State of S		<u> </u>		. e erseren organ 363. 01	3.34	and comments of the segretary	-	A STATE OF THE STA	-	n an agent man dead	<u> </u>		a seminar managan	<u> a contrat</u>	11/11/2	THE PERSON NAMED IN COLUMN		**************************************

APPLICATION AND CERTIFICATION FOR PAYMENT, CONTAINING CONTRACTOR'S SIGNED CERTIFICATION IS ATTACHED IN TABULATIONS BELOW, AMOUNTS ARE STATED TO THE NEAREST DOLLAR.

APPLICATION NO : APPLICATION DATE : 1/31/2018

PERIOD FROM:

1/1/2018

PERIOD TO :

CONTRACT DATE:

1/31/2018

1600

JOB#:

JOB #1600 - 1401 Howard Street, San Francisco, CA

A	В	C			D	E	F	G		Н	}
			Change		Work Com	pleted	Materials	Total	%		
ITEM	Description of work	Scheduled	Orders	New	Previous	This	Presently	Completed	Complete	Balance to	Retainage
NO.		Value	To	Scheduled	Applications	Period	Stored	and Stored		Finish	at 10%
			Date	Value		Work in Place	(Not in D or	to Date			ļ
	· ·		(Thru PCCO#11)		(D + E)	(F-D)	E)	(D+E+F)	(G/C)	(C-G)	
	DIRECT COSTS:										
	Division 1 - General Requirements	\$ 935,000.0	0 \$ 339,455.98	\$ 1,274,455.98	\$ 1,174,231.49	\$ 79,777.75	\$ -	\$ 1,254,009.24	98%	\$ 20,446.74	\$ 13,068.75
	Division 2 - Site Improvements	\$ 835,820.0	0 \$ 353,432.12	\$ 1,189,252.12	\$ 1,057,581.08	\$ 70,301.93	\$ -	\$ 1,127,883.01	95%	\$ 61,369.11	\$ 56,753.54
	Division 3 - 17 Bidg. Improvements	\$ 7,962,593.0	0 \$1,628,360.70	\$ 9,590,953.70	\$ 9,247,885.65	\$ 162,276.45	\$ -	S 9,410,162.10	98%	\$ 180,791.60	\$ 810,792.79
	TOTAL DIRECT COST	\$ 9,733,413.0	0 \$2,321,248.80	\$ 12,054,661.80	\$ 11,479,698.22	\$ 312,356.13	\$ -	\$ 11,792,054.35	98%	\$ 262,607.45	\$ 880,615.08

9	000	OVERHEAD & PROFIT	\$ 632,672.00	\$	119,247.56	\$ 751,919.55	\$ 722,925.28	S	12,613.91		\$	735,539.19	98%	\$	16,380.36	S	73,553,92
8	000	CONSTRUCTION CONTINGENCY 1.5%	\$ 486,671.00	\$	(486,671.00)	\$ -	\$ 				\$	-	100%	\$	-	\$	- 1
1	102	CCIP INSURANCE	\$ 259,152.00	\$	48,056.38	\$ 307,208.38	\$ 282,631.70	\$	15,360.42		\$	297,992.12	97%	\$	9,216.26	\$	3,884.01
													***************************************	1			
		TOTAL GUARANTEED MAXIMUM PRICE	\$ 11,111,908.00	\$:	2,001,881.74	\$ 13,113,789.73	\$ 12,485,255.20	\$	340,330.46	\$ -	\$ 1	2,825,585.66	98%	\$	288,204.07	\$ :	958,053.01

# II. EXEMPTION STATEMENT AND SIGNIFICANCE EVALUATION

#### **EXEMPTION STATEMENT**

The Mills Act Historical Property Contract requires all commercial properties that are assessed at a value of more than \$5 million to include a Historic Structure Report (HSR) as part of the application. The value of this property was less than \$5 million before renovations but is over the threshold due to the extensive renovations that were necessary to place it in service. Representatives of the San Francisco Planning Department have indicated that the HSR could be limited in scope and should include, at minimum, a brief history of the building, a description of the building's historic condition, a summary of its existing condition, and an outline of short-term and long-term recommendations for rehabilitation.

This limited Historic Structure Report, together with the Rehabilitation/Restoration & Maintenance Plan, serves to fulfill the requirements of the Mills Act application.

# 2019 MILLS ACT APPLICATION CRITERIA

This Mills Act application is submitted for 1401 Howard Street in San Francisco. During the process of preparing the application, staff at the Planning Department was consulted and the applicant was notified that changes to the Mills Act Program had been made but that the revised/updated application had not yet been posted to the city website. For this reason, the applicant was instructed to submit the old application, and strongly encouraged to include a written justification as to how the property meets the priority consideration criteria.

The priority consideration criteria and justification is summarized below, demonstrating that the property qualifies in three of the five categories for priority consideration. Further justification is summarized in the application that follows.

#### **NECESSITY**

For more than thirty years, this Landmark property sat vacant and suffered vandalism and continued deterioration. New owners assumed a risk and it took more than 10 years to assemble a pro-forma with financial incentives that enabled the project to 'pencil out'. Thorough assessment of architectural and structural conditions was required: use of the State Historical Building Code and Historic Rehabilitation Tax Credits were necessary for the substantial rehabilitation and restoration to be implemented in ways that allowed for the preservation and reuse of this Landmark.

#### INVESTMENT

The substantial rehabilitation of 1401 Howard resulted in significant private investment and placed it on the tax roll for the first time since its construction in 1913. The applicant spent more than \$12 million dollars to reinvest in the Landmark and the project has improved the investment climate of the entire neighborhood.

# DISTINCTIVENESS

The project preserves a distinctive example of a property that is especially deserving of a contract due to its exceptional nature. 1401 Howard is City Landmark #120 and is listed in the National Register of Historic Places (#1982002250); it has long been recognized as exceptional due to its architectural design and its significance to the early Irish, Filipino and Hispanic communities as a Catholic parish. The project

is also distinct in that it preserved the architectural significance of the church, a challenging typology to reuse, while adapting it to a new future.

RECENTLY DESIGNATED CITY LANDMARK—not applicable, already a Landmark.

LEGACY BUSINESS - not applicable - yet.

# III. HISTORIC STRUCTURE REPORT

Historic context and evaluation sections of this Historic Structure Report have been incorporated from the Historic Resource Evaluation authored by Page & Turnbull in 2011.

#### HISTORY OF 1401 HOWARD STREET

St. Joseph's Parish was established in 1861 by Archbishop Joseph Sadoc Alemany at the corner of 10<sup>th</sup> and Howard streets in San Francisco. The parish originally served the large Irish-Catholic population in the South of Market Area. The first St. Joseph's Church was dedicated on December 8, 1861 and was the seventh parish established in the city. (Figure 1).




Figure 1. St. Joseph's Church, 1861.

Source: "History of St. Joseph's Parish," Diamond Jubilee of St. Joseph's Church: 1861-1936 (San Francisco: unpublished pamphlet, 29 October 1936).

Father Hugh Gallagher was the first pastor of St. Joseph's Parish. Born in County Donegal, Ireland on Easter Sunday, 1815, he was ordained in 1840 and was sent to Pittsburg, Pennsylvania, where he labored for eight years at Master's Vineyard. Father Gallagher met Archbishop Alemany at the Council of Baltimore in 1854 and was recruited to California to help build the Diocese of San Francisco. Father Gallagher was appointed pastor of St. Joseph's in 1861 and selected a site beside an abandoned waterworks at 10<sup>th</sup> and Howard streets for the construction of St. Joseph's Church. Under Father Gallagher's guidance, the parish quickly grew to be one of the most populous and prosperous in San Francisco. A larger church was erected in 1865 on 10<sup>th</sup> Street, and in 1867, this church was expanded to accommodate additional parishioners.<sup>2</sup>

In 1867, Father Gallagher established a girls' school under Mrs. Margaret Deane, and a boys' school under Professor W.J.G. Williams. These schools, which taught children from the South of Market Area and the Mission district, were secularly operated until 1871, when the Sisters of the Holy Names were brought on to teach classes. Girls' classes were held in the original church building, which had been remodeled and moved to the rear of the parcel. The boys' school was housed in the pavilion of the old

April 2019 31 Page & Turnbull, Inc.

<sup>&</sup>lt;sup>1</sup> Archdiocese of San Francisco, "The History of St. Joseph's Parish," in Archdiocese of San Francisco Archives. <sup>2</sup> Ibid.; "History of St. Joseph's Parish," *Diamond Jubilee of St. Joseph's Church: 1861–1936* (San Francisco: unpublished pamphlet, 29 October 1936).

City Gardens. This building was purchased from the city and moved from its original location at 12<sup>th</sup> and Folsom streets to the corner of 10<sup>th</sup> and Howard streets (the portion of the parcel presently occupied by St. Joseph's Church). A convent was also erected on the St. Joseph's Church property shortly thereafter.<sup>3</sup>

Father Gallagher died in 1882 and was succeeded by Father Patrick Scanlon. Father Scanlon was born in County Kerry, Ireland, and educated at All Hallows College near Dublin until he was ordained as a priest in 1864. In 1865, Father Scanlon was sent to California, where he worked in Mariposa and Sacramento before coming to St. Joseph's Parish in San Francisco. Father Scanlon further improved St. Joseph's schools and secured the Brothers of Mary to take charge of the boys' school in 1886. Father Scanlon also built a new residence for the clergy and improved the boys' school facilities. The parish continued to flourish under Father Scanlon, with over twelve thousand predominantly Irish parishioners in regular attendance. Upon Father Scanlon's death in 1904, Father Patrick E. Mulligan, who was born in San Francisco and attended St. Mary's College, was appointed as the third pastor of St. Joseph's Parish.<sup>4</sup> (Figure 2).



Figure 2. Father Patrick E. Mulligan, 1906. Source: San Francisco Call-Bulletin, 3 December 1906.

The 1906 Earthquake and Fire decimated the entire South of Market Area, and St. Joseph's Church and its associated buildings were all destroyed. The congregation of St. Joseph's Church celebrated the first Mass after the disaster, on Sunday April 22, 1906, at the McDade home at 17<sup>th</sup> and Bryant streets<sup>5</sup>. By 1907, Father Mulligan led the congregation in erecting a temporary church on the site of the former St. Joseph's Church and had already begun constructing new school and residence buildings. Mass was held in the hall of the temporary church for eight years, until the completion of the large permanent church on the corner of the property. The temporary hall was later converted into a gymnasium and parish assembly hall, and currently houses part of the day-care center. After the fire, the clergy lived in the rear

<sup>&</sup>lt;sup>3</sup> Ibid.

<sup>&</sup>lt;sup>4</sup> Ibid.

<sup>&</sup>lt;sup>5</sup> San Francisco Chronicle (San Francisco), 25 October 1936.

of the temporary church until the completion of the rectory in 1908 on Howard Street, where the brothers' home had formerly stood. The convent was reconstructed behind the school as well.<sup>6</sup>




Figure 3. "Architect's Drawing of Proposed St. Joseph's Church," 1913. Source: San Francisco Examiner, 27 April 1913.




Figure 4. St. Joseph's Church interior, 1915. Source: San Francisco Chronicle, 27 June 1915.

<sup>&</sup>lt;sup>6</sup> Archdiocese of San Francisco, "The History of St. Joseph's Parish."

Construction began on the present St. Joseph's Church in 1913. Father Mulligan selected architect John J. Foley to design the massive structure (Figure 3). Foley's striking Romanesque Revival design featured steel and brick masonry construction, with two towers capped by gilded domes flanking the primary entrance. The new church was to have a seating capacity of 1,000, with white eastern oak pews crafted by Dubuque Altar Manufacturing Company in Dubuque, Iowa, and stained glass windows depicting biblical scenes lining the walls.<sup>7</sup> The cornerstone for St. Joseph's Church was laid by Archbishop Riordan on April 27, 1913, and construction was completed one year later.<sup>8</sup> St. Joseph's Church was dedicated in November 1914, and the altars were consecrated in June 1915.<sup>9</sup> (Figure 4). Father Richard Collins succeeded Father Mulligan as pastor on March 1, 1929.<sup>10</sup>

As the South of Market Area was rebuilt in the first half of the twentieth century, it became more industrial and never fully regained its previous residential character. Many of the Irish families who had once inhabited the area did not return, and the composition of St. Joseph's congregation gradually changed. By the 1950s, the church's membership was composed largely of Latino and Filipino immigrants.<sup>11</sup> St. Joseph's Church and its associated buildings underwent a series of renovations in the late 1950s and early 1960s by architects Wilton Smith and John G. Minton; a garage, a convent, and a school were also constructed on the site.<sup>12</sup> Additionally, a concrete shrine modeled after the famous grotto at Lourdes in France was built in the garden next to the church in the 1950s, and was dedicated to Our Lady of Fatima.<sup>13</sup> (Figure 5).




Figure 5. Grotto in courtyard, n.d. Source: Willard, Sacred Places of San Francisco, 108.

In 1968, St. Joseph's began to host the celebration of the feast of the *Santo Niño de Cebu*, the Filipino patron saint. The festival became a major celebration complete with a parade and a fiesta, and was extremely popular among the Filipino community. By 1979, St. Joseph's Church had become the home of

<sup>&</sup>lt;sup>7</sup> Archdiocese of San Francisco Archives.

<sup>&</sup>lt;sup>8</sup> San Francisco Examiner (San Francisco), 27 April 1913.

<sup>&</sup>lt;sup>9</sup> San Francisco Chronicle (San Francisco), 23 November 1914, 27 June 1915.

<sup>&</sup>lt;sup>10</sup> "History of St. Joseph's Parish," Diamond Jubilee of St. Joseph's Church.

<sup>&</sup>lt;sup>11</sup> "St. Joseph's Church," National Register of Historic Places Nomination Form (23 November 1981).

<sup>&</sup>lt;sup>12</sup> Building Permit Applications.

<sup>&</sup>lt;sup>13</sup> Ruth Hendricks Willard and Carol Green Wilson, *Sacred Places of San Francisco* (Novato: Presidio Press, 1985), 107.

the largest Filipino parish in San Francisco. A marble chapel which enshrined the *Santo Niño de Cebu* was dedicated in 1980 as the "National Shrine of Filipinos in the United States of America," and was the first shrine to the *Santo Niño de Cebu* to be constructed outside the Philippines (no longer extant).<sup>14</sup>

The Loma Prieta Earthquake in 1989 damaged St. Joseph's Church, which was immediately closed and declared seismically unstable. As the combined result of the expense to repair the church and the overall decline in church attendance in San Francisco, St. Joseph's Church remained closed. In order to help the parishioners of St. Joseph's find a new place of worship, St. Joseph's merged with neighboring St. Patrick's parish, and on March 19, 1994, a symbolic procession from St. Joseph's Church to St. Patrick's Church was held along Mission Street. In 1997, the parish buildings on the St. Joseph's site were converted into a center for homeless families and pregnant women. Operated by Catholic Charities of the Archdiocese, the center opened on June 13, 1997, as St. Joseph's Village. Today, St. Joseph's Church is no longer associated with the other buildings on the site.

# CONSTRUCTION CHRONOLOGY

1860s-1890s

1861: St. Joseph's Parish established on southwest corner of 10th & Howard streets.

1900s

1906: Original St. Joseph's Church destroyed by San Francisco Earthquake & Fire.

- <u>1907:</u> Parish hall (still extant, but no longer associated with the parcel containing the church) constructed for use as a temporary church and school.<sup>16</sup> A 16' x 20' wood-frame horse stable was also constructed on the St. Joseph's Church site.<sup>17</sup>
- <u>1908:</u> Rectory (still extant, but no longer associated with the parcel containing the church) constructed. The two-story wood-frame building was designed by an unknown architect for use as clergy residences. A convent (no longer extant) was also constructed on the rear of parcel at around this time.

1910s

<u>1911:</u> Alterations to convent (formerly located on rear of parcel, no longer extant)—addition of basement and mansard roof; completed by architect John J. Foley.<sup>19</sup>

April 2019 35 Page & Tumbull, Inc.

<sup>&</sup>lt;sup>14</sup> Burns, *History of the Archdiocese of San Francisco*, vol. III, 32; "St. Joseph's Church," National Register of Historic Places Nomination Form (23 November 1981).

<sup>&</sup>lt;sup>15</sup> Burns, History of the Archdiocese of San Francisco, vol. III, 45.

<sup>&</sup>lt;sup>16</sup> San Francisco Architectural Heritage, Vertical Files: "220 10<sup>th</sup> Street." Note: Sanborn Fire Insurance maps list date of construction as "1913," as does San Francisco Planning Department's Parcel Information Database. The original building permits were not found to verify this information.

<sup>&</sup>lt;sup>17</sup> Building Permit Application #8225 (20 February 1907).

<sup>&</sup>lt;sup>18</sup> San Francisco Architectural Heritage, Vertical Files: "1415 Howard Street," San Francisco Assessor's Office. Note: Original building permits were unavailable at the time of this report.

<sup>&</sup>lt;sup>19</sup> John J. Foley, "St. Joseph's Parish Convent," Plans (1911); Building Permit Application #26218 (2 June 1911).

1913: St. Joseph's Church constructed. Designed in the Romanesque Revival style by architect John J. Foley, the cornerstone was laid in April 1913.<sup>20</sup> The steel-frame masonry church was dedicated in November 1914, and the altars were consecrated in June 1915.<sup>21</sup>

<u>Circa 1915:</u> Alterations to Parish Hall—two 35' towers added to primary façade of parish hall by architect John J. Foley.<sup>22</sup>

1920s-1940s

No activity recorded. (Figure 6).




Figure 6. St. Joseph's Church, 1946.
Source: St. Paul Fire and Marine Insurance Company, "St. Joseph's Church,"
(San Francisco: unpublished case report, 1 October 1946), in Archdiocese of San Francisco Archives.

1950s

<u>Circa 1950:</u> Construction of rock-like concrete grotto, built as a shrine to Our Lady of Fatima (demolished in 1999).<sup>23</sup>

<u>1952:</u> Alterations to St. Joseph's Church complex completed by architects Wilton Smith and John G. Minton and contractor Frank Portman, Jr.

Church—install new lights; install metal railings on 10<sup>th</sup> Street side; install 4 overhead doors in existing ports; repair stained glass windows.

Other buildings—various alterations and demolition work.<sup>24</sup>

<u>1956:</u> Alterations to St. Joseph's Church—remove existing wood floor and install concrete floor; replace and relocate pews; relocate altar; install cabinets in sacristy; build new confessionals; lower metal

<sup>&</sup>lt;sup>20</sup> San Francisco Call-Bulletin (San Francisco), 28 April 1913.

<sup>&</sup>lt;sup>21</sup> San Francisco Chronicle (San Francisco), 23 November 1914, 27 June 1915; San Francisco Examiner (San Francisco), 23 November 1914.

<sup>&</sup>lt;sup>22</sup> Sanborn Fire Insurance Maps (1913, 1929, & 1986); San Francisco Architectural Heritage, Vertical Files: "220 10<sup>th</sup> Street." Note: The building appears without the towers on the 1913 Sanborn Map, but did appear on a 1929 Sanborn Map.

 <sup>23 &</sup>quot;St. Joseph's Church and Complex," National Register of Historic Places Nomination Form (23 November 1981).
 24 Building Permit Application #151746 (11 December 1952); Wilton Smith, San Francisco, to Rev. Msgr. Harold E. Collins, San Francisco, 26 December 1952, in Archdiocese of San Francisco Archives.

lath and plaster ceiling and install new light fixtures in baptistery. Work completed by contractor Frank Portman, Jr. and architect Denis Shanagher for an estimated cost of \$31,000.<sup>25</sup>

## 1960s

- <u>1960:</u> Permit issued for the construction of a four-car concrete garage at 220 10<sup>th</sup> Street (still extant, but no longer associated with the parcel containing the church). Designed by architect Wilton Smith, the garage was completed for an estimated cost of \$5,000.<sup>26</sup> St. Joseph's School at 250 10<sup>th</sup> Street was also constructed by architect Wilton Smith at this time.<sup>27</sup>
- <u>1961:</u> Permit issued for erection of concrete building at 244 10<sup>th</sup> Street to be used as a convent (still extant, but no longer associated with the parcel containing the church). The convent was designed by architect Wilton Smith and was completed for an estimated cost of \$504,606.<sup>28</sup>
- 1967: Alterations to St. Joseph's Church complex completed by contractor Frank Portman, Jr. and architect Denis Shanagher for an estimated cost of \$26,000.
  Rectory—construct addition at rear; remodel kitchen (new cabinets, windows, floor, etc.); remodel bathrooms upstairs and install new bathrooms downstairs; install new gate at entrance.<sup>29</sup>
  Parish Hall—create new door openings and concrete stairs with railings; install new heaters and exhaust fans; install new vinyl asbestos floor covering.<sup>30</sup>

#### 1970s-1980s

- 1985: Alterations to Parish Hall—move partition; add new room; add new stairway; install new sheetrock, and re-sheetrock three classrooms. Work completed by contractor Stephen M. Smith for an estimated cost of \$15,000.31
- <u>1989:</u> St. Joseph's Church damaged in Loma Prieta Earthquake. The church was declared seismically unstable and was closed.

1990s

- 1994: St. Joseph's Parish merged with St. Patrick's Parish on Mission Street. 32
- <u>1997:</u> St. Joseph's Village opens in the parish buildings as homeless shelter and child-care center operated by Catholic Charities of the Archdiocese.<sup>33</sup>
- <u>1999:</u> Alterations to Rectory—remove shrine to provide space for access ramp; add handicap access ramp; install fire alarms and fire suppression system; renovate interior to provide housing for 35 people (add bathrooms, kitchen, rooms); reduce windows on west elevation.<sup>34</sup>

<sup>&</sup>lt;sup>25</sup> Building Permit Application #337884 (15 December 1956).

<sup>&</sup>lt;sup>26</sup> Building Permit Application #237643 (17 June 1960).

<sup>&</sup>lt;sup>27</sup> Sanborn Fire Insurance Map, San Francisco (1986).

<sup>&</sup>lt;sup>28</sup> Building Permit Application #244156 (1 February 1961).

<sup>&</sup>lt;sup>29</sup> Building Permit Application #349245 (13 October 1967).

<sup>&</sup>lt;sup>30</sup> Building Permit Application #349244 (13 October 1967).

<sup>31</sup> Building Permit Application #8502825 (20 March 1985).

<sup>32</sup> Burns, History of the Archdiocese of San Francisco, vol. III, 45.

<sup>33</sup> Ihid

<sup>34</sup> Building Permit Applications #9802661, #9822109, and #9900789 (19 March 1999).

#### 2000s

- <u>2003:</u> Alterations to St. Joseph's Church—remove 31 stained glass windows. The process included removal of interior wood trim, glazing or sealant, and stained glass.<sup>35</sup>
- 2008: The archdiocese sells the property to a private developer.
- <u>2011:</u> St. Joseph's Church remains vacant. The rectory, parish hall, convent, school, and garage buildings are no longer associated with the parcel containing St. Joseph's Church.
- <u>2016</u>: The building permit on structural repairs was issued in May 2016 and the construction started in June 2016. The scope included the restoration work for the roof, new foundations, and structural repairs.
- 2017: The building permit on the tenant improvements was issued in November. The scope of this permit included the new mezzanine, new mechanical and electrical systems, new toilets, new stairs and interior finishes.
- 2018: The construction of the structural work and TI was completed, and the owners received the Certificate of Final Completion in August.

# HISTORIC SIGNIFICANCE

St. Joseph's Church is a designated San Francisco City Landmark (#120) and is listed in the National Register of Historic Places (#1982002250).

# National Register of Historic Places

The National Register of Historic Places is the nation's most comprehensive inventory of historic resources. The National Register is administered by the National Park Service and includes buildings, structures, sites, objects, and districts that possess historic, architectural, engineering, archaeological, or cultural significance at the national, state, or local level. Typically, resources over fifty years of age are eligible for listing in the National Register if they meet any one of the four criteria of significance and if they sufficiently retain historic integrity. However, resources under fifty years of age can be determined eligible if it can be demonstrated that they are of "exceptional importance," or if they are contributors to a potential historic district. National Register criteria are defined in depth in National Register Bulletin Number 15: How to Apply the National Register Criteria for Evaluation. There are four basic criteria under which a structure, site, building, district, or object can be considered eligible for listing in the National Register. These criteria are:

<u>Criterion A (Event):</u> Properties associated with events that have made a significant contribution to the broad patterns of our history;

<u>Criterion B (Person)</u>: Properties associated with the lives of persons significant in our past;

April 2019 38 Page & Turnbull, Inc.

<sup>35 &</sup>quot;St. Joseph's Church," Landmarks Preservation Advisory Board Case Report #2003.0197A (21 May 2003).

<u>Criterion C (Design/Construction)</u>: Properties that embody the distinctive characteristics of a type, period, or method of construction, or that represent the work of a master, or that possess high artistic values, or that represent a significant distinguishable entity whose components lack individual distinction; and

<u>Criterion D (Information Potential):</u> Properties that have yielded, or may be likely to yield, information important in prehistory or history.

A resource can be considered significant on a national, state, or local level to American history, architecture, archaeology, engineering, and culture. The following examines the significance of St. Joseph's Church under these criteria:

St. Joseph's Church is currently listed in the National Register under Criteria A (Event) and C (Design/Construction) in the areas of architecture, religion, and ethnic history for a period of significance from 1906 to 1914. The church, which is no longer associated with any of the adjacent buildings that once formed the church complex (including the rectory and parish hall that were included in the nomination), is significant for its association with the reconstruction of the South of Market Area and religious institutions following the 1906 Earthquake and Fire. The church also played an important role in the ethnic history of San Francisco, having witnessed the change from a predominantly Irish Catholic parish to a Filipino parish. St. Joseph's Church is also architecturally significant as an excellent local example of Romanesque Revival architecture, and as a typical example of ecclesiastical architecture of this period. <sup>36</sup>

# San Francisco City Landmark

Under Article 10 of the San Francisco Planning Code, the evaluative criteria used by the Landmarks Board for determining eligibility are closely based on those developed for use by the National Park Service for the National Register of Historic Places.

St. Joseph's Church was listed as San Francisco City Landmark #120 in 1980. The Landmarks Board nomination form attributes the significance of St. Joseph's Church to its meaning to ethic groups in the city, especially the Irish and Filipino communities; its contribution to education in San Francisco, namely the establishment of one of the city's first parochial schools; and its association with the development of the South of Market Area. The grounds, rectory, and parish hall were included in the landmark nomination as contributing features to the site.<sup>37</sup> St. Joseph's Church is currently owned by a different entity and is no longer associated with the rectory or parish hall. Additionally, the church is no longer associated with the garage, convent, or school, which were not included or listed as contributing resources in the nomination.

# South of Market Survey & Area Plan

The South of Market Area Plan (Area Plan or Plan) is a component of the city's General Plan that contains a set of objectives and policies created by the San Francisco Planning Department to guide decisions affecting the development of San Francisco's South of Market neighborhood. The South of Market Area Plan is primarily geared towards guiding residential development and public facilities within the area covered by the plan, which roughly is bordered by South Van Ness, Mission, Townsend and

<sup>&</sup>lt;sup>36</sup> "St. Joseph's Church and Complex," National Register of Historic Places Nomination Form (23 November 1981). <sup>37</sup> "Final Case Report: St. Joseph's Church & Complex," San Francisco Landmarks Preservation Advisory Board Nomination Form (5 March 1980).

Second Streets.<sup>38</sup> The Plan provides for a mixture of low-income residential areas, rent-sensitive small business areas, and downtown visitor and office industries. The South of Market Area Plan identified a couple of potential historic districts and included a list of individually significant buildings outside those districts. St. Joseph's Church (1401 Howard Street) is listed as a "significant building located outside the proposed historic district" in the South of Market Area Plan.<sup>39</sup>




Figure 7. Parcel map of the Western SoMa Community Plan area, with St. Joseph's Church marked with a star. Source: San Francisco Planning Department; altered by author.

In conjunction with the Western SoMa Community Plan (2011), the Planning Department undertook a survey of historic resources within the Plan area. The SoMa Historic Resources Survey was adopted by the Historic Preservation Commission in July 2010. As part of this survey, St. Joseph's Church was found to be a contributor to the proposed "Western SoMa Light Industrial & Residential Historic District," which appears eligible for listing in the National Register of Historic Places.

<sup>&</sup>lt;sup>38</sup> San Francisco Planning Department, Area Plan: South of Market, 6 July 1995,

<sup>&</sup>lt;a href="http://www.sfgov.org/site/planning">http://www.sfgov.org/site/planning</a> index.asp?id=24896> (1 November 2007).

<sup>&</sup>lt;sup>39</sup> San Francisco Planning Department, Area Plan: South of Market, 6 July 1995,

<sup>&</sup>lt;a href="http://www.sfgov.org/site/planning">http://www.sfgov.org/site/planning</a> index.asp?id=24896> (1 November 2007).

#### CHARACTER DEFINING FEATURES

For a property to be eligible for national, state, or local designation under criteria related to type, period, or method of construction, the essential physical features (or character-defining features) that enable the property to convey its historic identity must be evident. These distinctive character-defining features are the physical traits that commonly recur in property types and/or architectural styles. To be eligible, a property must clearly contain enough of those characteristics to be considered a true representative of a particular type, period, or method of construction, and these features must also retain a sufficient degree of integrity. Characteristics can be expressed in terms such as form, proportion, structure, plan, style, or materials.

The character-defining features of St. Joseph's Church include, but are not limited to:

#### Exterior

- Cruciform plan
- Massing
- Faux-stone stucco
- Sheet metal architectural elements including cornices, upper towers, gilded domes and crosses
- Wooden window tracery
- Shapes of window openings
- Granite steps
- Wooden doors

#### Interior


- Marble wainscoting and floor in the lobby and side exit vestibules
- Decorative plaster elements including moldings, dentil cornice, pilasters and columns, vaults and coffered ceilings
- Oak woodwork including doors, door frames, window frames, column bases and railings
- Stained glass in the bell towers and rear office
- Interior volume over 50 feet high

The character-defining features of the overall site include, but are not limited to:

- Low brick perimeter wall with brick piers and metal fence
- Low concrete curb at northeast corner
- Landscaped open space surrounding the church
- Flat grade of the site

# ARCHITECTURAL DESCRIPTION

St. Joseph's Church (1401 Howard Street; APN 3517/035) is located on an irregular-shaped lot on the southwest corner of 10th and Howard streets in San Francisco's South of Market Area (Figure 8). The church was previously the focal point of a complex of six buildings that were once associated with St. Joseph's Parish. Four of the other buildings—St. Joseph's School, Convent, Parish Hall, and Rectory—are under different ownership and are no longer associated with the church. The garage (APN 3517/036) has since been demolished and now serves as a parking area for St. Joseph's Church.



10th Street

Figure 8. Site plan of the former St. Joseph's Church complex. The parcel on which the church is located (APN 3517/035) is shown in red. The rectory, parish hall, convent, and school buildings are no longer associated with St. Joseph's Church. The garage has since been demolished, and the parcel (APN 3517/036) is now associated with the subject building, shown in blue.

Source: Page & Turnbull.

# Exterior

Constructed in 1913, St. Joseph's Church is a three-story, steel-frame masonry church designed in the Romanesque Revival style (Figure 9). The cruciform-plan building is clad in stucco, scored to simulate stone, and sits on a concrete foundation and is capped by a gable roof. The building features a combination of large stained glass lancet windows, arched windows with keyhole details and contemporary glazing, and large rose windows. A layer of protective glazing has been installed at the exterior of the lancet windows. Typical doors include paneled wood doors with either an arched stained glass transom or a decorative wood paneled tympanum.

The primary façade faces north onto Howard Street and is symmetrical. The main entrance is located in the center section of the façade and three sets of paired double doors with quatrefoil paneling (Figure 10). The main entrance is accessed via granite steps with two metal hand rails. Flanking either side of the stairs are two contemporary steel planters. Each door is surrounded by a Roman arch with dentil molding and a paneled wood tympanum. These doors are separated by paired engaged Corinthian columns. On the upper floors, a large rose window set into a large, recessed arch dominates this portion of the façade. The center section of the primary façade terminates in a gable roof with a pressed metal raked cornice supported by dentils and a corbel table and is capped by a gold cross finial.



Figure 9. St. Joseph's Church. View south from Howard Street. Source: Rick Stapleton, September 2018.



Figure 10. Main entrance to St. Joseph's Church. Source: Page & Turnbull, April 2019.

The center gabled section of the primary façade is flanked by two square corner towers. Each tower contains a rose window above a pair of tall lancet windows of geometric stained glass separated and flanked on either side by colonettes. The towers terminate in a cornice, dentil molding, and corbel table similar to those found throughout the building. Octagonal cupolas with arched vents separated by engaged lonic columns support the gold domes with gold crosses that crown the towers.

The east (10th Street) façade is similar to the primary façade in detailing and organization. The overall form of the east façade features a corner tower at the north end, a long recessed section with clerestory windows above a projecting first floor, the transept end in the center, and another recessed section at the south end. The treatment of the corner tower is identical to the treatment of the towers on the primary façade. The long recessed section features a projecting ground floor capped by a shed roof. A simple pressed metal cornice supported by a corbel table and a row of arched windows with decorative steel muntins (formerly stained glass windows) separated by pilasters decorate the ground floor. A row of similar but smaller windows and pilasters occupies the clerestory. The transept end repeats the detailing of the center section of the primary façade but has a solid wall instead of an entrance on the ground floor and is topped by a gold cross finial (Figure 11). Projecting portals are located on either side of the transept and feature gable roofs supported by corbel tables and door treatments similar to those found at the main entrance. A contemporary steel planter is located along the transept, at the 10th Street sidewalk (Figure 12). A covered, concrete stairwell provides access to a door below ground level, north of the east transept.




Figure 11. Detail of corbel table and cornice on the transept. Source: Rick Stapleton, September 2018.




Figure 12. Contemporary steel planter at transept of east façade. Source: Page & Turnbull, April 2019.

The west façade has a similar overall composition and features similar treatments to the east façade. An accessible concrete ramp with metal handrails runs along the recessed portion of the west façade, accessing the projecting portal on the north side of the transept (Figure 13). South of the west transept is a small recessed area and a projecting bay. Concrete steps with metal handrails access a door on the south side of the transept and on the north side of the projecting bay (Figure 14).




Figure 13. Accessible concrete ramp on the west façade.



Figure 14. Recessed area between the west transept (left) and projecting bay (right).

The rear (south) façade is dominated by a blank wall clad in molded stucco; it has a gable roof with raked pressed metal cornice, dentil molding, and corbel table similar to those found on the primary façade (Figure 15). A structural steel frame spans the blank wall of the rear façade, between the pilasters and below the corbel table (Figure 16). The metal frame is composed of one horizontal beam and two vertical beams; between the vertical beams are metal mesh screens with climbing vine plantings. The gable end is flanked by one-story projections that feature multi-light steel sash windows with arched transoms, pilasters, and the church's characteristic pressed metal dentilated cornice. A metal bike rack is mounted on the wall of the west projecting volume.



Figure 15. St. Joseph's Church, south and west façades. View north from midblock.

Source: Google Maps, 2019.




Figure 16. Structural metal frame with mesh screen and climbing vines on rear (south) façade.
Source: Page & Turnbull, April 2019.

#### Interior

The interior of St. Joseph's Church is a classic cruciform basilica plan, with a narthex, barrel vaulted nave, clerestory, side aisles, and a barrel vaulted transept. The three entrance arches of the Howard Street façade open into a marble-paneled narthex with coffered plaster ceiling, marble floor, and contemporary light fixtures (Figure 17). Three round-arched, heavy wooden doors with leaded glass insets open into the nave. On either side of the narthex through arched doorways with glass transoms are small rooms that form the first floors of the towers. The room to the west is the former baptistery, which opaque glass windows and a contemporary mural painted on the walls (Figure 18). On the east side of the narthex is a small room with green and yellow diamond pane stained glass and stairs leading up to a mezzanine.




Figure 17. Narthex, looking east. Source: Page & Turnbull, April 2019.




Figure 18. Former baptistry, west of the narthex, with painted mural. Source: Page & Turnbull, April 2019.

From the narthex, the nave is a large linear open space with a coffered plaster barrel vault ceiling. The flat concrete floor features radiant heating. Beneath the clerestory on each side are aisles that are supported by four arches springing from columns; the columns have white oak bases and are capped with gilded Scamozzi capitals. A cornice with dentils and acanthus leaf modillions runs above the arches and extends the length of the nave. On the east and west walls, pointed arch windows with keyhole wooden tracery are located in the aisles and the clerestory.

Large rose windows dominate the transept ends and the northwest end of the nave above the entrance. A former choir loft is located above the entrance and are recessed over the narthex (Figure 19). At the south end of the church, the former altar area is a raised wooden platform reached by wood steps (Figure 20). The altar is surrounded by a semicircular series of arched niches with ionic columns and pilasters on oak bases. Photographic murals have been installed in the center three arched niches. Above the columns is a coffered half dome, with gilded flowers inset into the coffers. A large steel skylight allows light into the altar area.




Figure 19. St. Joseph's Church interior, looking north toward choir loft. Source: Page & Turnbull, April 2019.




Figure 20. St. Joseph's Church apse, looking south. Source: Page & Turnbull, April 2019.

To the west of the altar is the former sacristy which features an arched ceiling, rounded arch windows. A contemporary mural has been painted on the concrete walls of the former sacristy (Figure 21). To the east of the altar is an office, which has a large painted stained glass window and a rounded arch door.




Figure 21. Former sacristy, with a contemporary painted mural. Source: Page & Turnbull, April 2019.

A non-original steel frame, open mezzanine with concrete floors runs along the full length of the aisles and crosses over the nave, just north of the transept (Figure 22). A metal balustrade with thin metal quatrefoil panels surrounds the mezzanine (Figure 23). Although the mezzanine runs along the exterior walls, it is not attached to the walls. Seating areas, divided by hanging curtains, are located along the aisle, below the mezzanine. On the ground floor of the east transept, at the former location of the confessionals, partition walls enclose a restroom area which features four narrow toilet rooms and two larger, accessible toilet rooms. On the ground floor of the west transept, is a free-standing open servery (Figure 24). The mezzanine level is accessed via straight stairs along the west wall of the west transept and a wheelchair elevator at the west end of the apse (Figure 25).




Figure 22. Non-original mezzanine along the aisles and spanning the nave, looking north. Source:
Page & Turnbull, April 2019.




Figure 23. Mezzanine balustrade, looking down toward the nave. Source: Page & Turnbull, April 2019.




Figure 24. Servery area below the mezzanine in the west transept, looking northwest. Source: Page & Turnbull, April 2019.




Figure 25. Wheelchair elevator accessing the mezzanine at the west end of the apse, looking south. Source: Page & Turnbull, April 2019.

Restrooms are located at either end of the east transept at the mezzanine level, behind a partial-height museum style wall (Figure 26). A marble, former alter has been converted to feature a sink at either end. A small gallery is located at the mezzanine level, east of the apse (Figure 27). A free-standing bar area, and partial-height storage area is located in the west transept at the mezzanine level. The two towers, located east and west of the narthex and choir loft, feature large stained glass lancet windows, rose windows, and non-original, metal-frame seismic bracing and concrete shear walls. A rope in the east tower operates an original bell (Figure 28). A non-original, free-standing spiral metal staircase accesses a small room above the lancet windows in the west tower (Figure 29). The church also has a one-room basement in the southwest corner of the building accessed by an exterior staircase.




Figure 26. View of mezzanine level east transept. Restrooms are located behind the partial-height wall. Source: Page & Turnbull, April 2019.




Figure 27. Restrooms, including a marble alter converted to sinks, on the mezzanine level of the east transept. Source: Page & Turnbull, April




Figure 28. West tower, featuring seismic bracing and a spiral staircase. Source: Page & Turnbull, April 2019.




Figure 29. Small room at top of west tower, with rose windows. Source: Page & Turnbull, April 2019.

# Site

The south and west perimeters of the site, which abut adjacent properties, are lined by a chain-link fence. A courtyard at the northwest corner of the site, a landscaped area at the northeast corner, and a parking area at the southeast corner, are all enclosed by metal fencing. A small garage constructed in 1960 (220 10th Street), located southeast St. Joseph's Church, was demolished in 2018 and the area was paved with scored concrete. The parcel on which the garage was located, APN 3517/036, is owned by 1401 Howard LLC, located within the same fenced area as St. Joseph's Church, and is currently used as parking area for St. Joseph's Church (Figure 30). A palm tree located north of St. Joseph's Church was retained and is surrounded by a low concrete planter. The area along the west side of St. Joseph's Church features a courtyard and walkways with herringbone pattern stone paving (Figure 31). Plantings line the perimeter of the courtyard and walkways, and various benches, fountains, and sculptural elements are installed throughout.



Figure 30. Concrete parking area southeast of St. Joseph's Church, at the former location of the garage, looking south.




Figure 31. Courtyard at northwest corner of the site, looking north.

# Surrounding Buildings

There are four buildings in the immediate vicinity that were formerly associated with St. Joseph's Church. These include a rectory constructed in 1908 (1415 Howard Street), a parish hall constructed in 1907 that served as a temporary church and school until the completion of the main sanctuary (240 10th Street), a convent constructed in 1961 (244 10th Street), and a school constructed in 1960 (250 10th Street). These buildings are located on individual parcels separate from the subject property and are not owned by 1401 Howard LLC. They are no longer associated with St. Joseph's Church.

# **BIBLIOGRAPHY**

# A. Published

Burns, Jeffrey M. San Francisco: A History of the Archdiocese of San Francisco, vols. I-III. Strasbourg, France: Editions du Signe, 1999.

Byington, Lewis Francis, and Oscar Lewis, eds. *The History of San Francisco*, vol. III. Chicago: S.J. Clarke Publishing Co., 1931.

Davis' Commercial Encyclopedia (1911). In San Francisco Architectural Heritage, Vertical Files: "Foley, John J."

Willard, Ruth Hendricks and Carol Green Wilson. Novato, CA: Presidio Press, 1985.

# B. Public Records

San Francisco Assessor's Office

San Francisco Department of Building Inspection. Building Permit Applications

San Francisco Planning Department

San Francisco Public Library

San Francisco Public Library Historical Photograph Collection

Sanborn Fire Insurance Maps (San Francisco). 1889, 1899, 1913, 1950, 1986.

### C. Newspapers and Periodicals

Architect and Engineer

San Francisco Call-Bulletin

San Francisco Chronicle

San Francisco Examiner

VerPlanck, Christopher. "South of Market Architecture." San Francisco Apartment Magazine (August 2002).

# D. Unpublished Drawings and Manuscripts

Archdiocese of San Francisco Archives.

"Final Case Report: St. Joseph's Church & Complex." San Francisco Landmarks Preservation Advisory Board Nomination Form. 5 March 1980.

Foley, John J. "St. Joseph's Parish Convent." Plans, 1911.

"History of St. Joseph's Parish." Diamond Jubilee of St. Joseph's Church: 1861-1936. San Francisco: unpublished pamphlet, 29 October 1936.

- Republic Urban Properties. "St. Joseph's Church: a Tool for Political and Historical Reference." San Francisco: unpublished report, 2 November 2007.
- "St. Joseph's Church and Complex." National Register of Historic Places Nomination Form. 23 November 1981.
- St. Paul Fire and Marine Insurance Company. "St. Joseph's Church." (San Francisco: unpublished case report, 1 October 1946). In Archdiocese of San Francisco Archives.

San Francisco Architectural Heritage. Vertical Files: "220 10" Street,"
Vertical Files: "1401 Howard Street."
Vertical Files: "1415 Howard Street."
Vertical Files: "Foley, John J."

Smith, Wilton, San Francisco, to Rev. Msgr. Harold E. Collins, San Francisco, 26 December 1952. In Archdiocese of San Francisco Archives.

# E. Internet Sources

- Archdiocese of San Francisco. <a href="http://www.sfarchdiocese.org/sfparishes.html">http://www.sfarchdiocese.org/sfparishes.html</a> (accessed 29 November 2007).
- ArchitectDB. <a href="http://digital.lib.washington.edu/php/architect">http://digital.lib.washington.edu/php/architect</a> (accessed 1 November 2007).
- Bower, Mark A. "Putting Offices in the Sanctuary: Utilizing Rehabilitation Tax Credits for Adaptive Reuse of Religious Buildings." *Inspired* (March-April 1989) pp.4-6, 8, 16-17. In Partners for Sacred Places <a href="http://www.sacredplaces.org/free">http://www.sacredplaces.org/free</a> articles.htm (accessed 27 November 2007).
- National Park Service. *Preservation Briefs.* <a href="http://www.nps.gov/history/hps/tps/briefs/brief02.htm">http://www.nps.gov/history/hps/tps/briefs/brief02.htm</a> (accessed 27 November 2007).
- National Trust for Historic Preservation. *Preserving Historic Religious Properties* (June 2005). <a href="http://www.nationaltrust.org/issues/downloads/worship">http://www.nationaltrust.org/issues/downloads/worship</a> preserving toolkit.pdf (accessed 27 November 2007).

# **EXISTING CONDITIONS & TREATMENT RECOMMENDATIONS (2014)**

The following existing conditions and treatment recommendations were developed by Page & Turnbull in 2014, prior to the rehabilitation/restoration project which was completed in the summer of 2018.

#### **EXTERIOR**

Perimeter Fence

#### Description

A discontinuous metal fence is located around the perimeter of the property. At the northwest and southeast corners of the property, the fence rests on a brick curb with brick piers. At the northeast corner, a non-historic metal fence rests on a concrete curb without piers. A gated driveway in the fence on Howard Street provides vehicular access to the church and the garden area on the west side of the property. A double metal gate on 10th Street provides access to the church and the garden area at the northeast corner of the property. A single metal gate on 10th Street provides access to the rear of the church.

# Condition

The condition of the fence, gates, curbs, and piers varies from poor to good condition. The following deterioration was observed:

- Corroded metal at some locations where the fence is set into the curb (Figure 32a and Figure 32c).
- Graffiti at some locations (Figure 32c).
- Gaps and voids at some curb and pier attachments (Figure 32c).
- Damage to the metal fence at the northeast corner of the property caused by an automobile collision (Figure 32b).
- Piers are displaced in some locations (Figure 32a).

# Recommended Treatments

- The direction of the swing of all gates should be reversed to be in the direction of egress. The gates should be prepared, primed, and painted, and latch and lock sets should be provided. The original hinges should be retained at the piers.
- At the gate on Howard Street, the mortar joints should be cut to reveal the corroded fence and gate anchors that have displaced the brick piers. The metal should be repaired and painted, and the displaced sections of the piers should be reset in the original locations and grouted. The cement plaster parge should be repaired as required to match the original.
- The fence should be prepared, primed, and painted. The gaps and voids should be filled with mortar at the base and column attachments. Where the fence is set into the curb and is corroded, the metal should be repaired, painted, and set into lead or sealant as required to prevent future damage to the fence or curb.
- At the piers, the cement plaster parge should be cleaned and graffiti should be removed or painted over. The cement plaster parge should be repaired to match the existing adjacent color and texture as required.
- At the west tower, the attachment of the fence to the building and piers should be repaired.

## Granite Steps

## **Description**

Granite steps are found at all main entrances to the church including the main portal at Howard Street, and both north and south entrances to the east and west transepts. The main portal steps are composed of six tiers of square-cut granite blocks of varying dimensions. The four entrances to the transepts feature granite treads embellished with a decorative bull nose reveal, and vary from two tiers of tread at the north entrance of the east transept, to five tiers of tread at the east transept's south entrance.

## Condition

The granite steps are generally in good condition. The following deterioration was observed:

- Mortar loss, particularly in the vertical joints of the main portal steps (Figure 33a).
- Uneven settling of the east side of the main portal steps evidenced by the approximately 1.5-inch gap between the third and fourth step (Figure 33b).
- Biological growth and soiling (Figure 33c).
- Paint spatters (Figure 33a).
- Spalling surface of the granite (Figure 33d and Figure 33e).

## Recommended Treatments

- Existing joints should be raked out and cleared of debris.
- Vertical and horizontal joints should be repointed with a compatible mortar chosen to match the color of the original mortar.
- Uneven settling between the blocks should be monitored and a structural engineer consulted regarding future treatment.
- Algae, moss and other biological growth should be removed with a biocide, water and light brushing with a natural, soft bristle brush. Mock-up tests should be conducted to determine the most effective product and appropriate dwell time.
- Soiling should be removed with the gentlest means possible. This may include a non-ionic
  detergent in water and light scrubbing with a natural, soft bristle brush, or the use of a commercial
  stone-cleaner. Mock-up tests should be conducted to determine the most effective product and
  appropriate dwell time.
- Paint spatters should be removed with a commercial paint stripper. Tests should be conducted to determine the most effective product and appropriate dwell time.
- Stone spalling is likely caused by rising moisture or salts. Further study should be carried out to
  determine the root cause of the spalling, and it should be addressed before any treatment is
  carried out.
- Because of the shallow depth of the spalled areas and the difficulty of matching the stone color, patching is not recommended. Spalled areas can be retooled, reducing the surface of the stone by approximately 1/8 1/4 inch, in order to give the tread a smooth surface.

#### Stucco

## Description

St. Joseph's Church is constructed of steel reinforced brick masonry covered in stucco, which is incised to resemble finished stone blocks, arches and corbelling, and used to form columns, capitals and other decorative elements. The stucco veneer is approximately 1-2 inches thick and covers the entire exterior

of the building, except for the cornice and upper portions of the towers, which are constructed of sheet metal.

## Condition

The stucco is generally in good condition. The following deterioration was observed:

- General staining and soiling, particularly at upper surfaces near the cornice, and lower surfaces at ground level (Figure 34a).
- Extensive hairline cracking (Figure 34a).
- Spalling, detachment and large areas of stucco loss (Figure 34b).
- Vegetation growth (ivy).

#### **Recommended Treatments**

- The existing stucco should be analyzed to determine if it is lime or Portland cement-based. Repairs made with an incompatible stucco formula are likely to fail. These tests can be performed by an architectural conservator.
- Staining and soiling should be removed by the gentlest means possible, this may include light brushing and water washing, poulticing, or cleaning with a commercial agent. Mock-up tests should be conducted to determine the most effective product and appropriate dwell time.
- Areas of significant hairline cracking should be analyzed to determine the root cause of the condition. Investigation may include testing for underlying detachment of the stucco layer, moisture intrusion, structural movement or other causes.
- Climbing vegetation such as ivy should be removed and killed with an herbicide. Because many herbicides contain salts that can damage historic masonry, mock up tests should be conducted to determine an effective product that does not contain salts.
- Spalls and cracks through cement plaster should be repaired. The crack should be routed and patched to match the existing adjacent texture, profile, and appearance.
- The existing deteriorated or detached cement plaster should be removed. New cement plaster should be installed that is compatible with the substrate and the existing plaster to remain.
- Unsound paint should be removed and coated with a new breathable paint coating.

## **Exterior Lighting**

#### Description

In 2007, two historic lighting fixtures were mounted above the main entry to the church on Howard Street. They have since been removed.

#### Conditions

In 2007, the historic exterior lighting fixtures appeared to be in good condition (Figure 35a). The current whereabouts of the historic lighting fixtures are unknown. The original mounting hardware remains in place on the north façade of the church (Figure 35b).

## Recommended Treatments

Attempts should be made to locate the historic lighting fixtures. It is possible that they are currently being stored inside the church. If they are not found, new light fixtures that replicate the missing original fixtures should be fabricated and installed.

#### Roof

#### Description

The main roof is capped by a cross-gabled roof with slate tiles and features a skylight over the main altar. Parapets with metal coping are located at the gable ends of the main roof. The portals over the entrances to the transepts are also capped by gable roofs with slate tiles. The aisles and auxiliary interior spaces are capped by built-up shed roofs. The two towers are capped by painted sheet metal cupolas with gilded sheet metal domes. Various roof elements are sheet metal, including the ridge vent at the main roof, the skylight, the cupolas and gilded domes, and the crosses on top of the towers and above the pediment of each transept.

## Conditions

The slate tile roof is generally in good condition. The built-up roof has reached the end of its serviceable life. The condition of the sheet metal cupolas and gilded domes range from poor to fair. The gilded crosses appear to be in good condition. The following deterioration was observed:

- There are several broken, loose, or missing slate tiles at the main roof (Figure 36d).
- There are many instances of rust-through at the painted sheet metal cupolas (Figure 36a and Figure 37c).
- Surface corrosion and loss of paint and gilding is evident at domes (Figure 36c and Figure 37c).
- The crosses require minor sheet metal and gilding repair (Figure 36b).

## **Recommended Treatments**

- Existing slate roof tile at the main roof and portals should be removed, salvaged, and reinstalled to allow access for structural stabilization of the roof structure. Deteriorated and broken tiles should be replaced with salvage stock or new tile to match the existing. New felt underlayment and galvanized flashing should be installed.
- Existing built-up roofing at the lower roofs should be removed, and new built-up roofing should be installed over new structural decking.
- Roof, flashing, gutters and other drainage system elements should be repaired to ensure that water does not enter the structure. Gutters and downspouts should be cleaned, and drainage spouts should be extended beyond the foundation of the building with flexible tubing.
- Additional or larger downspouts may be required for proper roof drainage. Replace with similar.
- The existing metal skylight should be restored and painted. New tempered glazing and sealant should be installed.
- Sheet metal crosses should be removed and salvaged for reinstallation. They should be cleaned and touched up with new gilding to match the existing.
- Paint and gilding should be removed over the sheet metal domes. Deteriorated sheet metal should be repaired or replaced to match the original profile and appearance. A gold paint should be used to closely match the gold leaf appearance:

#### Sheet Metal Architectural Elements

## Description

Pressed, painted sheet metal is used extensively at St. Joseph's Church for ornate architectural elements, particularly for the cornices of the main structure and the upper third of both towers. The gilded domes of the towers, as well as the crosses on top of the towers and above the pediment of both transepts are constructed of sheet metal. The ridge vent at the main roof is sheet metal. Additionally, the central columns and bases of the towers' double windows are sheet metal.

## Conditions

The sheet metal elements are generally in fair condition. The following deterioration was observed:

- Cracking, flaking and loss of the protective paint layer (Figure 37a).
- Corrosion (rusting) of the sheet metal units and connections, causing perforation and rust staining, particularly at the cornice level and upper towers (Figure 37b).
- Loss of paint, gilding and architectural details, particularly on the towers (Figure 37c).

## Recommended Treatments

- Scrape and sand peeling or blistering paint.
- Remove corrosion with hand scrapers or a wire brush.
- For panels with heavy corrosion and resulting perforation of the sheet metal unit, there are four options:
  - 1. Remove corroded panel and replace unit with a new piece of sheet metal cut to the appropriate dimension and profile;
  - 2. Cut out corroded area of existing sheet metal, braze weld a new piece and grind joint flat;
  - 3. Cut out corroded area of existing sheet metal, paint, and install painted matching sheet metal patch with mechanical fasteners and a neoprene gasket; or
  - 4. Cut out corroded area of existing sheet metal and install steel filled epoxy compound to patch small holes.
- Paint all exposed metal with a rust-inhibiting primer, and two coats of color appropriate outdoor paint.
- Missing elements should be replaced to maintain visual consistency. Further research should be conducted to determine the best replacement material, or if sheet metal replicas can be made.
- Sheet metal parapet cap flashing should be replaced with new painted galvanized or stainless steel sheet metal to match the existing profile.

Wood-Sash Windows and Tracery

#### Description

The windows of St. Joseph's Church are generally fixed wood-sash designed to contain an inner layer of stained glass and an outer, protective layer of translucent glass. Ornate wooden tracery frames the formerly stained glass rose windows of the front façade and east and west transepts, and wooden tracery is used minimally in the apse and clerestory windows of the nave and transepts. Textured, clear glass, originally designed to protect the stained glass, remains in place throughout the building. All window frames are painted beige, in imitation of the faux stone stucco. The long double windows and small rose windows of the towers, and the south facing window of the kitchen, are the only exterior windows that retain original stained glass.

### Conditions

The wood window tracery generally ranges from good to poor condition, with the poor condition more evident on the southern and western exposures. The following deterioration was observed:

- Breakage or loss of glazing, causing accelerated deterioration of stained glass, surrounding wood, adjacent masonry, and interior plaster (Figure 38a).
- Rotting, separation and bowing of wooden tracery elements (Figure 38b).
- Cracking, flaking and loss of surface paint (Figure 38c).
- Deterioration and loss of glazing compound.

#### **Recommended Treatments**

- A detailed conditions assessment of windows at St. Joseph's Church is necessary to determine the extent of deterioration and appropriate treatments at each window. This should include careful inspection and documentation of each window frame and its conditions, resistance and moisture testing to determine the extent of wood deterioration, wood type identification, and other noninvasive diagnostic tests.
- Any repair of the window frames should attempt to retain as much original material as possible while providing adequate protection for the building, and may include paint removal, treatment of rotted wood with a fungicide and consolidation with epoxy fillers, splicing of new wooden elements in areas of severe deterioration, and replacement of all glazing compound.

#### INTERIOR

Marble Wainscoting and Floor Tiles

#### Description

Polished marble wainscoting lines the lower walls of the vestibule. The wainscoting is composed of a 3-4-inch border of white and black striated, mitered marble strips, surrounding central panels of white marble with grey/black inclusions. The base board and upper border of the wainscoting are made of a darker black and white striated marble. Floor tiles of the vestibule are made of white marble surrounded by a border of grey marble and are covered by modern vinyl tiles at the vestibule and an older type of tile at the adjacent baptistery.

## Conditions

The marble wainscoting and tiles in the vestibule are generally in good condition. The following deterioration was observed:

- Light soiling and wear of the polished surface (Figure 39a and Figure 39b).
- Soiling and chipping of the baseboard (Figure 39a).
- Tape and adhesive residue from former signs posted on the wainscoting (Figure 39b).
- Vinyl tile at the vestibule is lightly adhered to the underlying marble floor.
- A more robust tile is securely adhered to the marble tile of the baptistery. The tile and its mastic may contain asbestos or other hazardous materials.

## **Recommended Treatments**

- Tape residue and soiling should be removed with a gentle stone cleaner. Mock-ups should be conducted to determine the most effective product.
- Tiles in the vestibule should be removed without causing damage to underlying marble, which should be cleaned with a gentle stone cleaner to remove staining and adhesive. Mockups should be conducted to determine the most effective product.
- Tiles and mastic should be removed from the baptistery floor and cleaned using the gentlest means possible. The floor should be polished or honed as required.

#### Decorative Plaster

#### Description

Painted plaster is used to create moldings, cornices, columns and decorative details, such as the coffered ceilings that contribute to the interior's sense of grandeur and define distinct architectural spaces.

## Conditions

The decorative plaster is generally in fair condition. The following deterioration was observed:

- Moisture penetration from blocked drainage and broken or missing window glazing (Figure 40 a and Figure 41b).
- Sugaring and softening of moisture damaged decorative elements (Figure 40c).
- Structural cracks and detachment from underlying masonry (Figure 40d).
- Small areas of historic decorative painting are exposed where the paint is flaking.
- Non-historic wood veneer over plaster at the base of the wall.

## **Recommended Treatments**

- Sources of moisture such as broken glazing and blocked drainage should be repaired.
- Further testing of the plaster to determine the extent of deterioration should be conducted. This
  will determine if patching and reshaping damaged elements is possible, or if replacement is
  necessary.
- Detached or cracked plaster elements, if in otherwise sound condition, may be repaired with an injected epoxy or gypsum-based grout. Testing should be conducted to determine the most effective adhesive.
- A barrier coat should be installed to protect small areas of exposed decorative painting prior to repainting.
- Wood veneer should be removed. Plaster at base of the wall should be restored and painted.

## Oak Woodwork and Doors

## **Description**

Quarter sawn white oak is used extensively at St. Joseph's for the construction of decorative wooden elements such as doors, frames, column bases and railings. Woodwork is generally treated with a clear shellac or varnish.

## Conditions

The oak woodwork is generally in good condition. The following deterioration was observed:

- Blistering of the varnish (Figure 41a).
- General soiling from dust (Figure 41b).
- White stains from paint or pigeon guano (Figure 41b).

## **Recommended Treatments**

- Blistered varnish should be treated with the gentlest means possible in order to preserve the existing finish. Possible treatments include lightly scraping blistered areas of varnish and spottreating with fine steel wool or cotton, alcohol and a compatible varnish or shellac.
- Soiling should be cleaned with the gentlest means possible, using a soft bristle brush to remove loose dust and a damp cloth for tenacious soiling.
- White stains should be tested to determine if they are paint or guano. Paint and guano may be removed mechanically with a scraper taking care not to damage the existing wood finish.
- Where required by the level of damage, select areas should be refinished to match the original.
- Wood should be replaced where missing to match the original.
- At exterior doors, deteriorated wood should be repaired with wood Dutchman and should match the original species, grade, grain, and profile. The exterior should be prepared and painted. The interior should be cleaned and touched up or refinished to match the original stain or clear coat

#### Stained Glass

## Description

Extant stained glass windows at St. Joseph's Church include the multi-story double windows and rosettes of the towers, the window of the kitchen, and one remaining stained glass transom above the northeast transept door. The windows of the towers are made primarily of yellow and green diamond-shaped glass panes with lead cames, iron or steel saddle bars, and wood frames. The kitchen window is made of various colored glasses painted with black floral decoration, and is supported in a flat stock steel frame, the upper portion of which opens inward. The only remaining stained glass transom of the nave, covered from the interior with plaster board, appears to have a figurative or floral motif.

## Conditions

The stained glass windows are generally in poor condition. The following deterioration was observed:

- Loss of the protective outer glazing.
- General soiling (Figure 42a, Figure 42b, and Figure 42c).
- Sagging and bowing of lead cames (Figure 42b and Figure 42c).
- Cracking, breakage and loss of panes (Figure 42c).
- Inappropriate additions (Figure 42d).
- Corrosion of saddle bars (Figure 42e).

#### **Recommended Treatments**

- Because of the importance of the church's stained glass, immediate efforts to protect them should be made. This should include stabilization and protection measures determined in consultation with a professional stained glass conservator.
- Documentation and restoration of the windows should be performed by a professional conservator. As restoration is rarely preformed on site, it will likely include removal, transport, restoration, and reinstallation of the stained glass.

Where stained glass has been previously removed, the existing wood frame should be restored. The deteriorated areas should be removed back to sound wood substrate and an epoxy consolidant wood repair or wood Dutchman should be provided as required. The wood and steel armature remaining from the previous stained glass window installation should be prepared and painted. The frame should be modified to accept new ribbed protective heavy glass or dual glazing to match the original ribbed glass appearance.

# EXISTING CONDITIONS IMAGES PRIOR TO REHABILITATION/RESTORATION

All of the Existing Condition Photos were taken between 2011 and 2016 by Page&Turnbull




Figure 32a. Pier near west tower, showing large cracks and displaced areas of brick (arrow) and corroded metal fence.




Figure 32b. Damage to metal fence at northeast corner of property.




Figure 32c. Low brick wall along Howard Street, showing gaps and voids, corroded metal fence, and graffiti (painted over with mismatched paint).




Figure 33a. Main portal steps, showing soiling, paint stains and vertical joints without mortar.



Figure 33b. Detail, east side of main portal steps, showing gap between blocks (arrow) due to uneven settling.




Figure 33c. East transept, north portal steps, showing decorative bull nose with biological growth and soiling.



Figure 33d. West transept, south portal steps, showing paint stains (left), soiling and spalling surface (arrow).




Figure 33e. Detail, south portal steps, spalled surface of granite tread.




Figure 34a. East nave façade, showing soiling, water staining and hairline cracking of stucco.



Figure 34b. East tower, north façade, showing loss of stucco at ground level.




Figure 35a. Light fixtures (now missing) at main entry on north façade in 2007.



Figure 35b. Detail, original mounting hardware is all that remains in place.



Figure 36a. Detail, rust-through at painted sheet metal cupolas.




Figure 36b. The rooftop crosses require minor sheet metal and gilding repair.




Figure 36c. Detail, corrosion and loss of paint and gilding at domes.




Figure 36d. Broken, loose, and missing slate tiles at main roof.



Figure 37a. Column base, south side of east tower, showing flaking and loss of protective paint layer.




Figure 37b. Cornice above north portal, east transept, showing perforation (arrow) of the metal due to corrosion.




Figure 37c. East tower detail, constructed entirely of pressed sheet metal, showing missing architectural detail, loss of gilding and protective paint, and corrosion stains. Birds were nesting inside the towers.




Figure 38a. West tower, north window, showing broken protective glazing.



Figure 38b. East façade, transept window, showing soiling, paint loss and rotting/loss of tracery elements.



Figure 38c. West transept rose window, showing paint loss and missing glazing.




Figure 39a. Marble wainscoting of the narthex, showing soiling of the baseboard, wear of polished surface, and adhered tape. Original marble floor was covered with vinyl tile.



Figure 39b. Detail, showing tape and adhesive residue.




Figure 40a. West façade, showing blocked or perforated drainage which is causing damage to interior plaster.




Figure 40b. Deterioration of plaster caused by moisture from poorly sealed window.



Figure 40c. Softening and deterioration of decorative plaster elements caused by moisture from faulty roofing.




Figure 40d. Structural cracking and separation of plaster details from masonry substrate caused by moisture from blocked drains.




Figure 41a. Blistering of varnish on an oak door caused by moisture penetration.




Figure 41b. Dust (on molding) and paint/guano spatters can cause permanent damage to wood finish.




Figure 42a. North-east transept portal, showing blocked figurative stained glass window with heavy soiling and corrosion of steel frame




Figure 42 b. East tower, east windows, showing bowing of windows due to sagging lead cames or detachment from saddle bars.




Figure 42c. Breakage and loss of colored glass panes due to distortion of lead cames.




Figure 42d. Kitchen window, showing partition partially covering painted stained glass.




Figure 42 e. Upper portion of window showing corroded hopper-type opening assembly.

## IV. 1401 HOWARD STREET ADDITIONAL PHOTOGRAPHY

## PHOTOS AFTER REHABILITATION/RESTORATION




Figure 43. Perimeter fence and gate along Howard Street. View southwest. (Page & Turnbull, 05/25/2018)

Figure 44. Perimeter fence and gate along 10th Street at the northeast corner of St. Joseph's Church. View southwest. (Page & Turnbull, 05/25/2018)




Figure 45. Perimeter fence and gate along 10<sup>th</sup> Street at the southeast corner of St. Joseph's Church. View northwest. (Page & Turnbull, 05/25/2018)



Figure 46. Main portal steps. (Page & Turnbull, 05/25/2018)




Figure 47. North portal on east transept. (Page & Turnbull, 05/25/2018)




Figure 48. Detail, North portal stairs on east transept. (Page & Turnbull, 05/25/2018)




Figure 49. Exterior landing on west façade between west transept and sacristy. (Page & Turnbull, 05/25/2018)




Figure 50. East façade, showing stucco condition after restoration (Page & Turnbull, 05/25/2018).




Figure 51. East façade, showing stucco condition after restoration (Page & Turnbull, 05/25/2018)




Figure 52. West façade, showing stucco condition after restoration (Page & Turnbull, 05/25/2018).




Figure 53. Exterior lighting fixture above main entrance on north façade (Rich Stapleton, 05/21/2018)




Figure 54. Detail, gilded sheet metal dome and cross. (Palisade Builders, 05/20/2018)



Figure 55. Gilded sheet metal dome and top of sheet metal cupola. (Palisade Builders, 05/20/2018)



Figure 56. Main roof after restoration. (Palisade Builders, 05/20/2018)




Figure 57. Column capitals at the main entry façade after restoration. (Rich Stapleton, 05/21/2018)




Figure 58. Cornice above main entry façade after restoration. (Rich Stapleton, 05/21/2018




Figure 59. East tower detail after restoration (Rich Stapleton, 05/21/2018).




Figure 60. West tower, north window after restoration (Rich Stapleton, 05/21/2018).



Figure 61. East façade, transept window after restoration. (Palisade Builders, 05/20/2018)




Figure 62. West transept rose window after restoration. (Palisade Builders, 05/20/2018)




Figure 63. Marble wainscoting and interior doors of the narthex, after restoration (Page & Turnbull, 05/25/2018)



Figure 64. Narthex, view toward west tower. (Rich Stapleton, 05/21/2018)




Figure 65. Interior view toward main altar. (Page & Turnbull, 05/25/2018)




Figure 67. Interior view toward choir loft from the bridge. (Rich Stapleton, 05/21/2018)




Figure 66. Interior view of west transept. (Page & Turnbull, 05/25/2018)




Figure 68. East aisle, view toward choir loft. (Page & Turnbull, 05/25/2018)




Figure 69. Detail, plaster arches. (Rich Stapleton, 05/21/2018)




Figure 71. East aisle and transept towards main altar from the second floor. (Rich Stapleton, 05/21/2018)




Figure 70. Typical clerestory window with protective glazing, interior view. (Rich Stapleton, 05/21/2018).




Figure 72. Painted medallions from inside the half-dome. (Rich Stapleton, 05/21/2018)




Figure 73. Oak door from the main altar to Room 115 (Page & Turnbull, 05/25/2018)




Figure 75. East tower, east windows after restoration (Page & Turnbull, 05/25/2018)




Figure 74. Wood finish detail after restoration (Page & Turnbull, 05/25/2018).




Figure 76. Detail, stained glass window. (Page & Turnbull, 05/25/2018)




Figure 77. Detail, stained glass window. (Page & Turnbull, 05/25/2018).




Figure 78. Detail, stained glass window. (Page & Turnbull, 05/25/2018)





Figure 79. Stained glass window (Rich Stapleton, 05/21/2018)

# V. SITE PLAN

10TH STREET (80' WIDE R/W)



### VI. TAX BILL



City & County of San Francisco José Cisneros, Treasurer David Augustine, Tax Collector Property Tax Bill (Secured)
For Fiscal Year July 1, 2018 through June 30, 2019

1 Dr. Carlton B. Goodlett Place City Hall, Room 140 San Francisco, CA 94102 www.sftreasurer.org

				i jear July 1, 2018 tillough Ju		
Voi	Rinck	Lot	Tax Bill No	Mail Date	Property Location	
23	.3517	035	115187	October 12, 2018	1401 HOWAF	RD ST
	ed on Januar		12:01am		Assessed Value	
To:	1401 HOW	ARD LLC		Description	F-CB Value	Tax Amount
				Land	542,570	6,310.08
8	140	HOWAR	D LLC	Structure	15,254,027	. 177,411,31
02223D	850	7TH STRE	FT	Fixtures		
-		,	CO CA 94107	Personal Property		
	SAN	PRANCIS	CO CM 94107	Gross Taxable Value	15,797,197	183,721.40
				Less HO Exemption	•	
				Less Other Exemption	1	
				Net Taxable Value	15,797,197	\$183,721.40

Code	Турс	Telephone	Amount Due
45	LWEA2018TAX	(415) 355-2203	298.00
46	SF BAY RS PARCEL TAX	(510) 286-7193	12.00
89	SFUSD FACILITY DIST	(415) 355-2203	37.52
91	SFCCD PARCEL TAX	(415) 487-2400	99.00
98	SF - TEACHER SUPPORT	(415) 355-2203	251.96

► TOTAL	. DUE		\$184,419.88
istli	stallment	2nd	Installment
	\$92,209.94		\$92,209.94
DUE	12/10/2018	DUE	04/10/2019

City & County of San Francisco Property Tax Bill (Secured) For Fiscal Year July 1, 2018 through June 30, 2019 Pay online at www.sftreasurer.org

\$698.48

						·
4	Vol	Block	Lot	Tuk Bill No	Mail Onte	Property Lucition
-	-23	3517	035	115187	October 12, 2018	1401 HOWARD ST

Check if contribution to Arts Fund is enclosed.
For other donation opportunities go to www.Give2SF.org

Total Direct Charges and Special Assessments

Detach stub and return with your payment Write your block and lot on your check. 2nd Installment cannot be accepted unless 1st is,

San Francisco Tax Collector Secured Property Tax P.O. Box 7426 San Francisco, CA 94120-7426

San Francisco, CA 94120-7426

2nd Installment Due \$92,209.94

If paid or postmarked after APRIL 10, 2019 the amount due (includes delinquent penalty of 10% and other applicable fees) is:

2335170003500 115187 00000000 00000000 0000 2003

City & County of San Francisco Property Yax Bill (Secured)
For Fiscal Year July 1, 2018 through June 30, 2019 Property Location 1401 HOWARD ST 3517 035 115187 October 12, 2018 Check if contribution to Arts Fund is enclosed.
For other donation opportunities go to www.Give2SF.org 1st Installment Due Detach stub and return with your payment. Write your block and lot on your check. \$92,209.94 If property has been sold, please forward bill to new owner. If paid or postmarked after **DECEMBER 10, 2018** the amount due (includes definquent penalty of 10%) is: San Francisco Tax Collection Secured Property Tax P.O. Box 7426 \$101,430.93

2335170003500 115187 000000000 00000000 0000 1003

### VII. RENTAL INCOME INFORMATION


### 1401 HOWARD RENTAL INCOME

Full rental agreement is 332 pages which is available on request. 100% of the building is rented.

Base Rent

	Master Lease
Year `	Expense
2016	\$ -
. 2017	176,780
2018	710,000
2019	720,650
2020	731,460
2021	742,432
2022	753,568
2023	764,872
2024	776,345
2025	787,990
2026	799,810
2027	811,807
2028	823,984
2029	836,344
2030	848,889
2031	861,622
2032	874,547
2033	887,665
2034	900,980
2035	914,494
2036	928,212
2037	942,135
2038	956,267
2039	970,611
2040	985,170
2041	999,948
2042	1,014,947
2043	1,030,171
2044	1,045,624
2045	1,061,308
2046	1,077,228
2047	1,093,386
2048	1,109,787
2049	1,126,434
	<u>\$29,065,465</u>

<sup>\*\*</sup>Base Rent for the first and final Lease Year shall be determined based on the rent commencement date agreed to by Master Landlord and Master Tenant in the Rent Commencement Notice as set forth in Section 3.1 hereof.



# UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

OMB Approved No. 1024-0009 Form 10-168 Rev. 2014

# HISTORIC PRESERVATION CERTIFICATION APPLICATION PART 3 - REQUEST FOR CERTIFICATION OF COMPLETED WORK

NATIONAL PARK SERVICE

Commence of the second second	TIVE PROGRAM	al de la companya de		NP8 Project Numb	₽
	is page must bear the appli	cant's original signature and must be	deled;	. 27025	**************************************
. Property I	Name St Joseph's Chu	urch	Will distribution to the control of		•
Street 140	01 Howard Street		· · · · · · · · · · · · · · · · · · ·		
F		County San F	rancisco	State CA	Zip 94103
		? ⊠ yes ☐ no lifyes, dete of NP			
Project Da		•	A the second state of the second seco	• ,	A Market of the section of the secti
Project start	t date _12/01/2015		Project completed and buil	ding placed in service date	12/27/2017
Estimated re	ehabilitation costs (QRE)	\$18;643,054	. Total estimated costs (QRE		
		ehebilitation0/0	Number of low-moderate h	ousing units before/after re	habilitation/
Project Co	ontact. (if different from a	pplicant)			
Name Rut	th Todd, Principal	<u>renamina</u>	Company Page	& Tumbull, Inc	· · · · · · · · · · · · · · · · · · ·
Street 417	7 Montgomery Street		City San Francisco	·	State CA
zip <u>.9410</u>	7. Telephon	4155933234	Email Address ruthtodd@pa	age-tumbull.com	
Applicant	List all additional owners	on next page.	Parameter (Parameter ) and the		AND THE COMMENT OF THE PROPERTY OF THE PROPERT
statement (s (1) (2011). F representati up to 8 year	<ul> <li>a) either is attached to this For purposes of this attests tions in this epplication may rs.</li> </ul>	cilon I am taking relative to this appli application form and incorporated he alion, the singular shall include the pi subject me to fines and imprisonme	erein, or has been previously su ural wherever appropriate. I und nt under 18 U.S.C. § 1001, whit	bmitted, and (b) meets the lenstand that knowing and v th, under certain circumsta	requirements of 96 CFR § 67,3(a) villful falsification of factual nces, provides for imprisonment of
		ative), Donotas Ross, Ren Folk Sto			
		Communication of the communica		•	•
Street 850	07th Street		City San Francisco	FF 3	State CA
zip 9410	07 Telephon	ne 4154454670	Email Address _cfoley@gr	oundmatrix.com	<u></u>
	cant, SSN, or TIN has ohen	iged since previously submitted appl			
	cant, SSN, or TIN has chan see no additional owners t	within the meaning of "owner" set for	th in 36 CFR 6 67.2 (2011).		
There	cant, SSN, or TIN has chan e are no additional owners v ise Only	within the meaning of "owner" set for	th in 36 CFR § 67,2 (2011).		
There S Official U  National Park I  the complet applicable, rehabilitatio interpretatio of the Secret completion form and au	cant, SSN, or TIN has chan a are no additional owners to lise Only  Service has reviewed the Hist ted rehabilitation meets the the district in which it is locu on." This certification is to be clist of the infernet Revenue etary to determine it the wo of the rehabilitation and to	within the meaning of "owner" set for toric Preservation Certification Applicated Secretary of the Interior's Standards ated. Effective the date indicated between the conjunction with appropriate Code should be addressed to the Intervoke certification, if it is determined the owner, upon obtaining certification.	th in 36 CFR § 67.2 (2011).  n - Request for Certification of Coffee Rehabilitation and is consist by, the feshabilitation of the "cert is internal Revenue Service, Completimal Revenue Service, Completion. The Secretary reserves the their the rehabilitation project w	mpleted Work (Pert 3) for this ent with the historic charact fied historic structure? Is he telfjons. Questions concerni sted projects may be inspec- er right to make inspections as not undertaken as prese as not undertaken as prese	property and his determined that:  Let of the property and, where  reby designated a "certified  ng specific tax consequences or  tied by an authorized representative  at any time up to five years after  inted by the owner in the application
There  S Official U  Note National Park is the complete applicable, rehabilitation of the Secre completion form and at with the Secre completion interpretation historic distributional completion form and at the Secre completion and at the Secretary completion and at the Secretary completion and at the Secre	cant, SSN, or TIN has chan a are no additional owners of the Only  Service has reviewed the Hist ted retrabilitation meets the the district in which it is loce on. This certification is to be one of the Infernet Revenue etary to determine it the wo of the rehabilitation and to upporting documentation, or uppering documentation, or uppering documentation, or uppering determine it relevant to the rehabilitation meets the on cannot be designated a " strict in which it is located is on." It is the owner asspon ons of the Internat Revenue etary to determine if the wo of the rehabilitation and to	within the meaning of "owner" set for income the meaning of "owner" set for Secretary of the Intertur's Standards ated. Effective the date Indicated between the Code should be addressed to the Indicated between the Code should be addressed to the Indicated between the Standards for Rehabilitarevoke certification, if it is determined the owner, upon obtaining certification.  Secretary of the Interior's Standards certified rehabilitation.  Secretary of the Interior's Standards certified rehabilitation. Editional Register of Histolication than the National Register of Histolication in the National Register of Histolication. The Code should be addressed to the Infinite media the Standards for Rehabilitarevoke certification, if it is determined the owner, upon obtaining cirtification in the cavitification of the contribution of the cavitification of t	th in 36 CFR § 67.2 (2011).  In - Request for Certification of Co- for Rehabilitation and is consist w, the rehabilitation of the "cert w, the rehabilitation of the "cert is intermal Revenue Service, Completion. The Secretary reserves the their the rehabilitation project woon, undertook unapproved furth for Rehabilitation. However, be teral tex credits at this time. It w one Places. On that date, the cr ters state flistoric Preservation C ternal Revenue Service. Complet dition. The Secretary reserves the It has the rehabilitation project w	impleted Work (Part 3) for this ent with the historic charactied historic structure" is he lations. Questions concerning the projects may be impected in the make inspections as not undertaken as prese er alterations as part of the course this property is not yell the course a "certified history mighted rehabilitation will a fiftier. Questions concerning the right to make inspections as not undertaken as prese	property and his determined that:  Let of the property and, where  reby designated a "certified  ng specific tax consequences or  tad by an authorized representative  at any time up to five years after  nited by the owner in the application  rehabilitation project inconsistent  at a "certified historic structure," the  fic structure" on the date it or the  nited management of the presentative  at any time up to five years  at eny time up to five years  at each tim
There  S Official U  National Park is the complete applicable, rehabilitation interpretation of the Secretary with the Secretary interpretation interpretation interpretation of the Secretary application interpretation of the Secretary interpretation interpretation interpretation of the Secretary in the Secretar	cant, SSN, or TIN has chan e are no additional owners to lise Only  Service has reviewed the Hist ted restrabilitation meets the the district in which it is loca on. This certification is to be oris of the infermet Revenue etary to defermine it the wo of the enhabilitation and to upperfing documentation, o orcetary's Standards for Ref- on cannot be designated a " strict in which it is located is on." It is the owner's respon ons of the Internat Revenue etary to determine if the wo of the rehabilitation and to upperfitting documentation, and or the properties of the relation of the testing to determine if the wo of the rehabilitation and to upperfitting documentation, a ceretary's Standards for Ref- litation is not consistent with	within the meaning of "owner" set for income preservation Certification Applicate Secretary of the Intertur's Standards and Effective the date Indicated between the Code should be addressed to the In it was the Standards for Fierbolitz revoke certification, if it is determined the evener, upon obtaining certification of the evener, upon obtaining certification is Secretary of the Interior's Standards certified rehabilitation, eligible for Fellisted in the National Register of his isolitate to be anouth be addressed to the in the measure should be addressed to the information of the owner, upon obtaining certification, if it is determined the owner, upon obtaining certification abilitation.	th in 36 CFR § 67.2 (2011).  In - Request for Certification of Coffee Rehabilitation and is consist by, the rehabilitation of the "certification rehabilitation of the "certification rehabilitation project won, undertook unapproved furth for Rehabilitation, However, be leral tex credits at this time. It works a like the consideration of the Rehabilitation of the Revenue Service. Completion, The Secretary reserves the that the rehabilitation project won, undertook unapproved furth the the rehabilitation project won, undertook unapproved furth	impleted Work (Pert 3) for this ent with the historic character with the historic character with the historic structure" is he lations. Questions concerning the projects may be inspected as not undertaken as presser alterations as part of the cause this property is not yell become a "certified history with the projects may be inspected projects may be inspected in the projects may be inspected in the projects may be inspected as not undertaken as presser it literations as part of the	property and his determined that:  Let of the property and, where reby designated a "certified ng specific tax consequences or the by an authorized representative at any time up to five years after intend by the owner in the application rehabilitation project inconsistent  et a "certified historic structure," the fic structure" on the date it or the in structure on the date it or the generalically become a "certified generalically become a "certified generalically become a "certified generalically consequences or the by an authorized representative at any time up to five years after inted by the owner in the application rehabilitation project inconsistent
PS Official U  The complete applicable, rehabilitation interpretation for mand at with the South interpretation interpretation for mand at with the South interpretation interpretation form and at with the South interpretation in the pretabilitation in the south interpretation form and at with the South interpretation in the south interp	cant, SSN, or TIN has chan a ere no additional owners value Only  Service has reviewed the Hist tell retrabilitation meots the the district in which it is locure. This certification is to be only of the internet Revenue etary to determine it the wood the rehabilitation and to supporting documentation, or supporting documentation, or supporting declayers the cannot be designated a "strict in which it is located is on." It is the owner's response of the Internat Revenue etary to determine if the world the probabilitation and to supporting documentation, or of the rehabilitation and to upporting documentation, accretary's Standards for Refullation is not consistent with thanderds for Renabilitation.	within the meaning of "owner" set for income preservation Certification Applicate Secretary of the Intertur's Standards and Effective the date Indicated between the Code should be addressed to the In it was the Standards for Fierbolitz revoke certification, if it is determined the evener, upon obtaining certification of the evener, upon obtaining certification is Secretary of the Interior's Standards certified rehabilitation, eligible for Fellisted in the National Register of his isolitate to be anouth be addressed to the in the measure should be addressed to the information of the owner, upon obtaining certification, if it is determined the owner, upon obtaining certification abilitation.	th in 36 CFR § 67.2 (2011).  In - Request for Certification of Cofor Rehebilitation and is consist tow, the rehabilitation of the "certification for the "certification of the "certification for the secretary reserves the that the rehebilitation project work, undertook unapproved furth for Rehabilitation. However, be derafted for the State Historic Preservation Completion for the State Historic Preservation Completion. The Secretary reserves the thet the rehabilitation project with undertook unapproved furth you the dietrict in which it is foculty.	impleted Work (Pert 3) for this ent with the historic character with the historic character with the historic structure" is he lations. Questions concerning the projects may be inspected as not undertaken as presser alterations as part of the cause this property is not yell become a "certified history with the projects may be inspected projects may be inspected in the projects may be inspected in the projects may be inspected as not undertaken as presser it literations as part of the	property and his determined that:  Let of the property and, where reby designated a "certified ng specific tax consequences or the by an authorized representative at any time up to five years after intend by the owner in the application rehabilitation project inconsistent  et a "certified historic structure," the fic structure" on the date it or the in structure on the date it or the generalically become a "certified generalically become a "certified generalically become a "certified generalically consequences or the by an authorized representative at any time up to five years after inted by the owner in the application rehabilitation project inconsistent
There  S Official U  National Park is the complete applicable, rehabilitation of the Secretary with the South in the South	cant, SSN, or TIN has chan a ere no additional owners value Only  Service has reviewed the Hist tell retrabilitation meots the the district in which it is locure. This certification is to be only of the internet Revenue etary to determine it the wood the rehabilitation and to supporting documentation, or supporting documentation, or supporting declayers the cannot be designated a "strict in which it is located is on." It is the owner's response of the Internat Revenue etary to determine if the world the probabilitation and to supporting documentation, or of the rehabilitation and to upporting documentation, accretary's Standards for Refullation is not consistent with thanderds for Renabilitation.	within the meaning of "owner" set for its preservation Certification Applicate Secretary of the Intertur's Standards and Effective the date Indicated between the Code should be addressed to the Indicated between the Standards for Rienbolitz revoke certification, if it is determined the owner, upon obtaining certification.  Secretary of the Interior's Standards certified rehabilitation.  Secretary of the Interior's Standards certified rehabilitation.  Secretary of the Interior's Standards certified rehabilitation. Register of Histolication in the National Register of Histolication in the Standards for Republication of the Standards for Republication. If it is determined the diviner, upon obtaining certification in the historic character of the propert	th in 36 CFR § 67.2 (2011).  In - Request for Certification of Co- for Rehabilitation and is consist as, the rehabilitation of the "cert set internal Revenue Service, Completion. The Secretary reserves the their the rehabilitation project woon, undertook unapproved furth for Rehabilitation. However, be seral tex credits at this time. It we for Rehabilitation. However, be seral tex credits at this time. It we for Rehabilitation project we fine State historic Preservation C ternal Revenue Service. Complet the the rehabilitation project we for, undertook unapproved furth y or the district in which it is local accordance of the Federal law.	impleted Work (Pert 3) for this ent with the historic character with the historic character with the historic structure" is he lations. Questions concerning the projects may be inspected as not undertaken as presser alterations as part of the cause this property is not yell become a "certified history with the projects may be inspected projects may be inspected in the projects may be inspected in the projects may be inspected as not undertaken as presser it literations as part of the	property and his determined that:  Let of the property and, where reby designated a "certified ng specific tax consequences or the by an authorized representative at any time up to five years after intend by the owner in the application rehabilitation project inconsistent  et a "certified historic structure," the fic structure" on the date it or the in structure on the date it or the generalically become a "certified generalically become a "certified generalically become a "certified generalically consequences or the by an authorized representative at any time up to five years after inted by the owner in the application rehabilitation project inconsistent

HARD COST APPLICATION	AND CERTIFICATE FOR	PAYMENT		PAGE 1 OF 6 PAGES		
TO OWNER: 1401 Howard, LLC.	PROJECT: 1401		APPLICATION NO:	22		
FROM CONTRACTOR: Palisade Builde		et, San Francisco, CA	PERIOD TO: CONTRACT DATE:	1/31/2018		
1875 S. Bascom Ave. #2400, Campbell,			PROJECT MANAGE	₹: S. Clark		
CONTRACTOR'S APPLICAT				and the second		
·						
CHANGE ORDER SUMMARY		Application is made for Payment,	as shown below, in connecti	on with the Contract.		
Total changes approved in previous months By Owner	ADDITIONS DEDUCTIONS	1. ORIGINAL CONTRACT SUM		\$ 11,111,908.00		
Totals	2,001,881.73	2. NET CHANGES BY CHANGE		\$ 2,001,881.73		
Total approved this Month		3. CONTRACT SUM TO DATE (		\$ 13,113,789.73		•
No. Approval Date		<ol> <li>TQTAL COMPLETED &amp; STOP</li> <li>RETAINAGE:</li> </ol>	(ED TO DATE	\$ 12,825,585.66 \$ 958,053.01		
		6. TOTAL EARNED LESS RETA	INAGE	\$ 11,867,532,65		
	.	7. LESS PREVIOUS CERTIFICA	TES FOR PAYMENT*	\$ 11,553,903.06		
		8. CURRENT PAYMENT DUE		\$ 313,629,59		
NET CHANGES by Change Order	0.00 0:00	9. BALANCE TO FINISH, INCLU	DING RETAINAGE	\$ <u>1,246,257.08</u>	•	
The undersigned Contractor certifies that to the	. as bent of the Contractors	·. •				
knowledge, information and belief the Work of		*Includes prior unpaid amount	of \$379.370.94 from AIA#2	1 (December 2017)		
Payment has been completed in accordance	· ·			(		
that all amounts have been paid by the Contri		Y (		,		
previous Certificates of Playment were issued						•
the Owner, and that the current payment shou	wa herein is now due.					
CONTRACTOR:	•					
•						
By:	Date:					
OWNER'S CERTIFICATE FO	OR PAYMENT	AMOUNT CERTIFIED	- francisco francisco de la companya	5		
		(Attach explanation if amount certified				
In accordance with the Contract Documents,	besed on on-site observations and the	Owner: 1401 Howard, LLC		•		
data comprising the above application, the Ar						
of his/her knowledge, information and belief,		Ву:		Date:		
the quality of the Work is in eccordance with						
Contractor is entitled to payment of the AMO	UNICERTIFIED.	Architect: Page & Turnball				
		Arcinteet. Fage & Idinibali				

APPLICATION AND CERTIFICATION FOR PAYMENT, CONTAINING CONTRACTOR'S SIGNED CERTIFICATION IS ATTACHED IN TABULATIONS BELOW, AMOUNTS ARE STATED TO THE NEAREST DOLLAR.

APPLICATION NO:
APPLICATION DATE: 1/

1/31/2018 1/1/2018

PERIOD FROM : PERIOD TO : 1

1/31/2018 1600

JOB#: 16

CONTRACT DATE:

JOB #1600 - 1401 Howard Street, San Francisco, CA

Α	B	С			D	E	F	G	1	H	T 1
			Change		Work Com		Materials	Total	%		
ITEM	Description of work	Scheduled	Orders	New	Previous	This	Presently	Completed	Complete	Balance to	Retainage
NO.		Value	To	Scheduled	Applications	Period	Stored	and Stored		Finish	at 10%
,,_,		,	Date	Value		Work In Place	(Not in D or	to Date			
			(Thru PCCO#11)	,	(D + E)	(F-D)	E)	(D + E + F)	(G/C)	(C-G)	
1290	Weather Protection	\$ 25,000.00	111111111111111111111111111111111111111	\$ 25,000,00	\$ 24,231,49			\$ 24,231,49	97%	\$ 768.51	\$ 2,423,15
1390	Hoisting/Equipment Rentals	\$ 110,000.00	\$ (3,544.02)	\$ 106,455.98	\$ 100,000.00	\$ 6,455.98		\$ 106,455.98	100%	\$ -	\$ 10,645.50
1800	General Conditions/Supervision	\$ 800,000.00	\$ 343,000,00		\$ 1,050,000,00	\$ 73,321.77		\$ 1,123,321,77	98%	\$ 19,678.23	\$
2050	Demo Existing Concrete SOG	\$ 37,500.00	\$ (7,500,00)	\$ 12 30,000.00	\$ 30,000.00			\$ 30,000.00	100%	\$ -	\$ -
2070	Selective Demolition	\$ 125,000.00	\$ 92,298,53	\$ 217,298.53	\$ 217,298.53	\$ -		\$ 217,298.53	100%	\$ -	\$ 15,479.85
2080	Core Drilling	\$ 7,500.00		\$ 12 7.500.00	\$ 7,500.00			\$ 7,500.00	100%	\$ -	\$ 750.00
2250	Underpinning pits/misc.	\$ -	\$ 79,847.59	\$ 179.847.59	\$ 79,847.59			\$ 79,847.59	100%	ęs -	\$ (0.00)
2300	Spoils Removal	\$ 13,280,00		\$ 45.410.00	\$ 45,410.00	\$ -		\$ 45,410.00	100%	\$ -	\$ 4,541.00
2310	Excavation	\$ 25,000.00	\$ 5,905,00	\$ 30,906.00	\$ 30,906.00	\$ .		\$ 30,906.00	100%	\$ .	\$ 3,090.60
2450	Micropiles	\$ 328,000,00		S \$2328,000.00	\$ 328,000.00	\$ -		\$ 328,000.00	100%	\$ -	S -
2460	Casing Upper 10' of each Micropile	\$ 36,000.00	\$ 24,000.00	\$ 60,000.00	\$ 60,000,00			\$ 60,000.00	100%	\$	\$ -
2510	Domestic Water Underground	\$ 24,100.00	\$ (24,100,00)	S -		1		S -	100%	\$ -	\$ -
2520	Sanitary Sewer & SD	\$ 143,440.00	\$ (36,000,00)	\$ 107,440.00	\$ 107,440,00	\$ -		\$ 107,440.00	100%	\$ -	\$ 10,744.00
2800	Landscape; Irrigation & Planting	\$ 46,000.00	\$ 48,000.00	\$417 94,000.00	\$ 27,328.96	\$ 40,301,93		\$ 67,630.89	72%	\$ 26,369.11	\$ 6,763.09
2810	Site Lighting (excludes fixtures)	\$ -	\$ 26,350.00	\$ 26,350.00	\$ 26,350,00	\$ -		\$ 26,350.00	100%	5 -	\$ 2,635.00
2860	Landscape Arbors	\$ -		\$\$2 15,000.00				\$ <u>-</u>	0%	\$ 15,000.00	3 -
2920	Fencing	\$ 25,000.00	\$JF 25,000.00	鳅 50,000.00		\$ 30,000.00		\$ 30,000.00	60%	\$ 20,000.00	\$ 3,000.00
	Landscape Gas Lights (piping										
2950	only)	\$	\$ 12,500.00		\$ 12,500.00			S 12,500.00	100%	\$ -	\$ 1,250.00
2960	Joint Trench	\$ 25,000.00			\$ 85,000.00			\$ 85,000.00	100%	\$ -	\$ 8,500.00
	Rebar/Mesh, Shotcrete & CIP	\$ 1,245,000.00			\$ 1,315,728.00	· · · · · · · · · · · · · · · · · · ·		\$ 1,315,728.00	100%	\$ -	\$ 5,329.43
3070	Struct. Excavation, Backfill & Offhaul				5 146,278,64			\$ 146,278.64	100%	\$ -	\$ 14,523.51
3100	On Grade Site Concrete (Hardscape)		\$ 25,000.00		\$ 70,815,67	S -		\$ 70,815,67	94%	\$ 4,184.33	\$ 7.081.57
	Offsile Concrele	\$ 50,000.00		\$ 50,000.00	\$ 28,854,00	\$ -		\$ 28,864.00	58%	\$ 21,136,00	\$ 2,886,40
	Misc. Concrete	\$ 50,000.00				\$ -			100%	S	<b>5</b> -
10 (A)	SUBTOTALS PAGE 1	\$ 3,316,820.00	\$ - 733,894,74	\$ 4,050,714.74	\$ 3,793,498.88	\$ 150,079,68	\$ 1. Call 1. Call	\$ 3,943,578.56	97%	\$ 107,136.18	\$ 99,643,20

APPLICATION AND CERTIFICATION FOR PAYMENT. CONTAINING CONTRACTOR'S SIGNED CERTIFICATION IS ATTACHED

IN TABULATIONS BELOW. AMOUNTS ARE STATED TO THE NEAREST DOLLAR.

JOB #1600 - 1401 Howard Street, San Francisco, CA

APPLICATION NO:

APPLICATION DATE: 1/3

1/31/2018 1/1/2018

PERIOD FROM : PERIOD TO :

1/31/2018 1/31/2018 1600

JOB #:

CONTRACT DATE:

Title   Description of work   Description of work   Description of work   Value   Value   Value   Value   Value   Value   Value   Value   Description of work   Value   Value   Value   Value   Description of work   Value   Value   Value   Description of work   Value   Value   Value   Value   Description of work   Value   Value   Description of work   Value   Description of work   Value   Value   Description of work   Value   Value   Description of work   Value   Description of work   Value   Value   Description of work   Value   Value   Description of work   Value   Value   Value   Value   Description of work   Value   Description of work   Value   Description of work   Value   Value   Description of work   Description of work   Value   Description of work   Value   Description of work   Value   Description of work   Descriptio	A	В	С			D	E.	F	G		Н	
NO.   Value   Date   Characteristic   Ch				Change		Work Com	oleted	Materials	Total	%		
Pale   Value   CD-06113	ITEM	Description of work	Scheduled	· Orders	New	Previous	This	Presently	Completed	Complete	Balance to	Refainage
Massarry	NO.		Value	To	Scheduled	Applications	Period	Stored	and Stored		Finish	al 10%
4900   Masonny				Date	Value		Work In Place	(Not in D or	to Date			ļ
5000   Structural Steel   \$ 275,000.00   \$ (40,000.00)   \$ 235,000.00   \$ 235,000.00   \$ 3,000				(Thru PCCO#11		(D+E)	(F-D)	E)	(D + E + F)	(G/C)	(C-G)	
Structural Structura	4900	Masonry	\$ 20,000.00	\$ (20,000.00	) S				.\$ -	100%	\$ -	\$ -
Solid   Mezzanine Bislet   \$ 401,143.00   \$ 48,000.00   \$ 3,000.00   \$ 317,143.	5050	Structural Steel	\$ 275,000.00	\$ (40,000,00	S 49 235,000.00	\$ 235,000,00			\$ 235,000.00	100%	\$ -	\$ 23,500.00
5000   Mezzanine Birdge	5070	Structural Steel Installation	\$ 400,000.00	\$ (88,158,91	5 4, 311,841.09	\$ 311,841.09	\$ -		\$ 311,841.09	100%	\$ -	
STID   Mezzanine Glass Reil System   \$205,000.00   \$117,600.00   \$47,500.00   \$3,898.20   \$5,800.00   \$3,250.00   \$5,800.00   \$7,500.00   \$5,800.00   \$7,500.00	5080	Mezzanine Steel	\$ 401,143.00	\$ (84,000.00	\$ \$ 317,143.00	\$ 317,143.00	\$ -	,	\$ 317,143.00	100%	\$ -	\$ 31,714.30
State   Stat	5090	Mezzanine Bridge	\$ 50,000.00	)	\$ 4, 50,000.00				\$ 50,000.00	100%	S -	\$- 5,000,00
5120   Misc. Steel   \$ 26,000.00   \$ \$ 27,500.00   \$ 11,812.50   \$ - \$ 11,812.50   \$ 47%   \$ 13,187.50   \$ 1,812.55   \$ 13.00   \$ 7,500.00   \$ 7,701.97   \$ 637,701.97   \$ 688,219.74   \$ 44,482.00   \$ 612,701.74   \$ 96%   \$ 25,000.23   \$ 25,000.23   \$ 21,895.57   \$ 20,000.00   \$ 41,895.57   \$ 26,000.00   \$ 21,895.57   \$ 20,000.00   \$ 21,895.50   \$ 20,000.00   \$ 21,895.57   \$ 20,000.00   \$ 21,895.57   \$	5100	Mezzanine Glass Rail System	\$ 205,000.00	\$ (117,500,00	\$ 4 87,500.00	\$ 83,696.20	\$ -		5 83,696.20	96%	\$ 3,803.80	\$ 8,369,62
Supports for the 700 lb. Trough sink   \$   \$   \$   \$   \$   \$   \$   \$   \$	5110	Stairs					\$ -				\$ 31.250.00	S. 3 125.00
6080   Cabinets							\$ -				\$ 13,187.50	S 1,181.25
6080   Cabinets	5130	Supports for the 700 lb. Trough sink	\$ -		\$ % 7,500.00	\$ 7,500.00				100%	\$ -	\$ 750 00
6150   Window Stop Repair   \$   50,000,00   \$   48,867,00   \$   \$   \$   \$   \$   \$   \$   \$   \$		Cabinets	\$ 10,000.0								\$ -	\$ -
6160   Bell Tower Rot Repair   \$   \$   \$   \$   \$   \$   \$   \$   \$	6100	Retrofit Carpentry	\$ 560,000,0	\$ 77,701,97	\$ 637,701.97	\$ 568,219,74	\$ 44,482.00		\$ 612,701.7	96%	\$ 25,000.23	\$ 61,270,17
Color   Colo	6150	Window Stop Repair	\$ 50,000,0				\$ -		\$ 96,867.00	100%	\$ -	\$ 9,686.70
Section   Sect	6160	Bell Tower Rot Repair										\$ 15.145,90
Section   Sect	6200	Trim Carpentry	\$ 50,000.0		4	\$ 21,895.57	\$ 20,000.00		\$ 41,895.5	84%	\$ 8,104.43	\$ 4,189,56
S	6250		\$ 175,000.0								\$ -	\$ 33,406,08
7200   Additional under slab insutation   \$	6250	Bell Tower Scaffolding				\$ 165,000.00	\$ -		S 165,000.00	100%	\$ -	\$ 16,500.00
Table   Tabl	6500										\$ .	\$
Tool   Lower Roof System   S   35,000.00   S   (6,890.00)   S   (7,28,110.00   S   28,110.00											\$ -	\$ 3,500.00
Flashing & Sheetmetal   \$ 200,000.00   \$ 234,323.47   \$ 464,434,323.47   \$ 434,323.47   \$ 5 - \$ 434,323.47   100%   \$ - \$ 434,323.47   100%   \$ - \$ 434,323.47   100%   \$ - \$ 434,323.47   100%   \$ - \$ 1,000.00   100%							\$ /Pty -				\$ -	\$ 25,895.00
Topology							,				\$ -	\$ 2,811.00
8050 Windows \$ 545,000.00 \$ (275,423.78) \$ \$ 5269,576.22 \$ 269,576.22 \$ - \$ 269,576.22 \$ - \$ 269,576.22 \$ 100% \$ - \$ 25,977.62 \$ 8070 \$ Stain Glass Repair \$ 120,000.00 \$ (38,739.33) \$ \$ \$ 6 6 81,260.67 \$ 81,260.67 \$ - \$ 81,260.67 \$ 100% \$ - \$ 21,26.07 \$ 8080 \$ Skylight Repair \$ - \$ 39,010.06 \$ \$ 49,000.00 \$ (15,000.00) \$ 49,000.00 \$ 264,631.12 \$ - \$ 264,631.12												\$ 43,432.35
8070 Stain Glass Repair \$ 120,000.00 \$ (38,739.33) \$4£ (681,260.67 \$ 51,260.67 \$ - \$81,260.67 \$ 100% \$ 5 - \$81,260.67 \$ 8080 \$kylight Repair \$ - \$39,010.06 \$4 \$39,010.06 \$ - \$39,010.06 \$											\$ -	S 1,000 00
8080 Skylight Repair \$ - \$ 39,010.08 \$ 39,010.06 \$ - \$ 39,010.06 100% \$ - \$ 3,901.01 8200 Doors/Millwork & Finish Hardware \$ 284,000.00 \$ (15,000.00) \$ \$ \( \frac{1}{2}\) \( \f											\$ -	\$ 26.957.62
8200 Doors/Millwork & Finish Hardware \$ 284,000.00 \$ (15,000.00) \$ \$ \$ \$ \$ 264,631.12 \$ - \$ \$ 264,631.12 98% \$ 4,368.88 \$ 26,463.11 9050 Plaster Repair \$ 775,000.00 \$ 675,577.80 \$ \$ 1,350,577.80 \$ - \$ 1.350,577.80 100% \$ - \$ 135.057.78 9100 Metal Studs & Drywall \$ 110,000.00 \$ (40,000.00) \$ 70,000.00 \$ - \$ 70,000.00 \$ - \$ 70,000.00 100% \$ - \$ 7.000.00 \$ - \$ 7.000.	8070		\$ 120,000.0								S -	\$ 8,126.07
9050 Plaster Repair \$ 775,000.00 \$ 675,577.80 \$ 1,350,577.80 \$ 1,350,577.80 \$ - \$ 1.350,577.80 100% \$ - \$ 135.057.78 9100 Metal Studs & Drywall \$ 110,000.00 \$ (40,000.00) \$ 70,000.00 \$ - \$ 70,000.00 \$ - \$ 70,000.00 100% \$ - \$ 7.000.00 Soffit below Transept Café, 9200 Green Rm Stage Metal Framing \$ - \$ 17,000.00 \$ 17,000.00 \$ - \$ 17,											S -	\$ 3,901.01
9100 Metal Studs & Drywall \$ 110,000.00 \$ (40,000.00) \$ 70,000.00 \$ 70,000.00 \$ - \$ 70,000.00 100% \$ - \$ 7,000.00 100% \$ - \$ 7,000.00 \$ 17,000.00 \$ 17,000.00 \$ - \$ 17,000.00 \$ - \$ 17,000.00 \$ - \$ 17,000.00 \$ - \$ 17,000.00 \$ - \$ 17,000.00 \$ - \$ 17,000.00 \$ - \$ 17,000.00 \$ - \$ 17,000.00 \$ - \$ 17,000.00 \$ - \$ 17,000.00 \$ - \$ 17,000.00 \$ - \$ 17,000.00 \$ - \$ 17,000.00 \$ - \$ 17,000.00 \$ - \$ 17,000.00 \$ - \$ 17,000.00 \$ - \$ 17,000.00 \$ - \$ 17,000.00 \$ - \$ 100% \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ - \$ 100% \$ 1	8200	Doors/Milwork & Finish Hardware									\$ 4,368,88	\$ 26,463,11
Soffit below Transept Café,   9200   Green Rm Stage Metal Framing   \$ - \$ 17,000.00 \$ 17,000.00 \$ - \$ 17,000.00 \$ - \$ 17,000.00 \$ 5 - \$ 17,000.00 \$ 5 - \$ 17,000.00 \$ 5 - \$ 17,000.00 \$ 5 - \$ 17,000.00 \$ 5 - \$ 17,000.00 \$ 5 - \$ 17,000.00 \$ 5 - \$ 100% \$ 5 - \$ 100% \$ 5 - \$ 100% \$ 5 - \$ 100% \$ 5 - \$ 100% \$ 5 - \$ 100% \$ 5 - \$ 100% \$ 5 - \$ 100% \$ 5 - \$ 100% \$ 5 - \$ 100% \$ 5 - \$ 100% \$ 100% \$ 5 - \$ 100%	9050										\$ -	\$ 135.057.78
Second   S	9100		\$ 110,000.0	0 \$ (40,000.00	0) \$ 70,000.00	\$ 70,000.00	\$ -		\$ 70,000.0	100%	\$ -	\$ 7,000.00
9400         Ceramic Tile         \$ 30,000.00         \$ (30,000.00)         \$ - 40% p. #         \$ - 100% p. #         \$ - 100% p. #         \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ -		Soffitt below Transept Café,										
9630         Flooring - Carpet Tile         \$ 78,000.00         \$ (78,000.00)         \$ -         \$ 79,000.00         \$ -         \$ 100%         \$ -         \$ -           9900         Painting         \$ 234,900.00         \$ 58,950.00         \$ 293,850.00/         \$ 279,213.41         \$ -         \$ 279,213.41         95%         \$ 14,636.59         \$ 27,921.34           9950         Gold Leaf at Dome         \$ -         \$ 60,000.00         \$ 60,000.00         \$ -         \$ 60,000.00         \$ -         \$ 6,000.00	9200											\$ 1,700,00
9900 Painting \$ 234,900.00 \$ 58,960.00 \$ 293,860.00 \$ 279,213.41 \$ - \$ 279,213.41 95% \$ 14,636.59 \$ 27,921.34 9950 Gold Leaf at Dome \$ - \$ 60,000.00 \$ 60,000.00 \$ - \$ 60,000.00 \$ 5 - \$ 60,000.00											S -	\$ -
9950 Gold Leaf at Dome \$ - \$ 60,000.00 \$\$ 60,000.00 \$ 60,000.00 \$ - \$ 60,000.00 \$\$ 5 - \$ 60,000.00		Flooring - Carpet Tile					19					
SUBTOTALS PAGE 20 1 5 5 6 3 12,813 00 1 5 1,501,132.82 5 9.813 9 45 8 2 1 1 9.813 9 45 8 2 1 1 9 8 9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1												
	- J. J. J. W	SUBTOTALS PAGE 2	\$ / 8,312,813.0	0 \$1,501,132.8	2 \$ 9,813,945,82	\$ 9,391,896,53	\$ 214,561.68	\$ 2000	\$ 9,606,458.2	1 98%	\$ 207,487.61	\$ 564,431.16

APPLICATION AND CERTIFICATION FOR PAYMENT, CONTAINING CONTRACTOR'S SIGNED CERTIFICATION IS ATTACHED IN TABULATIONS BELOW, AMOUNTS ARE STATED TO THE NEAREST DOLLAR.

APPLICATION NO :

22 APPLICATION DATE: 1/31/2018

PERIOD FROM : 1/1/2018 PERIOD TO : 1/31/2018

JOB#. 1600

CONTRACT DATE:

			-	_		
JOB #1600 -	- 1401	Howard	Street.	San	Francisco.	CA

Α	В		C						D		E	F		G	T-	T	Н		1
					Change				Work Com	ple	led	Materials		Total	%	T			
.ITEM	Description of work		Scheduled		Orders		New		Previous		This	Presently	1	Completed	Complete		Balance to	· F	letainago
NO.	, ,		Value		To		Scheduled		Applications		Period	Stored		and Stored		1	Finish		at 10%
					Date		Value			ν	Vork In Place	(Not in D or		to Date					]
				/13	ru PCCO#11)	l			(D + E)		(F-D)	E)		(D + E + F)	(G/C)		(C-G)		1
10320	Fire Extinguishers	S	1,600,00	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	101 0001117	\$	1,600.00	_		S	1,600.00		\$	1,600,00	100%	\$	70.0	Š	160.00
10400	Signage	S	6,500,00			Ş	6,500,00	\$	6,500.00		.,,,,,,,,,		\$	6,500.00	100%	\$	-	\$	650.00
10450	Mirrors	S	2,000,00	_		\$	2,000,00			\$	2,000.00		\$	2,000.00	100%	\$	-	\$	200.00
10530	Access Doors & Ladders	\$	12,000,00	<b></b> -		35		\$	12,000,00	\$	-		\$	12,000.00	100%	\$		\$	1,200.00
10600	Tollet Partitions	5	11,500,00			\$	11,500,00		11,500.00		-		\$	11,500.00	100%	\$		\$	1,150 00
10800	Bath Accessories	S	1,500.00			\$	1,500,00		1,500.00			,	\$	1,500.00	100%	\$	-	\$	150 00
10910	Misc. Specialties/Bike Racks	S	1,500.00	_		\$		\$	1,500,00		·-	·	\$	1,500.00	100%	\$		\$	150.00
11010	Appliances	5	2,500,00	\$	(2,500,00)		. 1000:00		71000100	Ť			\$	1,000.00	100%	\$		\$	100,00
	Window Coverings	5		Ť	(41441130)	\$	· · · · · · · · · · · · · · · · · · ·	_		_			\$		100%	\$		\$	
13170	Interior Plaster/Paint Lead Abatement	\$	100,000.00	5	(97,870,27)		2,129,73	3	2,129.73	5		<u> </u>	\$	2,129,73	100%	\$	(0.00)		212.97
13180	Bird Guano Abatement	\$	12,500.00	\$	(3,200.00)		9,300.00	\$	9,300.00	5			\$	9,300.00	100%	5	(0.00)	\$	212.07
13190	Asbestos Abatement	\$	16,000.00		(1,543,00)		14,457.00		14,457,00	S			\$	14,457.00	100%	1 5		S	
14200	Wheel Chair Lift	\$	25,000.00				45,000.00	3	45,000,00		-		5	45,000.00	100%	\$		<u>.s</u>	4,500.00
15050	Plumbing	\$	105,000.00		(21,000.00)		84.000.00	5	80,000.00	5	4.000.00	· · · · · · · · · · · · · · · · · · ·	S	84,000.00	100%	\$		\$	8,400.00
15150	Radiant Floor Heat	\$	145,000,00	\$	7,500.00		152,500,00	\$	152,500,00	7	7,000.00		5	152,500.00	100%	\$	-		15,250 00
15400	Ventilation	\$	185,000.00	\$	10,000.00		195,000.00			\$	5,200,80		\$	186,372.00	96%	\$	8,628,00	\$	18,637.20
16050	Electrical	\$	353,000.00	3	643,000.00		996,000,00	\$		8	17,385.65		\$	986,114.03	99%	\$	9.885.97		98,611.40
16070	Fixtures	\$	50,000.00	3			135,281.00	\$	126,327.00		77,000.00		\$	126,327.00	93%	3	8,954,00		12,632 70
16080	Site Lighting Fixtures	\$	- 00,000.00	3	92,625,00		92,625,00	\$	78,693.00		6,179,00		3	84,872.00	92%	5	7,753.00	Š	8,487,20
16090	Access Cantrol / Intercom	\$		\$	27,469.00		27,469,00	<u> </u>	8,240,70		19,228.30		\$	27,469.00	100%	\$	7,700,00	\$	2,746.90
16100	CCTV System	\$		\$	15,484.00		15,484.00		4,645,20		10,838,80		3	15,484.00	100%	\$	-	3	1,548.40
	WiFi System	\$		3	18,360.D0		18,360.00		9,180,00		9,180,00		\$	18,360.00	100%	\$		\$	1,836.00
	Music Speaker System	\$		\$	51,248.00			S	51,248.00	<del>  "</del>	0,100.00		S	51,248,00	100%	- 5		\$	5,124.80
	Commisary Service Upgrade	\$		\$	6,000,00		6,000,00		6,000,00	\$	-		5	6,000.00	100%	\$		\$	600.00
16180	Service Location Chg & Misc. Mods	\$	-	\$	9,975,00				9,975.00		-		\$	9,975,00	100%	\$	-	\$	997.50
16200	Low Voltage	\$	150,000.00	\$	(60,000,00)	-:-	90,000,00	\$	83,072,13		-		\$	83.072.13	92%	\$	6,927.87	S	8,307.21
16300	Telephone Data	\$	100,000.00	\$	6,248.00		6,248,00		6,248,00		_		\$	6,248.00	100%	S	- 1021.01	S	524 80
16400	Lighting Control System	\$		\$	124,790,00		124,790.00	\$	109,637,10		12,181.90		\$	121,819,00	98%	\$	2.971.00		12 181 90
16500	Engineering	S		\$		\$	27,500,00	\$	27,500,00	Ť	1211.01100		\$	27,500,00	100%	\$	2,011100	\$	2,750.00
17000	Additional Tenant Improvements	S	240,000.00		(240,000,00)			1		1			5	21,000,00	100%	\$	-	<u>\$</u>	
17001	Red Room - Ceiling restoration	S	- 121202100	\$	40,749,25	<u> </u>	40,749,25	\$	40,749.25	S			5	40,749,25	100%	\$		\$	4,074.93
17002	West Tower - X brace & spiral stair		*	S	40,000.00		40,000,00	\$	20,000,00		10,000,00		\$	30,000.00	75%	\$	10,000,00	<u>\$</u>	3,000.00
17003	East Tower - X brace	S		S	20,000.00		20,000,00	\$	20,000.00		-		\$	20,000.00	100%	\$		S	2.000.00
	SUBTOTALS PAGE 3	<u> </u>	9733.413 00	1			12,054,661,80	1 3-			312 356 13	36 15 13 15 12 15 18					262,607,45	<del></del>	
7	Incolor Control Maria Caracter Law	نستنا	21. 2214 (2100)	4	-1-5:1-40,00	٠,	(1.1) (2.1) (2.1) (2.1) (2.1)	1. *	THE PROPERTY OF	1.3	7, 77,2,000,10		<u> </u>	tier campagasian	1 2000	1.4	* (##### (1-4F)	SW	0010 1010

APPLICATION AND CERTIFICATION FOR PAYMENT, CONTAINING CONTRACTOR'S SIGNED CERTIFICATION IS ATTACHED

IN TABULATIONS BELOW, AMOUNTS ARE STATED TO THE NEAREST DOLLAR.

APPLICATION NO :

APPLICATION DATE: 1/31/2018

PERIOD FROM : PERIOD TO : 1

1/1/2018 1/31/2018

JOB#:

#: 1600

CONTRACT DATE:

JOB #1600 - 1401 Howard Street, San Francisco, CA

Α	В	¢			D .	E	F	G		H	1
			Change	-	Work Com	pleted	Materials	Total	%		
ITEM	Description of work	Scheduled	Orders	New	Previous	This	Presently	Completed	Complete	Balance to	Retainage
NO.		Value	To	Scheduled	Applications	Period	Stored	and Stored	<b>,</b>	Finish	at 10%
			Date.	Value		Work In Place	(Not in D or	to Date	] '		
	_		(Thru PCCO#11)		(D+E)	(F~D)	E)	(D+E+F)	(G/C)	(C-G)	
	DIRECT COSTS:										
	Division 1 - General Requirements	\$ 935,000.00			\$ 1,174,231.49			\$ 1,254,009.24	98%	\$ 20,446.74	\$ 13,068.75
	Division 2 - Site improvements	\$ 835,820.00			\$ 1,057,581.08			\$ 1,127,883.01	95%	\$ 61,369,11	\$ 59,753.54
	Division 3 - 17 Btdg. Improvements		\$1,628,360.70					S 9,410,162.10	98%	\$ 180,791.60	\$ 810,792.79
	TOTAL DIRECT COST	\$ 9,733,413.00	\$2,321,248.80	\$ 12,054,661.80	\$ 11,479,698.22	\$ 312,356,13	\$ -	\$ 11,792,054.35	98%	\$ 262,607.45	\$ 880,615.08
9000	OVERHEAD & PROFIT	\$ 632,672.00	\$ 119,247.56	\$ 751,919.55	\$ 722,925.28	S 12,613.91		\$ 735,539,19	98%	\$ 16,380.36	S 73,553.92
8000	CONSTRUCTION CONTINGENCY 1.5%	\$ 486,671.00	\$ (486,671.00)	\$ -	\$ -			\$ -	100%	\$ -	\$ -
102	CCIP INSURANCE	\$ 259,152.00	\$ 48,056.38	\$ 307,208.38	\$ 282,631.70	\$ 15,360.42		\$ 297,992.12	97%	.\$ 9,216.26	\$ 3,884.01
	TOTAL GUARANTEED MAXIMUM PRICE	\$ 11,111,908.00	\$2,001,881.74	\$ 13,113,789.73	\$ 12,485,255.20	\$ 340,330.46	\$ -	\$ 12,825,585.66	98%	\$ 288,204.07	\$ 958,053.01

Three Way Value Comparison Comparisons

						<b>克克斯克尔克克克克克克克</b> 克			Compansons				
	and the second		a da sa waka mu	and star		2019 Factored	Restricted	and the state of the	Proposition and the second section (S.)	Reduction in	Percentage %	2018	Estimated
			Owner	Year	Square	Base Year	Value by	Market	Taxable Mills	Assessed	Reduction	Property	Property Tax
APN	Address	Property Type	Occupied	Built	Feet	Value	Income	Value	Act Value	Value	From FBYV	Tax Rate	Savings
05-0612-001A	2251 Webster	Single Family	Yes	1900	1,586	\$ 1,837,603	\$ 618,000	\$ 1,840,000	\$ 618,000	\$ (1,219,603)	-66.37%	1.1630%	(\$14,184)
06-0866-014	64 Potomac	Single Family	Yes	1900	1,750	\$ 2,550,000	\$ 600,000	\$ 2,500,000	\$ 600,000	\$ (1,950,000)	-76.47%	1.1630%	(\$22,679)
23-3517-035	1401 Howard	Office	No	1913	21,943	\$ 18,458,740	\$12,700,000	\$13,700,000	\$ 12,700,000	\$ (5,758,740)	-31.20%	1.1630%	(\$66,974)
23-3542-062	2168-2174 Market	Retail	No	1907	17,132	\$ 684,218	\$ 4,030,000	\$ 6,850,000	\$ 684,218	\$ -	0.00%	1.1630%	\$0
24-3640-031	2731-2735 Folsom	3-units	Yes / No	1900	5,200	\$ 6,170,997	\$ 3,119,000	\$ 6,500,000	\$ 3,119,000	\$ (3,051,997)	-49.46%	1.1630%	(\$35,495)

# RECEIVED BOARD OF SUPERVISORS SAN FRANCISCO



# DAN FRANCISCU AND INC. DEPARTMENT 2019 OCT 15 PM 2: 25

ar Ak

October 15, 2018

Ms. Angela Calvillo, Clerk Board of Supervisors City and County of San Francisco City Hall, Room 244 1 Dr. Carlton B. Goodlett Place San Francisco, CA 94102

Re:

Transmittal of Planning Department Case Numbers: 2019-006323MLS; 2019-006384MLS; 2019-006322MLS; 2019-005831MLS; 2019-006455MLS

Six Individual Mills Act Historical Property Contract Applications for the following addresses: 2251 Webster Street; 1401 Howard Street; 64 Potomac Street; 2168 Market Street; 2731-2735 Folsom Street

BOS File Nos: \_\_\_\_\_ (pending)

Historic Preservation Commission Recommendation: Approval

Dear Ms. Calvillo,

On October 2, 2019 the San Francisco Historic Preservation Commission (hereinafter "Commission") conducted a duly noticed public hearing at a regularly scheduled meeting to consider the proposed Mills Act Historical Property Contract Applications. At the October 2, 2018 hearing, the Commission voted to *approve the proposed Resolutions*.

The Resolutions recommend the Board of Supervisors approve the Mills Act Historical Property Contracts as each property is a historical resource and the proposed Rehabilitation and Maintenance plans are appropriate and conform to the Secretary of the Interior's Standard for the Treatment of Historic Properties. Please refer to the attached exhibits for specific work to be completed for each property.

The Project Sponsors submitted the Mills Act applications on May 1, 2019. As detailed in the Mills Act application, the Project Sponsors have committed to Rehabilitation and Maintenance plans that will include both annual and cyclical scopes of work. The Mills Act Historical Property Contract will help the Project Sponsors mitigate expenditures and enable the Project Sponsors to maintain their historic properties in excellent condition in the future.

The Planning Department will administer an inspection program to monitor the provisions of the contract. This program will involve a yearly affidavit issued by the property owner verifying compliance with the approved Maintenance and Rehabilitation plans as well as a cyclical 5-year site inspection.

Suite 400 San Francisco, CA 94103-2479

1650 Mission St.

Reception: 415.558.6378

Fax: 415.558.6409

Planning Information: 415.558.6377

## Transmittal Materials Mills Act Historical Property Contracts

The Mills Act Historical Property Contracts are time sensitive. Contracts must be recorded with the Assessor-Recorder by December 30, 2019 to become effective in 2020. We respectfully request these items be introduced at the next available hearing date. Your prompt attention to this matter is appreciated.

If you have any questions or require further information, please do not hesitate to contact me.

Sincerely,

, Aaron D. Starr

Manager of Legislative Affairs

cc: jor

John Carroll, Office of the Clerk of the Board Andrea Ruiz-Esquide, City Attorney's Office

#### Attachments:

Mills Act Contract Case Report, dated October 2, 2019 Assessor Valuation Table

### 2251 Webster Street

Historic Preservation Commission Resolution
Draft Mills Act Historical Property Contract
Draft Rehabilitation & Maintenance Plans
Draft Mills Act Valuation provided by the Assessor-Recorder's Office
Mills Act Application

#### 1401 Howard Street

Historic Preservation Commission Resolution
Draft Mills Act Historical Property Contract
Draft Rehabilitation & Maintenance Plans
Draft Mills Act Valuation provided by the Assessor-Recorder's Office
Mills Act Application
Historic Structure Report

#### 64 Potomac Street

Historic Preservation Commission Resolution
Draft Mills Act Historical Property Contract
Draft Rehabilitation & Maintenance Plans
Draft Mills Act Valuation provided by the Assessor-Recorder's Office
Mills Act Application

#### 2168 Market Street

Historic Preservation Commission Resolution

SAN FRANCISCO
PLANNING DEPARTMENT

# Transmittal Materials Mills Act Historical Property Contracts

Draft Mills Act Historical Property Contract
Draft Rehabilitation & Maintenance Plans
Draft Mills Act Valuation provided by the Assessor-Recorder's Office
Mills Act Application
Historic Structure Report

### 2731-2735 Folsom Street

Historic Preservation Commission Resolution
Draft Mills Act Historical Property Contract
Draft Rehabilitation & Maintenance Plans
Draft Mills Act Valuation provided by the Assessor-Recorder's Office
Mills Act Application