File No	<u> 191</u>	<u>065 </u>
---------	-------------	-------------

Committee	Item No.	3
Board Item	No.	17

COMMITTEE/BOARD OF SUPERVISORS

AGENDA PACKET CONTENTS LIST

Committee:	Government Audit and Oversigh	<u>t</u> [Date:	Nov. 21,	2019
Board of Su	pervisors Meeting:		Date:	<u>Dec. 10, 1</u>	2019
Cmte Boar	r d				
	Motion				
\boxtimes	Resolution				•
	Ordinance				•
	Legislative Digest	D		,	
	Budget and Legislative Analyst	Report	Ĭ.	•	
	Youth Commission Report Introduction Form				
	Department/Agency Cover Lette	ar and/d	or Ren	ort	
	MOU	or arranc	31 1.0F	,010	
	Grant Information Form				
	Grant Budget				
	Subcontract Budget		. *		
	DRAFT Mills Act Agreement			•	
	Form 126 – Ethics Commission				
	Award Letter Mills Act Application Docs				
	Public Correspondence				
	i ubile correspondence	•			
OTHER					
	Planning Presentation – Novem				· · · · · · · · · · · · · · · · · · ·
	Planning Case Report – Octobe		9		·
	HPC Reso No. 1091 – October 2	<u>2, 2019</u>			
	Assessor's Mills Act Valuation	Fox Sov	ingo C	hort.	
	Assessor's Updated Estimated Transmittal Letter – October 15,		ings C	<u>Mail</u>	
	Transmittal Letter — October 15,	2010			
Prepared by	r: John Carroll	Date:	Nov.	15, 2019	
Prepared by		Date:		21, 2019	

[Mills Act Historical Property Contract - 1401 Howard Street]

Resolution approving an historical property contract between 1401 Howard LLC, the owner of 1401 Howard Street, and the City and County of San Francisco, under Administrative Code, Chapter 71; and authorizing the Planning Director and the Assessor-Recorder to execute and record the historical property contract.

WHEREAS, The California Mills Act (Government Code, Sections 50280 et seq.) authorizes local governments to enter into a contract with the owners of a qualified historical property who agree to rehabilitate, restore, preserve, and maintain the property in return for property tax reductions under the California Revenue and Taxation Code; and

WHEREAS, The Planning Department has determined that the actions contemplated in this Resolution comply with the California Environmental Quality Act (California Public Resources Code, Sections 21000 et seq.), and

WHEREAS, Said determination is on file with the Clerk of the Board of Supervisors in File No. 191065, is incorporated herein by reference, and the Board herein affirms it; and

WHEREAS, San Francisco contains many historic buildings that add to its character and international reputation and that have not been adequately maintained, may be structurally deficient, or may need rehabilitation, and the costs of properly rehabilitating, restoring, and preserving these historic buildings may be prohibitive for property owners; and

WHEREAS, Administrative Code, Chapter 71, was adopted to implement the provisions of the Mills Act and to preserve these historic buildings; and

WHEREAS, 1401 Howard Street is designated as Article 10 individual Landmark
Number 120 and is listed on the National Register of Historic Places and thus qualifies as an
historical property as defined in Administrative Code, Section 71.2; and

WHEREAS, A Mills Act application for an historical property contract has been submitted by 1401 Howard LLC, the owner of 1401 Howard Street, detailing rehabilitation work and proposing a maintenance plan for the property; and

WHEREAS, As required by Administrative Code, Section 71.4(a), the application for the historical property contract for 1401 Howard Street was reviewed by the Assessor's Office and the Historic Preservation Commission; and

WHEREAS, The Assessor-Recorder has reviewed the historical property contract and has provided the Board of Supervisors with an estimate of the property tax calculations and the difference in property tax assessments under the different valuation methods permitted by the Mills Act in its report transmitted to the Board of Supervisors on October 15, 2019, which report is on file with the Clerk of the Board of Supervisors in File No. 191065 and is hereby declared to be a part of this Resolution as if set forth fully herein; and

WHEREAS, The Historic Preservation Commission recommended approval of the historical property contract in its Resolution No. 1091, including approval of the Rehabilitation Program and Maintenance Plan, attached to said Resolution, which is on file with the Clerk of the Board of Supervisors in File No. 191065 and is hereby declared to be a part of this Resolution as if set forth fully herein; and

WHEREAS, The draft historical property contract between 1401 Howard LLC, the owner of 1401 Howard Street, and the City and County of San Francisco is on file with the Clerk of the Board of Supervisors in File No. 191065 and is hereby declared to be a part of this Resolution as if set forth fully herein; and

WHEREAS, The Board of Supervisors has conducted a public hearing pursuant to Administrative Code, Section 71.4(d), to review the Historic Preservation Commission's recommendation and the information provided by the Assessor's Office in order to determine whether the City should execute the historical property contract for 1401 Howard Street; and

WHEREAS, The Board of Supervisors has balanced the benefits of the Mills Act to the owner of 1401 Howard Street with the cost to the City of providing the property tax reductions authorized by the Mills Act, as well as the historical value of 1401 Howard Street and the resultant property tax reductions, and has determined that it is in the public interest to enter into a historical property contract with the applicants; now, therefore, be it

RESOLVED, That the Board of Supervisors hereby approves the historical property contract between 1401 Howard LLC, the owner of 1401 Howard Street, and the City and County of San Francisco; and, be it

FURTHER RESOLVED, That the Board of Supervisors hereby authorizes the Planning Director and the Assessor-Recorder to execute the historical property contract and record the historical property contract.

SIDELIUOD FOX SIIN OF SION

Government Audit and Oversight Committee Review

November 21, 2019





What is the Mills Act?


- California's leading financial incentive program for historic preservation since 1972.
- Contract between the City and property owner that allows for a potential reduction in property taxes.
- Tax savings will be used to offset cost of rehabilitation, restoration, and maintenance work in conformance with the Secretary's Standards.
- Only local financial incentive program for restoring, rehabilitating, and maintaining eligible properties to promote appreciation of the City's architecture, history, and culture.





Active Mills Act Contracts

























2251 Webster Street (built c. 1900) Contributor to Webster Street Historic District District 2



- Estimated Property Tax Savings of \$14,184 (a 66.37%% reduction from factored base year value)
- Rehabilitation work is estimated to cost \$113,610 over ten years
- Maintenance work is estimated to cost \$2,880 annually



1401 Howard Street (built 1913) Landmark No. 120, Saint Joseph's Church District 6




- Estimated Property Tax Savings of \$66,974 (a 31.20% reduction from factored base year value)
- Rehabilitation work is estimated to cost \$291,065 over ten years
- Maintenance work is estimated to cost \$31,040 annually



64 Potomac Street (built 1899) Duboce Park Historic District


District 8



- Estimated Property Tax Savings of \$22,679 (a 76.47% reduction from factored base year value)
- Rehabilitation work is estimated to cost \$126,035 over ten years
- Maintenance work is estimated to cost \$4,000 annually



2168 Market Street (built 1907) Landmark No. 267, Swedish American Hall Building District 8




- Estimated Property Tax Savings of \$0 (a 0.00% reduction from factored base year value)
- Rehabilitation work is estimated to cost \$95,160 over ten years
- Maintenance work is estimated to cost \$7,500 annually



2731-2735 Folsom Street (built 1900)

Landmark No. 276, Gaughran House



- Estimated Property Tax Savings of \$35,495 (a 49.46% reduction from factored base year value)
- Rehabilitation work is estimated to cost \$305,573 over ten years
- Maintenance work is estimated to cost \$5,148 annually



Recording Requested by, and when recorded, send notice to: Michelle Taylor 1650 Mission Street, Suite 400 San Francisco, CA 94103-2414

CALIFORNIA MILLS ACT HISTORIC PROPERTY AGREEMENT

THIS AGREEMENT is entered into by and between the City and County of San Francisco, a California municipal corporation ("City") and 1401 Howard, LLC ("Owner").

RECITALS

Owner is the owner of the property located at 1401 Howard Street, in San Francisco, California (Block 3517, Lot 035). The building located at 1401 Howard Street is designated as individual landmark No. 120 pursuant to Article 10 of the Planning Code, and is also known as the "Historic Property". The Historic Property is a Qualified Historic Property, as defined under California Government Code Section 50280.1.

Owner desires to execute a rehabilitation and ongoing maintenance project for the Historic Property. Owner's application calls for the rehabilitation and restoration of the Historic Property according to established preservation standards, which it estimates will cost two hundred ninety-one thousand and sixty-five dollars (\$291,065.00) (See Rehabilitation Plan, Exhibit A.) Owner's application calls for the maintenance of the Historic Property according to established preservation standards, which is estimated will cost approximately thirty-one thousand and forty dollars (\$31,040.00) annually (See Maintenance Plan, Exhibit B).

The State of California has adopted the "Mills Act" (California Government Code Sections 50280-50290, and California Revenue & Taxation Code, Article 1.9 [Section 439 et seq.]) authorizing local governments to enter into agreements with property Owner to reduce their property taxes, or to prevent increases in their property taxes, in return for improvement to and maintenance of historic properties. The City has adopted enabling legislation, San Francisco Administrative Code Chapter 71, authorizing it to participate in the Mills Act program.

Owner desires to enter into a Mills Act Agreement (also referred to as a "Historic Property Agreement") with the City to help mitigate anticipated expenditures to restore and maintain the Historic Property. The City is willing to enter into such Agreement to mitigate these expenditures and to induce Owner to restore and maintain the Historic Property in excellent condition in the future.

NOW, THEREFORE, in consideration of the mutual obligations, covenants, and conditions contained herein, the parties hereto do agree as follows:

- 1. <u>Application of Mills Act.</u> The benefits, privileges, restrictions and obligations provided for in the Mills Act shall be applied to the Historic Property during the time that this Agreement is in effect commencing from the date of recordation of this Agreement.
- 2. <u>Rehabilitation of the Historic Property.</u> Owner shall undertake and complete the work set forth in Exhibit A ("Rehabilitation Plan") attached hereto according to certain standards and

requirements. Such standards and requirements shall include, but not be limited to: the Secretary of the Interior's Standards for the Treatment of Historic Properties ("Secretary's Standards"); the rules and regulations of the Office of Historic Preservation of the California Department of Parks and Recreation ("OHP Rules and Regulations"); the State Historical Building Code as determined applicable by the City; all applicable building safety standards; and the requirements of the Historic Preservation Commission, the Planning Commission, and the Board of Supervisors, including but not limited to any Certificates of Appropriateness approved under Planning Code Article 10. The Owner shall proceed diligently in applying for any necessary permits for the work and shall apply for such permits within no more than six (6) months after recordation of this Agreement, shall commence the work within six (6) months of receipt of necessary permits, and shall complete the work within three (3) years from the date of receipt of permits. Upon written request by the Owner, the Zoning Administrator, at his or her discretion. may grant an extension of the time periods set forth in this paragraph. Owner may apply for an extension by a letter to the Zoning Administrator, and the Zoning Administrator may grant the extension by letter without a hearing. Work shall be deemed complete when the Director of Planning determines that the Historic Property has been rehabilitated in accordance with the standards set forth in this Paragraph. Failure to timely complete the work shall result in cancellation of this Agreement as set forth in Paragraphs 12 and 13 herein.

- 3. <u>Maintenance</u>. Owner shall maintain the Historic Property during the time this Agreement is in effect in accordance with the standards for maintenance set forth in Exhibit B ("Maintenance Plan"), the Secretary's Standards; the OHP Rules and Regulations; the State Historical Building Code as determined applicable by the City; all applicable building safety standards; and the requirements of the Historic Preservation Commission, the Planning Commission, and the Board of Supervisors, including but not limited to any Certificates of Appropriateness approved under Planning Code Article 10.
- Damage. Should the Historic Property incur damage from any cause whatsoever, which damages fifty percent (50%) or less of the Historic Property, Owner shall replace and repair the damaged area(s) of the Historic Property. For repairs that do not require a permit, Owner shall commence the repair work within thirty (30) days of incurring the damage and shall diligently prosecute the repair to completion within a reasonable period of time, as determined by the City. Where specialized services are required due to the nature of the work and the historic character of the features damaged, "commence the repair work" within the meaning of this paragraph may include contracting for repair services. For repairs that require a permit(s), Owner shall proceed diligently in applying for any necessary permits for the work and shall apply for such permits within no more than sixty (60) days after the damage has been incurred, commence the repair work within one hundred twenty (120) days of receipt of the required permit(s), and shall diligently prosecute the repair to completion within a reasonable period of time, as determined by the City. Upon written request by the Owner, the Zoning Administrator, at his or her discretion, may grant an extension of the time periods set forth in this paragraph. Owner may apply for an extension by a letter to the Zoning Administrator, and the Zoning Administrator may grant the extension by letter without a hearing. All repair work shall comply with the design and standards established for the Historic Property in Exhibits A and B attached hereto and Paragraph 3 herein. In the case of damage to twenty percent (20%) or more of the Historic Property due to a catastrophic event, such as an earthquake, or in the case of damage from any cause whatsoever that destroys more than fifty percent (50%) of the Historic Property, the City and Owner may mutually agree to terminate this Agreement. Upon such termination, Owner shall not be obligated to pay the cancellation fee set forth in Paragraph 13 of this Agreement. Upon such termination, the City shall assess the full value of the Historic Property without regard to any restriction imposed upon the Historic Property by this Agreement and Owner shall pay property taxes to the City based upon the valuation of the Historic Property as of the date of termination.

- 5. <u>Insurance.</u> Owner shall secure adequate property insurance to meet Owner's repair and replacement obligations under this Agreement and shall submit evidence of such insurance to the City upon request.
- 6. <u>Inspections and Compliance Monitoring.</u> Prior to entering into this Agreement and every five years thereafter, and upon seventy-two (72) hours advance notice, Owner shall permit any representative of the City, the Office of Historic Preservation of the California Department of Parks and Recreation, or the State Board of Equalization, to inspect of the interior and exterior of the Historic Property, to determine Owner's compliance with this Agreement. Throughout the duration of this Agreement, Owner shall provide all reasonable information and documentation about the Historic Property demonstrating compliance with this Agreement, as requested by any of the above-referenced representatives.
- 7. <u>Term.</u> This Agreement shall be effective upon the date of its recordation and shall be in effect for a term of ten years from such date ("Term"). As provided in Government Code section 50282, one year shall be added automatically to the Term, on each anniversary date of this Agreement, unless notice of nonrenewal is given as set forth in Paragraph 9 herein.
- 8. <u>Valuation</u>. Pursuant to Section 439.4 of the California Revenue and Taxation Code, as amended from time to time, this Agreement must have been signed, accepted and recorded on or before the lien date (January 1) for a fiscal year (the following July 1-June 30) for the Historic Property to be valued under the taxation provisions of the Mills Act for that fiscal year.
- 9. Notice of Nonrenewal. If in any year of this Agreement either the Owner or the City desire not to renew this Agreement, that party shall serve written notice on the other party in advance of the annual renewal date. Unless the Owner serves written notice to the City at least ninety (90) days prior to the date of renewal or the City serves written notice to the Owner sixty (60) days prior to the date of renewal, one year shall be automatically added to the Term of the Agreement. The Board of Supervisors shall make the City's determination that this Agreement shall not be renewed and shall send a notice of nonrenewal to the Owner. Upon receipt by the Owner of a notice of nonrenewal from the City, Owner may make a written protest. At any time prior to the renewal date, City may withdraw its notice of nonrenewal. If either party serves notice of nonrenewal of this Agreement, this Agreement shall remain in effect for the balance of the period remaining since the original execution or the last renewal of the Agreement, as the case may be. Thereafter, the Owner shall pay property taxes to the City without regard to any restriction imposed on the Historic Property by this Agreement, and based upon the Assessor's determination of the fair market value of the Historic Property as of expiration of this Agreement.
- 10. Payment of Fees. As provided for in Government Code Section 50281.1 and San Francisco Administrative Code Section 71.6, upon filing an application to enter into a Mills Act Agreement with the City, Owner shall pay the City the reasonable costs related to the preparation and approval of the Agreement. In addition, Owner shall pay the City for the actual costs of inspecting the Historic Property, as set forth in Paragraph 6 herein.
- 11. <u>Default.</u> An event of default under this Agreement may be any one of the following:
- (a) Owner's failure to timely complete the rehabilitation work set forth in Exhibit A, in accordance with the standards set forth in Paragraph 2 herein;
- (b) Owner's failure to maintain the Historic Property as set forth in Exhibit B, in accordance with the requirements of Paragraph 3 herein;
- (c) Owner's failure to repair any damage to the Historic Property in a timely manner, as provided in Paragraph 4 herein;

(d) Owner's failure to allow any inspections or requests for information, as provided in Paragraph 6 herein;

(e) Owner's failure to pay any fees requested by the City as provided in Paragraph 10

herein;

(f) Owner's failure to maintain adequate insurance for the replacement cost of the Historic Property, as required by Paragraph 5 herein; or

(g) Owner's failure to comply with any other provision of this Agreement.

An event of default shall result in Cancellation of this Agreement as set forth in Paragraphs 12 and 13 herein, and payment of the Cancellation Fee and all property taxes due upon the Assessor's determination of the full value of the Historic Property as set forth in Paragraph 13 herein. In order to determine whether an event of default has occurred, the Board of Supervisors shall conduct a public hearing as set forth in Paragraph 12 herein prior to cancellation of this Agreement.

- 12. <u>Cancellation</u>. As provided for in Government Code Section 50284, City may initiate proceedings to cancel this Agreement if it makes a reasonable determination that Owner has breached any condition or covenant contained in this Agreement, has defaulted as provided in Paragraph 11 herein, or has allowed the Historic Property to deteriorate such that the safety and integrity of the Historic Property is threatened or it would no longer meet the standards for a Qualified Historic Property. In order to cancel this Agreement, City shall provide notice to the Owner and to the public and conduct a public hearing before the Board of Supervisors as provided for in Government Code Section 50285. The Board of Supervisors shall determine whether this Agreement should be cancelled.
- 13. <u>Cancellation Fee.</u> If the City cancels this Agreement as set forth in Paragraph 12 above, and as required by Government Code Section 50286, Owner shall pay a Cancellation Fee of twelve and one-half percent (12.5%) of the fair market value of the Historic Property at the time of cancellation. The City Assessor shall determine fair market value of the Historic Property without regard to any restriction imposed on the Historic Property by this Agreement. The Cancellation Fee shall be paid to the City Tax Collector at such time and in such manner as the City shall prescribe. As of the date of cancellation, the Owner shall pay property taxes to the City without regard to any restriction imposed on the Historic Property by this Agreement and based upon the Assessor's determination of the fair market value of the Historic Property as of the date of cancellation.
- 14. <u>Enforcement of Agreement.</u> In lieu of the above provision to cancel the Agreement, the City may bring an action to specifically enforce or to enjoin any breach of any condition or covenant of this Agreement. Should the City determine that the Owner has breached this Agreement, the City shall give the Owner written notice by registered or certified mail setting forth the grounds for the breach. If the Owner do not correct the breach, or do not undertake and diligently pursue corrective action to the reasonable satisfaction of the City within thirty (30) days from the date of receipt of the notice, then the City may, without further notice, initiate default procedures under this Agreement as set forth in Paragraph 12 and bring any action necessary to enforce the obligations of the Owner set forth in this Agreement. The City does not waive any claim of default by the Owner if it does not enforce or cancel this Agreement.
- 15. <u>Indemnification</u>. The Owner shall indemnify, defend, and hold harmless the City and all of its boards, commissions, departments, agencies, agents and employees (individually and collectively, the "City") from and against any and all liabilities, losses, costs, claims, judgments, settlements, damages, liens, fines, penalties and expenses incurred in connection with or arising in whole or in part from: (a) any accident, injury to or death of a person, loss of or damage to property occurring in or about the Historic Property; (b) the use or occupancy of the Historic Property by the Owner, their Agents or Invitees; (c) the condition of the Historic Property; (d)

any construction or other work undertaken by Owner on the Historic Property; or (e) any claims by unit or interval Owner for property tax reductions in excess those provided for under this Agreement. This indemnification shall include, without limitation, reasonable fees for attorneys, consultants, and experts and related costs that may be incurred by the City and all indemnified parties specified in this Paragraph and the City's cost of investigating any claim. In addition to Owner's obligation to indemnify City, Owner specifically acknowledge and agree that they have an immediate and independent obligation to defend City from any claim that actually or potentially falls within this indemnification provision, even if the allegations are or may be groundless, false, or fraudulent, which obligation arises at the time such claim is tendered to Owner by City, and continues at all times thereafter. The Owner's obligations under this Paragraph shall survive termination of this Agreement.

- 16. <u>Eminent Domain.</u> In the event that a public agency acquires the Historic Property in whole or part by eminent domain or other similar action, this Agreement shall be cancelled and no cancellation fee imposed as provided by Government Code Section 50288.
- 17. <u>Binding on Successors and Assigns.</u> The covenants, benefits, restrictions, and obligations contained in this Agreement shall run with the land and shall be binding upon and inure to the benefit of all successors in interest and assigns of the Owner. Successors in interest and assigns shall have the same rights and obligations under this Agreement as the original Owner who entered into the Agreement.
- 18. <u>Legal Fees.</u> In the event that either the City or the Owner fail to perform any of their obligations under this Agreement or in the event a dispute arises concerning the meaning or interpretation of any provision of this Agreement, the prevailing party may recover all costs and expenses incurred in enforcing or establishing its rights hereunder, including reasonable attorneys' fees, in addition to court costs and any other relief ordered by a court of competent jurisdiction. Reasonable attorneys' fees of the City's Office of the City Attorney shall be based on the fees regularly charged by private attorneys with the equivalent number of years of experience who practice in the City of San Francisco in law firms with approximately the same number of attorneys as employed by the Office of the City Attorney.
- 19. <u>Governing Law.</u> This Agreement shall be construed and enforced in accordance with the laws of the State of California.
- 20. <u>Recordation.</u> Within 20 days from the date of execution of this Agreement, the parties shall cause this Agreement to be recorded with the Office of the Recorder of the City and County of San Francisco. From and after the time of the recordation, this recorded Agreement shall impart notice to all persons of the parties' rights and obligations under the Agreement, as is afforded by the recording laws of this state.
- 21. <u>Amendments.</u> This Agreement may be amended in whole or in part only by a written recorded instrument executed by the parties hereto in the same manner as this Agreement.
- 22. <u>No Implied Waiver.</u> No failure by the City to insist on the strict performance of any obligation of the Owner under this Agreement or to exercise any right, power, or remedy arising out of a breach hereof shall constitute a waiver of such breach or of the City's right to demand strict compliance with any terms of this Agreement.
- 23. <u>Authority</u>. If the Owner signs as a corporation or a partnership, each of the persons executing this Agreement on behalf of the Owner does hereby covenant and warrant that such entity is a duly authorized and existing entity, that such entity has and is qualified to do business in California, that the Owner has full right and authority to enter into this Agreement, and that each and all of the persons signing on behalf of the Owners are authorized to do so.

Severability. If any provision of this Agreement is determined to be invalid or unenforceable, the remainder of this Agreement shall not be affected thereby, and each other provision of this Agreement shall be valid and enforceable to the fullest extent permitted by law. Tropical Hardwood Ban. The City urges companies not to import, purchase, obtain or use for any purpose, any tropical hardwood or tropical hardwood product. 26. Charter Provisions. This Agreement is governed by and subject to the provisions of the Charter of the City. 27. Signatures. This Agreement may be signed and dated in parts IN WITNESS WHEREOF, the parties hereto have executed this Agreement as follows: CITY AND COUNTY OF SAN FRANCISCO: DATE: Carmen Chu, Assessor-Recorder By: DATE: John Rahaim, Director of Planning APPROVED AS TO FORM: DENNIS J. HERRERA CITY ATTORNEY DATE:

OWNER(S)' SIGNATURE(S) MUST BE NOTARIZED. ATTACH PUBLIC NOTARY FORMS HERE.

Christopher Foley, 1401 Howard Street, LLC, Owner

Andrea Ruiz-Esquide, Deputy City Attorney

OWNER(S)

REHABILITATION / RESTORATION & MAINTENANCE PLAN (CONTINUED/ ATTACHMENT)

Exhibit A. Rehabilitation/Restoration Plan

Scope:#1					
	rior Gates, Curbs	s, Fence, Piers, Granite Steps	5		
Rehab/Restoration	X Mainten	nance Completed	X Proposed		
Contract year work co	mpletion: 2018				
Total Cost: \$25,000.00	O Source SOV #2	2920			
Description of work: R	estoration and Re	epair of Exterior Gates, Curbs	s, Fences, Piers and Granite		
Steps					
The direction of the swing of all gates was reversed in the direction of egress. The gates					
were prepared, primed, and painted, and latch and lock sets were provided. At the two					

- were prepared, primed, and painted, and latch and lock sets were provided. At the two existing double gateways, the existing gates were reinstalled on new freestanding supports similar to the existing. The original hinges were retained at the original piers. The displaced sections of the piers were reset in the original locations and grouted. The cement plaster parge was repaired as required to match the original.
- The iron fence was prepared, primed, and painted. The gaps and voids were filled with mortar at the base and pier attachments. Where the fence is set into the curb and is corroded, the metal was repaired, painted, and set into lead or sealant as required to prevent future damage to the fence or curb.
- The cement plaster parge on the piers was cleaned and graffiti was removed or painted over. The cement plaster parge was repaired to match the existing adjacent color and texture as required.
- Existing joints were raked out and the granite steps were cleared of debris. Joints were repaired with mortar. Algae, moss, and other biological growth was removed. Soil and paint spatters were removed. New code-required bronze handrails were installed.

Scope: #2					
Building Feature: Exterior	Paint and Stucco Repa	air			
Rehab/Restoration X	Maintenance		Completed >	Proposed	
Contract year work compl	etion: 2018 Phase 1, P	hase 2	2 scheduled fo	r 2026	
Total Cost: \$146,950. Sou	irce SOV #9900 (half)	, \$293	850/2=\$146,9	50.	

Description of work: Façade Restoration and Full Repainting

- The existing stucco was analyzed to determine if it was lime or Portland cement-based. These tests were performed by an architectural conservator.
- Staining and soiling was removed by the gentlest means possible, this included light brushing and water washing, and cleaning with a commercial agent.
- Areas of significant hairline cracking were repaired based on analysis to determine the root cause of the condition. Investigation included testing for underlying detachment of the stucco layer, moisture intrusion, structural movement, or other causes.
- Climbing vegetation such as ivy was removed.
- Spalls and cracks through cement plaster were repaired. The cracks were routed and patched to match the existing adjacent texture, profile, and appearance.
- The existing deteriorated or detached cement plaster was removed. Graffiti and stains were removed.
- Unsound paint was removed and coated with a new breathable paint coating.

May 31, 2019

Page & Turnbull, Inc.

Scope: #18 Building Feature: Extendecorative moldings;	7456. 310	r_Sheet Metal Elements, r ers and down spouts	ncluding domes	on	towers, column capitals,	
Rehab/Restoration	X	Maintenance	Completed	X	Proposed	
Contract year work co	omp	letion: 2018	•			
Total Cont. \$424 222	<u> </u>	1100 COV #7600 - \$424 2	22			

Total Cost: \$424,323. Source SOV #7600 = \$434,323

Description of work: Repair and Restoration of Exterior Sheet Metal Elements

- Peeling or blistering paint was scraped or sanded.
- Corrosion was removed with hand scrapers or a wire brush.
- For panels with heavy corrosion and resulting perforation of the sheet metal unit, there were three options, dependent on severity and size:
 - 1. Corroded panels were removed and the unit was replaced with a new piece of sheet metal cut to the appropriate dimension and profile,
 - 2. The corroded area was cut out of existing sheet metal, a new piece was brazewelded and the joint was ground flat; or
 - 3. The corroded area was cut out of existing sheet metal and steel-filled epoxy compound was installed to patch small holes.
- All exposed metal was painted with a rust-inhibiting primer and two coats of color-appropriate outdoor paint.
- Missing elements were replaced to maintain visual consistency.

Scope:#4			
Building Feature: Exteri	or_Wood-sash Windows	and Steel Tracery	
Rehab/Restoration X	Maintenance	Completed X	Proposed
Contract year work.com	pletion: 2018		
Total Cost: \$366,443. S	ource SOV #6150 and #	8050 for \$96,867 and \$2	269,576 = 366,443
	pair, Restoration and Rep		
determine the e included careful	itions assessment of wind xtent of deterioration and I inspection and document nvasive diagnostic tests.	appropriate treatments a	t each window. This
while providing	ndow frames attempted to adequate moisture protect wood elements in areas of nd.	tion for the building, and	included paint removal,
The wood frame	es were prepared and pair reused. Ribbed glass that		

Scope #5								
Building Feature: Ex	teriorS	stained Glass W	/indows				Elekaria (d. 1	
Rehab/Restoration	X	Maintenance		Completed	χ	Proposed		
Contract year work of	completio	n: 2018				,		
Total Cost: \$81,260.	00 Sour	ce SOV #8070	•					

Description of work: Repair and Restoration of Stained Glass Windows

- Documentation and restoration of the windows was performed by a professional conservator. Restoration included removal, transport, restoration, and reinstallation of the stained glass.
- The wood and steel armatures remaining from the previous stained glass window installation were prepared and painted.
- The remaining stained glass in the south wall of the kitchen was removed, salvaged, and reinstalled in the office on the first floor.

April, 2019

Page & Turnbull, Inc.

Scope: #6						
Building Feature: Exte	rior Skylight					
Rehab/Restoration	X Maintenance	Completed X	Proposed :			
Contract year work co	mpletion: 2018		•			
Total Cost: \$39,010.00	0 Source SOV #8080					
Description of work: R	Description of work: Repair and Restoration of Exterior Skylight					
The steel skylight remained in place and was repaired and cleaned.						
New tempered glazing and sealant was installed, and all work and flashing details were						
coordinated with the roof strengthening and re-roofing work.						

Scope: #7 Building Feature: Into	erior S	tructural Steel for Seisi			
Rehab/Restoration		Maintenance	Completed X	Proposed	
Contract year work of	omple	tion: 2018			
Total Cost: \$571,841 Source SOV 8 items #5050, 5070 and 5120					
Description of work:			•	•	
 Steel was fa 	bricate	d and installed for seis	mic strengthening.		

Scope: # 8 Building Feature: Interior	Decorative Plaster			
Rehab/Restoration X	Maintenance	Completed X	Proposed	
Contract year work comp	letion: 2018			
Total Cost: \$1,350,577.00	Source SOV #9050,	\$1,350,577.		
D 1111111111111		D		

Description of work: Repair and Restoration of Interior Decorative Plaster

- Detached or cracked plaster elements were repaired, if in otherwise sound condition, with an injected epoxy or gypsum-based grout. Testing was conducted to determine the most effective adhesive.
- Non-historic wood veneer was removed so that plaster at the base of the wall could be restored and painted.
- Further testing of the plaster was conducted to determine the extent of deterioration. This determined the treatment method: patching and reshaping damaged elements when possible, or replacement in kind.

					· · · · · · · · · · · · · · · · · · ·
Scope: #9					
Building Feature: Inte	erior V	Voodwork, Doors and F	inish Hardware		
Rehab/Restoration	X	Maintenance	Completed X	Proposed	
Contract year work c	omple	etion: 2018		•	
Total Cost: \$269,000	.00 \$	Source SOV #8200		•	
Description of work:	Danai	r and Restoration of Inte	prior Moodwork Doors	s and Einich Hardw	Oro.

Description of work: Repair and Restoration of Interior Woodwork, Doors and Finish Hardware

- Soiling was cleaned with the gentlest means possible, using a soft bristle brush to remove loose dust and a damp cloth for tenacious soiling.
- Blistered varnish was treated with the gentlest means possible in order to preserve the existing finish. Treatments included lightly scraping blistered areas of varnish and spottreating with fine steel wool or cotton, alcohol and a compatible varnish or shellac.
- White stains were tested to determine the cause Paint and guano were removed mechanically with a scraper so as not to damage the existing wood finish.
- Where required by the level of damage, select areas of woodwork were refinished to match the original.

- Wood was replaced where missing to match the original.
- At exterior doors, deteriorated wood was repaired with wood Dutchman and matched the original species, grade, grain, and profile. The exterior surface was prepped and painted. The interior was cleaned and touched up or refinished to match the original stain or clear coat
- Door hardware was replaced or repaired to match existing and to meet current code.

Scope: #10 Building Feature: Inte	erior N	Marble Wainscoting and	d Tiles			
Rehab/Restoration	X	Maintenance	Completed	X	Proposed	
Contract year work c	omple	etion: 2018	,			
Total Cost: \$5,000.00) Sou	rce From KFI (3/28/19	email)			
Description of work:	Resto	ration of Interior Marble	9 .			

- Tape residue and soiling was removed with a gentle stone cleaner. Mock-ups were conducted to determine the most effective product.
- Vinyl tiles and mastic were removed in the vestibule without causing damage to underlying marble, which was cleaned with a gentle stone cleaner to remove staining and adhesive. Mockups were conducted to determine the most effective product.
- Vinyl tiles and mastic were removed from the vestibule floor and cleaned using the gentlest means possible.
- The marble floors were polished to restore luster

			·			
Scope	#11					
Buildin	g Feature: Inte	erior Na	ve Floor Concrete			
Rehab	/Restoration	X	Maintenance	Completed X	Proposed	
Contra	ct year work co	ompleti	on: 2018			
Total C	Cost: \$207,357	Sourc	e (4 items) SOV #205	50, #2250, #2300 and I	KFI, \$30,000 \$7,50	0
\$79,84	7 \$45,410 an	id \$44,	600	•		
Descrip	otion of work:		•	•	_	
Ħ	The existing	(non his	storic) slab was remov	red .	,	
	Soil was exca	avated	and the surrounding s	oil was underpinned.		
M			ith piers and grade be			
. #	New stage or	ver the	grade beams was ins	talled in the apse.		

			•	
Scope: #12				
Building Feature: Inte	erior Tower Floor Concrete			
Rehab/Restoration	X Maintenance	Completed X	Proposed	
Contract year work o	completion: 2018			
Total Cost: \$573,000	0.00 Source SOV #2450 ar	nd #2460 and KFI		
Description of work:				
 The concrete 	e sloped floor was replaced	I with a new flat structural	concrete slab.	
 New micropi 	ile foundations were installe	ed in the towers.	•	
 The top 10 fe 	eet of the micro piles were	cased in concrete.		
 Tower walls 	reinforced in concrete and	covered in plaster		

Scope #13 Building Feature: Ex	terior	Lighting			
Rehab/Restoration	X	Maintenance	Completed X	Proposed	
Contract year work of	ompl	etion: 2018			

Apríl, 2019

Page & Tumbull, Inc.

Total Cost: \$92,625.00 Source SOV #16080

Description of work:

- The missing original fixtures on the main entry façade were replicated based on historic documentation.
- Building façade lighting was replaced with LED fixtures to save energy.

Total and appropriate the second seco	the enthalteness of transitivitation between	Contract systems of an arrangement of the Contract of the Cont		en anne all'internationale de la company	Ottomer metalicana and mentral Maria Salara.
Scope:#14			4302		
Building Feature: Inte	erior Lighting				
Rehab/Restoration	X M:	aintenance	Completed X	Proposed	
Contract year work c	ompletion: 2	018			
Total Cost: \$135,281	.00 Source	SOV #16070			* 4 .
Description of work: I	Repair, Rest	oration and R	eplacement in kind of h	nistoric light fixture	es:
 The historic I 	ight fixtures	were cleaned	and relamped.		
 The missing 	fixtures in th	e main sanctı	uarv were replicated.		

		The state of the s		
Scope. # To				
Building Feature: Ro	of //E	Built-up Roof		
Rehab/Restoration	X	Maintenance	Completed X	Proposed
Contract year work of	omp	letion: 2018		
Total Cost: \$28,110.	00 S	ource SOV #7500		
Description of work:				
 Existing built 	t-up r	oofing was removed at t	he lower roofs.	
 New built-up 	roof	ing was installed over ne	w structural decking.	•

Scope:	#16				
Building	g Feature: Roo	f / Slate	Roof		
Rehab/	Restoration	X	Maintenance	Completed X	Proposed
Contrac	ct year work co	mpletion	າ: 2018		
Total C	ost: \$258,950.0	00 Sour	ce SOV #7300		
Descrip	otion of work:			·	
ń	Existing slate	roof tile	was removed at	the main roof and portals	, salvaged, and reinstalled
	to allow acces	ss for str	uctural stabilizat	tion of the roof structure.	
Ħ	Deteriorated a	and brok	en tiles were rep	placed with salvaged stock	or new tile to match the
	existing.		•	•	
×	New felt unde	rlaymen	t and galvanized	d flashing was installed.	,

Scope:	#17					
Building	g Feature: Inter	ior Paintir	19			
	Restoration		Maintenance	Complete	d X	Proposed
Contrac	ct year work co	mpletion:	2018 Phase 1, P	hase 2 schedule	d for	2026
Total C	ost: \$146,950.0	00 Source	e SOV #9900 (ha	alf), \$293850/2=	146,	,950
Descrip	otion of work:					
			paint to find origit			
. д	Interior plaster	r was pair	nted, interior woo	d was refinished	, and	window mullions were .
1	repainted.					
E	Lead paint wa	s abated.				

Scope: #18 Building Feature: Roof/Sheet Metal Dome and Sheet Metal.	Crosses
	pleted X Proposed
Contract year work completion: 2018	Joed [X] Proposed
Total Cost: \$60,000.00 Source SOV #9950	
Description of work:	
Gold leaf was reapplied to the domes and crosses.	
Scope: #19	
Building Feature: ADA Upgrades: Exterior Ramp	
	oleted X Proposed
Contract year work completion: 2018	
Total Cost: 12,000.00 Conversation with contractor	· · · · · · · · · · · · · · · · · · ·
Description of work:	
 Ramp provided at transept. Auto operator provided at existing door. 	
Auto operator provided at existing door.	
Scope #20	
Scope: #20 Building Feature: Interior Painting	
Building Feature: Interior Painting	pleted Proposed X
Building Feature: Interior Painting: Rehab/Restoration X Maintenance Comp	oleted Proposed X
Building Feature Interior Painting Rehab/Restoration X Maintenance Comp Contract year work completion: 2026	oleted Proposed X
Building Feature: Interior Painting: Rehab/Restoration X Maintenance Comp	oleted Proposed X
Building Feature Interior Painting Rehab/Restoration X Maintenance Comp Contract year work completion: 2026 Total Cost: \$50,000.00 See Source SOV #9900	oleted Proposed X
Building Feature Interior Painting Rehab/Restoration X Maintenance Comp Contract year work completion: 2026 Total Cost: \$50,000.00 See Source SOV #9900 Description of work:	oleted Proposed X
Building Feature: Interior Painting Rehab/Restoration X Maintenance Comp Contract year work completion: 2026 Total Cost: \$50,000.00 See Source SOV #9900 Description of work: Partial repainting of interior walls. Scope: #21	oleted Proposed X
Building Feature Interior Painting Rehab/Restoration X Maintenance Comp Contract year work completion: 2026 Total Cost: \$50,000.00 See Source SOV #9900 Description of work: Partial repainting of interior walls.	
Building Feature: Interior Painting Rehab/Restoration X Maintenance Comp Contract year work completion: 2026 Total Cost: \$50,000.00 See Source SOV #9900 Description of work: Partial repainting of interior walls. Scope: #21 Building Feature: Exterior Painting of Gement Plaster Rehab/Restoration X Maintenance Comp	
Building Feature: Interior Painting Rehab/Restoration X Maintenance Comp Contract year work completion: 2026 Total Cost: \$50,000.00 See Source SOV #9900 Description of work: Partial repainting of interior walls. Scope: #:21 Building Feature: Exterior Painting of Gement Plaster	oleted Proposed X
Building Feature: Interior Painting Rehab/Restoration X Maintenance Comp Contract year work completion: 2026 Total Cost: \$50,000.00 See Source SOV #9900 Description of work: Partial repainting of interior walls. Scope: #21 Building Feature: Exterior Painting of Gement Plaster Rehab/Restoration X Maintenance Comp Contract year work completion: 2026	oleted Proposed X

Exhibit B Maintenance Plan

Landscape									
Maintenance	X	Completed	Proposed	X	•				
Contract year work completion: 2028 and every 10 years thereafter									
) (\$1,000/month x 12	mo x	: 10 yrs)							
Description of work: Washing of sidewalks and granite entry steps. Granite steps will be cleaned									
using the gentlest means possible as recommended in NPS Preservation Brief No. 1: Assessing									
pellent Treatments for	or His	storic Masonry Buildings	. All work will	be pe	erformed				
Secretary of the Inte	erior	Standards.							
	npletion: 2028 and evo 0 (\$1,000/month x 12) ashing of sidewalks and as possible as recommo pellent Treatments for	Maintenance X ppletion: 2028 and every 1 0 (\$1,000/month x 12mo x ashing of sidewalks and grass possible as recommendated and the commendated as	Maintenance X Completed inpletion: 2028 and every 10 years thereafter 0 (\$1,000/month x 12mo x 10 yrs) ashing of sidewalks and granite entry steps. Grani ins possible as recommended in NPS Preservation	Maintenance X Completed Proposed ppletion: 2028 and every 10 years thereafter (\$1,000/month x 12mo x 10 yrs) ashing of sidewalks and granite entry steps. Granite steps will be no possible as recommended in NPS Preservation Brief No. 1: Appellent Treatments for Historic Masonry Buildings. All work will be not preserved.	Maintenance X Completed Proposed X ppletion: 2028 and every 10 years thereafter 0 (\$1,000/month x 12mo x 10 yrs) ashing of sidewalks and granite entry steps. Granite steps will be cleans possible as recommended in NPS Preservation Brief No. 1: Assessepellent Treatments for Historic Masonry Buildings. All work will be performed.				

Scope:#2					
Building Feature: Exterior	or_Stucco				
Rehab/Restoration	Maintenance	X	Completed	Proposed	X
Contract year work com	pletion: 2019 and an	nual	lly thereafter		
Total Cost: \$40,000 (ma	intenance of 4,000/y	/r x1	Oyrs) .		
Description of work: Reg	gular repainting of ex	teric	or stucco as needed	l to address graffiti.	. Perform
visual inspection annual	ly for signs of blister	ing c	or peeling paint.		-

Scope:#3								
Building Feature: Roof								
Rehab/Restoration	Maintenance [X	Completed	Proposed	X			
Contract year work completion: 2019 and annually thereafter								
Total Cost: \$30,000.00	maintenance of \$3,00	00 x 10yrs)						
Description of work: Inspect the slate roof for loose or broken tiles and replace as needed. Inspect								
and repair caulking and	lashing. Clear drains,	, overflow o	drains and scup	pers. Remove I	oirds nests			
and discourage roosting.								

· ·						
Scope:#4						
Building Feature: Exterior	or Sheet Metal Elem	ents,	including domes on	towers, column o	apitals,	
decorative moldings, gu	itters and down spo	uts.				
Rehab/Restoration	Maintenance	X	Completed	Proposed	X	
Contract year work com	pletion: 2019 and ar	nually	thereafter			
Total Cost: \$12,000.00 ((\$1200 per year)					
Description of work: Per	form visual inspection	on ann	nually for rust, holes	and signs of wat	er where i	it
shouldn't be. Clean gutt	ers, replace screens	, ched	ck down spouts and	clean drains. Re	pair dama	aged
pieces to match existing	using appropriate n	nateria	als and methods. All	repairs will be pe	erformed i	in
conformance with the Se	ecretary of the Interi	or Sta	indards.			

Scope: # 5					
Building Feature: Exterio	r Wood-sash Windov	vs an	id Steel Tracery.		
Rehab/Restoration	Maintenance	X	Completed	Proposed	X
Contract year work comp	letion: 2019 and ann	ually	thereafter.		
Total Cost: \$10,000.00 (\$	31000 per year)				
Description of work: Performed windows, window locks a					
performed in accordance				7 til Williad W To	pane will be

Scope.#6				
Building Feature: Exterior	or Skylight		· · · · · · · · · · · · · · · · · · ·	
Rehab/Restoration	Maintenance 2	Completed	Proposed X	
Contract year work comp	oletion: 2019 and annu	ally thereafter	•	
Total Cost: \$5,000.00 (\$	500 per year)			
Description of work: Per	form visual inspection	annually for signs of ca	aulking failure, condensation	
problems that might com	promise structure of s	kylight and replace an	y cracked or broken glass in	
kind. All repairs will be p	erformed in conformar	ice with the Secretary	of the Interior Standards.	•

Scope: #7/ Building Feature: Exteri	or Stained Glass Win	ndows						
Rehab/Restoration	Maintenance		Completed	Proposed	[X]			
Contract year work completion: 2019 and annually thereafter								
Total Cost: \$16,000.00	(\$1600 per year)							
Description of work: Ins matches original glass i All work will be performe accordance with NPS P and Leaded Glass	n color and texture. In ed in conformance wi	nspect	and repair lead came Secretary of the Interi	s. or's Standards	s and in			

Scope:#8 Building Feature Extend	r-Wood Doors						
Rehab/Restoration	Maintenan ce	X	C	ompleted	Proposed	X	
Contract year work completion: 2019 and annually thereafter							
Total Cost: \$7,900.00 (\$	790 per year)						
Description of work: The	face of the wood do	ors ha	ve extre	me exposur	e to rain and sur	n. They	
suffered significant deter						finishing. All	
work will be performed in	ı conformance with t	the Sec	cretary o	of the Interior	r's Standards		

				•		
Scope: #9						
Building Feature: Interior	Decorative Plaster					
Rehab/Restoration	Maintenance	X	Completed	Proposed	X	
Contract year work comp	oletion: 2019 and ev	егу 1	0 years thereafter		•	
Total Cost: \$20,000.00 (\$2000 per year)					
Description of work: The	existing plaster was	pre\	viously damaged when v	water got into	the attic a	and
behind the decorative pla	aster ceiling. Probler	ns o	n the surface appeared	only after cons	siderable	
damage was done inside	the concealed space	ces, f	therefore there will be vi	isual inspectio	ns annua	lly
must look inside the attic	for signs of water d	ama	ge and make needed re	pairs.		
All work will be performe	d in conformance wi	th th	e Secretary of the Interi	or's Standards	and in	
accordance with NPS Pr	eservation Brief No.	23: I	Preserving Historic Orna	emental Plaste	r.	

Scope: # 10 Building Feature: Interio	r. Woodwork							
Rehab/Restoration	Maintenance X	Completed	Proposed D	X				
Contract year work completion: 2019 and annually thereafter								
Total Cost: \$16,000.00	(\$1600 per year)							
Description of work: Per	form visual inspection annu	ally for damage and	repair in the gent	lest means				
possible. All work will be	e performed in conformance	with the Secretary o	f the Interior's Sta	andards.				

Scope: #11								
Building Feature: Bell To	ower							
Rehab/Restoration	Maintenance	X	Completed	Proposed	X			
Contract year work completion: 2019 and annually thereafter								
Total Cost: \$18,500.00 (\$1850 per year)		•					
Description of work: Ann	nual visual inspectio	n of l	bell rope and hanging r	nechanism. Clir	nb the			
ladders and go into the	attic spaces and ren	nove	birds and close up any	gaps in the scre	eens and.			
louvers.			•					

Scope: # IZ					Michael Commission (Commission Commission Commission Commission Commission Commission Commission Commission Co
Building Feature: Site D	rainage				
Rehab/Restoration	Maintenance	X	Completed	Proposed	Χ
Contract year work com	pletion: 2019 and an	nually	thereafter		•
Total Cost: \$11,500 (\$1,	500 per year)				
Description of work: Inst	ect drywells in gard	en are	eas and verify site drain	nage is function	ning to
remove standing water.					

Scope: #13	English of the Line								
Building Feature: Interior	plaster								
Rehab/Restoration .	Maintenance	X	Completed	Proposed	Χ				
Contract year work com	oletion: 2023 and bi-	annu	ally thereafter						
Total Cost: \$80,000			•						
Description of work; Rep	aint public spaces a	and re	epair plaster work as n	ecessary. All wo	ork will be				
	performed in conformance with the Secretary of the Interior's Standards and in accordance with								
NPS Preservation Brief I	No. 23: Preserving I	Histor	ic Ornamental Plaster	and No. 21: Re	pairing				
Historic Flat Plaster Wal	ls and Ceilings								

Scope: #14 Building Feature: Interio	r Marble Floors			
Rehab/Restoration	Maintenance X	Completed	Proposed	X
Contract year work com	pletion: 2022 and annuall	y thereafter		
Total Cost: \$8,000		,		, , , , , , , , , , , , , , , , , , ,
Description of work: Cle	an and reseal marble floo	rs and wainscot. All m	arble will be clea	aned using
the gentlest means poss	sible as recommended in l	NPS Preservation Brie	f No. 1: Assess	ing Cleaning
and Water-Repellent Tre	eatments for Historic Mas	onry Buildings	•	•

Scope: #15						
Building Feature: Interior	or wood floors, wood	doors	and wood paneling			
Rehab/Restoration	Maintenance	X	Completèd	Proposed	Χ	
Contract year work com	pletion: 2022 and ar	nually	thereafter			
Total Cost: \$12,000						
Description of work: Cor	iduct a visual inspec	tion a	nd repair as needed to	o match origina	I. All work	k will
meet the Secretary of th	e Interior's Standard	ls.	•	· ·	•	



Mills Act Historical Property Contracts Case Report

Hearing Date:

October 2, 2019

Staff Contact:

Michelle Taylor - (415) 575-9197

Michelle Taylor@sfgov.org

Reviewed By:

Elizabeth Gordon-Jonckheer – (415) 575-8728 Elizabeth Gordon-Jonckheer @sfgov.org 1650 Mission St.

CA 94103-2479

Reception:
415.558.6378

415.558.6409

415.558.6377

Planning Information:

Suite 400 San Francisco.

.

a. Filing Date:

May 1, 2019

Case No.:

2019-006323MLS

Project Address:

2251 Webster Street (District 2)

Landmark District:

Contributor to the Webster Street Historic District RH-2 (Residential-House, Two-Family District)

Zoning: Height &Bulk:

40-X

Block/Lot:

0612/001A

Applicant:

Sally A. Sadosky Revocable Trust

2251 Webster Street

San Francisco, CA 94115

b. Filing Date:

May 1, 2019

Case No.:

2019-006384MLS

Project Address:

1401 Howard Street (District 6)

Landmark No.:

120

Zoning:

RCD - Regional Commercial District

Height and Bulk:

55/65-X

Block/Lot:

3517/035

Applicant:

1401 Howard LLC

1401 Howard Street

San Francisco, CA 94103

c. Filing Date:

May 1, 2019

Case No.:

2019-006322MLS

Project Address:

64 Potomac Street (District 8)

Landmark District:

Contributor to the Duboce Park Historic District

Zoning:

RH-2 (Residential-House, Two-Family District)

Height and Bulk:

40-X

Block/Lot:

0866/014

Applicant:

Gustav Lindquist & Caroline Ingeborn

64 Potomac Street

San Francisco, CA 94117

www.sfplanning.org

1266

Mill Act Applications October 2, 2019

2019-006323MLS (2251 Webster Street); 2019-006384MLS (1401 Howard Street); 2019-006323MLS (64 Potomac Street); 2019-005831MLS (2168 Market Street); 2019-006455MLS (2731-2735 Folsom Street);

d. Filing Date:

May 1, 2019

Case No.:

2019-005831MLS

Project Address:

2168 Market Street (District 8)

Landmark No.:

267

Zoning:

NCT - Upper Market Neighborhood Commercial Transit

Height and Bulk:

40/50-X

Block/Lot:

3542/062

Applicant:

Swedish Society of San Francisco

2168 Market Street

San Francisco, CA 94114

e. Filing Date:

May 1, 2019

Case No.:

2019-006455MLS

Project Address:

2731-2735 Folsom Street (District 9)

Landmark No.:

276

Zoning:

RH-2 – Residential-House, Two-Family

Height and Bulk:

40-X 3640/031

Block/Lot:

Adele Feng

Applicant:

2733 Folsom Street

San Francisco, CA 94110

PROPERTY DESCRIPTIONS

- a. <u>2251 Webster Street:</u> The subject property is located on the west side of Webster Street between Washington and Clay streets, Assessor's Block 0612, Lot 001A. The subject property is located within a RH-2 (Residential-House, Two-Family District) zoning district and a 40-X Height and Bulk district. The subject property is a contributing building to the Webster Street Historic District. It is a two-story, plus basement, wood-frame, single-family dwelling designed in the Italianate style and built in circa 1900.
- b. 1401 Howard Street: The subject property is located on the south corner of Howard and 10th Streets, Assessor's Block 3517, Lot 035. The subject property is located within an RCD (Regional Commercial District) zoning district and a 55/65-X Height and Bulk district. The subject property, historically known as St. Joseph's Church, is an Article 10 individual landmark (No. 120), located in the California Register Western SOMA Light Industrial and Residential Historic District, and added to the National Register of Historic Places in 1982. The subject property is a former Catholic church constructed in 1913 and designed in the Romanesque Revival style by architect John J. Foley.
- c. 64 Potomac Street: The subject property is located on the east side of Potomac Street between Waller Street and Duboce Park, Assessor's Block 0866 Lot 014. The subject property is located within a RH-2 (Residential-House, Two-Family District) zoning district and a 40-X Height and

Bulk district. The subject property is a contributing building to the Article 10 Duboce Park Historic District. It is a two story over garage, wood-frame, single-family dwelling built in 1899 and features a gable roof and bay window.

- d. <u>2168 Market Street</u>: The subject property is located on the north side of Market Street between Sanchez and Church streets, Assessor's Block 3542 Lot 062. The subject property is located within an NCT (Upper Market Neighborhood Commercial Transit) zoning district and a 40/50-X Height and Bulk district. The subject property is an Article 10 individual landmark (No. 267). It is a three-story wood-frame commercial building constructed in 1907 and designed by master architect August Noridn.
- e. 2731-2735 Folsom Street: The subject property is located on the west side of Folsom Street between 23rd and 24th streets, Assessor's Block 3640, Lot 031. The subject property is located within the RH-2 (Residential House, Two Family) zoning district and 40-X Height and Bulk district. The subject property is a three-story, wood frame, three-unit residential building with a rectangular plan. The subject property is an Article 10 individual landmark building (No. 276). The subject property was designed in the Beaux-Arts style by architect James Francis Dunn (1874-1921) and constructed in 1900 for James Gaughran.

PROJECT DESCRIPTION

This project is a Mills Act Historical Property Contract application.

MILLS ACT REVIEW PROCESS

Once a Mills Act application is received, the matter is referred to the Historic Preservation Commission (HPC) for review. The HPC shall conduct a public hearing on the Mills Act application, historical property contract, and proposed rehabilitation and maintenance plan, and make a recommendation for approval or disapproval to the Board of Supervisors.

The Board of Supervisors will hold a public hearing to review and approve or disapprove the Mills Act application and contract. The Board of Supervisors shall conduct a public hearing to review the Historic Preservation Commission recommendation, information provided by the Assessor's Office, and any other information the Board requires in order to determine whether the City should execute a historical property contract for the subject property.

The Board of Supervisors shall have full discretion to determine whether it is in the public interest to enter into a Mills Act contract and may approve, disapprove, or modify and approve the terms of the contract. Upon approval, the Board of Supervisors shall authorize the Director of Planning and the Assessor-Recorder's Office to execute the historical property contract.

MILLS ACT REVIEW PROCEDURES

The Historic Preservation Commission is requested to review and make recommendations on the following:

- The draft Mills Act Historical Property Contract between the property owner and the City and County of San Francisco.
- The proposed rehabilitation and maintenance plan.

The Historic Preservation Commission may also comment in making a determination as to whether the public benefit gained through restoration, continued maintenance and preservation of the property is sufficient to outweigh the subsequent loss of property taxes to the City.

APPLICABLE PRESERVATION STANDARDS

Ordinance No. 191-96 amended the San Francisco Administrative Code by adding Chapter 71 to implement the California Mills Act, California Government Code Sections 50280 *et seq.* The Mills Act authorizes local governments to enter into contracts with private property owners who will rehabilitate, restore, preserve, and maintain a "qualified historical property." In return, the property owner enjoys a reduction in property taxes for a given period. The property tax reductions must be made in accordance with Article 1.9 (commencing with Section 439) of Chapter 3 of Part 2 of Division 1 of the California Revenue and Taxation Code.

TERM

Mills Act contracts must be made for a minimum term of ten years. The ten-year period is automatically renewed by one year annually to create a rolling ten-year term. One year is added automatically to the initial term of the contract on the anniversary date of the contract, unless notice of nonrenewal is given or the contract is terminated. If the City issues a notice of nonrenewal, then one year will no longer be added to the term of the contract on its anniversary date and the contract will only remain in effect for the remainder of its term. The City must monitor the provisions of the contract until its expiration and may terminate the Mills Act contract at any time if it determines that the owner is not complying with the terms of the contract or the legislation. Termination due to default immediately ends the contract term. Mills Act contracts remain in force when a property is sold.

ELIGIBILITY

San Francisco Administrative Code Chapter 71, Section 71.2, defines a "qualified historic property" as one that is not exempt from property taxation and that is one of the following:

- (a) Individually listed in the National Register of Historic Places;
- (b) Listed as a contributor to an historic district included on the National Register of Historic Places;
- (c) Designated as a City landmark pursuant to San Francisco Planning Code Article 10;
- (d) Designated as contributory to a landmark district designated pursuant to San Francisco Planning Code Article 10; or
- (e) Designated as significant (Categories I or II) or contributory (Categories III or IV) to a conservation district designated pursuant to San Francisco Planning Code Article 11.

SAN FRANCISCO
PLANNING DEPARTMENT

4

All properties that are eligible under the criteria listed above must also meet a tax assessment value to be eligible for a Mills Act Contract. The tax assessment limits are listed below:

Residential Buildings

Eligibility is limited to a property tax assessment value of not more than \$3,000,000.

Commercial, Industrial or Mixed-Use Buildings

Eligibility is limited to a property tax assessment value of not more than \$5,000,000.

Properties may be exempt from the tax assessment values if it meets any one of the following criteria:

- The qualified historic property is an exceptional example of architectural style or represents a
 work of a master architect or is associated with the lives of persons important to local or national
 history; or
- Granting the exemption will assist in the preservation and rehabilitation of a historic structure (including unusual and/or excessive maintenance requirements) that would otherwise be in danger of demolition, deterioration, or abandonment;

Properties applying for a valuation exemption must provide evidence that it meets the exemption criteria, including a historic structure report to substantiate the exceptional circumstances for granting the exemption. The Historic Preservation Commission shall make specific findings in determining whether to recommend to the Board of Supervisors that the valuation exemption should be approved. Final approval of this exemption is under the purview of the Board of Supervisors.

PRIORITY CRITERIA CONSIDERATIONS

Staff reviewed all applications on the merits of five Priority Consideration. The five priority considerations are:

Necessity: The project will require a financial incentive to help ensure the preservation of the property. This criterion will establish that the property is in danger of deterioration and in need of substantial rehabilitation and restoration that has significant associated costs. Properties with open complaints, enforcement cases or violations will not meet this criterion.

Investment: The project will result in additional private investment in the property other than for routine maintenance. This may include seismic retrofitting and substantial rehabilitation and restoration work. This criterion will establish that the owner is committed to investing in the restoration, rehabilitation and maintenance the property.

Distinctiveness: The project preserves a distinctive example of a property that is especially deserving of a contract due to its exceptional nature.

Recently Designated City Landmarks: properties that have been recently designated landmarks will be given priority consideration.

Legacy Business: The project will preserve a property at which a business included in the Legacy Business Registry is located. This criterion will establish that the owner is committed to preserving the property, including physical features that define the existing Legacy Business.

PUBLIC/NEIGHBORHOOD INPUT

The Department has not received any public comment regarding the Mills Act Historical Property Contract.

STAFF ANAYLSIS

The Department received five Mills Act applications by the May 1, 2019 filing date. The Project Sponsors, Planning Department Staff, and the Office of the City Attorney have negotiated the five attached draft historical property contracts, which include a draft rehabilitation and maintenance plan for the historic building. Department Staff believes the draft historical property contracts and plans are adequate. Please see below for complete analysis.

a. <u>2251 Webster Street:</u> As detailed in the Mills Act application, the applicant proposes to rehabilitate and maintain the historic property. Staff determined that the proposed work, detailed in the attachments, is consistent with the Secretary of Interior's Standards for Rehabilitation.

The subject property is currently valued by the Assessor's Office as under \$3,000,000 (see attached Market Analysis and Income Approach reports) and did not require a Historic Structure Report.

The applicant completed some rehabilitation of the building in 2019, including dry rot repair and painting with an estimated cost of \$12,650. The proposed Rehabilitation Plan includes in kind window replacement, interior plaster and lathe repair from and exterior leak, in-kind replacement of the front and rear doors, roof repair and replacement, painting. Rehabilitation work is estimated to cost \$113,610 over ten years.

The proposed Maintenance Plan includes annual inspection of the wood siding, windows, and roof. Maintenance work is estimated to cost \$2,880 annually. Any needed repairs will be made in kind and will avoid altering, removing or obscuring character-defining features of the building.

No changes to the use of the property are proposed. Please refer to the attached Rehabilitation and Maintenance Plan for a full description of the proposed work. The attached draft historical property contract will help the applicant mitigate these expenditures and will induce the applicant to maintain the property in excellent condition in the future.

The subject property meets three of the five Priority Considerations: Necessity, Investment and Distinctiveness. The proposed rehabilitation will require significant associated costs to ensure the preservation of the subject property. The property owner will invest additional money towards

the rehabilitation other than for routine maintenance. Finally, the proposed rehabilitation project will preserve a distinctive example of a grouping of Italianate homes constructed circa 1900. The subject property does not meet the Recently Designated City Landmarks or the Legacy Business criteria. The building was designated an Article 10 landmark district in 1991 and therefore is not a recent landmark. A Legacy Business is not located at the subject property.

b. 1401 Howard Street: As detailed in the Mills Act application, the applicant proposes to rehabilitate and maintain the historic property. Staff determined that the proposed work, detailed in the attachments, is consistent with the Secretary of Interior's Standards for Rehabilitation.

The subject property is currently valued by the Assessor's Office at over \$5,000,000 (see attached Market Analysis and Income Approach reports); therefore, an exemption from the tax assessment value is required. The subject property qualifies for an exemption as it is designated an individual landmark under Article 10 of the Planning Code. A Historic Structure Report was required in order to demonstrate that granting the exemption would assist in the preservation of a property that might otherwise be in danger of demolition, deterioration or abandonment.

In 2018, the applicant completed a full rehabilitation and restoration of the building and received final approval for the Federal Historic Preservation Tax Incentive in September 2018. Work included the restoration of exterior and interior finishes, seismic strengthening, repair of the slate roof, and restoration of the sheet metal domes. The cost of the completed work was approximately \$3,962,310.00.

Future rehabilitation and restoration scope items include full repainting of the interior and exterior. The estimated cost of the proposed rehabilitation work is \$291,065.00 over ten years.

The proposed Maintenance Plan includes annual inspection of exterior stucco, metal roof elements, windows, doors, and roof on a regular basis. The applicant will be maintaining interior character defining features identified in the National Register nomination, such as the entry lobby floors, plaster detailing, and woodwork. Maintenance work is estimated to cost \$31,040 annually. Any needed repairs will be made in kind and will avoid altering, removing or obscuring character-defining features of the building.

No changes to the use of the property are proposed. Please refer to the attached Rehabilitation and Maintenance Plan for a full description of the proposed work. The attached draft historical property contract will help the applicant mitigate these expenditures and will induce the applicant to maintain the property in excellent condition in the future.

The subject property meets two of the five Priority Considerations: Distinctiveness and Investment. The building represents a distinctive example of the Romanesque Revival architectural style. Completed in 2018, the applicant has invested in a full building restoration and rehabilitation scope, including seismic strengthening. The subject application does not meet the Necessity, Recently Designated Landmark, and Legacy Business criteria. The applicant completed a full building rehabilitation and restoration scope in 2018 and the building is in excellent condition; therefore, the application does not meet the Necessity criteria. The building

was designated an Article 10 landmark in 1980 and therefore is not a recent landmark. A Legacy Business is not located at the subject property.

c. <u>64 Potomac Street:</u> As detailed in the Mills Act application, the applicant proposes to rehabilitate and maintain the historic property. Staff determined that the proposed work, detailed in the attachments, is consistent with the Secretary of Interior's Standards for Rehabilitation.

The subject property is currently valued by the Assessor's Office as under \$3,000,000 (see attached Market Analysis and Income Approach reports) and did not require a Historic Structure Report.

The proposed Rehabilitation Plan includes seismic strengthening, roof replacement, wood siding repair and painting, front façade window repair, restoration of front stairs, front door and garage door replacement. Rehabilitation work is estimated to cost \$126,035 over ten years.

The proposed Maintenance Plan includes annual inspection of roof, gutters and downspouts, windows, doors, foundation, and wood siding and trim. Any needed repairs will be made in kind and will avoid altering, removing or obscuring character-defining features of the building. Maintenance work is estimated to cost approximately \$4,000 annually.

No changes to the use of the property are proposed. Please refer to the attached Rehabilitation and Maintenance Plan for a full description of the proposed work. The attached draft historical property contract will help the applicant mitigate these expenditures and will induce the applicant to maintain the property in excellent condition in the future.

The subject property meets three of the five Priority Considerations: Necessity, Investment and Distinctiveness. The proposed rehabilitation will require significant associated costs to ensure the preservation of the subject property. The property owner will invest additional money towards the rehabilitation other than for routine maintenance. Finally, the proposed rehabilitation project will preserve a distinctive example of Victorian style home. The subject property does not meet the Recently Designated City Landmarks or the Legacy Business criteria. The building was designated an Article 10 landmark district in 2013 and therefore is not a recent landmark. A Legacy Business is not located at the subject property.

d. <u>2168 Market Street:</u> As detailed in the Mills Act application, the applicant proposes to rehabilitate and maintain the historic property. Staff determined that the proposed work, detailed in the attachments, is consistent with the Secretary of Interior's Standards for Rehabilitation.

The subject property is currently valued by the Assessor's Office as under \$5,000,000 (see attached Market Analysis and Income Approach reports) and did not require a Historic Structure Report.

The proposed Rehabilitation Plan includes repair and restoration of the exterior front entry features such as terrazzo, doors, windows, and brick. Rehabilitation work is estimated to cost \$95,160 over ten years.

The proposed Maintenance Plan includes annual inspection of front façade, windows, interior wood elements, and roof. Any needed repairs resulting from inspection will be made in kind and will avoid altering, removing or obscuring character-defining features of the building. Maintenance work is estimated to cost approximately \$7,500 annually.

No changes to the use of the property are proposed. Please refer to the attached Rehabilitation and Maintenance Plan for a full description of the proposed work. The attached draft historical property contract will help the applicant mitigate these expenditures and will induce the applicant to maintain the property in excellent condition in the future. A Certificate of Appropriateness has been submitted for the following scopes to be completed in the next two to three years: replace existing non historic main doors and supporting framework; replace non-historic glass window facing market street with leaded glass window to match the historic nature of the façade.

The subject property meets three of the five Priority Considerations. It represents an exceptional example of the Arts & Crafts architectural style and therefore meets the Distinctiveness priority consideration. The building was designated an Article 10 landmark in 2015 and was designated on the National Register of Historic Places in 2019 and therefore is a recent landmark. In 2015 the applicant performed a full building rehabilitation, including seismic strengthening and elevator upgrades, at the subject property; therefore, the subject property not meet the Necessity or Investment criteria. Café du Nord, a registered Legacy Business ca. 2016, is located at the subject property and will continue to operate as such.

e. <u>2731-2735 Folsom Street:</u> As detailed in the Mills Act application, the applicant proposes to rehabilitate and maintain the historic property. Staff determined that the proposed work, detailed in the attachments, is consistent with the Secretary of Interior's Standards for Rehabilitation.

The subject property is currently valued by the Assessor's Office at over \$3,000,000 (see attached Market Analysis and Income Approach reports); therefore, an exemption from the tax assessment value is required. The subject property qualifies for an exemption as it is designated an individual landmark under Article 10 of the Planning Code. A Historic Structure Report was required in order to demonstrate that granting the exemption would assist in the preservation of a property that might otherwise be in danger of demolition, deterioration or abandonment.

The building underwent a full rehabilitation c.2014 which included full re-painting of all elevations, façade restoration, structural strengthening, and re-roofing. The proposed Rehabilitation Plan includes dry rot repair of wood elements at the base of the building, repair and restoration of windows, improve site drainage against foundation of building, repaint exterior, replace roof flashing, and fully re-roof the building. Rehabilitation work is estimated to cost \$305,573 over ten years.

The proposed Maintenance Plan includes annual inspection of gutters and downspouts, windows, front facade, and roof. Any needed repairs resulting from inspection will be made in

2019-006323MLS (2251 Webster Street); 2019-006384MLS (1401 Howard Street); 2019-006323MLS (64 Potomac Street); 2019-005831MLS (2168 Market Street); 2019-006455MLS (2731-2735 Folsom Street);

kind and will avoid altering, removing or obscuring character-defining features of the building. Maintenance work is estimated to cost approximately \$5,148 annually.

No changes to the use of the property are proposed. Please refer to the attached Rehabilitation and Maintenance Plan for a full description of the proposed work. The attached draft historical property contract will help the applicant mitigate these expenditures and will induce the applicant to maintain the property in excellent condition in the future.

The subject property meets three of the five Priority Considerations: Distinctiveness, Investment and Recently Designated City Landmark. The subject property represents a distinctive and well-preserved example of the Beaux-Arts style architecture. The property owner will be investing additional money towards the rehabilitation other than for routine maintenance. Additionally, in 2017 the City of San Francisco designated the subject building as an individual landmark under Article 10. The subject property does not meet the Necessity and Legacy Business criteria. In 2014, a full building rehabilitation, including seismic strengthening, was performed therefore the building is in good condition. Furthermore, the building is fully occupied and is not in danger of deterioration or abandonment. A Legacy Business is not located at the subject property.

ASSESSOR-RECORDER INFORMATION

Based on information received from the Assessor-Recorder, the following properties will receive an estimated first year reduction as a result of the Mills Act Contract. Please refer to the attached Preliminary Valuation spreadsheet prepared by the Assessor for detailed information about each property.

- a) <u>2251 Webster Street:</u> Estimated Property Tax Savings of <u>\$14,184</u> (a 66.37% reduction from factored base year value)
- b) <u>1401 Howard Street:</u> Estimated Property Tax Savings of <u>\$66,974</u> (a 31.20% reduction from factored base year value)
- c) <u>64 Potomac Street:</u> Estimated Property Tax Savings of <u>\$22,679</u> (a 76.47% reduction from factored base year value)
- d) <u>2168 Market Street:</u> Estimated Property Tax Savings of \$0 (a 0.00% reduction from factored base year value). The property owner is aware that they will not receive a tax savings but would like to move forward with the Mills Act knowing that the property will be re-evaluated in the future.
- e) <u>2731-2735 Folsom Street:</u> Estimated Property Tax Savings of <u>\$35,495</u> (a 49.46% reduction from factored base year value)

PLANNING DEPARTMENT RECOMMENDATION

- The Planning Department recommends that the Historic Preservation Commission adopt a resolution recommending approval of the Mills Act Historical Property Contracts and Rehabilitation and Maintenance Plans to the Board of Supervisors for the following properties:
 - a. 2251 Webster Street
 - b. 1401 Howard Street
 - c. 64 Potomac Street
 - d. 2168 Market Street
 - e. 2731-2735 Folsom Street

ISSUES AND OTHER CONSIDERATIONS

Mills Act Contract property owners are required to submit an annual affidavit demonstrating compliance with Rehabilitation and Maintenance Plans.

HISTORIC PRESERVATION COMMISSION ACTIONS

Review and adopt a resolution for each property:

- 1. Recommending to the Board of Supervisors approval of the proposed Mills Act Historical Property Contract between the property owner(s) and the City and County of San Francisco;
- Approving the proposed Mills Act Rehabilitation and Maintenance Plan for each property.

Attachments:

a. 2251 Webster Street:

Site & Aerial Photos

Draft Resolution

Draft Mills Act Historical Property Contract

Draft Rehabilitation Program& Maintenance Plan

Draft Mills Act Valuation provided by the Assessor-Recorder's Office

Pre-Approval Inspection Report

Mills Act Application

b. 1401 Howard Street:

Site & Aerial Photos

Draft Resolution

Draft Mills Act Historical Property Contract

Draft Rehabilitation Program & Maintenance Plan

Draft Mills Act Valuation provided by the Assessor-Recorder's Office

Pre-Approval Inspection Report

Mills Act Application

SAN FRANCISCO
PLANNING DEPARTMENT

. 11

Mill Act Applications October 2, 2019

2019-006323MLS (2251 Webster Street); 2019-006384MLS (1401 Howard Street); 2019-006323MLS (64 Potomac Street); 2019-005831MLS (2168 Market Street); 2019-006455MLS (2731-2735 Folsom Street);

Historic Structure Report

c. 64 Potomac Street:

Site & Aerial Photos

Draft Resolution

Draft Mills Act Historical Property Contract

Draft Rehabilitation Program & Maintenance Plan

Draft Mills Act Valuation provided by the Assessor-Recorder's Office

Pre-Approval Inspection Report

Mills Act Application

d. 2168 Market Street:

Site & Aerial Photos

Draft Resolution

Draft Mills Act Historical Property Contract

Draft Rehabilitation Program & Maintenance Plan

Draft Mills Act Valuation provided by the Assessor-Recorder's Office

Pre-Approval Inspection Report

Mills Act Application

e. 2731-2735 Folsom Street:

Site & Aerial Photos

Draft Resolution

Draft Mills Act Historical Property Contract

Draft Rehabilitation Program & Maintenance Plan

Draft Mills Act Valuation provided by the Assessor-Recorder's Office

Pre-Approval Inspection Report

Mills Act Application

Historic Structure Report

Case No.:

2019-006384MLS

Project Address:

1401 Howard Street (District 6) Article 10 Landmark Number 120

Landmark District:

Zoning:

RCD (Regional Commercial)

Height and Bulk:

55/65-X 3517/035

Block/Lot: Applicant:

1401 Howard Street, LLC


1401 Howard Street

San Francisco, CA 94103

SITE PHOTO



AERIAL PHOTO



Historic Preservation Commission Resolution No. 1091

HEARING DATE OCTOBER 2, 2019

1650 Mission St. Suite 400 San Francisco, CA 94103-2479

Reception; 415.558.6378

Fax:

415.558.6409

Planning information: 415.558.6377

Case No.:

2019-006384MLS

Project Address:

1401 Howard Street (District 6)

Eligibility:

Article 10 Landmark No. 120: Saint Joseph's Church

National Register listed property

Zoning:

RCD - Regional Commercial

Height and Bulk:

55/65-X

Block/Lot: Staff Contact: 3517/035 Michelle Taylor – (415) 575-9197

Michelle.Taylor@sfgov.org

Reviewed By:

Elizabeth Gordon-Jonckheer - (415) 575-8728

Elizabeth.Gordon-Jonckheer@sfgov.org

ADOPTING FINDINGS RECOMMENDING TO THE BOARD OF SUPERVISORS APPROVAL OF THE DRAFT MILLS ACT HISTORICAL PROPERTY CONTRACT, REHABILITATION PROGRAM, AND MAINTENANCE PLAN FOR 1401 HOWARD STREET.

WHEREAS, The Mills Act, California Government Code Sections 50280 et seq. ("the Mills Act") authorizes local governments to enter into contracts with owners of private historical property who assure the rehabilitation, restoration, preservation and maintenance of a qualified historical property; and

WHEREAS, In accordance with Article 1.9 (commencing with Section 439) of Chapter 3 of Part 2 of Division 1 of the California Revenue and Taxation Code; the City and County of San Francisco may provide certain property tax reductions, such as those provided for in the Mills Act; and

WHEREAS, Ordinance No. 191-96 amended the San Francisco Administrative Code by adding Chapter 71, to implement Mills Act locally; and

WHEREAS, The Planning Department has determined that the actions contemplated in this Resolution are categorically exempt from with the California Environmental Quality Act (California Public Resources Code Sections 21000 et seq.) under section 15331; and

WHEREAS, The existing building located at 1401 Howard Street is listed under Article 10 as Landmark Number 120 and listed on the National Register of Historic Places and thus qualifies as a historical property for the purposes of the Mills Act, and

WHEREAS, The Planning Department has reviewed the Mills Act Application, draft Historical Property Contract, Rehabilitation Program, and Maintenance Plan for 1401 Howard Street, which are located in

essatsitiannang.org

Case Docket No. 2019-006384MLS. The Planning Department recommends approval of the draft Mills Act historical property contract, rehabilitation program, and maintenance plan; and

WHEREAS, The Historic Preservation Commission (HPC) recognizes the historic building at 1401 Howard Street as an historical resource and believes the Rehabilitation Program and Maintenance Plan are appropriate for the property; and

WHEREAS, At a duly noticed public hearing held on October 2, 2019, the HPC reviewed documents, correspondence and heard oral testimony on the Mills Act Application, Historical Property Contract, Rehabilitation Program, and Maintenance Plan for 1401 Howard Street, which are located in Case Docket No. 2019-006384MLS.

THEREFORE BE IT RESOLVED that the HPC hereby recommends that the Board of Supervisors approve the draft Mills Act Historical Property Contract, including the Rehabilitation Program and Maintenance Plan for the historic building located at 1401 Howard Street, attached herein as Exhibits A. and B, and fully incorporated by this reference.

BE IT FURTHER RESOLVED That the HPC hereby directs its Commission Secretary to transmit this Resolution, the draft Mills Act Historical Property Contract, including the Rehabilitation Program, and Maintenance Plan for 1401 Howard Street, and other pertinent materials in the case file 2019-006384MLS to the Board of Supervisors.

I hereby certify that the foregoing Resolution was ADOPTED by the Historic Preservation Commission on October 2, 2019.

Jonas P. Ionin

Commissions Secretary

AYES:

Johns, Pearlman, So, Hyland, Matsuda, Black

NOES:

None.

ABSENT:

None.

RECUSED:

Foley

ADOPTED:

October 2, 2019

REHABILITATION / RESTORATION & MAINTENANCE PLAN (CONTINUED/ ATTACHMENT)

Exhibit A. Rehabilitation/Restoration Plan

Building Feature: Ext	erior (Sates, Curbs, Fence, P	iers, Granite Steps		
Rehab/Restoration	X	Maintenance	Completed X	Proposed	
Contract year work o	omple	tion: 2018		•	
Total Cost: \$25,000.0	00 Soi	urce SOV #2920			
Description of work: I	Resto	ation and Repair of Ex	terior Gates, Curbs, Fe	nces, Piers and Grani	te
Stens					

- The direction of the swing of all gates was reversed in the direction of egress. The gates were prepared, primed, and painted, and latch and lock sets were provided. At the two existing double gateways, the existing gates were reinstalled on new freestanding supports similar to the existing. The original hinges were retained at the original piers. The displaced sections of the piers were reset in the original locations and grouted. The cement plaster parge was repaired as required to match the original.
- The iron fence was prepared, primed, and painted. The gaps and voids were filled with mortar at the base and pier attachments. Where the fence is set into the curb and is corroded, the metal was repaired, painted, and set into lead or sealant as required to prevent future damage to the fence or curb.
- The cement plaster parge on the piers was cleaned and graffiti was removed or painted over. The cement plaster parge was repaired to match the existing adjacent color and texture as required.
- Existing joints were raked out and the granite steps were cleared of debris. Joints were repaired with mortar. Algae, moss, and other biological growth was removed. Soil and paint spatters were removed. New code-required bronze handrails were installed.

Scope: #.2 Building Feature: Ext	ATTENDED TO STATE OF THE STATE	THE PERSON AND PROPERTY OF THE PERSON AND PARTY OF THE PERSON AND PARTY.		-175		
Rehab/Restoration	X	Maintenance	Completed	Χ	Proposed	
Contract year work co	ompletio	n: 2018 Phase 1,	Phase 2 scheduled f	or 2	2026	
Total Cost: \$146,950	. Source	SOV #9900 (hali	f), \$293850/2=\$146,	950).	

Description of work: Façade Restoration and Full Repainting

- The existing stucco was analyzed to determine if it was lime or Portland cement-based.
 These tests were performed by an architectural conservator.
- Staining and soiling was removed by the gentlest means possible, this included light brushing and water washing, and cleaning with a commercial agent.
- Areas of significant hairline cracking were repaired based on analysis to determine the root cause of the condition. Investigation included testing for underlying detachment of the stucco layer, moisture intrusion, structural movement, or other causes.
- Climbing vegetation such as ivy was removed.
- Spalls and cracks through cement plaster were repaired. The cracks were routed and patched to match the existing adjacent texture, profile, and appearance.
- The existing deteriorated or detached cement plaster was removed. Graffiti and stains were removed.
- Unsound paint was removed and coated with a new breathable paint coating

May 31, 2019

Page & Turnbull, Inc.

Scope:#3	A SHAP IN A SHAPE					
Building Feature: Ex				s or	towers, column	capitals,
decorative moldings,	gutte	s and down spouts				
Rehab/Restoration	X	Maintenance	Completed	X	Proposed	
Contract year work of	omple	tion: 2018	•			
Total Cost: \$424,323	. Sou	rce SOV #7600 = \$43	4,323		•	

Description of work: Repair and Restoration of Exterior Sheet Metal Elements

- Peeling or blistering paint was scraped or sanded.
- Corrosion was removed with hand scrapers or a wire brush.
- For panels with heavy corrosion and resulting perforation of the sheet metal unit, there were three options, dependent on severity and size:
 - 1. Corroded panels were removed and the unit was replaced with a new piece of sheet metal cut to the appropriate dimension and profile,
 - 2. The corroded area was cut out of existing sheet metal, a new piece was brazewelded and the joint was ground flat; or
 - 3. The corroded area was cut out of existing sheet metal and steel-filled epoxy compound was installed to patch small holes.
- All exposed metal was painted with a rust-inhibiting primer and two coats of colorappropriate outdoor paint.
- Missing elements were replaced to maintain visual consistency

Scope #4						
Building Feature: Exterior	Wood-sash Windows	and: Steel Tracery				
Rehab/Restoration X	Maintenance	Completed X	Proposed .			
Contract year work completi	on: 2018					
Total Cost: \$366,443. Source	ce SOV #6150 and # 8	3050 for \$96,867 and	\$269,576 = 366,443			
Description of Work: Repair	, Restoration and Repl	lacement of Windows				
W. A detailed conditions appropriate at unindexion at Ct. January, Church was a subject of the						

- A detailed conditions assessment of windows at St. Joseph's Church was conducted to determine the extent of deterioration and appropriate treatments at each window. This included careful inspection and documentation of each window frame and its conditions, and other non-invasive diagnostic tests.
- Repair of the window frames attempted to retain as much original material as possible, while providing adequate moisture protection for the building, and included paint removal, splicing of new wood elements in areas of severe deterioration, and replacement of all glazing compound.
- The wood frames were prepared and painted, all the existing ribbed glass that could be preserved was reused. Ribbed glass that matched the original was installed in selected locations.

	·				
Scope # 5			Walter	建建筑建筑设置设置	
Building Feature: Exterior	Stained Glass vvindo	NS表面的影響的影響			
Rehab/Restoration X	Maintenance	Completed	Χ	Proposed	
Contract year work comple	etion: 2018	·			
Total Cost: \$81,260.00 So	urce SOV #8070				

Description of work: Repair and Restoration of Stained Glass Windows

- Documentation and restoration of the windows was performed by a professional conservator. Restoration included removal, transport, restoration, and reinstallation of the stained glass.
- The wood and steel armatures remaining from the previous stained glass window installation were prepared and painted.
- The remaining stained glass in the south wall of the kitchen was removed, salvaged, and reinstalled in the office on the first floor.

April. 2019

Scope:#6						
Building Feature: Ext	erior Sk	ylight				
Rehab/Restoration	X	Maintenance	Completed	X	Proposed	
Contract year work c	ompletic	n: 2018				
Total Cost: \$39,010.0	00 Sour	ce SOV #8080				
Description of work:	Repair a	nd Restoration of Ex	terior Skylight			
 The steel sky 	/light rer	mained in place and v	was repaired and	clean	ed.	
 New tempered 	ed glazir	ng and sealant was ir	istalled, and all we	ork ar	nd flashing details were	<u>.</u>
coordinated	with the	roof etranathaning as	ad re-roofing work		•	

Scope: # 7 Building Feature: Interior S			
Rehab/Restoration X	Maintenance	Completed X	Proposed ·
Contract year work comple	tion: 2018		
Total Cost: \$571,841 Sour	ce SOV 8 items #5050), 5070 and 5120	-
Description of work: Seism	ic Strengthening		
 Steel was fabricate 	d and installed for seis	mic strengthening.	

Scope:#8									
Building Feature: Inte	TIOL 1	Decorative Plaster	地位。	HERARO BARRARA			2		
Rehab/Restoration	X	Maintenance		Completed	X	Proposed			
Contract year work co	Contract year work completion: 2018								
Total Cost: \$1,350,577.00 Source SOV #9050 , \$1,350,577									
Description of work: Repair and Restoration of Interior Decorative Plaster									

Detached or cracked plaster elements were repaired, if in otherwise sound condition, with an injected epoxy or gypsum-based grout. Testing was conducted to determine the most

effective adhesive.
Non-historic wood veneer was removed so that plaster at the base of the wall could be restored and painted.

Further testing of the plaster was conducted to determine the extent of deterioration. This determined the treatment method: patching and reshaping damaged elements when possible, or replacement in kind.

Scope:#9						
Building Fea	ture: Inte	erior Wo	oodwork, Doors and F	inish Hardware		
Rehab/Resto	oration	X	Maintenance	Completed X]	Proposed
Contract year	r work c	ompleti	on: 2018			· .
Total Cost: \$	269,000	.00 Sc	ource SOV #8200			
Description of	of work:	Repair	and Restoration of In	terior Woodwork, Doo	ors a	nd Finish Hardware
Soili	ng was o	deaned	l with the gentlest me	ans possible, using a	soft	bristle brush to remove
loos	e dust ai	nd a da	mp cloth for tenaciou	s soiling.		
■ Blist	ered var	nish wa	as treated with the ge	ntlest means possible	e in c	order to preserve the
exis	ting finisl	n. Trea	tments included lightly	y scraping blistered a	reas	of varnish and spot-
treat	ing with	fine ste	el wool or cotton, alc	ohol and a compatible	e va	rnish or shellac.
■ \A/bi	a ctaine	wore to	acted to determine the	cause Paint and du	ano	were removed

mechanically with a scraper so as not to damage the existing wood finish.Where required by the level of damage, select areas of woodwork were refinished to match the original.

- Wood was replaced where missing to match the original.
- At exterior doors, deteriorated wood was repaired with wood Dutchman and matched the original species, grade, grain, and profile. The exterior surface was prepped and painted. The interior was cleaned and touched up or refinished to match the original stain or clear coat.
- Door hardware was replaced or repaired to match existing and to meet current code.

Scope # 10				0244		斯夫加
		larble Wainscoting and				
Rehab/Restoration	X	Maintenance	Completed		Proposed	
Contract year work	omple	tion: 2018				
Total Cost: \$5,000.0	0 Sou	rce From KFI (3/28/19	email)			
Description of work:	Resto	ration of Interior Marble				

- Tape residue and soiling was removed with a gentle stone cleaner. Mock-ups were conducted to determine the most effective product.
- Vinyl tiles and mastic were removed in the vestibule without causing damage to underlying marble, which was cleaned with a gentle stone cleaner to remove staining and adhesive. Mockups were conducted to determine the most effective product.
- Vinyl tiles and mastic were removed from the vestibule floor and cleaned using the gentlest means possible.
- The marble floors were polished to restore luster

	-					
Scope #11						
Building Feature: Inte	erior Nav	e Floor Concrete				
Rehab/Restoration,	X	Maintenance	Completed	Χ	Proposed	
Contract year work c	ompletio	n: 2018				
Total Cost: \$207,357	Source	(4 items) SOV #20	050, #2250, #2300	and	KFI, \$30,000 \$7,500	
\$79,847 \$45,410 ar	nd \$44,6	00				
Description of work:						
 The existing 	(non his	oric) slab was remo	oved		•	
·	·					

- Soil was excavated and the surrounding soil was underpinned.
- New foundations, with piers and grade beams were installed
- New stage over the grade beams was installed in the apse.

		•	·					
Scope #12								
Building Feature: Into	tenor Tower Floor Concre	ete L						
Rehab/Restoration	X Maintenance	Completed X	Proposed					
Contract year work c	completion: 2018							
Total Cost: \$573,000	0.00 Source SOV #2450	and #2460 and KFI						
Description of work:								
 The concrete 	te sloped floor was replac	ced with a new flat structural	concrete slab.					
 New micropile foundations were installed in the towers. 								
The top 10 feet of the micro piles were cased in concrete.								
 Tower walls reinforced in concrete and covered in plaster. 								

Scope: # 13 Building Feature: Ex	erior	Lighting		
Rehab/Restoration	X	Maintenance	Completed X	Proposed
Contract year work of	omple	etion: 2018		

April, 2019

Page & Turnbull, Inc.

Total Cost: \$92,625.00 Source SOV #16080

Description of work:

- The missing original fixtures on the main entry façade were replicated based on historic documentation.
- Building façade lighting was replaced with LED fixtures to save energy.

Scope:#14 Building Feature: Interior Lighting Rehab/Restoration X Maintenance Completed X Proposed Contract year work completion: 2018 Total Cost: \$135,281.00 Source SOV #16070 Description of work: Repair, Restoration and Replacement in kind of historic light fixtures: The historic light fixtures were cleaned and relamped. The missing fixtures in the main sanctuary were replicated.

Scope #15							
Building Feature: Ro	of / Buil	t-up Roof					
Rehab/Restoration	X	Maintenance		Completed	X	Proposed	
Contract year work of	ompleti	on: <u>20</u> 18					
Total Cost: \$28,110.	00 Soui	rce SOV #7500					
Description of work:			,				
 Existing built 	-up roo	fing was removed a	at the lov	er roofs.			
New built-up	roofing	was installed over	new stru	ictural deck	ing.		

Scope: #16 Building Feature: Ro	of / S	Slate Roof				
Rehab/Restoration	X	Maintenance	Completed	X	Proposed	
Contract year work c	omp	letion: 2018				
Total Cost: \$258,950	.00 \$	Source SOV #7300				
Description of work:						

- Existing slate roof tile was removed at the main roof and portals, salvaged, and reinstalled to allow access for structural stabilization of the roof structure.
- Deteriorated and broken tiles were replaced with salvaged stock or new tile to match the existing.
- New felt underlayment and galvanized flashing was installed.

Scope: #17				
Building Feature: Inte	rior P	ainting		
Rehab/Restoration	X	Maintenance	Completed X	Proposed
Contract year work o	omple	tion: 2018 Phase 1, Ph	nase 2 scheduled for 20	26
Total Cost: \$146,950	.00 S	ource SOV #9900 (hal	f), \$293850/2=\$146,95	0
Description of work:				
 Tested bottor 	n laye	er of paint to find origin	al colors.	

- Interior plaster was painted, interior wood was refinished, and window mullions were repainted.
- Lead paint was abated.

Scope:#18 Building Feature: Roof/Sl	eet Metal Dome and S	heet Metal Crosses		
Rehab/Restoration X	Maintenance	Completed X	Proposed	
Contract year work comple				
Total Cost: \$60,000.00 So				
Description of work:	•	,		
l '	plied to the domes and	crosses.		
Scope: # 19 Building Feature: ADA Up	ırades: «Extenor Ramp			
Rehab/Restoration X	Maintenance	Completed X	Proposed	l
Contract year work comple	etion: 2018			
Total Cost: 12,000.00 Con	versation with contra	ctor		
Description of work:				
 Ramp provided at 	transept.			
 Auto operator prov 	rided at existing door.			
- Control of the Cont	Commission of Control and Cont		·	-construction (Action and California
Scope: #'20'				
Building Feature Interior F	The state of the s			
Rehab/Restoration X	Maintenance	Completed	Proposed	X .
Contract year work comple				
Total Cost: \$50,000.00 Se	ee Source SOV #9900			
Description of work:	f :-42			
 Partial repainting of 	or interior wails.			
Scope #21				Zacio alevatika: 2006
Building Feature: Exterior	Dainting of Comont Dia	-10		
Rehab/Restoration X	Maintenance	Completed	Proposed	X
Contract year work comple		Completed	Toposed	N.
Total Cost: \$241,065.00 (F		2018 escalated 5%/	Vir for 8 years	
	epair any new cracks. A			
	ccordance with the Sec			
machais allu ill a	boordance with the occ	istary or the interior s	Canaa as.	

Exhibit B Maintenance Plan

Scope:#1						
Building Feature: Site_I	_andscape					
Rehab/Restoration	Maintenance	X	Completed	Proposed	Χ]
Contract year work com	pletion: 2028 and ev	ery	10 years thereafter			
Total Cost: \$120,000.00	(\$1,000/month x 12)	mo	x 10 yrs)			
Description of work: Wa	shing of sidewalks ar	nd g	ranite entry steps. Grai	nite steps will be	e cle:	aned
using the gentlest mean	s possible as recomi	ner	ided in NPS Preservation	on Brief No. 1: A	sses	ssing
Cleaning and Water-Re	pellent Treatments fo	r H	istoric Masonry Building	gs. All work will	be p	erformed
in conformance with the	Secretary of the Inte	rior	Standards.	· •		

Scope:#2						andre de la company
Building Feature: Extend						
Rehab/Restoration	Maintenance	X	Completed	Proposed	X	A CONTRACTOR OF THE PARTY OF TH
Contract year work com	pletion: 2019 and an	nuall	ly thereafter			
Total Cost: \$40,000 (ma	intenance of 4,000/y	/r x10	Dyrs)			
Description of work: Reg	gular repainting of ex	terio	r stucco as needed to	address graffiti.	Perf	orm
visual inspection annual	ly for signs of blister	ing o	r peeling paint.	-		

Scope:#3 Building Feature: Roof					78 TH 18
Rehab/Restoration	Maintenance	X	Completed	Proposed	X
Contract year work com	pletion: 2019 and ar	nnually	thereafter		
Total Cost: \$30,000.00	(maintenance of \$3	,000 x 1	10yrs)		
Description of work: Ins and repair caulking and and discourage roosting	flashing. Clear drair				

Scope:#4				le di Bres de Boli do d	
Building Feature: Exterior	Sheet Metal Elem	ents	, including domes on to	owers, column c	apitals,
decorative moldings, gut	ters and down spo	uts.			
Rehab/Restoration	Maintenance	X	Completed .	Proposed	X
Contract year work comp	letion: 2019 and ar	nua	lly thereafter	,	
Total Cost: \$12,000.00 (\$	1200 per year)				
Description of work: Perfo	orm visual inspection	on ar	nnually for rust, holes a	nd signs of water	er where it
shouldn't be. Clean gutte	rs, replace screens	, che	eck down spouts and c	lean drains. Rep	pair damaged
pieces to match existing i	using appropriate r	nate	rials and methods, All r	epairs will be pe	erformed in
conformance with the Sec	cretary of the Interi	or S	tandards.		

Scope:#5			
Building Feature: Exterior	or Wood-sash Windows and	l Steel Tracery	
Rehab/Restoration	Maintenance X	Completed	Proposed X
Contract year work com	pletion: 2019 and annually t	hereafter.	
Total Cost: \$10,000.00 (\$1000 per year)		
Description of work: Per	form visual inspection annu	ally for signs of caull	king failure, check operable
windows, window locks	and replace any cracked or	broken glass in kind	: All window repairs will be
performed in accordance	e with the Secretary of the I	nterior Standards.	

Scope: # o					
Building Feature: Exterior	r Skylight				
Rehab/Restoration	Maintenance	X	Completed	Proposed	X
Contract year work comp	letion: 2019 and ar	nually there	after		
Total Cost: \$5,000.00 (\$5	500 per year)	_			
Description of work: Perfe	orm visual inspection	on annually i	or signs of caul	king failure, cor	ndensation
problems that might com	promise structure o	f skylight ar	d replace any c	racked or broke	en glass in
kind. All repairs will be pe	erformed in conform	nance with the	ne Secretary of	the Interior Stai	ndards.

Building Feature: Exterior Stained Glass Windows Rehab/Restoration Maintenance X Completed Proposed X Contract year work completion: 2019 and annually thereafter Total Cost: \$16,000.00 (\$1600 per year)
Contract year work completion: 2019 and annually thereafter Total Cost: \$16,000.00 (\$1600 per year)
Description of work: Inspect stained glass and replace any cracked or missing pieces with glass that matches original glass in color and texture. Inspect and repair lead cames. All work will be performed in conformance with the Secretary of the Interior's Standards and in accordance with NPS Preservation Brief No. 33: The Preservation and Repair of Historic Stained and Leaded Glass

Scope:#8							
Building Feature: Exteri	or Wood Doors						
Rehab/Restoration	Maintenance <u>X</u>	Completed	Proposed	X ·			
Contract year work com	pletion: 2019 and annually	thereafter					
Total Cost: \$7,900.00 (\$	790 per ýear)						
Description of work: The	e face of the wood doors ha	ve extreme exposure	to rain and sur	n. They			
suffered significant deterioration in the past. They need regular cleaning and regular refinishing. All							
work will be performed i	work will be performed in conformance with the Secretary of the Interior's Standards						

l	Scope #9
l	Building Feature: Interior Decorative Plaster
ľ	Rehab/Restoration Maintenance X Completed Proposed X
ľ	Contract year work completion: 2019 and every 10 years thereafter
I	Total Cost: \$20,000.00 (\$2000 per year)
Ī	Description of work: The existing plaster was previously damaged when water got into the attic and
l	behind the decorative plaster ceiling. Problems on the surface appeared only after considerable
I	damage was done inside the concealed spaces, therefore there will be visual inspections annually
-	must look inside the attic for signs of water damage and make needed repairs.
-	All work will be performed in conformance with the Secretary of the Interior's Standards and in
-	accordance with NPS Preservation Brief No. 23: Preserving Historic Ornamental Plaster.

Scope:#10 Building Feature: Interio				
Rehab/Restoration	Maintenance X	Completed	Proposed	X
Contract year work com	pletion: 2019 and annu	ally thereafter		
Total Cost: \$16,000.00 (\$1600 per year)			
Description of work: Per	form visual inspection	annually for damage a	and repair in the ge	ntlest means
possible. All work will be				

April, 2019

Scope:#11					
Building Feature: Bell To	wer				
Rehab/Restoration	Maintenance	X	Completed	Proposed	X
Contract year work com	pletion: 2019 and ar	nually	thereafter		
Total Cost: \$18,500.00 (\$1850 per year)				
Description of work: Ann	ual visual inspectio	n of be	ell rope and hanging	mechanism. Cli	mb the
ladders and go into the	attic spaces and ren	nove b	irds and close up an	y gaps in the sci	reens and
louvers.					

Scope: #12 Building Feature: Site D	rainage					
Rehab/Restoration	Maintenance	X	Completed	Proposed	Χ	
Contract year work com	pletion: 2019 and ar	nually t	thereafter			
Total Cost: \$11,500 (\$1	,500 per year)					
Description of work: Ins	pect drywells in gard	len area	as and verify site drai	nage is function	ning to	
remove standing water.						


Scope: #13					
Building Feature: Interio	r plaster				
Rehab/Restoration	Maintenance	<u>X</u>	Completed	Proposed	Χ
Contract year work com	pletion: 2023 and bi	-anni	ually thereafter		
Total Cost: \$80,000					
Description of work; Rep	aint public spaces a	and r	epair plaster work as r	necessary. All wo	ork will be
performed in conforman	ce with the Secretar	y of	the Interior's Standard	s and in accorda	ince with
NPS Preservation Brief	No. 23: Preserving I	Histo	ric Ornamental Plaster	r and No. 21: Re	pairing
Historic Flat Plaster Wal	ls and Ceilings				

Scope # 14 Building Feature Interio	r Marble Floors						
Rehab/Restoration	Maintenance	<u>X</u>	Completed	Proposed	Χ		
Contract year work com	Contract year work completion: 2022 and annually thereafter						
Total Cost: \$8,000							
Description of work: Clean and reseal marble floors and wainscot. All marble will be cleaned using							
the gentlest means possible as recommended in NPS Preservation Brief No. 1: Assessing Cleaning							
and Water-Repellent Treatments for Historic Masonry Buildings							


Scope: #/15 Building Feature: Inte			and wood paneling			
Rehab/Restoration	Maintenance	<u>X</u>	Completed	Proposed	Х	
Contract year work completion: 2022 and annually thereafter						
Total Cost: \$12,000	•				•	
Description of work: C meet the Secretary of			nd repair as needed to	o match origina	l. All work will	




Office of the Assessor / Recorder - City and County of San Francisco Mills Act Valuation



1401 Howard Street





OFFICE OF THE ASSESSOR-RECORDER - CITY & COUNTY OF SAN FRANCISCO MILLS ACT VALUATION

APN:

3517-035

Lien Date:

7/1/2019

Address:

1401 Howard Street

Application Date: **Application Term:** 5/24/2019 10 years

SF Landmark No.:

4/29/1900

Applicant's Name:

1401 Howard LLC

Last Sale Date:

3/26/2008

Agt/Tax Rep./Atty: Fee Appraisal Provided: Unknown No

Last Sale Price:

\$500,000

T's and there a		**************************************			
FACTORED BASE Y	EAR (Roll) YALUE	INCOME CAPITALIZATI	ION APPROACH	SALES COMPARISON A	PPROACH
Land	\$553,421	Land	\$7,620,000	Land	\$8,220,000
Imps.	\$17,905,319	lmps.	\$5,080,000	lmps.	\$5;480,000
Personal Prop		Personal Prop	\$0	Personal Prop	\$0
Total	. \$18,458,740	Total	\$12,700,000	Total	\$ 13,700,000

Property Description

Property Type:

Commercial

Year Built:

1913 / 2017

21,943

Neighborhood:

Soma

Type of Use:

Interior Design Firm (Total) Rentable Area:

Land Area:

26,811

Owner-Occupied: No

Stories:

Zoning:

RCD - Regional Commercial

Unit Types:

Commercial

Parking Spaces:

Surface / 6

Total No. of Units: 1

Special Conditions (Where Applicable)

	Per Unit	Per SF	Total
Factored Base Year Roll	\$18,458,740	\$841	\$ 18,458,740
Income Approach - Direct Capitalization	\$12,700,000	\$579	\$ 12,700,000
Sales Comparison Approach	\$13,700,000	\$624	\$ 13,700,000
Recommended Value Estimate	\$ 12,700,000 \$	579	\$ 12,700,000.

Appraiser:

Jody Scott Reichel

Principal Appraiser: Orla Fahy

Hearing Date: Unknown

INCOME APPROACH

Address: 1401 Howard Street

Lien Date:

		,	•	
	Sq. Ft.	Annual Rent/SF	Comments	
Potential Gross Income	21,943	x \$61.06	\$1,339,800 Based on actua	al
Less: Vacancy & Collection Loss	. '	3%	lease amount (\$40,194).	
Effective Gross Income		•	\$1,299,606	
Less: Anticipated Operating Expenses (F	Pre-Property Tax)*	3%	(\$38,988)	
Net Operating Income (Pre-Property Tax)	. • . !		\$1,260,618	
	÷			
Restricted Capitalization Rate 2019 Interest rate per State Board of Equa Risk rate (4% owner occuped / 2% all othe 2019 property tax rate.* Amortization rate for improvements only Remaining economic life (in years) Improvements constitute % of total prop	er property types)	4.7500% 2.0000% 1.1630% 2.0000% 60%	9.9130%	

RESTRICTED VALUE ESTIMATE

\$12,716,815 \$12,700,000 RD

^{*} The 2019 property tax rate will be determined in September 2019. Rate utilized is from 2018.

omparable improved	3517-035	######################################			
ddress:	1401 Howard Street				
Sale No.	One	Two	Three	Four	SUBJECT
APN:	0839-032		0637-015 & -016	1080-035	3517-035
,		tanap.		Y	
Address Sale Date Sale Price Size (SF) Year Built Price/SF	240 Page Street 5/6/2019 \$2,780,000 5,495 1909 \$506	170 Valencia Street 12/31/2018 \$9,600,000 23,270 1931 \$413	2395 Sacramento St. 12/8/2017 \$9,500,000 20,110 1912 \$472	2398 Geary Blvd. 3/11/2016 \$4,400,000 7,937 1906 \$554	1401 Howard St. 7/1/2019 21,943 1913 / 2017
Use Site Zoning Site Size (SF) Land: Bldg. Ratio On Site Parking	Former Church RM2 3,968 0.72	Former Religious Hall RTO 8,250 0.35	Former Library RM1 15,105 0.75	Former Church RH3 5,031 0.63	Former Church SLR 26,811 1,22
Ratio/1,000 SF NRA Mos. Since Effective Date Time Adjustment	0.23 2 0%	0.00 6 3%	0.00 19 10%	0.00 39 15%	0.00
Size Adjustment (SF)	-5%	0%	0%	-5%	TOTAL THE STATE OF
Location Adj.	5%	5%	5% 	5%	
Age / Condition Adj.	10%	20%	10%	20%	
Land: Bldg. Ratio	5%	10%	5%	5%	
Zoning Adj	5%	5%	5%	5%	and the state of t
Parking	-3%	0%	0%	. 0%	Printing of the Control of the Contr
Net Adj, Price/Gross Office SF	17%	43%	: 35% :	45%	Concluded Value/S
Adjusted Price/SF Site Area	\$592	\$590	\$638	\$804	\$625 \$625/SF X 21,943 SF
Indicated Value/SF	s de la companya del companya de la companya del companya de la co				\$13,714,375
ROUNDED		. :			\$13,700,000

The subject property is a former church that had a complete renovation including seismic upgrade. It is now fully leased to an interior design firm. Sales One, Two and Four are also religious facilities and Sale Three is a former library. The subject property was significantly superior in age/condition due to the recent renovation. After adjustment the price per square feet range is \$592 to \$804/SF with \$625/SF considered to be supported by the sales comparables. The subject property is considered to be an investment property given it is fully leased on NNN basis with the tenant paying for expenses. The Income Capitalization Approach is typically the most applicable valuation approach for investment properties. Given the Restricted Capitalization Rate for Mills Act properties the Income Capitalization Approach for the subject property results in the lowest valuation.


Comparable Improved Sales Adjustment Grid

APN:

3517-035

Address:

1401 Howard Street



IMPROVED SALES MAP

PRE-APPROVAL INSPECTION REPORT

Report Date:

May 24, 2019

Inspection Date:

May 22, 2019; 11:00am

Filing Date:

May 1, 2018

Case No.:

2019-006384MLS

Project Address:

1401 Howard Street

Block/Lot:

3517/035

Eligibility

Article 10 Landmark No. 120: Saint Joseph's Church

National Register listed property

Zoning:

RCD - Regional Commercial District

Height &Bulk:

40-X

Supervisor District:

District 6 (Matt Haney)

Project Sponsor:

Christopher Foley of 1401 Howard LLC

Address:

1401 Howard Street

San Francisco, CA 94103

415-305-4600

cfoley@groundmatrix.com

Staff Contact:

Michelle Taylor - (415) 575-9197

michelle.taylor@sfgov.org

Reviewed By:

Tim Frye – (415) 575-6822

tim.frye@sfgov.org

PRE-INSPECTION

☑ Application fee paid

☑ Record of calls or e-mails to applicant to schedule pre-contract inspection

5/7/2019: Email applicant to schedule site visit.

5/14/2019: Email applicant to reschedule site visit.

1650 Mission.St. Suite 400 San Francisco, CA 94103-2479

Reception: 415.558.6378

415.558,6409

Planning Information: 415.558.6377

Mills Act Pre-Approval Inspection Report May 24, 2019

Case Number: 2019-006384MLS 1401 Howard Street

INSPECTION OVERVIEW

☑ Yes

□ No

Date and time of inspection: Wednesday, May 22, 2019, 11:00am Parties present: Michelle Taylor, Shannon Ferguson, Chris Foley, Rick Feldman ☑ Provide applicant with business cards ☑ Inform applicant of contract cancellation policy ☑ Inform applicant of monitoring process Inspect property. If multi-family or commercial building, inspection included a: ☑ Thorough sample of units/spaces ☐ Representative ☐ Limited ☑ Review any recently completed and in progress work to confirm compliance with Contract. ☑ Review areas of proposed work to ensure compliance with Contract. ☑ Review proposed maintenance work to ensure compliance with Contract. ☐ Identify and photograph any existing, non-compliant features to be returned to original condition during contract period. N/A M Yes Does the application and documentation accurately reflect the property's existing П No condition? If no, items/issues noted: Does the proposed scope of work appear to meet the Secretary of the Interior's M Yes \square No Standards? If no, items/issues noted: See below ☑ Yes П No Does the property meet the exemption criteria, including architectural style, work of a master architect, important persons or danger of deterioration or demolition without rehabilitation? If no, items/issues noted:

Conditions for approval? If yes, see below.

Case Number: 2019-006384MLS 1401 Howard Street

NOTES

1401 Howard Street (District 6) 1401 Howard Street is located on the south corner of Howard and 10th Streets, Assessor's Block 3517, Lots 39. The subject property is located within an RCD (Regional Commercial District) zoning district and a 55/65-X Height and Bulk district. The subject property is an Article 10 individual landmark No. 120 and added to the National Register of Historic Places in 1982. Formerly Saint Joseph's Church, the subject property is a former Catholic church constructed in 1913 and designed in the Romanesque Revival style by architect John J. Foley.

The subject property is currently valued by the Assessor's Office at over \$5,000,000; therefore, an exemption from the tax assessment value is required. The application includes a Historic Structure Report prepared by Page & Turnbull that provides evidence that the property meets the exemption criteria for tax assessment value.

At the preliminary inspection visit, the applicant was informed that some proposed scope items would not be considered qualifying scopes of work, such as maintenance of landscaping at the exterior and maintenance of the new concrete floor in the interior. The applicant was advised to include regular inspection and repairs of interior character defining features in the proposed maintenance plan.

In 2018, the applicant completed a full rehabilitation and restoration of the building and received Final approval for the Federal Historic Preservation Tax Incentive in September 2018. Work included the restoration of exterior and interior finishes, seismic strengthening, repair of the slate roof, restoration of the sheet metal domes, and addition of an accessibility ramp.

Future rehabilitation and restoration scope items include full repainting of the interior and exterior. The estimated cost of the proposed rehabilitation work is \$291,065.


The applicant has provided a revised maintenance plan which proposes to inspect and make any necessary repairs to the exterior stucco, metal roof elements, windows, doors, and roof on a regular basis. The applicant will be maintaining interior character defining features identified in the National Register nomination, such as the entry lobby floors, plaster detailing, and woodwork. The estimated cost of maintenance work is \$30,040 annually

Mills Act Pre-Approval Inspection Report May 24, 2019


PHOTOGRAPHS




Front and side elevations of 1401 Howard Street



Primary interior volume facing northwest



Detail of restored decorative plaster elements



MILLS ACT APPLICATION
1401 HOWARD STREET
SAN FRANCISCO, CALIFORNIA

PREPARED FOR: 1401 HOWARD LLC PRIMARY PROJECT CONTACT: Ruth Todd Page & Turnbull, 170 Maiden Lane, 5th Floor San Francisco, CA 94108 415.593.3234/415.362.5560 fax ruthtodd@page-turnbull.com

Page & Turnbuli

APRIL 30, 2019

imagining change in historic environments through design, research, and technology

TABLE OF CONTENTS

I. APPLICATION FORMS	
APPLICATION CHECKLIST	2
MILLS ACT HISTORICAL PROPERTY CONTRACT	
CALIFORNIA MILLS ACT HISTORICAL PROPERTY AGREEMENT	7
NOTARY ACKNOWLEDGEMENT FORM	13
REHABILITATION / RESTORATION & MAINTENANCE PLAN (CONTINUED/ATTACHMENT)	14
REHABILITATION/ RESTORATION PLANS SUPPORTING DOCUMENTATION	24
II. EXEMPTION STATEMENT AND SIGNIFICANCE EVALUATION	
EXEMPTION STATEMENT	29
2019 MILLS ACT APPLICATION CRITERIA	29
III. HISTORIC STRUCTURE REPORT	31
HISTORY OF 1401 HOWARD STREET	ا ك.,
HISTORIC SIGNIFICANCE	38
ARCHITECTURAL DESCRIPTION	42
BIBLIOGRAPHY	51
EXISTING CONDITIONS & TREATMENT RECOMMENDATIONS (2014)	53
EXISTING CONDITIONS IMAGES PRIOR TO REHABILITATION/RESTORATION	62
IV. 1401 HOWARD STREET ADDITIONAL PHOTOGRAPHY	76
PHOTOS AFTER REHABILITATION/RESTORATION	76
V. SITE PLAN	
VI. TAX BILL	
VII. RENTAL INCOME INFORMATION	91

MILLS ACT HISTORICAL PROPERTY CONTRACT Application Checklist:

Applicant should complete this checklist and submit along with the application to ensure that all necessary materials have been provided. Saying "No" to any of the following questions may nullify the timelines established in this application.

1	Mills Act Application	YES 🗵	№ 🗆
-	Has each property owner signed? Has each signature been notarized?		
2 .	High Property Value Exemption Form & Historic Structure Report	YES X	№ 🗆
	Required for Residential properties with an assessed value over \$3,000,000 and Commercial/Industrial properties with an assessed value over \$5,000,000. Have you included a copy of the Historic Structures Report completed by a qualified consultant?		N/A 🗌
3	Draft Mills Act Historical Property Contract	YES 🛛	NO 🗆
	Are you using the Planning Department's standard "Historical Property Contract?" Have all owners signed and dated the contract? Have all signatures been notarized?		
4	Notary Acknowledgement Form	YES X	№ □
	Is the Acknowledgement Form complete? Do the signatures match the names and capacities of signers?		
. 5	Draft Rehabilitation/Restoration/Maintenance Plan	YES 🗓	NO 🗌
	Have you identified and completed the Rehabilitation, Restoration, and Maintenance Plan organized by contract year, including all supporting documentation related to the scopes of work?		
6	Photographic Documentation	YES 🛚	NO 🗌
	Have you provided both interior and exterior images (either digital, printed, or on a CD)? Are the images properly labeled?		
7	Site Plan	YES X	NO □
	Does your site plan show all buildings on the property including lot boundary lines, street name(s), north arrow and dimensions?		
8	Tax Bill	YĖS 🛚	NO 🗌
	Did you include a copy of your most recent tax bill?		
9	Rental Income Information	YES X	ИО □
:	Did you include information regarding any rental income on the property, including anticipated annual expenses, such as utilities, garage, insurance, building maintenance, etc.?		·
10	Payment	YES X	NO 🗌
	Did you include a check payable to the San Francisco Planning Department? Current application fees can be found on the Planning Department Fee Schedule under Preservation Applications.		
11	Recordation Requirements	YES 🗌	ио □
	A Board of Supervisors approved and fully executed Mills Act Historical Property contract must be recorded with the Assessor-Recorder. The contract must be accompanied by the following in order to meet recording requirements:	•	
	- All approvals, signatures, recordation attachments		
	 Fee: Check payable to the Office of the Assessor-Recorder" in the appropriate recording fee amount Please visit www.sfassessor.org for an up-to-date fee schedule for property contracts. 		
	- Preliminary Change of Ownership Report (PCOR). Please visit www.sfassessor.org for an up-to-date	•	

Mills Act Application.

APPLICATION FOR

Mills Act Historical Property Contract

Applications must be submitted in both hard copy and digital copy form to the Planning Departmen at 1650 Mission St. Suite 400 by May 1st in order to comply with the timelines established in the Application Guide. Please submit only the Application and required documents.

Owner/Applicant Information (If more than three owners, atta	ach addition	al sheets as necessary.)		
PROPERTY OWNER 1 NAME:		TELEPHONE:		
1401 HOWARD LLC		(415) 640 - 0567		
PROPERTY OWNER 1 ADDRESS:		EMAIL:		
810 7TH STREET		sean@visitthemarl	ket.com	
PROPERTY OWNER 2 NAME:		TELEPHONE:		
		()		
PROPERTY OWNER 2 ADDRESS:		EMAIL:		
PROPERTY OWNER 3 NAME:		TELEPHONE:		•
	_	(.)		
PROPERTY OWNER 3 ADDRESS:	•	EMAIL:		
2. Subject Property Information				,
PROPERTY ADDRESS:			ZIP CODE:	
1401 HOWARD STREET			94103	
PROPERTY PURCHASE DATE;	ASSESSOR BI	LOCK/LOT(S):		
	3517 / 03	35		
MOST RECENT ASSESSED VALUE:	ZONING DIST	RICT:		
\$ 15,797,197	RCD		•	
			·, ·	
Are taxes on all property owned within the City and County of	f San Franc	isco paid to date?	YES 🛛	NO 🗌
Is the entire property owner-occupied? If No, please provide an approximate square footage for owner-occupied areas vs. rental			YEŞ 🗌	NO 🗵
income (non-owner-occupied areas) on a separate sheet of p	paper.			
Do you own other property in the City and County of San Francisco?			YES 🗌	NO X
If Yes, please list the addresses for all other property owned Francisco on a separate sheet of paper.	within the	City of San		
Are there any outstanding enforcement cases on the propert	y from the	San Francisco	YES 🗆	NO X
Planning Department or the Department of Building Inspection				
If Yes, all outstanding enforcement cases must be abated an the Mills Act.	d closed fo	or eligibility for		
1			***************************************	
I/we am/are the present owner(s) of the property described above contract. By signing below, I affirm that all information provided	e and hereb l in this app	y apply for an histor dication is true and c	ical proper orrect. I fui	ty ther
swear and affirm that false information will be subject to penalty	and revoca	ation of the Mills Act	Contract	
Owner Signature:		Date:		
Owner Signature:		Date:		
Owner Signature:		Date;		
· · · · · · · · · · · · · · · · · · ·		-		

CAN COANDONS DANIELS DEPLOTATION V. DE AN 20

Mills Act Application

3. Property Value Eligibility: Choose one of the following options: The property is a Residential Building valued at less than \$3,000,000. YES NO X The property is a Commercial/Industrial Building valued at less than \$5,000,000. YES NO X *If the property value exceeds these options, please complete the following: Application of Exemption. Application for Exemption from Property Tax Valuation If answered "no" to either question above please explain on a separate sheet of paper, how the property meets the following two criteria and why it should be exempt from the property tax valuations. 1. The site, building, or object, or structure is a particularly significant resource and represents an exceptional example of an architectural style, the work of a master, or is associated with the lives of significant persons or events important to local or natural history; or 2. Granting the exemption will assist in the preservation of a site, building, or object, or structure that would otherwise be in danger of demolition, substantial alteration, or disrepair. (A Historic Structures Report, completed by a qualified historic preservation consultant, must be submitted in order to meet this requirement.) 4. Property Tax Bill All property owners are required to attach a copy of their recent property tax bill. PROPERTY OWNER NAMES: 1401 HOWARD LLC MOST RECENT ASSESSED PROPERTY VALUE: \$ 15,797,197 PROPERTY ADDRESS: 1401 HOWARD ST, SAN FRANCISCO, CA 5. Other Information All property owners are required to attach a copy of all other information as outlined in the checklist on page 7 of this application. By signing below, I/we acknowledge that I/we am/are the owner(s) of the structure referenced above and by applying for exemption from the limitations certify, under the penalty of perjury, that the information attached and provided is accurate. Owner Signature: Date: Owner Signature:

Mills Act Application

Owner Signature:

5. Rehabilitation/Restor	ation & Maintenan	ce Plan			
A 10 Year Rehabilitation performed on the subject	YES X	NO 🗌			
A 10 Year Maintenance the subject property	Plan has been submit	ted detailing work to) be performed on	YES 🔼	NO 🗌
Proposed work will me Historic Properties and/o			r the Treatment of	YES 🗵	NO 🗌
Property owner will en				YES 🛚	NO 🗌
Use this form to outline you apply to your property. Bey work you propose to comp all scopes of work in order. Please note that all applicable components of the propose Zoning Administrator, or a Mills Act Historical Property part of the Mills Act Historical Property.	gin by listing recently lete within the next ter of priority. The Codes and Guidelines and Plan require approving other government to the Contract. This planty	completed rehabilitating years, followed by years, followed by yearply to all work, including the body, these approvals will be included alor	on work (if applicable our proposed mainted ding the Planning Conservation Commission must be secured pri	e) and continue nance work. Ar. de and Building on, Planning Cor or to applying t	with ranging Code. If mmission for a
# (Provide a scope number)	BUILDING	FEATURE:			
Rehab/Restoration	Maintenance	Completed	Proposed ☐		
CONTRACT: YEAR FOR WORK COMP	LETION:			• .	
TOTAL COST (rounded to nearest dol	ar):				
DESCRIPTION OF WORK: ALL OF THE RESTORA	ATION!/ DELIABILITA	TION AND MAINTE	NIANCE WORK IS D	DESCRIBED IN	TUE
FOLLOWING PAGES.		HON, AND MAIN L	NAME WORK IS D	LOCKIDED IN	1116
	,				
			·		

6. Draft Mills Act Historical Property Agreement

Please complete the following Draft Mills Act Historical Property Agreement and submit with your application. A final Mills Act Historical Property Agreement will be issued by the City Attorney once the Board of Supervisors approves the contract. The contract is not in effect until it is fully executed and recorded with the Office of the Assessor-Recorder.

Any modifications made to this standard City contract by the applicant or if an independently-prepared contract is used, it shall be subject to approval by the City Attorney prior to consideration by the Historic Preservation Commission and the Board of Supervisors. This will result in additional application processing time and the timeline provided in the application will be nullified.

Recording Requested by, and when recorded, send notice to: Director of Planning 650 Mission Street San Francisco, California 94103-2414

	California Mills	Act Historical Property A	greement	
	ST. JOSEP	H'S ART SOCIETY		•
	PROPERTY NAM	ME (IF ANY)		•
	1401 HO	WARD STREET	· .	
	PROPERTY ADJ	DRESS		
	Sa Sa	an Francisco, California		÷
// C34-J/\ 3	entered into by and between	the City and County of San Fra ("Owner/s").	ancisco, a California municipal co	rporation
		RECITALS		•
) Dwners are the owners	of the property located at	1401 HOWARD STREET	, in San Francisco,	California
3517	·	PROPERTY ADDRESS The building located at	1401 HOWARD STREET	
BLOCK NUMBER		. The building located at		
	LOT NUMBER		PROPERTY ADDRESS	
s designated as NATI	TY LANDMARK #120, ONAL REGISTER OF HISTORIC	PLACES #82002250	(e.g. "a City Landmark pursua	ant to Article
10 of the Planning Code	e") and is also known as the	HISTORIC NAME OF PI	PHS CHURCH	-
•				
		•		
calls for the rehabilitati estimates will cost app Exhibit A.	on and restoration of the Hi. FIVE MILLION SEVEN HU roximately EIGHT HUNDRED SEVEN AM	storic Property according to est NDRED TWENTY FIVE THOUSAND TY FOUR MOUNT IN WORD FORMAT AMC	Historic Property. Owners' appliablished preservation standards, 5 5,725,874). See Rehabilita untin numerical format	which it tion Plan,
which is estimated will	cost approximatelynine H	e Historic Froperty according to topred seventy thousand, UNDRED SIXTY FIVE	o established preservation standar (\$ 670,965 · AMOUNT IN NUMERICAL FORMAT	ras, .).
annually. See Maintena	ance Plan, Exhibit B.			
			•	•
Revenue & Taxation Co property owners to po	ode, Article 1.9 [Section 439 of tentially reduce their proper as adopted enabling legislation	et seq.) authorizing local govern ty taxes in return for improvern	Sections 50280-50290, and Californ nments to enter into agreements whent to and maintenance of histori we Code Chapter 71, authorizing in	vith .c
mitigate its anticipated	expenditures to restore and these expenditures and to in	l maintain the Historic Property	Property Agreement") with the Cit 7. The City is willing to enter into a aintain the Historic Property in ex	such
NOW, THEREFORE, i hereto do agree as follo		al obligations, covenants, and co	onditions contained herein, the pa	rties
Mills Act Applicati	on			

1. Application of Mills Act.

The benefits, privileges, restrictions and obligations provided for in the Mills Act shall be applied to the Historic Property during the time that this Agreement is in effect commencing from the date of recordation of this Agreement.

Rehabilitation of the Historic Property.

Owners shall undertake and complete the work set forth in Exhibit A ("Rehabilitation Plan") attached hereto according to certain standards and requirements. Such standards and requirements shall include, but not be limited to: the Secretary of the Interior's Standards for the Treatment of Historic Properties ("Secretary's Standards"); the rules and regulations of the Office of Historic Preservation of the California Department of Parks and Recreation ("OHP Rules and Regulations"); the State Historical Building Code as determined applicable by the City; all applicable building safety standards; and the requirements of the Historic Preservation Commission, the Planning Commission, and the Board of Supervisors, including but not limited to any Certificates of Appropriateness approved under Planning Code Article 10. The Owners shall proceed diligently in applying for any necessary permits for the work and shall apply for such permits not less than six (6) months after recordation of this Agreement, shall commence the work within six (6) months of receipt of necessary permits, and shall complete the work within three (3) years from the date of receipt of permits. Upon written request by the Owners, the Zoning Administrator, at his or her discretion, may grant an extension of the time periods set forth in this paragraph. Owners may apply for an extension by a letter to the Zoning Administrator, and the Zoning Administrator may grant the extension by letter without a hearing. Work shall be deemed complete when the Director of Planning determines that the Historic Property has been rehabilitated in accordance with the standards set forth in this Paragraph. Failure to timely complete the work shall result in cancellation of this Agreement as set forth in Paragraphs 13 and 14 herein.

Maintenance.

Owners shall maintain the Historic Property during the time this Agreement is in effect in accordance with the standards for maintenance set forth in Exhibit B ("Maintenance Plan"), the Secretary's Standards; the OHP Rules and Regulations; the State Historical Building Code as determined applicable by the City; all applicable building safety standards; and the requirements of the Historic Preservation Commission, the Planning Commission, and the Board of Supervisors, including but not limited to any Certificates of Appropriateness approved under Planning Code Article 10.

4. Damage.

Should the Historic Property incur damage from any cause whatsoever, which damages fifty percent (50%) or less of the Historic Property, Owners shall replace and repair the damaged area(s) of the Historic Property. For repairs that do not require a permit, Owners shall commence the repair work within thirty (30) days of incurring the damage and shall diligently prosecute the repair to completion within a reasonable period of time, as determined by the City. Where specialized services are required due to the nature of the work and the historic character of the features damaged, "commence the repair work" within the meaning of this paragraph may include contracting for repair services. For repairs that require a permit(s), Owners shall proceed diligently in applying for any necessary permits for the work and shall apply for such permits not less than sixty (60) days after the damage has been incurred, commence the repair work within one hundred twenty (120) days of receipt of the required permit(s), and shall diligently prosecute the repair to completion within a reasonable period of time, as determined by the City. Upon written request by the Owners, the Zoning Administrator, at his or her discretion, may grant an extension of the time periods set forth in this paragraph. Owners may apply for an extension by a letter to the Zoning Administrator, and the Zoning Administrator may grant the extension by letter without a hearing. All repair work shall comply with the design and standards established for the Historic Property in Exhibits A and B attached hereto and Paragraph 3 herein. In the case of damage to twenty percent (20%) or more of the Historic Property due to a catastrophic event, such as an earthquake, or in the case of damage from any cause whatsoever that destroys more than fifty percent (50%) of the Historic Property, the City and Owners may mutually agree to terminate this Agreement. Upon such termination, Owners shall not be obligated to pay the cancellation fee set forth in Paragraph 14 of this Agreement. Upon such termination, the City shall assess the full value of the Historic Property without regard to any restriction imposed upon the Historic Property by this Agreement and Owners shall pay property taxes to the City based upon the valuation of the Historic Property as of the date of termination.

5. Insurance.

Owners shall secure adequate property insurance to meet Owners' repair and replacement obligations under this Agreement and shall submit evidence of such insurance to the City upon request.

Mills Act Application

6. Inspections.

Owners shall permit periodic examination of the exterior and interior of the Historic Property by representatives of the Historic Preservation Commission, the City's Assessor, the Department of Building Inspection, the Planning Department, the Office of Historic Preservation of the California Department of Parks and Recreation, and the State Board of Equalization, upon seventy-two (72) hours advance notice, to monitor Owners' compliance with the terms of this Agreement. Owners shall provide all reasonable information and documentation about the Historic Property demonstrating compliance with this Agreement as requested by any of the above-referenced representatives.

7. Term.

This Agreement shall be effective upon the date of its recordation and shall be in effect for a term of ten years from such date ("Initial Term"). As provided in Government Code section 50282, one year shall be added automatically to the Initial Term, on each anniversary date of this Agreement, unless notice of nonrenewal is given as set forth in Paragraph 10 herein.

8. Valuation.

Pursuant to Section 439.4 of the California Revenue and Taxation Code, as amended from time to time, this Agreement must have been signed, accepted and recorded on or before the lien date (January 1) for a fiscal year (the following July 1-June 30) for the Historic Property to be valued under the taxation provisions of the Mills Act for that fiscal year.

9. Termination.

In the event Owners terminates this Agreement during the Initial Term, Owners shall pay the Cancellation Fee as set forth in Paragraph 15 herein. In addition, the City Assessor-Recorder shall determine the fair market value of the Historic Property without regard to any restriction imposed on the Historic Property by this Agreement and shall reassess the property taxes payable for the fair market value of the Historic Property as of the date of Termination without regard to any restrictions imposed on the Historic Property by this Agreement. Such reassessment of the property taxes for the Historic Property shall be effective and payable six (6) months from the date of Termination.

10. Notice of Nonrenewal.

If in any year after the Initial Term of this Agreement has expired either the Owners or the City desires not to renew this Agreement that party shall serve written notice on the other party in advance of the annual renewal date. Unless the Owners serves written notice to the City at least ninety (90) days prior to the date of renewal or the City serves written notice to the Owners sixty (60) days prior to the date of renewal, one year shall be automatically added to the term of the Agreement. The Board of Supervisors shall make the City's determination that this Agreement shall not be renewed and shall send a notice of nonrenewal to the Owners. Upon receipt by the Owners of a notice of nonrenewal from the City, Owners may make a written protest. At any time prior to the renewal date, City may withdraw its notice of nonrenewal. If in any year after the expiration of the Initial Term of the Agreement, either party serves notice of nonrenewal of this Agreement, this Agreement shall remain in effect for the balance of the period remaining since the execution of the last renewal of the Agreement.

11. Payment of Fees.

Within one month of the execution of this Agreement, City shall tender to Owners a written accounting of its reasonable costs related to the preparation and approval of the Agreement as provided for in Government Code Section 50281.1 and San Francisco Administrative Code Section 71.6. Owners shall promptly pay the requested amount within forty-five (45) days of receipt.

12. Default.

An event of default under this Agreement may be any one of the following:

- (a) Owners' failure to timely complete the rehabilitation work set forth in Exhibit A in accordance with the standards set forth in Paragraph 2 herein;
- (b) Owners' failure to maintain the Historic Property in accordance with the requirements of Paragraph 3 herein;
- (c) Owners' failure to repair any damage to the Historic Property in a timely manner as provided in Paragraph 4 herein;
- (d) Owners' failure to allow any inspections as provided in Paragraph 6 herein;
- (e) Owners' termination of this Agreement during the Initial Term;
- (f) Owners' failure to pay any fees requested by the City as provided in Paragraph 11 herein;
- (g) Owners' failure to maintain adequate insurance for the replacement cost of the Historic Property; or
- (h) Owners' failure to comply with any other provision of this Agreement.

Mills Act Application

An event of default shall result in cancellation of this Agreement as set forth in Paragraphs 13 and 14 herein and payment of the cancellation fee and all property taxes due upon the Assessor's determination of the full value of the Historic Property as set forth in Paragraph 14 herein. In order to determine whether an event of default has occurred, the Board of Supervisors shall conduct a public hearing as set forth in Paragraph 13 herein prior to cancellation of this Agreement.

13. Cancellation.

As provided for in Government Code Section 50284, City may initiate proceedings to cancel this Agreement if it makes a reasonable determination that Owners have breached any condition or covenant contained in this Agreement, has defaulted as provided in Paragraph 12 herein, or has allowed the Historic Property to deteriorate such that the safety and integrity of the Historic Property is threatened or it would no longer meet the standards for a Qualified Historic Property. In order to cancel this Agreement, City shall provide notice to the Owners and to the public and conduct a public hearing before the Board of Supervisors as provided for in Government Code Section 50285. The Board of Supervisors shall determine whether this Agreement should be cancelled. The cancellation must be provided to the Office of the Assessor-Recorder for recordation.

14. Cancellation Fee.

If the City cancels this Agreement as set forth in Paragraph 13 above, Owners shall pay a cancellation fee of twelve and one-half percent (12.5%) of the fair market value of the Historic Property at the time of cancellation. The City Assessor shall determine fair market value of the Historic Property without regard to any restriction imposed on the Historic Property by this Agreement. The cancellation fee shall be paid to the City Tax Collector at such time and in such manner as the City shall prescribe. As of the date of cancellation, the Owners shall pay property taxes to the City without regard to any restriction imposed on the Historic Property by this Agreement and based upon the Assessor's determination of the fair market value of the Historic Property as of the date of cancellation.

15. Enforcement of Agreement.

In lieu of the above provision to cancel the Agreement, the City may bring an action to specifically enforce or to enjoin any breach of any condition or covenant of this Agreement. Should the City determine that the Owners has breached this Agreement, the City shall give the Owners written notice by registered or certified mail setting forth the grounds for the breach. If the Owners do not correct the breach, or if it does not undertake and diligently pursue corrective action, to the reasonable satisfaction of the City within thirty (30) days from the date of receipt of the notice, then the City may, without further notice, initiate default procedures under this Agreement as set forth in Paragraph 13 and bring any action necessary to enforce the obligations of the Owners set forth in this Agreement. The City does not waive any claim of default by the Owners if it does not enforce or cancel this Agreement.

16. Indemnification.

The Owners shall indemnify, defend, and hold harmless the City and all of its boards, commissions, departments, agencies, agents and employees (individually and collectively, the "City") from and against any and all liabilities, losses, costs, claims, judgments, settlements, damages, liens, fines, penalties and expenses incurred in connection with or arising in whole or in part from: (a) any accident, injury to or death of a person, loss of or damage to property occurring in or about the Historic Property; (b) the use or occupancy of the Historic Property by the Owners, their Agents or Invitees; (c) the condition of the Historic Property; (d) any construction or other work undertaken by Owners on the Historic Property; or (e) any claims by unit or interval Owners for property tax reductions in excess those provided for under this Agreement. This indemnification shall include, without limitation, reasonable fees for attorneys, consultants, and experts and related costs that may be incurred by the City and all indemnified parties specified in this Paragraph and the City's cost of investigating any claim. In addition to Owners' obligation to indemnify City, Owners specifically acknowledge and agree that they have an immediate and independent obligation to defend City from any claim that actually or potentially falls within this indemnification provision, even if the allegations are or may be groundless, false, or fraudulent, which obligation arises at the time such claim is tendered to Owners by City, and continues at all times thereafter. The Owners' obligations under this Paragraph shall survive termination of this Agreement.

17. Eminent Domain.

In the event that a public agency acquires the Historic Property in whole or part by eminent domain or other similar action, this Agreement shall be cancelled and no cancellation fee imposed as provided by Government Code Section 50288.

18. Binding on Successors and Assigns.

The covenants, benefits, restrictions, and obligations contained in this Agreement shall be deemed to run with the land and shall be binding upon and inure to the benefit of all successors and assigns in interest of the Owners.

19. Legal Fees

In the event that either the City or the Owners fail to perform any of their obligations under this Agreement or in the event a dispute arises concerning the meaning or interpretation of any provision of this Agreement, the prevailing party may recover all costs and expenses incurred in enforcing or establishing its rights hereunder, including reasonable attorneys' fees, in addition to court costs and any other relief ordered by a court of competent jurisdiction. Reasonable attorneys fees of the City's Office of the City Attorney shall be based on the fees regularly charged by private attorneys with the equivalent number of years of experience who practice in the City of San Francisco in law firms with approximately the same number of attorneys as employed by the Office of the City Attorney.

20. Governing Law.

This Agreement shall be construed and enforced in accordance with the laws of the State of California.

21. Recordation.

The contract will not be considered final until this agreement has been recorded with the Office of the Assessor-Recorder of the City and County of San Francisco.

22. Amendments.

This Agreement may be amended in whole or in part only by a written recorded instrument executed by the parties hereto in the same manner as this Agreement.

23. No Implied Waiver.

No failure by the City to insist on the strict performance of any obligation of the Owners under this Agreement or to exercise any right, power, or remedy arising out of a breach hereof shall constitute a waiver of such breach or of the City's right to demand strict compliance with any terms of this Agreement.

24. Authority.

If the Owners sign as a corporation or a partnership, each of the persons executing this Agreement on behalf of the Owners does hereby covenant and warrant that such entity is a duly authorized and existing entity, that such entity has and is qualified to do business in California, that the Owner has full right and authority to enter into this Agreement, and that each and all of the persons signing on behalf of the Owners are authorized to do so.

25. Severability.

If any provision of this Agreement is determined to be invalid or unenforceable, the remainder of this Agreement shall not be affected thereby, and each other provision of this Agreement shall be valid and enforceable to the fullest extent permitted by law.

26. Tropical Hardwood Ban.

The City urges companies not to import, purchase, obtain or use for any purpose, any tropical hardwood or tropical hardwood product.

27. Charter Provisions.

This Agreement is governed by and subject to the provisions of the Charter of the City.

28. Signatures.

This Agreement may be signed and dated in parts

IN WITNESS WHEREOF, the parties hereto have executed this Agreement as follows:

·				
CARMEN CHU ASSESSOR-RECORDER CITY & COUNTY OF SAN FRANCISCO		Date	JOHN RAHAIM DIRECTOR OF PLANNING CITY & COUNTY OF SAN FRANCISCO	Date
		•		
APPROVED AS PER FORM: DENNIS HERRERA CITY ATTORNEY			Signature	Date
CITY & COUNTY OF SAN FRAI	NCISCO	•	Print name DEPUTY CITY ATTORNEY	
•				
Signature		Date	Signature	Date
Print name OWNER			Print name OWNER	

Owner/s' signatures must be notarized. Attach notary forms to the end of this agreement. (If more than one owner, add additional signature lines. All owners must sign this agreement.)

Mills Act Application

7. Notary Acknowledgment Form

The notarized signature of the majority representative owner or owners, as established by deed or contract, of the subject property or properties is required for the filing of this application. (Additional sheets may be attached.)

State of California		,		,
			•	
County of:				
				•
On:	before me,			
DATE		ISERT NAME OF THE OFF	ICER .	
NOTARY PUBLIC personally appears	,d.			
·	NAME(S) OF SIGNER(S)			,
·				
ha arayad ta ma an tha hasia of as	tiofooto z r óvidonoo	to be the person	(a) who name(a) in/arc	aubaaribad ta
who proved to me on the basis of sa the within instrument and acknowled				
capacity(ies), and that by his/her/the				
of which the person(s) acted, execut				
	., , ,			
I certify under PENALTY OF PERJUR true and correct.	Y under the laws o	of the State of Calr	fornia that the foregoir	ng paragraph is
lide and correct.				•
·.				•
WITNESS my hand and official seal.				
•	•	•		
•				
w ·				
				•
SIGNATURE				
			•	•
	•			
•				
		•	(PLACE NOTARY S	EAL ABOVE)
			•	•

REHABILITATION / RESTORATION & MAINTENANCE PLAN (CONTINUED/ ATTACHMENT)

Exhibit A. Rehabilitation/Restoration Plan

Scope:#1			
Building Feature: Exterior	r Gates, Curbs, Fence, P	iers, Granite Steps	
Rehab/Restoration X	Maintenance .	Completed X	Proposed ·
Contract year work comp	letion: 2018		•
Total Cost: \$25,000.00 S	ource SOV #2920		
Description of work: Rest	oration and Repair of Ex	terior Gates, Curbs, Fe	nces, Piers and Granite
OL	•		•

- The direction of the swing of all gates was reversed in the direction of egress. The gates were prepared, primed, and painted, and latch and lock sets were provided. At the two existing double gateways, the existing gates were reinstalled on new freestanding supports similar to the existing. The original hinges were retained at the original piers. The displaced sections of the piers were reset in the original locations and grouted. The cement plaster parge was repaired as required to match the original.
- The iron fence was prepared, primed, and painted. The gaps and voids were filled with mortar at the base and pier attachments. Where the fence is set into the curb and is corroded, the metal was repaired, painted, and set into lead or sealant as required to prevent future damage to the fence or curb.
- The cement plaster parge on the piers was cleaned and graffiti was removed or painted over. The cement plaster parge was repaired to match the existing adjacent color and texture as required.
- Existing joints were raked out and the granite steps were cleared of debris. Joints were repaired with mortar. Algae, moss, and other biological growth was removed. Soil and paint spatters were removed. New code-required bronze handrails were installed.

Scope: #2 Building Feature: Extend	r Paint and Stucco Repa	ir.					
Rehab/Restoration X	Maintenance	Completed X	Proposed				
Contract year work completion: 2018 Phase 1, Phase 2 scheduled for 2026							
Total Cost: \$146,950. Source SOV #9900 (half), \$293850/2=\$146,950.							
Description of works Founds Destruction and Full Panaisting							

Description of work: Façade Restoration and Full Repainting

- The existing stucco was analyzed to determine if it was lime or Portland cement-based. These tests were performed by an architectural conservator.
- Staining and soiling was removed by the gentlest means possible, this included light brushing and water washing, and cleaning with a commercial agent.
- Areas of significant hairline cracking were repaired based on analysis to determine the root cause of the condition. Investigation included testing for underlying detachment of the stucco layer, moisture intrusion, structural movement, or other causes.
- Climbing vegetation such as ivy was removed.
- Spalls and cracks through cement plaster were repaired. The cracks were routed and patched to match the existing adjacent texture, profile, and appearance.
- The existing deteriorated or detached cement plaster was removed. Graffiti and stains were removed
- Unsound paint was removed and coated with a new breathable paint coating.

May 31, 2019

Page & Turnbull, Inc.

		· · · · · · · · · · · · · · · · · · ·		
Scope: #3 Building Feature: Exterior.	Sheet Metal Elements			
decorative moldings, gutte	ers and down spouts.			
Rehab/Restoration X	Maintenance	Completed X	Proposed	
Contract year work compl	etion: 2018			•
Total Cost: \$424,323. Sou	rce SOV #7600 = \$434	,323		
Description of work: Dane	ir and Doctoration of Ext	eriar Chart Matal Ela	monto	

Description of work: Repair and Restoration of Exterior Sheet Metal Elements

- Peeling or blistering paint was scraped or sanded.
- Corrosion was removed with hand scrapers or a wire brush.
- For panels with heavy corrosion and resulting perforation of the sheet metal unit, there were three options, dependent on severity and size:
 - 1. Corroded panels were removed and the unit was replaced with a new piece of sheet metal cut to the appropriate dimension and profile.
 - 2. The corroded area was cut out of existing sheet metal, a new piece was brazewelded and the joint was ground flat: or
 - 3. The corroded area was cut out of existing sheet metal and steel-filled epoxy compound was installed to patch small holes.
- All exposed metal was painted with a rust-inhibiting primer and two coats of colorappropriate outdoor paint.
- Missing elements were replaced to maintain visual consistency.

Building Feature. Ext	enor	Wood-sash-Windows:	and Steel Tracen	y		
Rehab/Restoration	X	Maintenance	Completed	X	Proposed	
Contract year work co	omple	tion: 2018				
Total Cost: \$366,443	Sou	rce SOV #6150 and # 8	3050 for \$96,867	anc	1 \$269,576 = 366,443	
Description of Work: Repair, Restoration and Replacement of Windows						
	1*1*					

- A detailed conditions assessment of windows at St. Joseph's Church was conducted to
 - determine the extent of deterioration and appropriate treatments at each window. This included careful inspection and documentation of each window frame and its conditions, and other non-invasive diagnostic tests.
 - Repair of the window frames attempted to retain as much original material as possible, while providing adequate moisture protection for the building, and included paint removal, splicing of new wood elements in areas of severe deterioration, and replacement of all glazing compound.
- The wood frames were prepared and painted, all the existing ribbed glass that could be preserved was reused. Ribbed glass that matched the original was installed in selected locations.

Scope: # 5 Building Feature: Exterior					
Rehab/Restoration X	Maintenance	Completed	Χ	Proposed	
Contract year work comple	etion: 2018				
Total Cost: \$81,260.00 So	urce SOV #8070			-	

Description of work: Repair and Restoration of Stained Glass Windows

- Documentation and restoration of the windows was performed by a professional conservator. Restoration included removal, transport, restoration, and reinstallation of the
- The wood and steel armatures remaining from the previous stained glass window installation were prepared and painted.
- The remaining stained glass in the south wall of the kitchen was removed, salvaged, and reinstalled in the office on the first floor.

Scope:#6	2012/05/2014/05		A CONTROL OF A STANIA	ATT TO THE SECOND CONTRACT (ASSA)	Territor Land	子的原则是是一种自己的自己的原则	制度的不能量的影響的影響的學士的	2.9
Building Feature: Ext	erior Skylig	ht	Terrogra	SANTERS !				S
Rehab/Restoration	X N	/laintenance		Completed	X	Proposed		
Contract year work o	ompletion:	2018						
Total Cost: \$39,010.0	00 Source	SOV #8080	•			•		~
Description of work: I	Description of work: Repair and Restoration of Exterior Skylight							
The steel skylight remained in place and was repaired and cleaned.								
 New tempered glazing and sealant was installed, and all work and flashing details were 								

coordinated with the roof strengthening and re-roofing work.

Scope: #7			
Rehab/Restoration X	Maintenance	Completed X	Proposed
Contract year work compl	etion: 2018		
Total Cost: \$571,841 Sou	rce SOV 8 items #5050), 5070 and 5120	
Description of work: Seisn	nic Strengthening		
 Steel was fabricat 	ed and installed for seis	mic strengthening	•

Scope.#8	2007年14年20日	(25.25.25)		6.40年10年1	全世纪1992年1992年1898年1898年1	医保险性的 机机工工工		
Building Feature: Inte	erior Deco	rative Plaster						
Rehab/Restoration	X	Maintenance	Completed	X	Proposed			
Contract year work c	ompletion	: 2018						
Total Cost: \$1,350,57	Total Cost: \$1,350,577.00 Source SOV #9050 , \$1,350,577							
Description of work: I	Repair and	d Restoration of	Interior Decorative	Plaste	r			
 Detached or cracked plaster elements were repaired, if in otherwise sound condition, with 								
					. 1 4 . 1 4 1	,		

- an injected epoxy or gypsum-based grout. Testing was conducted to determine the most effective adhesive.

 Non-historic wood veneer was removed so that plaster at the base of the wall could be
- Non-historic wood veneer was removed so that plaster at the base of the wall could be restored and painted.
- Further testing of the plaster was conducted to determine the extent of deterioration. This determined the treatment method: patching and reshaping damaged elements when possible, or replacement in kind.

		·	·			
Scope #9 Building Feature: Inte		CONTRACTOR OF THE		and the second		
Rehab/Restoration		aintenance	Completed		Proposed	
Contract year work co	ompletion: 20	018	•	•		
Total Cost: \$269,000.	00 Source	SOV #8200				
Description of work:	Panair and D	ostoration of Inf	orior Woodwork I	Joore o	nd Einich Hardware	

Description of work: Repair and Restoration of Interior Woodwork, Doors and Finish Hardware

- Soiling was cleaned with the gentlest means possible, using a soft bristle brush to remove loose dust and a damp cloth for tenacious soiling.
- Blistered varnish was treated with the gentlest means possible in order to preserve the existing finish. Treatments included lightly scraping blistered areas of varnish and spottreating with fine steel wool or cotton, alcohol and a compatible varnish or shellac.
- White stains were tested to determine the cause Paint and guano were removed mechanically with a scraper so as not to damage the existing wood finish.
- Where required by the level of damage, select areas of woodwork were refinished to match the original.

April, 2019

- Wood was replaced where missing to match the original.
- At exterior doors, deteriorated wood was repaired with wood Dutchman and matched the original species, grade, grain, and profile. The exterior surface was prepped and painted. The interior was cleaned and touched up or refinished to match the original stain or clear
- Door hardware was replaced or repaired to match existing and to meet current code.

Scope: # 10 Building Feature: Interior	Marble Wainscoting and	Tiles		
Rehab/Restoration X	Maintenance	Completed X	Proposed	
Contract year work comp	oletion: 2018 .			
Total Cost: \$5,000,00 Sc	ource From KFI (3/28/19	email)		

Description of work: Restoration of Interior Marble

- Tape residue and soiling was removed with a gentle stone cleaner. Mock-ups were conducted to determine the most effective product.
- Vinyl tiles and mastic were removed in the vestibule without causing damage to underlying marble, which was cleaned with a gentle stone cleaner to remove staining and adhesive. Mockups were conducted to determine the most effective product.
- Vinyl tiles and mastic were removed from the vestibule floor and cleaned using the gentlest means possible.
- The marble floors were polished to restore luster

	•					
Scope: #11 Building Feature: Inter	ior Nave Flo	or Concrete				
Rehab/Restoration		intenance		Completed		Proposed
Contract year work co	mpletion: 20)18	•			
Total Cost: \$207,357	Source (4 it	ems) SOV #	2050, #	2250, #2300	and K	FI, \$30,000 \$7,500
\$79,847 \$45,410 and	d \$44,600					
Description of work:						

- The existing (non historic) slab was removed
- Soil was excavated and the surrounding soil was underpinned.
- New foundations, with piers and grade beams were installed
- New stage over the grade beams was installed in the apse.

·			•
Scope:#12		fileszáltásátását	
Building Feature: Interio	r Tower Floor Concrete		
Rehab/Restoration X	Maintenance	Completed X	Proposed
Contract year work com	pletion: 2018	,	
Total Cost: \$573,000.00	Source SOV #2450 and #24	60 and KFI	
Description of work:			
 The concrete sle 	oped floor was replaced with a	a new flat structural	concrete slab.
.,, .,			

New micropile foundations were installed in the towers.

The top 10 feet of the micro piles were cased in concrete.

Tower walls reinforced in concrete and covered in plaster.

•				•	
Scope: #13			Handrick broken	Actor Control March	
Building Feature: Ext	erior Lig	hting			
Rehab/Restoration	X	Maintenance	Completed X	Proposed	
Contract year work of	ompletio	n: 2018			

Total Cost: \$92,625.00 Source SOV #16080

Description of work:

- The missing original fixtures on the main entry façade were replicated based on historic documentation.
- Building façade lighting was replaced with LED fixtures to save energy.

Scope #14				
Building Feature: Inte	erior Lighting			
Rehab/Restoration	X Mainten	ance . Co	ompleted X	Proposed
Contract year work of	completion: 2018			·
Total Cost: \$135,281	.00 Source SOV #	<i>‡</i> 16070	,	
Description of work:	Repair, Restoration	n and Replacemen	t in kind of histo	oric light fixtures:
 The historic 	light fixtures were	cleaned and relam	ped.	•
■ The missing	fixtures in the main	n sanctuary were r	eplicated.	•

Scope: #15:				
Building Feature: Roof /	Built-up Roof			
Rehab/Restoration X	Maintenance	Completed X	· Proposed ·	
Contract year work com	pletion: 2018			
Total Cost: \$28,110.00	Source SOV #7500			
Description of work:				
 Existing built-up 	roofing was removed at the	lower roofs.		
 New built-up roo 	ofing was installed over new	structural decking.		

Scope:#16 Building Feature: Roof/SI	ate Roof		
Rehab/Restoration X	Maintenance	Completed X	Proposed
Contract year work comple	tion: 2018		
Total Cost: \$258,950.00 S	ource SOV #7300	•	,
Description of work:			
* Existing clote roof	tile was removed at the	main roof and partale	calvaged and rainstelled

- Existing slate roof tile was removed at the main roof and portals, salvaged, and reinstalled to allow access for structural stabilization of the roof structure.
- Deteriorated and broken tiles were replaced with salvaged stock or new tile to match the existing.
- New felt underlayment and galvanized flashing was installed.

			•	<u> </u>			
Scope: # 17							
Building Feature: Inte	rior Painting	ye seerawa					
Rehab/Restoration	X Maint	enance	Completed X	Proposed			
Contract year work co	ompletion: 2018	Phase 1, Ph	ase 2 scheduled for 20	026			
Total Cost: \$146,950	Total Cost: \$146,950.00 Source SOV #9900 (half), \$293850/2=\$146,950						
Description of work:			•				
 Tested bottor 	 Tested bottom layer of paint to find original colors. 						
 Interior plaster was painted, interior wood was refinished, and window mullions were 							
repainted.	•			·			
 Lead paint w 	as abated.		•				

Scope: #18						
Building Feature: Roof / Sheet Metal Dome and Shee			Calability (1962)			
Rehab/Restoration X Maintenance	Completed X	Proposed				
Contract year work completion: 2018	•					
Total Cost: \$60,000.00 Source SOV #9950						
Description of work:						
 Gold leaf was reapplied to the domes and cro 	sses.					
Scope: #19						
Building Feature: ADA Upgrades _ Exterior Ramp						
Rehab/Restoration X Maintenance	Completed X	Proposed	,			
Contract year work completion: 2018						
Total Cost: 12,000.00 Conversation with contractor						
Description of work:						
 Ramp provided at transept. 	:					
 Auto operator provided at existing door. 	•	•				
Scope:#20						
Building Feature: Interior Painting						
Rehab/Restoration X Maintenance	Completed	Proposed X				
Contract year work completion: 2026						
Total Cost: \$50,000.00 See Source SOV #9900			•			
Description of work:						
 Partial repainting of interior walls. 			•			
Scope: #21						
Building Feature: Exterior Painting of Cement Plaster						
Rehab/Restoration X Maintenance	Completed	Proposed X				
Contract year work completion: 2026						
Total Cost: \$241,065.00 (Exterior painting costs in 20	18 escalated 5%/	yr for 8 years)				
Repaint exterior, repair any new cracks. All re			ble			
materials and in accordance with the Secretary of the Interior's Standards.						

Exhibit B Maintenance Plan

Scope: #1		12 ./) [72]					
Building Feature: Site	Landscape						
Rehab/Restoration	Maintenance	X	Completed	Proposed	X		
Contract year work com	pletion: 2028 and eve	∍ry	10 years thereafter			•	
Total Cost: \$120,000.00) (\$1,000/month x 12r	no	x 10 yrs)				
Description of work: Washing of sidewalks and granite entry steps. Granite steps will be cleaned							
using the gentlest means possible as recommended in NPS Preservation Brief No. 1: Assessing							
Cleaning and Water-Repellent Treatments for Historic Masonry Buildings. All work will be performed							
in conformance with the	in conformance with the Secretary of the Interior Standards.						

Scope: #2 Building Feature: Exterior	Stucco					
Rehab/Restoration .	Maintenance	X	Completed	Proposed	X	
Contract year work completion: 2019 and annually thereafter						
Total Cost: \$40,000 (maintenance of 4,000/yr x10yrs)						
Description of work: Regular repainting of exterior stucco as needed to address graffiti. Perform						
visual inspection annually for signs of blistering or peeling paint.						

Scope: #3	(CP)					
Rehab/Restoration	Maintenance X	Completed	Proposed X			
Contract year work com	pletion: 2019 and annually t	hereafter				
Total Cost: \$30,000.00 (maintenance of \$3,000 x 10yrs)						
Description of work: Inspect the slate roof for loose or broken tiles and replace as needed. Inspect and repair caulking and flashing. Clear drains, overflow drains and scuppers. Remove birds nests and discourage roosting.						

	ŔW			
iters and down spot	IIS.		Annahile takabuk	
Maintenance	X	Completed	Proposed	<u>X</u>
	nua	lly thereafter .		
\$1200 per <u>y</u> ear)				
			repairs will be pe	rformed in
cretary of the Interior	or S	tandards.		
	tters and down spot Maintenance pletion: 2019 and an \$1200 per year) form visual inspecticers, replace screens using appropriate m	Maintenance X Maintenance X pletion: 2019 and annua \$1200 per year) form visual inspection ares, replace screens, cheusing appropriate mate	tters and down spouts: Maintenance X Completed Detion: 2019 and annually thereafter \$1200 per year) orm visual inspection annually for rust, holes ers, replace screens, check down spouts and	oletion: 2019 and annually thereafter \$1200 per year) orm visual inspection annually for rust, holes and signs of waters, replace screens, check down spouts and clean drains. Repusing appropriate materials and methods. All repairs will be pe

Scope:#5 Building Feature: Exteri	or Wood-sash Windo	ws	and Steel Tracery.
Rehab/Restoration	Maintenance	X	Completed Proposed X
Contract year work com	pletion: 2019 and an	nua	lly thereafter.
Total Cost: \$10,000.00	(\$1000 per year)		
Description of work: Per	form visual inspectio	n ar	nnually for signs of caulking failure, check operable
windows, window locks	and replace any crac	:kec	d or broken glass in kind. All window repairs will be
performed in accordance	e with the Secretary	of th	ne Interior Standards.

Building Feature: Exterior	Skylight		
Rehab/Restoration	Maintenance X	Completed	Proposed X
Contract year work comp	letion: 2019 and annu	ally thereafter	
Rehab/Restoration Maintenance X Completed Proposed X Contract year work completion: 2019 and annually thereafter Total Cost: \$5,000.00 (\$500 per year) Description of work: Perform visual inspection annually for signs of caulking failure, condensation			
Building Feature: Extenor Skylight Rehab/Restoration Maintenance X Completed Proposed X Contract year work completion: 2019 and annually thereafter Total Cost: \$5,000.00 (\$500 per year) Description of work: Perform visual inspection annually for signs of caulking failure, condensation problems that might compromise structure of skylight and replace any cracked or broken glass in			
Building Feature: Exterior Skylight Rehab/Restoration Maintenance X Completed Proposed X Contract year work completion: 2019 and annually thereafter Total Cost: \$5,000.00 (\$500 per year) Description of work: Perform visual inspection annually for signs of caulking failure, condensation problems that might compromise structure of skylight and replace any cracked or broken glass in			
kind. All repairs will be pe	erformed in conforman	ce with the Secretary	of the Interior Standards.

Scope:#7	
Building Feature: Exterior Stained Glass Windows	2017.55
Rehab/Restoration Maintenance X Completed Proposed X	
Contract year work completion: 2019 and annually thereafter	
Total Cost: \$16,000.00 (\$1600 per year)	
Description of work: Inspect stained glass and replace any cracked or missing pieces with glass matches original glass in color and texture. Inspect and repair lead cames. All work will be performed in conformance with the Secretary of the Interior's Standards and in accordance with NPS Preservation Brief No. 33: The Preservation and Repair of Historic Staine and Leaded Glass	

Scope: #8					
Building Feature: Exterio	r VVood Doors				
Rehab/Restoration	Maintenan <u>ce</u>		Completed	Proposed	X
Contract year work comp	oletion: 2019 and ann	ually there:	after		
Total Cost: \$7,900.00 (\$	790 per year)				
Description of work: The	face of the wood doo	ors have ex	treme exposure	to rain and su	n. They
suffered significant deter	ioration in the past. T	hey need r	egular cleaning	and regular re	finishing. All
work will be performed in	conformance with th	ie Secretar	y of the Interior's	Standards	

Scope: #9		ROKÄ			
Building Feature: Interio	r Decorative Plaster				
Rehab/Restoration	Maintenance	X	Completed	. Proposed	X
Contract year work com	pletion: 2019 and ev	ery 1	0 years thereafter		
Total Cost: \$20,000.00 (\$2000 per year)	•			
Description of work: The	existing plaster was	s prev	riously damaged wher	n water got into	the attic and
behind the decorative pl	aster ceiling. Proble	ms or	n the surface appeare	d only after cons	siderable
damage was done inside					ns annually
must look inside the attic					
All work will be performed					
accordance with NPS Pi	reservation Brief No	. 23: F	Preserving Historic Or	namental Plaste	er

		·		
	or Woodwork			
Rehab/Restoration	Maintenance X	Completed	Proposed X	
Contract year work com	pletion: 2019 and annually t	thereafter		
Total Cost: \$16,000.00	(\$1600 per year)		· .	
Description of work: Pe	rform visual inspection annu	ally for damage and	repair in the gentles	st means
possible. All work will be	e performed in conformance	with the Secretary of	f the Interior's Stan	dards.

Scope:#11		#1960 #1980 #1980			
Building Feature: Bell To	ower				
Rehab/Restoration	Maintenance	X	Completed	Proposed	X
Contract year work com	pletion: 2019 and anr	nual	ly thereafter		
Total Cost: \$18,500.00 (\$1850 per year)		·		
Description of work: Ann					
ladders and go into the	attic spaces and remo	ove	birds and close up any	gaps in the sc	reens and
louvers.			• •		

Scope:#12 Building Feature: Site D	ansaisı				
Rehab/Restoration	Maintenance	X	Completed	Proposed	X
Contract year work com	pletion: 2019 and an	inually	thereafter ·		
Total Cost: \$11,500 (\$1	,500 per year)		\		
Description of work: Ins	pect drywells in gard	en are	eas and verify site drai	nage is functio	ning to
remove standing water.	Repair if needed if w	vater i	s not being completely	absorbed as it	ntended.

Scope. # 13					
Building Feature: Interior					
Rehab/Restoration ·	Maintenance	_ <u>X</u> _	. Completed	Proposed	X
Contract year work comp	letion: 2023 and bi	-annu	ally thereafter		
Total Cost: \$80,000	,	•			
Description of work; Rep					
performed in conformand	e with the Secretar	y of t	he Interior's Standard	s and in accorda	ince with
NPS Preservation Brief N	No. 23: Preserving I	Histor	ic Ornamental Plaster	rand No. 21: Re	pairing
Historic Flat Plaster Wall	s and Ceilings				

Scope: # 14 Building Feature: Interior		APPENDING TO A		第一种经验的特别的 建产品的人物	A STATE OF THE STA	2000
Rehab/Restoration	Maintenance	<u>X</u>	Completed	Proposed	Χ	
Contract year work com	oletion: 2022 and an	inually t	thereafter	•		
Total Cost: \$8,000			• •			
Description of work: Clea	an and reseal marbl	e floors	and wainscot. All m	arble will be cle	aned usi	ng
the gentlest means poss	ible as recommende	ed in Ni	PS Preservation Brie	f No. 1: Assess	ing Clear	ning
and Water-Repellent Tre	eatments for Historic	: Mason	ry Buildings			

Scope:#15 Building Feature: Interc					
Rehab/Restoration	Maintenance	X	Completed	Proposed	Χ
Contract year work com	oletion: 2022 and ar	nuall	y thereafter		
Total Cost: \$12,000 .	••				
Description of work: Cor	iduct a visual inspec	ction a	and repair as needed	to match origina	I. All work will
meet the Secretary of th	e Interior's Standard	ds.			

April 2019

Page & Turnbull, Inc

PAGE

APPLICATION NO:

1 OF 6 PAGES

22

325

REHABILITATION/ RESTORATION PLANS SUPPORTING DOCUMENTATION

1401 Howard Street, San Francisco, CA PERIOD TO: 1/31/2018 FROM CONTRACTOR: Pallsade Bullders, Inc. CONTRACT DATE: 1875 S. Bascom Ave. #2400, Campbell, CA 95008 PROJECT MANAGER: S. Clark CONTRACTOR'S APPLICATION FOR PAYMENT CHANGE ORDER SUMMARY Application is made for Payment, as shown below, in connection with the Contract. DEDUCTIONS **ADDITIONS** Total changes approved 1. ORIGINAL CONTRACT SUM in previous months By Owner 11,111,908.00 Totals 2,001,881.73 2. NET CHANGES BY CHANGE ORDERS 2,001,881.73 3. CONTRACT SUM TO DATE (Line 1 + 2) 13,113,789,73 Total approved this Month No. Approval Date 4. TOTAL COMPLETED & STORED TO DATE 12,825,585.66 5. RETAINAGE: 958,053,01 6. TOTAL EARNED LESS RETAINAGE 11,867,532.65 7. LESS PREVIOUS CERTIFICATES FOR PAYMENT* 11,553,903.06 8. CURRENT PAYMENT DUE 313,629.59 NET CHANGES by Change Order 0.00 0:00 1,246,257.08 9. BALANCE TO FINISH, INCLUDING RETAINAGE The undersigned Contractor certifies that to the best of the Contractor's knowledge, Information and belief the Work covered by this Application for *Includes prior unpaid amount of \$379,370.94 from AIA#21 (December 2017) Payment has been completed in accordance with the Contract Documents. SCHEDULE OF VALUES that all amounts have been paid by the Contractor for Work for which previous Certificates of Payment were issued and payments received from the Owner, and that the current payment shown herein is now due. CONTRACTOR: By: OWNER'S CERTIFICATE FOR PAYMENT AMOUNT CERTIFIED (Attach explanation if amount certified differs from the amount applied for) In accordance with the Contract Documents, based on on-site observations and the Owner; 1401 Howard, LLC data comprising the above application, the Architect certifies to the Owner to the best CONTRACTOR'S Date: of his/her knowledge, information and belief, the Work has progressed as indicated, By: the quality of the Work is in accordance with the Contract Documents, and the Contractor is entitled to payment of the AMOUNT CERTIFIED. Architect: Page & Turnball

PROJECT: 1401 Howard Street

HARD COST APPLICATION AND CERTIFICATE FOR PAYMENT

TO OWNER: 1401 Howard, LLC.

APPLICATION AND CERTIFICATION FOR PAYMENT, CONTAINING CONTRACTOR'S SIGNED CERTIFICATION IS ATTACHED IN TABULATIONS BELOW, AMOUNTS ARE STATED TO THE NEAREST DOLLAR.

APPLICATION NO : APPLICATION DATE :

22 1/31/2018

CATION DATE : PERIOD FROM :

1/1/2018 1/31/2018

PERIOD TO :

JOB#: 1600

CONTRACT DATE:

A	В .		С						٠ . ۵		E	F		G		T	Н	Π	ī
					Change		_		Work Com	ple	ted .	Malerials		Total	%	1			
ITEM	Description of work		Scheduled		Orders		New ·		Previous		This	Presently	1	Completed	Complete		Balance to]	Retainage
NO.			Value		To ·		Scheduled		Applications		Parlod	Stored		and Stored			Finish		at 10% ·
}					Date		Value			V	Vork in Place	(Not in D or		to Date				1	
.				(Th	ru PCCO#11)				(D + E)		(F-D)	- E)		(D + E + F)	(G/C)		(C-G)		
1290	Weather Protection	\$	25,000,00			\$	25,000.00	\$	24,231.49				\$	24,231,49	97%	\$	768,51	\$	2,423.15
·1390	Hoisting/Equipment Rentals	\$	110,000.00	\$	(3,544.02)	\$	106,455.98	\$	100,000.00	\$	6,455.98		\$	106,455,98	100%	\$		\$	10,645,60
1800	General Conditions/Supervision	\$	800,000.00	-\$	343,000.00	\$	1,143,000.00	\$	1,050,000.00	\$	73,321.77		\$	1,123,321.77	98%	\$	19,678.23	\$	-
2050	Demo Existing Concrete SOG	\$	37,500.00	S	(7,500.00)	\$. 30,000.00	\$		\$			\$	30,000.00	100%	.\$	-	\$	-
2070	Selective Demolition	\$	125,000.00	\$	92,298.53	\$	217,298.53	\$	217,298,53	\$			\$	217,298,53	100%	\$		\$	15,479.85
2080	Core Drilling	\$	7,500.00			\$	7,500.00	F	7,500.00	<u> </u>			\$	7,500,00	100%	\$	· <u>-</u>	\$	750.00
2250	Underpinning pits/misc.	\$		\$	79,847.59	\$	79,847.59	\$	79,847.59	L			\$	79,847.59	100%	\$.	-	\$	(0.00
2300	Spoils Removal	\$	13,280.00	\$	32,130.00	\$	45.410.00	\$	45,410.00				\$	45,410.00	100%	S		\$	4,541.00
2310	Excavation	\$	25,000.00	\$	5,906.00	\$		\$	30,906,00	\$	-		\$	30,906.00	100%	\$		\$	3,090.60
2450	Microplies	·\$	328,000.00			\$	328,000.00	\$	328,000.00	\$			\$	328,000.00	100%	\$		\$	-
2460	Casing Upper 10' of each Micropils	\$	36,000.00	\$	-24,000,00		60,000.00	\$	60,000,00	L			S	60,000.00	100%	\$	· -	\$	
2510	Domestic Water Underground	\$	24,100.00	\$	(24,100.00)	_		٠		_			\$		100%	\$		\$	-
2520	Sanitary Sewer & SD	\$	143,440.00	\$	(36,000.00)	\$	107,440.00	\$	107,440.00		-		\$	107,440,00	100%	\$		\$	10,744,00
2800	Landscape; Irrigation & Planting	\$	46,000.00	\$	48,000.00	\$	94,000.00	\$	27,328.96	\$	40,301.93		\$	67,630.89	72%	5	26,369.11	\$	6,763.09
2810	Site Lighting (excludes fixtures)	\$		\$	26,350.00		26,350.00	\$	26,350.00	\$			\$	28,350.00	100%	3		\$	2,635.00
2860	Landscape Arbors	\$		\$	15,000.00		15,000.00						\$		0%	\$	15,000.00	\$	-
2920	Fencing	\$	25,000.00	\$	25,000.00	\$	50,000.00			\$	30,000.00		\$	30,000.00	60%	\$	20,000.00	\$	3,000.00
	Landscape Gas Lights (piping				.		·		•	1	1				}				•
	anly) ·	\$		\$	12,500.00		12,500.00	_	12,500.00				5	12,500.00	100%	\$	_	\$	1,250.00
2960 .	Joint Trench	<u>,\$</u>	25,000.00	\$	60,000.00			\$	85,000.00				\$	85,000,00	100%	\$		\$	8,500.00
	Rebar/Mesh, Shotcrete & CIP	\$	1,245,000.00	\$	70,728.00			\$		\$			\$		100%	\$	-	\$	5,329.43
	Struct. Excavation, Backfill & Offhaul		151,000.00	\$	(4,721.36)			ş	146,278.64	\$			\$	146,278.64	100%	\$		\$	14,523.51
	On Grade Site Concrete (Hardscape)	\$	50,000,00	\$	25,000.00	\$	75,000.00	_	70,815,67	5			\$	70,815.67	94%	\$	4,184.33	\$	7,081.57
	Offsite Concrete	\$	50,000.00			\$	50,000.00	\$	28,864.00	\$			\$	28,864.00	58%	S	21,136,00	\$	2,886.40
	Misc. Concrete	\$	50,000.00	\$	(50,000.00)	\$	_		12 4 1. N	\$			\$		100%	S	-	\$	
	SUBTOTALS PAGE 1	3	3,316,820,00	1	733,894.74	\$.	4,050,714.74	\$	3)793,498,68		14150.079.68	\$100 MARCHAR	\$	3,943,578,56	97%	\$	1.107,136:18	3	99,643.70

APPLICATION NO: APPLICATION DATE: PERIOD FROM:

1/31/2018 1/1/2018

PERIOD FROM :

1/1/2018 1/31/2018 1600

JOB #: CONTRACT DATE:

					·						·	· · · · · · · · · · · · · · · · · · ·							
Α	В		C						D ·		E	F		G		\perp	Н		1
					Change				Work Com	plete		Materials		Total	%	T			
ITEM	Description of work	1	Scheduled		Orders		New		Previous		This	Presently		Completed	Comple	te	Balance to	1	Retainage
NO.			Value		To		Scheduled		Applications		Period	Stored	1	and Stored		-	Finish		at 10%
		ŀ			Date		Value			٧v	ork in Place	(Not in D or		to Date					
		1		m	ru PCCO#11)				(D + E)		(F-D)	, E)		(D + E + F)	(G/C	,	(C-G)		
4900	Masonry	\$	20,000.00	\$	(20,000.00)	S	- 1	-					\$	-	100%	\$		\$	
5050	Structural Steel	\$	275,000.00	\$	(40,000.00)		235,000.00	\$	235,000.00				\$	235,000.00	100%	. \$		\$	23,500,00
5070	Structural Steel Installation	\$	400,000.00	\$	(88,158,91)	\$	311,841.09	\$	311,841.09	\$	-		\$	311,841.09	100%	\$	-	\$	31,184.11
5080	Mezzanine Steel	\$	401,143.00	\$	(84,000,00)	\$	317,143,00	\$	317,143.00	\$	_		\$	317,143.00	100%	\$	-	\$	31,714.30
5090	Mezzanine Bridge	\$	50,000.00			\$	50,000.00	\$	50,000.00				\$	50,000.00	100%	\$	-	\$	5,000.00
5100	Mezzanine Glass Rall System	\$	205,000.00	\$	(117,500,00)	\$	87,500.00	\$	83,696.20	\$	-		5	83,696.20	96%	\$	3,803.80	\$	8,369.62
5110	Stairs	\$	80,000,00	\$	(17,500,00)	\$	62,500.00	\$			- 1		S	31,250.00	50%	\$	31,250.00	\$	3,125.00
5120	Misc, Steel	\$	25,000.00			\$	25,000.00	\$	11,812.50	\$	-		\$	11,812.60	47%	\$	13,187.50	\$	1,181.28
5130	Supports for the 700 lb. Trough sink	\$	-	\$	7,500.00	\$	7,500.00	\$	7,500.00				\$	7,500.00	100%	\$	-	\$	750.00
6050	Cabinets	\$	10,000.00	\$	(10,000.00)	\$	•						\$	-	100%	\$, -	\$	*
6100	Retrofit Carpentry	\$	560,000.00	\$.77,701.97		637,701.97	\$	568,219.74	\$	44,482.00		\$	612,701.74	96%	\$	25,000.23	\$	61,270.17
6150	Window Stop Repair	\$	50,000.00	. \$	46,867.00	\$	96,867.00	\$	96,867.00	\$	- ·		\$	96,867.00	100%	\$	-	\$	9,686,70
6160	Bell Tower Rot Repair	\$		\$	151,458.96	\$	151,458.96	\$	151,458.96	S	-		\$	151,458.96	100%	\$		\$	15,145,90
6200	Trim Carpentry	\$	50,000.00			\$	50,000,00	\$	21,895.57	\$	20,000.00		\$	41,895.57	84%	\$	8,104.43	\$	4,189,56
6250	Scaffolding	\$	175,000.00	\$	174,060.84	\$	349,060.84	\$	349,060.84	\$	-		\$	349,060.84	100%	\$	-	\$	33,406,08
6250	Bell Tower Scaffolding	\$	-	\$	165,000.00	\$	165,000.00	S	165,000.00	\$	-		S	165,000.00	· 100%	\$	-	\$	16,500.00
6500	Counterlops	\$	5,000.00	\$	(5,000.00)	\$	-						\$	-	100%	\$	-	\$	•
7200	Additional under slab insulation	\$		\$	35,000,00	\$	35,000.00		35,000.00	\$	-		\$	35,000.00	100%	\$	-	\$	3,500,00
	Slate Tile Roof	\$	267,950.00	\$	(9,000.00)		258,950.00	\$	258,950.00	\$			\$	258,950.00	100%	\$	-	\$	25,895.00
7500	Lower Roof System	\$	35,000.00	\$	(6,890.00)	\$	28,110,00	\$	28,110.00				\$	28,110.00	100%	\$	_	\$	2,811.00
7600	Flashing & Sheetmetal	\$		\$	234,323.47	\$	434,323.47		434,323.47		-		\$	434,323.47	100%	\$	-	\$	43,432.35
	Sealants & Caulking	\$	10,000.00			\$	10,000.00	\$	10,000.00		_		\$	10,000.00	100%	\$		S	1,000.00
	Windows	\$		S	(275,423.78)			\$	269,576.22				\$	269,576,22	100%	\$	-	\$	26,957.62
8070	Stain Glass Repair	\$	120,000.00	5	(38,739.33)		81,260.67	\$	81,260.67	\$	-		\$	81,260.67	100%	\$	-	\$	8,128.07
	Skylight Repair	\$	•	\$	39,010.06			\$	39,010.06		1		\$.	39,010,06	100%	\$		\$	3,901.01
	Doors/Milwork & Finish Hardware	\$	284,000.00		(15,000.00)		2001000100	\$	264,631.12		_		\$	264,631.12	98%	\$	4,368.88	\$	25,463.11
9050	Plaster Repair	\$	775,000.00	\$	575,577.80	\$	1,350,577.80	\$	1,350,577.80	\$			\$	1,350,577.80	100%	\$	-		35,057.78
9100	Metal Studs & Drywall	\$	110,000,00	\$	(40,000.00)	\$	70,000.00	\$	70,000.00	\$			\$	70,000.00	100%	\$		S	7,000.00
	Soffitt below Transept Café,															\top			
9200	Green Rm Stage Metal Framing	\$		\$	17,000.00	\$	17,000.00	\$	17,000.00	\$		·	S	17,000.00	100%	\$	_	\$	1,700.00
9400	Ceramic Tile	\$	30,000.00	\$	(30,000.00)	\$	_						\$	-	100%	S		\$	•
9630	Flooring - Carpet Tile	\$	78,000.00	\$	(78,000.00)	\$	-						\$	-	100%	\$	·	\$	
9900	Painting	\$	234,900.00	\$	58,950.00	\$	293,850.00	\$	279,213.41	\$	-		\$	279,213.41	95%	\$	14,636.59	\$	27,921,34
9950	Gold Leaf at Dome	\$		\$	60,000.00		60,000.00		60,000.00		-		\$	60,000.00	100%		-	\$	6,000.00
312530	SUBTOTALS PAGE 2	3.1	8.312,813.00	\$ 1	501,132,82	\$	9,813,945,82	\$	9,391,898,53	\$	214,561,68	\$1,200 12 15 11	\$	9,606,458,21	989	6 3.	207 487 81	\$,:6	64:437:16
	man and the same a			, se 17"	<u> </u>					أست ك	named of the Land of the				***********	240167	A. P. S. L. C.	11111	

APPLICATION AND CERTIFICATION FOR PAYMENT, CONTAINING CONTRACTOR'S SIGNED CERTIFICATION IS ATTACHED IN TABULATIONS BELOW, AMOUNTS ARE STATED TO THE NEAREST DOLLAR.

APPLICATION DATE: 1/ PERIOD FROM: 1

APPLICATION NO :

1/31/2018 1/1/2018 1/31/2018

PERIOD TO:

f: 1600

JOB#: CONTRACT DATE:

Α	В .		С)	D		E .	. F	L	G				Н.]
					Change				Wark Comp	lef		Materials		Total		%				
ITEM	Description of work		Scheduled		Orders		New		Previous		This	Presently	1	Completed	Con	plete	£	Balance to	F	Retainage
NO.			Value .		To		Scheduled		Applications		Period	Stored		and Stored		•		Finish		at 10%
					Date		Value		1	1/1	Vork In Place	(Not in D or		to Date		i				
				m	hru PCCO#11)	•			(D + E)		(F-D)	` E)		(D + E + F)	ſG	/ C)		(C-G)		
10320	Fire Extinguishers	\$	1,600,00			\$	1,600.00			\$	1,600,00		\$	1,600.00	10	0%	\$	- 1	ŝ	160.0
10400		S	6,500.00			\$	6,500.00	\$	6,500.00	\$		***************************************	\$	6,500.00	10	10%	\$		\$	650.0
10450		5	2,000,00	1		\$	2,000.00		-	\$	2,000.00		\$	2,000.00	10	0%	\$	_	\$	200,0
	Access Doors & Ladders	S	12,000,00			\$	12,000.00	\$	12,000.00	\$	~		\$	12,000.00	10	0%	\$	-	\$.	. 1,200.0
10600	Tollet Partitions	S	. 11,500,00			\$	11,500.00	\$	11,500.00	\$	-		\$	11,500,00	10	0%	\$		\$	1,150.0
		\$	1,500,00			\$	1,500,00	\$	1,500.00	\$	-		\$	1,500.00	10	0%	\$	-	\$	150.0
10910	Misc. Speciallies/Bike Racks	\$	1,500.00			\$	1,500.00	\$	1,500.00	\$	-		\$	1,500.00	10	0%	.\$	-	\$	150,0
11010	Appliances	\$.	2,500.00	\$	(2,500.00)	\$	-						\$	-	10	0%	\$	-	\$	
12050	Window Coverings	\$	· -			\$	-						\$	_	10	0%	\$	-	\$	· .
13170	Interior Plaster/Paint Lead Abatement	\$	100,000.00	\$	(97,870.27)	\$.	2,129.73	\$	2,129.73	\$	-		\$	2,129.73	10	0%	\$	(0.00)	\$	212,9
13180	Bird Guano Abatement	\$	12,500.00	\$	(3,200.00)	\$	9,300.00	\$	9,300.00	\$	-		\$	9,300.00	10	0%	\$	-	\$	
13190	Asbestos Abatement	\$	16,000.00	\$	(1,543.00):	\$	14,457.00	\$	14,457.00	Ş	-		\$	14,457.00	10	0%	\$	-	\$	-
14200	Wheel Chalr Lift	\$	25,000.00	\$	20,000.00	\$	45,000.00	\$	45,000,00	\$	-		\$	45,000.00	10	0%	\$	-	\$	4,500.0
15050	Plumbing .	.\$	105,000.00	\$	(21,000.00)	\$	84,000.00	S	80,000.00	\$	4,000.00		S	84,000.00	10	0%	\$		\$	8,400.0
15150	Radiant Floor Heat	\$	145,000.00	\$	7,500.00	\$	152,500.00	\$	152,500.00	\$	-		\$	152,500.00	10	0%	\$		\$	15,250.0
15400	Ventilation	\$	185,000.00	\$	10,000.00	S		\$	181,171.20	\$	5,200,80		\$	186,372.00	9(3%	\$	8,628.00	\$	18,637.2
18050	Electrical	\$	353,000.00	\$	643,000.00	\$		\$	968,728.38	\$	17,385.65		\$	986,114.03	. 99	3%	\$.		\$	98,611.4
16070	Fixtures	\$	50,000,00	\$	85,281.00	\$	135,281.00		126,327.00	\$			\$	126,327.00		3%	\$	8,954,00	3	12,632.7
16080	Site Lighting Fixtures	\$		\$	92,625.00		92,625.00		78,693.00		6,179.00		\$	84,872.00	9:	2%	\$	7,753,00	\$. 8,487.2
16090	Access Control / Intercom	\$		\$	27,469.00	\$	27,469.00		8,240.70	\$	19,228.30		\$	27,469.00	10	0%	\$.	-	\$	2,746.9
	CCTV System	\$	-	\$	15,484.00		15,484.00			\$	10,838.80		\$	15,484.00		0%	\$	-	\$	1,548.4
16150	WIFi System	\$		\$	18,360.00	\$	18,360.00	\$\$	9,180.00	\$	9,180.00		\$	18,360.00		0%	\$	-	\$	1,836.0
16160	Music Speaker System	\$	- .	\$	51,248.00		51,248.00		51,248.00				\$	51,248.00	10	0%	\$	- 1	\$	5,124.8
16170	Commisary Service Upgrade	\$	_	\$.6,000.00		6,000.00		6,000.00		-		\$	6,000.00		0%	\$		\$	600.0
16180	Service Location Chg & Misc. Mods	\$	-	\$	9,975.00	\$	9,975.00	S	9,975.00	\$			\$	9,975.00	10	0%	\$		\$	997,5
16200	Low Voltage	\$	150,000.00	\$	(60,000,00)	\$	90,000.00	\$	83,072.13	\$	-		\$	83,072.13	92	2%	\$	6,927.87	\$	8,307.2
16300	Telephone Data .	\$	·	\$	6,248.00	\$	6,248.00	\$	6,248.00	\$	· - ' l		\$	6,248.00	10	D%	\$	-	Š	624,8
16400	Lighting Control System	\$		\$	124,790.00	\$	124,790.00	\$	109,637.10	\$	12,181.90		\$	121,819.00	98	3%	5	2,971.00	\$	12,181.6
16500	Engineering	\$		\$	27,500.00	\$	27,500.00	\$	27,500.00				\$	27,500,00	10	0%	\$	-	\$	2,750.0
17000	Additional Tenant Improvements	\$	240,000,00	\$	(240,000.00)	\$							\$		10	0%	\$		\$	-
17001	Red Room - Ceiling restoration	Ş	• -	\$	40,749.25	\$	40,749.25	\$	40,749.25	3	-		\$	40,749.25	10	0% .	\$	-	\$	4,074.9
17002	West Tower - X brace & spiral stair	\$	-	\$	40,000.00	\$	40,000.00	\$	20,000.00	\$	10,000.00		\$	30,000.00	75	%	\$	10,000.00	\$	3,000.0
17003	East Tower - X brace	\$	-	S	20,000.00		20,000.00	\$	20,000.00	\$	-		\$	20,000.00			\$	-	S	2,000,0
THE STATE OF	SUBTOTALS PAGE 3	· · ·	:0790 412 WO.	u.	0.000000000000	:(61)	12,054,661,80		322256 286652	4	12346 600-457	Secretary of the second	-	1 792,054 35	3.54 N. A.	mod)	AL-	33355555555555555555555555555555555555	C 2 (500.07 E.A

APPLICATION AND CERTIFICATION FOR PAYMENT, CONTAINING CONTRACTOR'S SIGNED CERTIFICATION IS ATTACHED IN TABULATIONS BELOW, AMOUNTS ARE STATED TO THE NEAREST DOLLAR.

APPLICATION NO : APPLICATION DATE ;

CONTRACT DATE:

1/31/2018

PERIOD FROM : PERIOD. TO ;

1/1/2018 1/31/2018

JOB#:

1600

Α	В		С					D		. <u>E</u>		F		G				Н		1	
				Change				Work Completed			Materials			Total		1					1
ITEM	Description of work	Sche	eduled	Orders		New		Previous		This	Pre	ently	C	ompleted	Comp	lete	Bala	nce to	F	Retainage	
NO.		. Va	alue	To	5	Scheduled	م	Applications	1	Period	St	ored	·a	nd Stored			Fi	ilsh		al 10%	
				Date	1	Value		•		ork in Place	(Not	n D or	to Date					-			
			.]	(Thru PCCO#11)				·(D + E)		(F-D)		Ξ)	(I)+E+F)	(G/	C)	(0	-G)]		
	DIRECT COSTS:																				1
	Division 1 - General Requirements	\$ 93	35,000.00	\$ 339,455.98	\$	1,274,455.98	\$	1,174,231.49	\$	79,777.75	\$		\$ 1	,254,009,24	989	6	\$ 2	0,446.74	\$	13,068.75	ĺ
	Division 2 - Site Improvements	\$ 83	35,820.00	\$ 353,432.12	\$	1,189,252.12	\$	1,057,581.08	\$	70,301.93	\$		\$ 1	,127,883,01	959	6	\$ 6	1,369.11	\$	56,753.54	
	Division 3 - 17 Bldg. Improvements	\$ 7,96	32,593.00	\$1,628,360.70	\$	9,590,953.70	\$	9,247,885.65	\$	162,276.45	\$		S 9	,410,162.10	989	6	\$ 18	0,791.60	\$	810,792.79	1
	TOTAL DIRECT COST	\$ 9,73	33,413.00	\$2,321,248.80	\$ 1	12,054,661.80	\$ 1	1,479,698.22	\$	312,356.13	\$	-	\$ 11	,792,054.35	989	%	\$ 25	2,607.45	\$	880,615.08	

9000	OVERHEAD & PROFIT	\$ 632,672.00	\$	119,247.56	\$	751,919.55	\$ 722,925.28	S	12,613.91		\$	735,539,19	98%	,	\$ 16,380.36	3	73,553.92
8000	CONSTRUCTION CONTINGENCY 1.5%	\$ 486,671.00	\$	(486,671.00)	\$		\$ 				\$	-	1009	6	\$ -	\$	- 1
102	CCIP INSURANCE	\$ 259,152.00	\$	48,056.38	\$	307,208.38	\$ 282,631.70	\$	15,360.42		\$	297,992.12	97%		\$ 9,216.26	\$	3,884.01
		 			<u></u>					l	 				 		
	TOTAL GUARANTEED MAXIMUM PRICE	\$ 11,111,908.00	\$:	2,001,881.74	\$	13,113,789.73	\$ 12,485,255.20	\$	340,330.46	\$	 \$ 12	2,825,585.66	98%	···	\$ 288,204.07	\$:	958,053.01

II. EXEMPTION STATEMENT AND SIGNIFICANCE EVALUATION

EXEMPTION STATEMENT

The Mills Act Historical Property Contract requires all commercial properties that are assessed at a value of more than \$5 million to include a Historic Structure Report (HSR) as part of the application. The value of this property was less than \$5 million before renovations but is over the threshold due to the extensive renovations that were necessary to place it in service. Representatives of the San Francisco Planning Department have indicated that the HSR could be limited in scope and should include, at minimum, a brief history of the building, a description of the building's historic condition, a summary of its existing condition, and an outline of short-term and long-term recommendations for rehabilitation.

This limited Historic Structure Report, together with the Rehabilitation/Restoration & Maintenance Plan, serves to fulfill the requirements of the Mills Act application.

2019 MILLS ACT APPLICATION CRITERIA

This Mills Act application is submitted for 1401 Howard Street in San Francisco. During the process of preparing the application, staff at the Planning Department was consulted and the applicant was notified that changes to the Mills Act Program had been made but that the revised/updated application had not yet been posted to the city website. For this reason, the applicant was instructed to submit the old application, and strongly encouraged to include a written justification as to how the property meets the priority consideration criteria.

The priority consideration criteria and justification is summarized below, demonstrating that the property qualifies in three of the five categories for priority consideration. Further justification is summarized in the application that follows.

NECESSITY

For more than thirty years, this Landmark property sat vacant and suffered vandalism and continued deterioration. New owners assumed a risk and it took more than 10 years to assemble a pro-forma with financial incentives that enabled the project to 'pencil out'. Thorough assessment of architectural and structural conditions was required: use of the State Historical Building Code and Historic Rehabilitation Tax Credits were necessary for the substantial rehabilitation and restoration to be implemented in ways that allowed for the preservation and reuse of this Landmark.

INVESTMENT

The substantial rehabilitation of 1401 Howard resulted in significant private investment and placed it on the tax roll for the first time since its construction in 1913. The applicant spent more than \$12 million dollars to reinvest in the Landmark and the project has improved the investment climate of the entire neighborhood.

DISTINCTIVENESS

The project preserves a distinctive example of a property that is especially deserving of a contract due to its exceptional nature. 1401 Howard is City Landmark #120 and is listed in the National Register of Historic Places (#1982002250); it has long been recognized as exceptional due to its architectural design and its significance to the early Irish, Filipino and Hispanic communities as a Catholic parish. The project

April 2019 29 Page & Tumbull, Inc.

is also distinct in that it preserved the architectural significance of the church, a challenging typology to reuse, while adapting it to a new future.

RECENTLY DESIGNATED CITY LANDMARK—not applicable, already a Landmark.

LEGACY BUSINESS - not applicable - yet.

III. HISTORIC STRUCTURE REPORT

Historic context and evaluation sections of this Historic Structure Report have been incorporated from the Historic Resource Evaluation authored by Page & Turnbull in 2011.

HISTORY OF 1401 HOWARD STREET

St. Joseph's Parish was established in 1861 by Archbishop Joseph Sadoc Alemany at the corner of 10th and Howard streets in San Francisco. The parish originally served the large Irish-Catholic population in the South of Market Area. The first St. Joseph's Church was dedicated on December 8, 1861 and was the seventh parish established in the city. (Figure 1).




Figure 1. St. Joseph's Church, 1861.

Source: "History of St. Joseph's Parish," Diamond Jubilee of St. Joseph's Church: 1861-1936 (San Francisco: unpublished pamphlet, 29 October 1936).

Father Hugh Gallagher was the first pastor of St. Joseph's Parish. Born in County Donegal, Ireland on Easter Sunday, 1815, he was ordained in 1840 and was sent to Pittsburg, Pennsylvania, where he labored for eight years at Master's Vineyard. Father Gallagher met Archbishop Alemany at the Council of Baltimore in 1854 and was recruited to California to help build the Diocese of San Francisco. Father Gallagher was appointed pastor of St. Joseph's in 1861 and selected a site beside an abandoned waterworks at 10th and Howard streets for the construction of St. Joseph's Church. Under Father Gallagher's guidance, the parish quickly grew to be one of the most populous and prosperous in San Francisco. A larger church was erected in 1865 on 10th Street, and in 1867, this church was expanded to accommodate additional parishioners.²

In 1867, Father Gallagher established a girls' school under Mrs. Margaret Deane, and a boys' school under Professor W.J.G. Williams. These schools, which taught children from the South of Market Area and the Mission district, were secularly operated until 1871, when the Sisters of the Holy Names were brought on to teach classes. Girls' classes were held in the original church building, which had been remodeled and moved to the rear of the parcel. The boys' school was housed in the pavilion of the old

¹ Archdiocese of San Francisco, "The History of St. Joseph's Parish," in Archdiocese of San Francisco Archives. ² Ibid.; "History of St. Joseph's Parish," *Diamond Jubilee of St. Joseph's Church: 1861–1936* (San Francisco: unpublished pamphlet, 29 October 1936).

City Gardens. This building was purchased from the city and moved from its original location at 12th and Folsom streets to the corner of 10th and Howard streets (the portion of the parcel presently occupied by St. Joseph's Church). A convent was also erected on the St. Joseph's Church property shortly thereafter.³

Father Gallagher died in 1882 and was succeeded by Father Patrick Scanlon. Father Scanlon was born in County Kerry, Ireland, and educated at All Hallows College near Dublin until he was ordained as a priest in 1864. In 1865, Father Scanlon was sent to California, where he worked in Mariposa and Sacramento before coming to St. Joseph's Parish in San Francisco. Father Scanlon further improved St. Joseph's schools and secured the Brothers of Mary to take charge of the boys' school in 1886. Father Scanlon also built a new residence for the clergy and improved the boys' school facilities. The parish continued to flourish under Father Scanlon, with over twelve thousand predominantly Irish parishioners in regular attendance. Upon Father Scanlon's death in 1904, Father Patrick E. Mulligan, who was born in San Francisco and attended St. Mary's College, was appointed as the third pastor of St. Joseph's Parish.⁴ (Figure 2).



Figure 2. Father Patrick E. Mulligan, 1906. Source: San Francisco Call-Bulletin, 3 December 1906.

The 1906 Earthquake and Fire decimated the entire South of Market Area, and St. Joseph's Church and its associated buildings were all destroyed. The congregation of St. Joseph's Church celebrated the first Mass after the disaster, on Sunday April 22, 1906, at the McDade home at 17th and Bryant streets⁵. By 1907, Father Mulligan led the congregation in erecting a temporary church on the site of the former St. Joseph's Church and had already begun constructing new school and residence buildings. Mass was held in the hall of the temporary church for eight years, until the completion of the large permanent church on the corner of the property. The temporary hall was later converted into a gymnasium and parish assembly hall, and currently houses part of the day-care center. After the fire, the clergy lived in the rear

³ lbid.

⁴ Ibid.

⁵ San Francisco Chronicle (San Francisco), 25 October 1936.

of the temporary church until the completion of the rectory in 1908 on Howard Street, where the brothers' home had formerly stood. The convent was reconstructed behind the school as well.⁶




Figure 3. "Architect's Drawing of Proposed St. Joseph's Church," 1913. Source: San Francisco Examiner, 27 April 1913.




Figure 4. St. Joseph's Church interior, 1915. Source: San Francisco Chronicle, 27 June 1915.

⁶ Archdiocese of San Francisco, "The History of St. Joseph's Parish."

Construction began on the present St. Joseph's Church in 1913. Father Mulligan selected architect John J. Foley to design the massive structure (Figure 3). Foley's striking Romanesque Revival design featured steel and brick masonry construction, with two towers capped by gilded domes flanking the primary entrance. The new church was to have a seating capacity of 1,000, with white eastern oak pews crafted by Dubuque Altar Manufacturing Company in Dubuque, Iowa, and stained glass windows depicting biblical scenes lining the walls.⁷ The cornerstone for St. Joseph's Church was laid by Archbishop Riordan on April 27, 1913, and construction was completed one year later.⁸ St. Joseph's Church was dedicated in November 1914, and the altars were consecrated in June 1915.⁹ (Figure 4). Father Richard Collins succeeded Father Mulligan as pastor on March 1, 1929.¹⁰

As the South of Market Area was rebuilt in the first half of the twentieth century, it became more industrial and never fully regained its previous residential character. Many of the Irish families who had once inhabited the area did not return, and the composition of St. Joseph's congregation gradually changed. By the 1950s, the church's membership was composed largely of Latino and Filipino immigrants.¹¹ St. Joseph's Church and its associated buildings underwent a series of renovations in the late 1950s and early 1960s by architects Wilton Smith and John G. Minton; a garage, a convent, and a school were also constructed on the site.¹² Additionally, a concrete shrine modeled after the famous grotto at Lourdes in France was built in the garden next to the church in the 1950s, and was dedicated to Our Lady of Fatima.¹³ (Figure 5).




Figure 5. Grotto in courtyard, n.d. Source: Willard, Sacred Places of San Francisco, 108.

In 1968, St. Joseph's began to host the celebration of the feast of the *Santo Niño de Cebu*, the Filipino patron saint. The festival became a major celebration complete with a parade and a fiesta, and was extremely popular among the Filipino community. By 1979, St. Joseph's Church had become the home of

⁷ Archdiocese of San Francisco Archives.

⁸ San Francisco Examiner (San Francisco), 27 April 1913.

⁹ San Francisco Chronicle (San Francisco), 23 November 1914, 27 June 1915.

¹⁰ "History of St. Joseph's Parish," Diamond Jubilee of St. Joseph's Church.

^{11 &}quot;St. Joseph's Church," National Register of Historic Places Nomination Form (23 November 1981).

¹² Building Permit Applications.

¹³ Ruth Hendricks Willard and Carol Green Wilson, Sacred Places of San Francisco (Novato: Presidio Press, 1985), 107.

the largest Filipino parish in San Francisco. A marble chapel which enshrined the Santo Niño de Cebu was dedicated in 1980 as the "National Shrine of Filipinos in the United States of America," and was the first shrine to the Santo Niño de Cebu to be constructed outside the Philippines (no longer extant).¹⁴

The Loma Prieta Earthquake in 1989 damaged St. Joseph's Church, which was immediately closed and declared seismically unstable. As the combined result of the expense to repair the church and the overall decline in church attendance in San Francisco, St. Joseph's Church remained closed. In order to help the parishioners of St. Joseph's find a new place of worship, St. Joseph's merged with neighboring St. Patrick's parish, and on March 19, 1994, a symbolic procession from St. Joseph's Church to St. Patrick's Church was held along Mission Street. In 1997, the parish buildings on the St. Joseph's site were converted into a center for homeless families and pregnant women. Operated by Catholic Charities of the Archdiocese, the center opened on June 13, 1997, as St. Joseph's Village. Today, St. Joseph's Church is no longer associated with the other buildings on the site.

CONSTRUCTION CHRONOLOGY

1860s-1890s

1861: St. Joseph's Parish established on southwest corner of 10th & Howard streets.

1900s

1906: Original St. Joseph's Church destroyed by San Francisco Earthquake & Fire.

- 1907: Parish hall (still extant, but no longer associated with the parcel containing the church) constructed for use as a temporary church and school.¹⁶ A 16' x 20' wood-frame horse stable was also constructed on the St. Joseph's Church site.¹⁷
- <u>1908:</u> Rectory (still extant, but no longer associated with the parcel containing the church) constructed. The two-story wood-frame building was designed by an unknown architect for use as clergy residences.¹⁸ A convent (no longer extant) was also constructed on the rear of parcel at around this time.

1910s

<u>1911:</u> Alterations to convent (formerly located on rear of parcel, no longer extant)—addition of basement and mansard roof; completed by architect John J. Foley.¹⁹

April 2019

¹⁴ Burns, *History of the Archdiocese of San Francisco*, vol. III, 32, "St. Joseph's Church," National Register of Historic Places Nomination Form (23 November 1981).

¹⁵ Burns, History of the Archdiocese of San Francisco, vol. III, 45.

¹⁶ San Francisco Architectural Heritage, Vertical Files: "220 10th Street." Note: Sanborn Fire Insurance maps list date of construction as "1913," as does San Francisco Planning Department's Parcel Information Database. The original building permits were not found to verify this information.

¹⁷ Building Permit Application #8225 (20 February 1907).

¹⁸ San Francisco Architectural Heritage, Vertical Files: "1415 Howard Street;" San Francisco Assessor's Office. Note: Original building permits were unavailable at the time of this report.

¹⁹ John J. Foley, "St. Joseph's Parish Convent," Plans (1911); Building Permit Application #26218 (2 June 1911).

1913: St. Joseph's Church constructed. Designed in the Romanesque Revival style by architect John J. Foley, the cornerstone was laid in April 1913.²⁰ The steel-frame masonry church was dedicated in November 1914, and the altars were consecrated in June 1915.²¹

<u>Circa 1915:</u> Alterations to Parish Hall—two 35' towers added to primary façade of parish hall by architect John J. Foley.²²

1920s-1940s

No activity recorded. (Figure 6).




Figure 6. St. Joseph's Church, 1946. Source: St. Paul Fire and Marine Insurance Company, "St. Joseph's Church," (San Francisco: unpublished case report, 1 October 1946), in Archdiocese of San Francisco Archives.

1950s

<u>Circa 1950:</u> Construction of rock-like concrete grotto, built as a shrine to Our Lady of Fatima (demolished in 1999).²³

1952: Alterations to St. Joseph's Church complex completed by architects Wilton Smith and John G. Minton and contractor Frank Portman, Jr.

Church—install new lights; install metal railings on 10th Street side; install 4 overhead doors in existing ports; repair stained glass windows.

Other buildings—various alterations and demolition work.²⁴

1956: Alterations to St. Joseph's Church—remove existing wood floor and install concrete floor; replace and relocate pews; relocate altar; install cabinets in sacristy; build new confessionals; lower metal

²⁰ San Francisco Call-Bulletin (San Francisco), 28 April 1913.

²¹ San Francisco Chronicle (San Francisco), 23 November 1914, 27 June 1915; San Francisco Examiner (San Francisco), 23 November 1914.

²² Sanborn Fire Insurance Maps (1913, 1929, & 1986); San Francisco Architectural Heritage, Vertical Files: "220 10th Street." Note: The building appears without the towers on the 1913 Sanborn Map, but did appear on a 1929 Sanborn Map.

 ^{23 &}quot;St. Joseph's Church and Complex," National Register of Historic Places Nomination Form (23 November 1981).
 24 Building Permit Application #151746 (11 December 1952); Wilton Smith, San Francisco, to Rev. Msgr. Harold E. Collins, San Francisco, 26 December 1952, in Archdiocese of San Francisco Archives.

lath and plaster ceiling and install new light fixtures in baptistery. Work completed by contractor Frank Portman, Jr. and architect Denis Shanagher for an estimated cost of \$31,000.²⁵

1960s

- <u>1960:</u> Permit issued for the construction of a four-car concrete garage at 220 10th Street (still extant, but no longer associated with the parcel containing the church). Designed by architect Wilton Smith, the garage was completed for an estimated cost of \$5,000.²⁶ St. Joseph's School at 250 10th Street was also constructed by architect Wilton Smith at this time.²⁷
- <u>1961:</u> Permit issued for erection of concrete building at 244 10th Street to be used as a convent (still extant, but no longer associated with the parcel containing the church). The convent was designed by architect Wilton Smith and was completed for an estimated cost of \$504,606.²⁸
- 1967: Alterations to St. Joseph's Church complex completed by contractor Frank Portman, Jr. and architect Denis Shanagher for an estimated cost of \$26,000.
 Rectory—construct addition at rear, remodel kitchen (new cabinets, windows, floor, etc.); remodel bathrooms upstairs and install new bathrooms downstairs; install new gate at entrance.²⁹
 Parish Hall—create new door openings and concrete stairs with railings; install new heaters and exhaust fans; install new vinyl asbestos floor covering.³⁰

1970s-1980s

- 1985: Alterations to Parish Hall—move partition; add new room; add new stairway; install new sheetrock, and re-sheetrock three classrooms. Work completed by contractor Stephen M. Smith for an estimated cost of \$15,000.31
- <u>1989:</u> St. Joseph's Church damaged in Loma Prieta Earthquake. The church was declared seismically unstable and was closed.

1990s

- 1994: St. Joseph's Parish merged with St. Patrick's Parish on Mission Street.32
- 1997: St. Joseph's Village opens in the parish buildings as homeless shelter and child-care center operated by Catholic Charities of the Archdiocese.³³
- 1999: Alterations to Rectory—remove shrine to provide space for access ramp; add handicap access ramp; install fire alarms and fire suppression system; renovate interior to provide housing for 35 people (add bathrooms, kitchen, rooms); reduce windows on west elevation.³⁴

²⁵ Building Permit Application #337884 (15 December 1956).

²⁶ Building Permit Application #237643 (17 June 1960).

²⁷ Sanborn Fire Insurance Map, San Francisco (1986).

²⁸ Building Permit Application #244156 (1 February 1961).

²⁹ Building Permit Application #349245 (13 October 1967).

³⁰ Building Permit Application #349244 (13 October 1967).

³¹ Building Permit Application #8502825 (20 March 1985).

³² Burns, History of the Archdiocese of San Francisco, vol. III, 45.

³³ Ibid.

³⁴ Building Permit Applications #9802661, #9822109, and #9900789 (19 March 1999).

2000s

- 2003: Alterations to St. Joseph's Church—remove 31 stained glass windows. The process included removal of interior wood trim, glazing or sealant, and stained glass.³⁵
- 2008: The archdiocese sells the property to a private developer.
- <u>2011:</u> St. Joseph's Church remains vacant. The rectory, parish hall, convent, school, and garage buildings are no longer associated with the parcel containing St. Joseph's Church.
- 2016: The building permit on structural repairs was issued in May 2016 and the construction started in June 2016. The scope included the restoration work for the roof, new foundations, and structural repairs.
- 2017: The building permit on the tenant improvements was issued in November. The scope of this permit included the new mezzanine, new mechanical and electrical systems, new toilets, new stairs and interior finishes.
- 2018: The construction of the structural work and TI was completed, and the owners received the Certificate of Final Completion in August.

HISTORIC SIGNIFICANCE

St. Joseph's Church is a designated San Francisco City Landmark (#120) and is listed in the National . Register of Historic Places (#1982002250).

National Register of Historic Places

The National Register of Historic Places is the nation's most comprehensive inventory of historic resources. The National Register is administered by the National Park Service and includes buildings, structures, sites, objects, and districts that possess historic, architectural, engineering, archaeological, or cultural significance at the national, state, or local level. Typically, resources over fifty years of age are eligible for listing in the National Register if they meet any one of the four criteria of significance and if they sufficiently retain historic integrity. However, resources under fifty years of age can be determined eligible if it can be demonstrated that they are of "exceptional importance," or if they are contributors to a potential historic district. National Register criteria are defined in depth in *National Register Bulletin Number 15: How to Apply the National Register Criteria for Evaluation*. There are four basic criteria under which a structure, site, building, district, or object can be considered eligible for listing in the National Register. These criteria are:

<u>Criterion A (Event):</u> Properties associated with events that have made a significant contribution to the broad patterns of our history;

<u>Criterion B (Person):</u> Properties associated with the lives of persons significant in our past;

April 2019

38

^{35 &}quot;St. Joseph's Church," Landmarks Preservation Advisory Board Case Report #2003.0197A (21 May 2003).

<u>Criterion C (Design/Construction):</u> Properties that embody the distinctive characteristics of a type, period, or method of construction, or that represent the work of a master, or that possess high artistic values, or that represent a significant distinguishable entity whose components lack individual distinction; and

<u>Criterion D (Information Potential)</u>: Properties that have yielded, or may be likely to yield, information important in prehistory or history.

A resource can be considered significant on a national, state, or local level to American history, architecture, archaeology, engineering, and culture. The following examines the significance of St. Joseph's Church under these criteria:

St. Joseph's Church is currently listed in the National Register under Criteria A (Event) and C (Design/Construction) in the areas of architecture, religion, and ethnic history for a period of significance from 1906 to 1914. The church, which is no longer associated with any of the adjacent buildings that once formed the church complex (including the rectory and parish hall that were included in the nomination), is significant for its association with the reconstruction of the South of Market Area and religious institutions following the 1906 Earthquake and Fire. The church also played an important role in the ethnic history of San Francisco, having witnessed the change from a predominantly Irish Catholic parish to a Filipino parish. St. Joseph's Church is also architecturally significant as an excellent local example of Romanesque Revival architecture, and as a typical example of ecclesiastical architecture of this period. ³⁶

San Francisco City Landmark

Under Article 10 of the San Francisco Planning Code, the evaluative criteria used by the Landmarks Board for determining eligibility are closely based on those developed for use by the National Park Service for the National Register of Historic Places.

St. Joseph's Church was listed as San Francisco City Landmark #120 in 1980. The Landmarks Board nomination form attributes the significance of St. Joseph's Church to its meaning to ethic groups in the city, especially the Irish and Filipino communities; its contribution to education in San Francisco, namely the establishment of one of the city's first parochial schools; and its association with the development of the South of Market Area. The grounds, rectory, and parish hall were included in the landmark nomination as contributing features to the site.³⁷ St. Joseph's Church is currently owned by a different entity and is no longer associated with the rectory or parish hall. Additionally, the church is no longer associated with the garage, convent, or school, which were not included or listed as contributing resources in the nomination.

South of Market Survey & Area Plan

The South of Market Area Plan (Area Plan or Plan) is a component of the city's General Plan that contains a set of objectives and policies created by the San Francisco Planning Department to guide decisions affecting the development of San Francisco's South of Market neighborhood. The South of Market Area Plan is primarily geared towards guiding residential development and public facilities within the area covered by the plan, which roughly is bordered by South Van Ness, Mission, Townsend and

April 2019

39

³⁶ "St. Joseph's Church and Complex," National Register of Historic Places Nomination Form (23 November 1981). ³⁷ "Final Case Report: St. Joseph's Church & Complex," San Francisco Landmarks Preservation Advisory Board Nomination Form (5 March 1980).

Second Streets.³⁸ The Plan provides for a mixture of low-income residential areas, rent-sensitive small business areas, and downtown visitor and office industries. The South of Market Area Plan identified a couple of potential historic districts and included a list of individually significant buildings outside those districts. St. Joseph's Church (1401 Howard Street) is listed as a "significant building located outside the proposed historic district" in the South of Market Area Plan.³⁹




Figure 7. Parcel map of the Western SoMa Community Plan area, with St. Joseph's Church marked with a star. Source: San Francisco Planning Department; altered by author.

In conjunction with the Western SoMa Community Plan (2011), the Planning Department undertook a survey of historic resources within the Plan area. The SoMa Historic Resources Survey was adopted by the Historic Preservation Commission in July 2010. As part of this survey, St. Joseph's Church was found to be a contributor to the proposed "Western SoMa Light Industrial & Residential Historic District," which appears eligible for listing in the National Register of Historic Places.

³⁸ San Francisco Planning Department, *Area Plan: South of Market*, 6 July 1995, http://www.sfqov.org/site/planning_index.asp?id=24896 (1 November 2007).

³⁹ San Francisco Planning Department, *Area Plan: South of Market*, 6 July 1995, http://www.sfqov.org/site/planning_index.asp?id=24896 (1 November 2007).

CHARACTER DEFINING FEATURES

For a property to be eligible for national, state, or local designation under criteria related to type, period, or method of construction, the essential physical features (or character-defining features) that enable the property to convey its historic identity must be evident. These distinctive character-defining features are the physical traits that commonly recur in property types and/or architectural styles. To be eligible, a property must clearly contain enough of those characteristics to be considered a true representative of a particular type, period, or method of construction, and these features must also retain a sufficient degree of integrity. Characteristics can be expressed in terms such as form, proportion, structure, plan, style, or materials.

The character-defining features of St. Joseph's Church include, but are not limited to:

Exterior

- Cruciform plan
- Massing
- Faux-stone stucco
- Sheet metal architectural elements including cornices, upper towers, gilded domes and crosses
- Wooden window tracery
- Shapes of window openings
- Granite steps
- Wooden doors

Interior

- Marble wainscoting and floor in the lobby and side exit vestibules
- Decorative plaster elements including moldings, dentil cornice, pilasters and columns, vaults and coffered ceilings
- Oak woodwork including doors, door frames, window frames, column bases and railings
- Stained glass in the bell towers and rear office
- Interior volume over 50 feet high

The character-defining features of the overall site include, but are not limited to:

- Low brick perimeter wall with brick-piers and metal fence
- Low concrete curb at northeast corner
- Landscaped open space surrounding the church
- Flat grade of the site

ARCHITECTURAL DESCRIPTION

St. Joseph's Church (1401 Howard Street; APN 3517/035) is located on an irregular-shaped lot on the southwest corner of 10th and Howard streets in San Francisco's South of Market Area (Figure 8). The church was previously the focal point of a complex of six buildings that were once associated with St. Joseph's Parish. Four of the other buildings—St. Joseph's School, Convent, Parish Hall, and Rectory—are under different ownership and are no longer associated with the church. The garage (APN 3517/036) has since been demolished and now serves as a parking area for St. Joseph's Church.




Figure 8. Site plan of the former St. Joseph's Church complex. The parcel on which the church is located (APN 3517/035) is shown in red. The rectory, parish hall, convent, and school buildings are no longer associated with St. Joseph's Church. The garage has since been demolished, and the parcel (APN 3517/036) is now associated with the subject building, shown in blue.

Source: Page & Turnbull.

Exterior

Constructed in 1913, St. Joseph's Church is a three-story, steel-frame masonry church designed in the Romanesque Revival style (Figure 9). The cruciform-plan building is clad in stucco, scored to simulate stone, and sits on a concrete foundation and is capped by a gable roof. The building features a combination of large stained glass lancet windows, arched windows with keyhole details and contemporary glazing, and large rose windows. A layer of protective glazing has been installed at the exterior of the lancet windows. Typical doors include paneled wood doors with either an arched stained glass transom or a decorative wood paneled tympanum.

The primary façade faces north onto Howard Street and is symmetrical. The main entrance is located in the center section of the façade and three sets of paired double doors with quatrefoil paneling (Figure 10). The main entrance is accessed via granite steps with two metal hand rails. Flanking either side of the stairs are two contemporary steel planters. Each door is surrounded by a Roman arch with dentil molding and a paneled wood tympanum. These doors are separated by paired engaged Corinthian columns. On the upper floors, a large rose window set into a large, recessed arch dominates this portion of the façade. The center section of the primary façade terminates in a gable roof with a pressed metal raked cornice supported by dentils and a corbel table and is capped by a gold cross finial.



Figure 9. St. Joseph's Church. View south from Howard Street. Source: Rick Stapleton, September 2018.




Figure 10. Main entrance to St. Joseph's Church. Source: Page & Turnbull, April 2019.

The center gabled section of the primary façade is flanked by two square corner towers. Each tower contains a rose window above a pair of tall lancet windows of geometric stained glass separated and flanked on either side by colonettes. The towers terminate in a cornice, dentil molding, and corbel table similar to those found throughout the building. Octagonal cupolas with arched vents separated by engaged lonic columns support the gold domes with gold crosses that crown the towers.

The east (10th Street) façade is similar to the primary façade in detailing and organization. The overall form of the east façade features a corner tower at the north end, a long recessed section with clerestory windows above a projecting first floor, the transept end in the center, and another recessed section at the south end. The treatment of the corner tower is identical to the treatment of the towers on the primary façade. The long recessed section features a projecting ground floor capped by a shed roof. A simple pressed metal cornice supported by a corbel table and a row of arched windows with decorative steel muntins (formerly stained glass windows) separated by pilasters decorate the ground floor. A row of similar but smaller windows and pilasters occupies the clerestory. The transept end repeats the detailing of the center section of the primary façade but has a solid wall instead of an entrance on the ground floor and is topped by a gold cross finial (Figure 11). Projecting portals are located on either side of the transept and feature gable roofs supported by corbel tables and door treatments similar to those found at the main entrance. A contemporary steel planter is located along the transept, at the 10th Street sidewalk (Figure 12). A covered, concrete stairwell provides access to a door below ground level, north of the east transept.




Figure 11. Detail of corbel table and cornice on the transept. Source: Rick Stapleton, September 2018.




Figure 12. Contemporary steel planter at transept of east façade. Source: Page & Turnbull, April 2019.

The west façade has a similar overall composition and features similar treatments to the east façade. An accessible concrete ramp with metal handrails runs along the recessed portion of the west façade, accessing the projecting portal on the north side of the transept (Figure 13). South of the west transept is a small recessed area and a projecting bay. Concrete steps with metal handrails access a door on the south side of the transept and on the north side of the projecting bay (Figure 14).




Figure 13. Accessible concrete ramp on the west façade.




Figure 14. Recessed area between the west transept (left) and projecting bay (right).

The rear (south) façade is dominated by a blank wall clad in molded stucco; it has a gable roof with raked pressed metal cornice, dentil molding, and corbel table similar to those found on the primary façade (Figure 15). A structural steel frame spans the blank wall of the rear façade, between the pilasters and below the corbel table (Figure 16). The metal frame is composed of one horizontal beam and two vertical beams; between the vertical beams are metal mesh screens with climbing vine plantings. The gable end is flanked by one-story projections that feature multi-light steel sash windows with arched transoms, pilasters, and the church's characteristic pressed metal dentilated cornice. A metal bike rack is mounted on the wall of the west projecting volume.




Figure 15. St. Joseph's Church, south and west façades. View north from midblock.
Source: Google Maps, 2019.




Figure 16. Structural metal frame with mesh screen and climbing vines on rear (south) façade.
Source: Page & Turnbull, April 2019.

Interior

The interior of St. Joseph's Church is a classic cruciform basilica plan, with a narthex, barrel vaulted nave, clerestory, side aisles, and a barrel vaulted transept. The three entrance arches of the Howard Street façade open into a marble-paneled narthex with coffered plaster ceiling, marble floor, and contemporary light fixtures (Figure 17). Three round-arched, heavy wooden doors with leaded glass insets open into the nave. On either side of the narthex through arched doorways with glass transoms are small rooms that form the first floors of the towers. The room to the west is the former baptistery, which opaque glass windows and a contemporary mural painted on the walls (Figure 18). On the east side of the narthex is a small room with green and yellow diamond pane stained glass and stairs leading up to a mezzanine.



Figure 17. Narthex, looking east. Source: Page & Turnbull, April 2019.




Figure 18. Former baptistry, west of the narthex, with painted mural. Source: Page & Turnbull, April 2019.

From the narthex, the nave is a large linear open space with a coffered plaster barrel vault ceiling. The flat concrete floor features radiant heating. Beneath the clerestory on each side are aisles that are supported by four arches springing from columns; the columns have white oak bases and are capped with gilded Scamozzi capitals. A cornice with dentils and acanthus leaf modillions runs above the arches and extends the length of the nave. On the east and west walls, pointed arch windows with keyhole wooden tracery are located in the aisles and the clerestory.

Large rose windows dominate the transept ends and the northwest end of the nave above the entrance. A former choir loft is located above the entrance and are recessed over the narthex (Figure 19). At the south end of the church, the former altar area is a raised wooden platform reached by wood steps (Figure 20). The altar is surrounded by a semicircular series of arched niches with ionic columns and pilasters on oak bases. Photographic murals have been installed in the center three arched niches. Above the columns is a coffered half dome, with gilded flowers inset into the coffers. A large steel skylight allows light into the altar area.




Figure 19. St. Joseph's Church interior, looking north toward choir loft. Source: Page & Turnbull, April 2019.




Figure 20. St. Joseph's Church apse, looking south. Source: Page & Turnbull, April 2019.

To the west of the altar is the former sacristy which features an arched ceiling, rounded arch windows. A contemporary mural has been painted on the concrete walls of the former sacristy (Figure 21). To the east of the altar is an office, which has a large painted stained glass window and a rounded arch door.




Figure 21. Former sacristy, with a contemporary painted mural. Source: Page & Turnbull, April 2019.

A non-original steel frame, open mezzanine with concrete floors runs along the full length of the aisles and crosses over the nave, just north of the transept (Figure 22). A metal balustrade with thin metal quatrefoil panels surrounds the mezzanine (Figure 23). Although the mezzanine runs along the exterior walls, it is not attached to the walls. Seating areas, divided by hanging curtains, are located along the aisle, below the mezzanine. On the ground floor of the east transept, at the former location of the confessionals, partition walls enclose a restroom area which features four narrow toilet rooms and two larger, accessible toilet rooms. On the ground floor of the west transept, is a free-standing open servery (Figure 24). The mezzanine level is accessed via straight stairs along the west wall of the west transept and a wheelchair elevator at the west end of the apse (Figure 25).




Figure 22. Non-original mezzanine along the aisles and spanning the nave, looking north. Source:
Page & Turnbull, April 2019.




Figure 23. Mezzanine balustrade, looking down toward the nave. Source: Page & Turnbull, April 2019.




Figure 24. Servery area below the mezzanine in the west transept, looking northwest. Source: Page & Turnbull, April 2019.




Figure 25. Wheelchair elevator accessing the mezzanine at the west end of the apse, looking south. Source: Page & Turnbull, April 2019.

Restrooms are located at either end of the east transept at the mezzanine level, behind a partial-height museum style wall (Figure 26). A marble, former alter has been converted to feature a sink at either end. A small gallery is located at the mezzanine level, east of the apse (Figure 27). A free-standing bar area, and partial-height storage area is located in the west transept at the mezzanine level. The two towers, located east and west of the narthex and choir loft, feature large stained glass lancet windows, rose windows, and non-original, metal-frame seismic bracing and concrete shear walls. A rope in the east tower operates an original bell (Figure 28). A non-original, free-standing spiral metal staircase accesses a small room above the lancet windows in the west tower (Figure 29). The church also has a one-room basement in the southwest corner of the building accessed by an exterior staircase.




Figure 26. View of mezzanine level east transept. Restrooms are located behind the partial-height wall. Source: Page & Turnbull, April 2019.




Figure 27. Restrooms, including a marble alter converted to sinks, on the mezzanine level of the east transept. Source: Page & Turnbull, April 2019.




Figure 28. West tower, featuring seismic bracing and a spiral staircase. Source: Page & Turnbull, April 2019.




Figure 29. Small room at top of west tower, with rose windows. Source: Page & Turnbull, April 2019.

Site

The south and west perimeters of the site, which abut adjacent properties, are lined by a chain-link fence. A courtyard at the northwest corner of the site, a landscaped area at the northeast corner, and a parking area at the southeast corner, are all enclosed by metal fencing. A small garage constructed in 1960 (220 10th Street), located southeast St. Joseph's Church, was demolished in 2018 and the area was paved with scored concrete. The parcel on which the garage was located, APN 3517/036, is owned by 1401 Howard LLC, located within the same fenced area as St. Joseph's Church, and is currently used as parking area for St. Joseph's Church (Figure 30). A palm tree located north of St. Joseph's Church was retained and is surrounded by a low concrete planter. The area along the west side of St. Joseph's Church features a courtyard and walkways with herringbone pattern stone paving (Figure 31). Plantings line the perimeter of the courtyard and walkways, and various benches, fountains, and sculptural elements are installed throughout.



Figure 30. Concrete parking area southeast of St. Joseph's Church, at the former location of the garage, looking south.



Figure 31. Courtyard at northwest corner of the site, looking north.

Surrounding Buildings

There are four buildings in the immediate vicinity that were formerly associated with St. Joseph's Church. These include a rectory constructed in 1908 (1415 Howard Street), a parish hall constructed in 1907 that served as a temporary church and school until the completion of the main sanctuary (240 10th Street), a convent constructed in 1961 (244 10th Street), and a school constructed in 1960 (250 10th Street). These buildings are located on individual parcels separate from the subject property and are not owned by 1401 Howard LLC. They are no longer associated with St. Joseph's Church.

BIBLIOGRAPHY

A. Published

Burns, Jeffrey M. San Francisco: A History of the Archdiocese of San Francisco, vols. I-III. Strasbourg, France: Editions du Signe, 1999.

Byington, Lewis Francis, and Oscar Lewis, eds. *The History of San Francisco*, vol. III. Chicago: S.J. Clarke Publishing Co., 1931.

Davis' Commercial Encyclopedia (1911). In San Francisco Architectural Heritage, Vertical Files: "Foley, John J."

Willard, Ruth Hendricks and Carol Green Wilson. Novato, CA: Presidio Press, 1985.

B. Public Records

San Francisco Assessor's Office

San Francisco Department of Building Inspection. Building Permit Applications

San Francisco Planning Department

San Francisco Public Library

San Francisco Public Library Historical Photograph Collection

Sanborn Fire Insurance Maps (San Francisco). 1889, 1899, 1913, 1950, 1986.

C. Newspapers and Periodicals

Architect and Engineer

San Francisco Call-Bulletin

San Francisco Chronicle

San Francisco Examiner

VerPlanck, Christopher. "South of Market Architecture." San Francisco Apartment Magazine (August 2002).

D. Unpublished Drawings and Manuscripts

Archdiocese of San Francisco Archives.

"Final Case Report: St. Joseph's Church & Complex." San Francisco Landmarks Preservation Advisory Board Nomination Form. 5 March 1980.

Foley, John J. "St. Joseph's Parish Convent." Plans, 1911.

"History of St. Joseph's Parish." Diamond Jubilee of St. Joseph's Church: 1861-1936. San Francisco: unpublished pamphlet, 29 October 1936.

April 2019

- Republic Urban Properties. "St. Joseph's Church: a Tool for Political and Historical Reference." San Francisco: unpublished report, 2 November 2007.
- "St. Joseph's Church and Complex." National Register of Historic Places Nomination Form. 23 November 1981.
- St. Paul Fire and Marine Insurance Company. "St. Joseph's Church." (San Francisco: unpublished case report, 1 October 1946). In Archdiocese of San Francisco Archives.

San Francisco Architectural Heritage. Vertical Files: "220 10th Street,"
Vertical Files: "1401 Howard Street."
Vertical Files: "1415 Howard Street."
Vertical Files: "Foley, John J."
Smith, Wilton, San Francisco, to Rev. Msgr. Harold E. Collins, San Francisco, 26 December

E. Internet Sources

Archdiocese of San Francisco. http://www.sfarchdiocese.org/sfparishes.html (accessed 29 November 2007).

1952. In Archdiocese of San Francisco Archives.

- ArchitectDB, http://digital.lib.washington.edu/php/architect (accessed 1 November 2007).
- Bower, Mark A. "Putting Offices in the Sanctuary: Utilizing Rehabilitation Tax Credits for Adaptive Reuse of Religious Buildings." *Inspired* (March-April 1989) pp.4-6, 8, 16-17. In Partners for Sacred Places http://www.sacredplaces.org/free articles.htm (accessed 27 November 2007).
- National Park Service. *Preservation Briefs*. http://www.nps.gov/history/hps/tps/briefs/brief02.htm (accessed 27 November 2007).
- National Trust for Historic Preservation. *Preserving Historic Religious Properties* (June 2005). http://www.nationaltrust.org/issues/downloads/worship preserving toolkit.pdf (accessed 27 November 2007).

EXISTING CONDITIONS & TREATMENT RECOMMENDATIONS (2014)

The following existing conditions and treatment recommendations were developed by Page & Turnbull in 2014, prior to the rehabilitation/restoration project which was completed in the summer of 2018.

EXTERIOR

Perimeter Fence

Description

A discontinuous metal fence is located around the perimeter of the property. At the northwest and southeast corners of the property, the fence rests on a brick curb with brick piers. At the northeast corner, a non-historic metal fence rests on a concrete curb without piers. A gated driveway in the fence on Howard Street provides vehicular access to the church and the garden area on the west side of the property. A double metal gate on 10th Street provides access to the church and the garden area at the northeast corner of the property. A single metal gate on 10th Street provides access to the rear of the church.

Condition

The condition of the fence, gates, curbs, and piers varies from poor to good condition. The following deterioration was observed:

- Corroded metal at some locations where the fence is set into the curb (Figure 32a and Figure 32c).
- Graffiti at some locations (Figure 32c).
- Gaps and voids at some curb and pier attachments (Figure 32c).
- Damage to the metal fence at the northeast corner of the property caused by an automobile collision (Figure 32b).
- Piers are displaced in some locations (Figure 32a).

Recommended Treatments

- The direction of the swing of all gates should be reversed to be in the direction of egress. The gates should be prepared, primed, and painted, and latch and lock sets should be provided. The original hinges should be retained at the piers.
- At the gate on Howard Street, the mortar joints should be cut to reveal the corroded fence and gate anchors that have displaced the brick piers. The metal should be repaired and painted, and the displaced sections of the piers should be reset in the original locations and grouted. The cement plaster parge should be repaired as required to match the original.
- The fence should be prepared, primed, and painted. The gaps and voids should be filled with mortar at the base and column attachments. Where the fence is set into the curb and is corroded, the metal should be repaired, painted, and set into lead or sealant as required to prevent future damage to the fence or curb.
- At the piers, the cement plaster parge should be cleaned and graffiti should be removed or painted over. The cement plaster parge should be repaired to match the existing adjacent color and texture as required.
- At the west tower, the attachment of the fence to the building and piers should be repaired.

Granite Steps

Description

Granite steps are found at all main entrances to the church including the main portal at Howard Street, and both north and south entrances to the east and west transepts. The main portal steps are composed of six tiers of square-cut granite blocks of varying dimensions. The four entrances to the transepts feature granite treads embellished with a decorative bull nose reveal, and vary from two tiers of tread at the north entrance of the east transept, to five tiers of tread at the east transept's south entrance.

Condition

The granite steps are generally in good condition. The following deterioration was observed:

- Mortar loss, particularly in the vertical joints of the main portal steps (Figure 33a).
- Uneven settling of the east side of the main portal steps evidenced by the approximately 1.5-inch gap between the third and fourth step (Figure 33b).
- Biological growth and soiling (Figure 33c). .
- Paint spatters (Figure 33a).
- Spalling surface of the granite (Figure 33d and Figure 33e).

Recommended Treatments

- Existing joints should be raked out and cleared of debris.
- Vertical and horizontal joints should be repointed with a compatible mortar chosen to match the color of the original mortar.
- Uneven settling between the blocks should be monitored and a structural engineer consulted regarding future treatment.
- Algae, moss and other biological growth should be removed with a biocide, water and light brushing with a natural, soft bristle brush. Mock-up tests should be conducted to determine the most effective product and appropriate dwell time.
- Soiling should be removed with the gentlest means possible. This may include a non-ionic
 detergent in water and light scrubbing with a natural, soft bristle brush, or the use of a commercial
 stone-cleaner. Mock-up tests should be conducted to determine the most effective product and
 appropriate dwell time.
- Paint spatters should be removed with a commercial paint stripper. Tests should be conducted to determine the most effective product and appropriate dwell time.
- Stone spalling is likely caused by rising moisture or salts. Further study should be carried out to
 determine the root cause of the spalling, and it should be addressed before any treatment is
 carried out.
- Because of the shallow depth of the spalled areas and the difficulty of matching the stone color, patching is not recommended. Spalled areas can be retooled, reducing the surface of the stone by approximately 1/8 1/4 inch, in order to give the tread a smooth surface.

Stucco

Description

St. Joseph's Church is constructed of steel reinforced brick masonry covered in stucco, which is incised to resemble finished stone blocks, arches and corbelling, and used to form columns, capitals and other decorative elements. The stucco veneer is approximately 1-2 inches thick and covers the entire exterior

of the building, except for the cornice and upper portions of the towers, which are constructed of sheet

Condition

The stucco is generally in good condition. The following deterioration was observed:

- General staining and soiling, particularly at upper surfaces near the cornice, and lower surfaces at ground level (Figure 34a).
- Extensive hairline cracking (Figure 34a).
- Spalling, detachment and large areas of stucco loss (Figure 34b).
- Vegetation growth (ivy).

Recommended Treatments

- The existing stucco should be analyzed to determine if it is lime or Portland cement-based. Repairs made with an incompatible stucco formula are likely to fail. These tests can be performed by an architectural conservator.
- Staining and soiling should be removed by the gentlest means possible, this may include light brushing and water washing, poulticing, or cleaning with a commercial agent. Mock-up tests should be conducted to determine the most effective product and appropriate dwell time.
- Areas of significant hairline cracking should be analyzed to determine the root cause of the condition. Investigation may include testing for underlying detachment of the stucco layer, moisture intrusion, structural movement or other causes.
- Climbing vegetation such as ivy should be removed and killed with an herbicide. Because many herbicides contain salts that can damage historic masonry, mock up tests should be conducted to determine an effective product that does not contain salts.
- Spalls and cracks through cement plaster should be repaired. The crack should be routed and patched to match the existing adjacent texture, profile, and appearance.
- The existing deteriorated or detached cement plaster should be removed. New cement plaster should be installed that is compatible with the substrate and the existing plaster to remain.
- Unsound paint should be removed and coated with a new breathable paint coating.

Exterior Lighting

Description

In 2007, two historic lighting fixtures were mounted above the main entry to the church on Howard Street. They have since been removed.

Conditions

In 2007, the historic exterior lighting fixtures appeared to be in good condition (Figure 35a). The current whereabouts of the historic lighting fixtures are unknown. The original mounting hardware remains in place on the north façade of the church (Figure 35b).

Recommended Treatments

Attempts should be made to locate the historic lighting fixtures. It is possible that they are currently being stored inside the church. If they are not found, new light fixtures that replicate the missing original fixtures should be fabricated and installed.

April 2019 55 Page & Turnbull, Inc.

Roof

Description

The main roof is capped by a cross-gabled roof with slate tiles and features a skylight over the main altar. Parapets with metal coping are located at the gable ends of the main roof. The portals over the entrances to the transepts are also capped by gable roofs with slate tiles. The aisles and auxiliary interior spaces are capped by built-up shed roofs. The two towers are capped by painted sheet metal cupolas with gilded sheet metal domes. Various roof elements are sheet metal, including the ridge vent at the main roof, the skylight, the cupolas and gilded domes, and the crosses on top of the towers and above the pediment of each transept.

Conditions

The slate tile roof is generally in good condition. The built-up roof has reached the end of its serviceable life. The condition of the sheet metal cupolas and gilded domes range from poor to fair. The gilded crosses appear to be in good condition. The following deterioration was observed:

- There are several broken, loose, or missing slate tiles at the main roof (Figure 36d).
- There are many instances of rust-through at the painted sheet metal cupolas (Figure 36a and Figure 37c).
- Surface corrosion and loss of paint and gilding is evident at domes (Figure 36c and Figure 37c).
- The crosses require minor sheet metal and gilding repair (Figure 36b).

Recommended Treatments

- Existing slate roof tile at the main roof and portals should be removed, salvaged, and reinstalled to allow access for structural stabilization of the roof structure. Deteriorated and broken tiles should be replaced with salvage stock or new tile to match the existing. New felt underlayment and galvanized flashing should be installed.
- Existing built-up roofing at the lower roofs should be removed, and new built-up roofing should be installed over new structural decking.
- Roof, flashing, gutters and other drainage system elements should be repaired to ensure that water does not enter the structure. Gutters and downspouts should be cleaned, and drainage spouts should be extended beyond the foundation of the building with flexible tubing.
- Additional or larger downspouts may be required for proper roof drainage. Replace with similar.
- The existing metal skylight should be restored and painted. New tempered glazing and sealant should be installed.
- Sheet metal crosses should be removed and salvaged for reinstallation. They should be cleaned and touched up with new gilding to match the existing.
- Paint and gilding should be removed over the sheet metal domes. Deteriorated sheet metal should be repaired or replaced to match the original profile and appearance. A gold paint should be used to closely match the gold leaf appearance.

Sheet Metal Architectural Elements

Description

Pressed, painted sheet metal is used extensively at St. Joseph's Church for ornate architectural elements, particularly for the cornices of the main structure and the upper third of both towers. The gilded domes of the towers, as well as the crosses on top of the towers and above the pediment of both transepts are constructed of sheet metal. The ridge vent at the main roof is sheet metal. Additionally, the central columns and bases of the towers' double windows are sheet metal.

Conditions

The sheet metal elements are generally in fair condition. The following deterioration was observed:

- Cracking, flaking and loss of the protective paint layer (Figure 37a).
- Corrosion (rusting) of the sheet metal units and connections, causing perforation and rust staining, particularly at the comice level and upper towers (Figure 37b).
- Loss of paint, gilding and architectural details, particularly on the towers (Figure 37c).

Recommended Treatments

- Scrape and sand peeling or blistering paint.
- Remove corrosion with hand scrapers or a wire brush.
- For panels with heavy corrosion and resulting perforation of the sheet metal unit, there are four options:
 - 1. Remove corroded panel and replace unit with a new piece of sheet metal cut to the appropriate dimension and profile;
 - 2. Cut out corroded area of existing sheet metal, braze weld a new piece and grind joint flat;
 - 3. Cut out corroded area of existing sheet metal, paint, and install painted matching sheet metal patch with mechanical fasteners and a neoprene gasket; or
 - 4. Cut out corroded area of existing sheet metal and install steel filled epoxy compound to patch small holes.
- Paint all exposed metal with a rust-inhibiting primer, and two coats of color appropriate outdoor paint.
- Missing elements should be replaced to maintain visual consistency. Further research should be conducted to determine the best replacement material, or if sheet metal replicas can be made.
- Sheet metal parapet cap flashing should be replaced with new painted galvanized or stainless steel sheet metal to match the existing profile.

Wood-Sash Windows and Tracery

Description

The windows of St. Joseph's Church are generally fixed wood-sash designed to contain an inner layer of stained glass and an outer, protective layer of translucent glass. Ornate wooden tracery frames the formerly stained glass rose windows of the front façade and east and west transepts, and wooden tracery is used minimally in the apse and clerestory windows of the nave and transepts. Textured, clear glass, originally designed to protect the stained glass, remains in place throughout the building. All window frames are painted beige, in imitation of the faux stone stucco. The long double windows and small rose windows of the towers, and the south facing window of the kitchen, are the only exterior windows that retain original stained glass.

Conditions

The wood window tracery generally ranges from good to poor condition, with the poor condition more evident on the southern and western exposures. The following deterioration was observed:

- Breakage or loss of glazing, causing accelerated deterioration of stained glass, surrounding wood, adjacent masonry, and interior plaster (Figure 38a).
- Rotting, separation and bowing of wooden tracery elements (Figure 38b).
- Cracking, flaking and loss of surface paint (Figure 38c).
- Deterioration and loss of glazing compound.

Recommended Treatments

- A detailed conditions assessment of windows at St. Joseph's Church is necessary to determine the extent of deterioration and appropriate treatments at each window. This should include careful inspection and documentation of each window frame and its conditions, resistance and moisture testing to determine the extent of wood deterioration, wood type identification, and other non-invasive diagnostic tests.
- Any repair of the window frames should attempt to retain as much original material as possible while providing adequate protection for the building, and may include paint removal, treatment of rotted wood with a fungicide and consolidation with epoxy fillers, splicing of new wooden elements in areas of severe deterioration, and replacement of all glazing compound.

INTERIOR:

Marble Wainscoting and Floor Tiles

Description

Polished marble wainscoting lines the lower walls of the vestibule. The wainscoting is composed of a 3-4-inch border of white and black striated, mitered marble strips, surrounding central panels of white marble with grey/black inclusions. The base board and upper border of the wainscoting are made of a darker black and white striated marble. Floor tiles of the vestibule are made of white marble surrounded by a border of grey marble and are covered by modern vinyl tiles at the vestibule and an older type of tile at the adjacent baptistery.

Conditions

The marble wainscoting and tiles in the vestibule are generally in good condition. The following deterioration was observed:

- Light soiling and wear of the polished surface (Figure 39a and Figure 39b).
- Soiling and chipping of the baseboard (Figure 39a).
- Tape and adhesive residue from former signs posted on the wainscoting (Figure 39b).
- Vinyl tile at the vestibule is lightly adhered to the underlying marble floor.
- A more robust tile is securely adhered to the marble tile of the baptistery. The tile and its mastic may contain asbestos or other hazardous materials.

Recommended Treatments

- Tape residue and soiling should be removed with a gentle stone cleaner. Mock-ups should be conducted to determine the most effective product.
- Tiles in the vestibule should be removed without causing damage to underlying marble, which should be cleaned with a gentle stone cleaner to remove staining and adhesive. Mockups should be conducted to determine the most effective product.
- Tiles and mastic should be removed from the baptistery floor and cleaned using the gentlest means possible. The floor should be polished or honed as required.

Decorative Plaster

Description

Painted plaster is used to create moldings, cornices, columns and decorative details, such as the coffered ceilings that contribute to the interior's sense of grandeur and define distinct architectural spaces.

Conditions

The decorative plaster is generally in fair condition. The following deterioration was observed:

- Moisture penetration from blocked drainage and broken or missing window glazing (Figure 40 a and Figure 41b).
- Sugaring and softening of moisture damaged decorative elements (Figure 40c).
- Structural cracks and detachment from underlying masonry (Figure 40d).
- Small areas of historic decorative painting are exposed where the paint is flaking.
- Non-historic wood veneer over plaster at the base of the wall.

Recommended Treatments

- Sources of moisture such as broken glazing and blocked drainage should be repaired.
- Further testing of the plaster to determine the extent of deterioration should be conducted. This will determine if patching and reshaping damaged elements is possible, or if replacement is necessary.
- Detached or cracked plaster elements, if in otherwise sound condition, may be repaired with an injected epoxy or gypsum-based grout. Testing should be conducted to determine the most effective adhesive.
- A barrier coat should be installed to protect small areas of exposed decorative painting prior to repainting.
- Wood veneer should be removed. Plaster at base of the wall should be restored and painted.

Oak Woodwork and Doors

Description

Quarter sawn white oak is used extensively at St. Joseph's for the construction of decorative wooden elements such as doors, frames, column bases and railings. Woodwork is generally treated with a clear shellac or varnish.

Conditions

The oak woodwork is generally in good condition. The following deterioration was observed:

- Blistering of the varnish (Figure 41a).
- General soiling from dust (Figure 41b).
- White stains from paint or pigeon guano (Figure 41b).

Recommended Treatments

- Blistered varnish should be treated with the gentlest means possible in order to preserve the existing finish. Possible treatments include lightly scraping blistered areas of varnish and spottreating with fine steel wool or cotton, alcohol and a compatible varnish or shellac.
- Soiling should be cleaned with the gentlest means possible, using a soft bristle brush to remove loose dust and a damp cloth for tenacious soiling.
- White stains should be tested to determine if they are paint or guano. Paint and guano may be removed mechanically with a scraper taking care not to damage the existing wood finish.
- Where required by the level of damage, select areas should be refinished to match the original.
- Wood should be replaced where missing to match the original.
- At exterior doors, deteriorated wood should be repaired with wood Dutchman and should match the original species, grade, grain, and profile. The exterior should be prepared and painted. The interior should be cleaned and touched up or refinished to match the original stain or clear coat

Stained Glass

Description

Extant stained glass windows at St. Joseph's Church include the multi-story double windows and rosettes of the towers, the window of the kitchen, and one remaining stained glass transom above the northeast transept door. The windows of the towers are made primarily of yellow and green diamond-shaped glass panes with lead cames, iron or steel saddle bars, and wood frames. The kitchen window is made of various colored glasses painted with black floral decoration, and is supported in a flat stock steel frame, the upper portion of which opens inward. The only remaining stained glass transom of the nave, covered from the interior with plaster board, appears to have a figurative or floral motif.

Conditions

The stained glass windows are generally in poor condition. The following deterioration was observed:

- Loss of the protective outer glazing.
- General soiling (Figure 42a, Figure 42b, and Figure 42c).
- Sagging and bowing of lead cames (Figure 42b and Figure 42c).
- Cracking, breakage and loss of panes (Figure 42c).
- Inappropriate additions (Figure 42d).
- Corrosion of saddle bars (Figure 42e).

Recommended Treatments

- Because of the importance of the church's stained glass, immediate efforts to protect them should be made. This should include stabilization and protection measures determined in consultation with a professional stained glass conservator.
- Documentation and restoration of the windows should be performed by a professional conservator. As restoration is rarely preformed on site, it will likely include removal, transport, restoration, and reinstallation of the stained glass.

Where stained glass has been previously removed, the existing wood frame should be restored. The deteriorated areas should be removed back to sound wood substrate and an epoxy consolidant wood repair or wood Dutchman should be provided as required. The wood and steel armature remaining from the previous stained glass window installation should be prepared and painted. The frame should be modified to accept new ribbed protective heavy glass or dual glazing to match the original ribbed glass appearance.

EXISTING CONDITIONS IMAGES PRIOR TO REHABILITATION/RESTORATION

All of the Existing Condition Photos were taken between 2011 and 2016 by Page&Turnbull




Figure 32a. Pier near west tower, showing large cracks and displaced areas of brick (arrow) and corroded metal fence.




Figure 32b. Damage to metal fence at northeast corner of property.




Figure 32c. Low brick wall along Howard Street, showing gaps and voids, corroded metal fence, and graffiti (painted over with mismatched paint).




Figure 33a. Main portal steps, showing soiling, paint stains and vertical joints without mortar.




Figure 33b. Detail, east side of main portal steps, showing gap between blocks (arrow) due to uneven settling.




Figure 33c. East transept, north portal steps, showing decorative bull nose with biological growth and soiling.



Figure 33d. West transept, south portal steps, showing paint stains (left), soiling and spalling surface (arrow).




Figure 33e. Detail, south portal steps, spalled surface of granite tread.



Figure 34a. East nave façade, showing soiling, water staining and hairline cracking of stucco.




Figure 34b. East tower, north façade, showing loss of stucco at ground level.




Figure 35a. Light fixtures (now missing) at main entry on north façade in 2007.




Figure 35b. Detail, original mounting hardware is all that remains in place.




Figure 36a. Detail, rust-through at painted sheet metal cupolas.




Figure 36b. The rooftop crosses require minor sheet metal and gilding repair.





Figure 36c. Detail, corrosion and loss of paint and gilding at domes.



April 2019

Figure 36d. Broken, loose, and missing slate tiles at main roof.



Figure 37a. Column base, south side of east tower, showing flaking and loss of protective paint layer.




Figure 37b. Cornice above north portal, east transept, showing perforation (arrow) of the metal due to corrosion.




Figure 37c. East tower detail, constructed entirely of pressed sheet metal, showing missing architectural detail, loss of gilding and protective paint, and corrosion stains. Birds were nesting inside the towers.



Figure 38a. West tower, north window, showing broken protective glazing.




Figure 38b. East façade, transept window, showing soiling, paint loss and rotting/loss of tracery elements.




Figure 38c. West transept rose window, showing paint loss and missing glazing.




Figure 39a. Marble wainscoting of the narthex, showing soiling of the baseboard, wear of polished surface, and adhered tape. Original marble floor was covered with vinyl tile.




Figure 39b. Detail, showing tape and adhesive residue.




Figure 40a. West façade, showing blocked or perforated drainage which is causing damage to interior plaster.




Figure 40b. Deterioration of plaster caused by moisture from poorly sealed window.




Figure 40c. Softening and deterioration of decorative plaster elements caused by moisture from faulty roofing.




Figure 40d. Structural cracking and separation of plaster details from masonry substrate caused by moisture from blocked drains.




Figure 41a. Blistering of varnish on an oak door caused by moisture penetration.




Figure 41b. Dust (on molding) and paint/guano spatters can cause permanent damage to wood finish.




Figure 42a. North-east transept portal, showing blocked figurative stained glass window with heavy soiling and corrosion of steel frame




Figure 42 b. East tower, east windows, showing bowing of windows due to sagging lead cames or detachment from saddle bars.




Figure 42c. Breakage and loss of colored glass panes due to distortion of lead cames.




Figure 42d. Kitchen window, showing partition partially covering painted stained glass.




Figure 42 e. Upper portion of window showing corroded hopper-type opening assembly.

IV. 1401 HOWARD STREET ADDITIONAL PHOTOGRAPHY

PHOTOS AFTER REHABILITATION/RESTORATION




Figure 43. Perimeter fence and gate along Howard Street. View southwest. (Page & Turnbull, 05/25/2018)

Figure 44. Perimeter fence and gate along 10th Street at the northeast corner of St. Joseph's Church. View southwest. (Page & Turnbull, 05/25/2018)




Figure 45. Perimeter fence and gate along 10th Street at the southeast corner of St. Joseph's Church. View northwest. (Page & Turnbull, 05/25/2018)




Figure 46. Main portal steps. (Page & Turnbull, 05/25/2018)




Figure 47. North portal on east transept. (Page & Turnbull, 05/25/2018)




Figure 48. Detail, North portal stairs on east transept. (Page & Turnbull, 05/25/2018)




Figure 49. Exterior landing on west façade between west transept and sacristy. (Page & Turnbull, 05/25/2018)




Figure 50. East façade, showing stucco condition after restoration (Page & Turnbull, 05/25/2018).




Figure 51. East façade, showing stucco condition after restoration (Page & Turnbull, 05/25/2018)



Figure 52. West façade, showing stucco condition after restoration (Page & Turnbull, 05/25/2018).




Figure 53. Exterior lighting fixture above main entrance on north façade (Rich Stapleton, 05/21/2018)




Figure 54. Detail, gilded sheet metal dome and cross. (Palisade Builders, 05/20/2018)




Figure 55. Gilded sheet metal dome and top of sheet metal cupola. (Palisade Builders, 05/20/2018)




Figure 56. Main roof after restoration. (Palisade Builders, 05/20/2018)




Figure 57. Column capitals at the main entry façade after restoration. (Rich Stapleton, 05/21/2018)




Figure 58. Cornice above main entry façade after restoration. (Rich Stapleton, 05/21/2018




Figure 59. East tower detail after restoration (Rich Stapleton, 05/21/2018).




Figure 60. West tower, north window after restoration (Rich Stapleton, 05/21/2018).



Figure 61. East façade, transept window after restoration. (Palisade Builders, 05/20/2018)




Figure 62. West transept rose window after restoration. (Palisade Builders, 05/20/2018)




Figure 63. Marble wainscoting and interior doors of the narthex, after restoration (Page & Turnbull, 05/25/2018)




Figure 64. Narthex, view toward west tower. (Rich Stapleton, 05/21/2018)




Figure 65. Interior view toward main altar. (Page & Turnbull, 05/25/2018)




Figure 67. Interior view toward choir loft from the bridge. (Rich Stapleton, 05/21/2018)




Figure 66. Interior view of west transept. (Page & Turnbull, 05/25/2018)




Figure 68. East aisle, view toward choir loft. (Page & Turnbull, 05/25/2018)




Figure 69. Detail, plaster arches. (Rich Stapleton, 05/21/2018)




Figure 71. East aisle and transept towards main altar from the second floor. (Rich Stapleton, 05/21/2018)




Figure 70. Typical clerestory window with protective glazing, interior view. (Rich Stapleton, 05/21/2018).




Figure 72. Painted medallions from inside the half-dome. (Rich Stapleton, 05/21/2018)




Figure 73. Oak door from the main altar to Room 115 (Page & Turnbull, 05/25/2018)




Figure 75. East tower, east windows after restoration (Page & Turnbull, 05/25/2018)




Figure 74. Wood finish detail after restoration (Page & Turnbull, 05/25/2018).



Figure 76. Detail, stained glass window. (Page & Turnbull, 05/25/2018)




Figure 77. Detail, stained glass window. (Page & Turnbull, 05/25/2018).




Figure 78. Detail, stained glass window. (Page & Turnbull, 05/25/2018)





Figure 79. Stained glass window (Rich Stapleton, 05/21/2018)

V. SITE PLAN

10TH STREET (80' WIDE R/W)



VI. TAX BILL



City & County of San Francisco José Cisneros, Treasurer David Augustine, Tax Collector Property Tax Bill (Secured)

1 Dr. Carlton B. Goodlett Place City Hail, Room 140 San Francisco, CA 94702 www.sftreasurer.org

For Fiscal Year July 1, 2018 through June 30, 2019 The Galls nperty Location 1401 HOWARD ST 035 115187 October 12, 2018 Assessed on January 1, 2018 at 12:01am
To: 1401 HOWARD LLC Assesséd Value Land 542,570 6,310.08 Structure 1401 HOWARD LLC 15,254,027 177,411,31 Fixtures 850 7TH STREET Personal Property SAN FRANCISCO CA 94107 Gross Taxable Value 15,797,197 183,721,40 Less HO Exemption Less Other Exemption Net Taxable Value 15,797,197 \$183,721.40

Corte	· Type	Telephone	Amount Due
45	LWEA2018TAX	(415) 355-2203	298.00
46	SF BAY RS PARCEL TAX	(510) 286-7193	12.00
89	· SFUSD FACILITY DIST	(415) 355-2203	37.57
91	SFCCD PARCEL TAX	(415) 487-2400	99,00
98	SF - TEACHER SUPPORT	(415) 355-2203	. 251.96
			·

\$184,419.88
2nd Installment
. \$92,209.94
DUE 04/10/2019

City & County of San Francisco Property Tax Bill (Secured) For Fiscal Year July 1, 2018 through June 30, 2019

Pay online at www.sftreasurer.org

Val	Block	Lot	Tax Bill No	Mail Date	Property Location
.23	3517	035	115187	October 12, 2018	1401 HOWARD ST

Check if contribution to Arts Fund is enclosed.
For other, donation opportunities go to www.Give2SF.org

Detach stub and return with your payment Write your block and lot on your check.
2nd installment cannot be accepted unless 1st

San Francisco Tax Collector Secured Property Tax P.O. Box 7426 San Francisco, CA 94120-7426


San Francisco Tax Collection Secured Property Tax P.O. Box 7426

San Francisco, CA 94170-7426

2nd Installment Due \$92,209.94

If paid or postmarked after APRIL 10, 2019 the amount due (includes delinquent penalty of 10% and other applicable fees) is:

2335170003500 115187 00000000 00000000 0000 2003



2335170003500 115187 00000000 00000000 0000 1003

\$101,430.93

VII. RENTAL INCOME INFORMATION

1401 HOWARD RENTAL INCOME

Full rental agreement is 332 pages which is available on request. 100% of the building is rented.

Base Rent

	Master Lease
Year '	Expense
2016	\$ -
. 2017	176,780
2018	710,000
2019	720,650
2020	731,460
2021	742,432
2022	753,568
2023 ·	764,872
2024	776,345
2025	787,990
2026	799,810
2027	811,807
2028	823,984
2029	836,344
2030	848,889
· 2031	861,622
2032	874,547
2033	887,665
2034	900,980
2035	914,494
2036	928,212
2037	942,135
2038	956,267
2039	970,611
2040	985,170
2041	999,948
2042	1,014,947
2043	1,030,171
2044	1,045,624
2045	1,061,308
2046	1,077,228
2047	1,093,386
2048	1,109,787
2049	1,126,434
	<u>\$29,065,465</u>

^{**}Base Rent for the first and final Lease Year shall be determined based on the rent commencement date agreed to by Master Landlord and Master Tenant in the Rent Commencement Notice as set forth in Section 3.1 hereof.

DECEIVED

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

OMB Approved Ng. 1024-0009 Form 10-168 Rev. 2014

HISTORIC PRESERVATION CERTIFICATION APPLICATION PART \$ - REQUEST FOR CERTIFICATION OF COMPLETED WORK

NATIONAL PARK SERVICE TAX INCENTIVE PROGRAM

LICATION Rev. 2013
LETED WORK

E NPS Project Number

OCH ACCELLATE LEGICAL MAINE	27026
istructions: This page must bear the applicants original signature and must be dated;	
Property Name St Joseph's Church	
Street 1401 Howard Street	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
City Sen Francisco	State CA Zip 94103
is property a certified historic structure? X yes I no If yes, date of NPS certification	
, Project Data	•
Project start date 12/01/2015 Project completed and build	ling placed in service date 12/27/2017
Estimated rational literature costs (QRE) \$15:643,054 . Total estimated costs (QRE	plus non-ORE) \$20,584,699
	ousing units before/after rehabilitation//
Project Contact. (If different from applicant)	2.75 5 W
Name Ruth Todd, Principal Company	e Tunbull Inc
Street 417 Montgomery Street city San Francisco	State CA
Zip 94107 Telephona 4155933234 Email Address nuthtodd@pa	ige-tumbull.com
Applicant List all additional owners on next page.	•
I hereby attest that the information I have provided is, to the best of my knowledge, correct and that I am the of "owner" set forth in 36 CFR § 67.2 (2011). If I am not the fee simple owner of the above-described proper	
the fee simple owner is aware of the action I am taking relative to this application and has no objection, as t statement (a) wither is attached to this application form and incorporated herein, or has been previously sub-	
(1) (2011). For purposes of this attested on, the singular shall include the plural wherever appropriate. I unde	eraland that knowing and willful falsification of factual
representations in this application may subject me to fines and imprisonment under 18 U.S.C. § 1001, which up to 8 years.	
Name Chris Foley (HTC Representative), Contributions, ten Fills Signature,	Date 8/23/18
Applicant Entity 1401 Howard LLC	
Street 850 7th Street City San Francisco	State CA
Zip 94107 Telephone 4154454670 Email Address cfoley@gro	
Applicant, SEN, or TIN has changed since previously submitted application.	
There are no additional owners within the meaning of "owner" set forth in 36 CFR § 67.2 (2011).	
NP3 Official Use Only	ar agamatan katan kat
the National Park Service has reviewed the Historic Preserveton Certification Application - Request for Certification of Cor	mpleted Work (Part 3) for this property and has determined that:
the completed rehabilitation meets the Secretary of the Interior's Standards for Rehabilitation and is consiste	
applicable, the district in which it is located. Effective the date indicated below, the rehabilitation of the "certification" This certification is to be used in conjunction with appropriate internal Revenue Service regulation.	lations. Questions concerning specific tax consequences or
interpretations of the lifternal Revenue Code should be addressed to the Internal Revenue Service, Complete the Secretary to determine if the work meets the Standards for Renabilitation. The Secretary reserves the	
completion of the rehabilitation and to revoke certification, if it is determined that the rehabilitation project wa	as not undertaken as presented by the owner in the epidication
form and supporting documentation, or the owner, upon obtaining certification, undertook unapproved furths with the Secretary's Standards for Rehabilitation.	
fine completed renabilitation meets the Secretary of the Interior's Standards for Renabilitation. However, but rehabilitation cannot be designated a "certified (chabilitation" eliquide for Federal tax credits at this time. It will	cause this preperty is not yet a "certified historic structure," the
historic district in which it is located is listed in the National Register of Historic Plases. On that date, the co	impleted rehabilitation will automatically become a "contilled
rehabilitation." It is the owner's responsibility to obtain such listing through the State Historic Preservation C interpretations of the Internal Revenue Code should be addressed to the Internal Revenue Service. Comple	
of the Secretary to determine if the work meets the Standards for Republication. The Secretary reserves th completion of the rehabilitation and to revoke certification, if it is datermined that the rehabilitation project we	e right to make inspections at any time up to five years efter
form and supporting decumentation, or the dwiter, upon obtaining certained by, undertook unapproved feature	
with the Secretary's Standards for Rehabilitation. The rehabilitation is not consistent with the historic cheracter of the property on the dietrict in which it is local theorem for Rehabilitation.	ated and that the project does not meet the Georetary of the
Interior's Standards for Rehabilitation, A copy of this determination withbe provided to the internal Revenue Service in accordance with Federal law.	
A copy of and decrimination with the producted of the minestration in the production of the production	
9/20/18 Autorics Igrillo Date National Park Service Authorized Stonature	an 202-354-203

ω	
င	
4	

					•	
		. •		,	, ,	
	•					
*						
*	,	• • • • • • • • • • • • • • • • • • • •	•			
· ·	,					
	• •		•		•	
	:	·				•
	•	•				
HARD COST APPLICATION	NAND CERTIFICATE FOR	₹ PAYMENT	Ţ,	PAGE 1 OF 8 PAGES		
TO OWNER: 1401 Howard, LLC.	PROJECT: 1401	Howard Street	APPLICATION NO:	22	•	
10 0 1111111111111111111111111111111111		eet, San Francisco, CA	PERIOD TO:	1/31/2018	•	
FROM CONTRACTOR: Pallsade Buil			CONTRACT DATE:			
1875 S. Bascom Ave. #2400, Campbe			PROJECT MANAGER	S. Clark	•	•
	·					
CONTRACTOR'S APPLICA	TION FOR PAYMENT				•	
				ha at a constant		
CHANGE ORDER SUMMARY		Application is made for Payment,	as ghown below, in connection	on with the Confract.		
Total changes approved	ADDITIONS DEDUCTIONS	1. ORIGINAL CONTRACT SUM		Ø 44 444 DDØ DD		
In previous months By Owner Totak	2,001,881.73	2. NET CHANGES BY CHANGE	ORDERS	\$ <u>11,111,908.00</u> \$ 2,001,881.73		
Total approved this Month	1 2,000,000,000	3. CONTRACT SUM TO DATE (·	\$ 13,113,789.73	_	
No. Approval Date	7 . 1	4. TOTAL COMPLETED & STOR		\$ 12,825,585.66	·	
		5. RETAINAGE:	•	\$ 958,053.01	•	
· ·		6. TOTAL EARNED LESS RETA	INAGE	\$ 11,867,532,65		
		7. LESS PREVIOUS CERTIFICA	TES FOR PAYMENT*	\$ 11,553,903.06		
		8. CURRENT PAYMENT DUE		\$ 313,629,59		
NET CHANGES by Change Order	0.00 0.00	9. BALANCE TO FINISH, INCLU	IDING RETAINAGE	\$ <u>1,246,257.08</u>	•	
knowledge, information and belief the World Payment has been completed in accordant that all amounts have been paid by the Corprevious Certificates of Playment were issuine Owner, and that the current payment structure of the Contractors:	ce with the Contract Occuments. ntractor for Work for which sed and payments received from	*includes prior unpaid amount		,		
GOWTHONG TORC .						
By:	Date:	•	• •			
OWNER'S CERTIFICATE	FOR PAYMENT	AMOUNT CERTIFIED	* * *	.,\$		
<u>-</u>	•	(Attach explanation if amount certified	d differs from the amount applied	for)		
in accordance with the Contract Document		Owner: 1401 Howard, LLC		•	•	
data comprising the above application, the					•	
of his/her knowledge, information and belie		Ву:		Date:		
the quality of the Work is in accordance wi		-	•			
Contractor is entitled to payment of the AN	OUNT CERTIFIED.	Architect: Page & Turnball	·			
	•	Ву:		Date:		
				•	• •	
				•	•	
					•	

CONTINUATION SHEET APPLICATION AND CERTIFICATION FOR PAYMENT, CONTAINING CONTRACTOR'S SIGNED CERTIFICATION IS ATTACHED IN TABULATIONS BELOW, AMOUNTS ARE STATED TO THE NEAREST DOLLAR.

APPLICATION NO: APPLICATION DATE: PERIOD FROM:

1/31/2018 1/1/2018 1/31/2018

PERIOD TO :

1600

JOB #: CONTRACT DATE:

JOB #1600 - 1401 Howard Street, San Francisco, CA

									· · · · · · · · · · · · · · · · · · ·		,
A	В	c			D	E	F	G		Н	1
	:		Change		Work Com		Ivialerials	Total	%		
ITEM	Description of work	Scheduled	Orders	New	Previous	This	Presently	Completed	Complete	Balance to	Retainage .
NO.		Value	· To	Scheduled	Applications	Period	Stored	and Stored		Finish	al 10%
· '			Date	Value		Work in Place	(Not in D or	lo Date			1
ļ			(Thru PCCO#1		(D + E)	(F-D)	E)	· (D + E + F)	(G/C)	(C-G)-	
1290	Weather Protection	\$ 25,000.0		\$ 25,000,00				\$ 24,231.49	.97%	\$ 768.51	\$ 2,423.16
1390	Hoisling/Equipment Rentals	\$ 110,000.0			\$ 100,000.00	\$ 5,455.98		\$ 106,455,98	100%	\$ -	\$ 10,645.60
1800	General Conditions/Supervision	\$ 800,000.0			\$ 1,050,000.00	\$ 73,321.77	<u> </u>	\$ 1,123,321,77	98%	\$ 19,678.23	\$ -
2050	Demo Existing Concrete SOG	\$ 37,500.0		0) \$ [30,000.00		<u></u>		\$ 30,000,00	100%	\$ -	\$ -
.2070	Selective Demolition	\$ 125,000.0	0 \$ 92,298,5			\$ -		\$ 217,298.53	100%	\$ -	\$ 15,479.85
2080	Core Drilling	\$, 7,500.0		\$ 12 7.500.00				\$ 7;500.00	100%	\$ -	\$ 750.00
2250	Underpinning pits/misc.	.\$ -	\$ 79,847.5	9 \$ 174 79.847.59	\$ 79,847,59			\$ 79,847.59	100%	·S -	\$ {0.00
2300	Spoils Removal	\$ 13,280.0	0 \$ 32,130.0	0 \$ 45.410.00	\$ 45,410.00	\$ -		\$ 45,410.00	100%	\$	\$ 4,541.00
2310	Excavation-	\$ 25,000.0	0.806,0	0 \$ 30,906,00	\$ 30,906,00	\$.		\$ 30,906.00	100%	\$:	\$ 3,090.60
2450	Microplles	\$ 328,000.0	0	\$ 7328,000.00	\$ 328,000.00	\$ -		9 328,000.00	100%	\$ -	S -
2460	Casing Upper 10' of each Micropile	\$ 36,000.0	0 \$ 24,000.0	0 \$ 7 60,000.00	\$ 60,000,00			·S 60,000.00	100%	\$	\$ -
2510	Domestic Water Underground	\$ 24,100.0	\$ (24,100,0	D) S -				s -	100%	\$ -	\$ -
2520	Sanitary Sewer & SD	\$ 143,440.0	0.000,08) \$ (0) S 107,440.00	\$ 107,440.00	\$ -		\$ 107,440.00	100%	\$ -	\$ 10,744.00
2800	Landscape; Irrigation & Planting .	\$ 46,000.0	\$ 48,000.0	0 \$:117 94,000.00	\$ 27,328.96	\$ 40,301.93		\$ 67,630.89	72%	\$ 26,369.11	\$ 6,763.09
-2810	Site Lighting (excludes fixtures)	\$ -	\$ 26,350.0		\$ 26,350,00	\$ -		\$ 26,350.00	100%	5 -	\$ 2,635.00
-2860	Landscape Arbors	\$	\$ 75,000.0	0 多型で 15,000.00				\$ -	0%	\$ 15,000.00	3 -
2920	Fencing	\$ 25,000.0	0.000.0	0 0.000.00		\$ 30,000.00		\$ 30,000.00	60%	\$ 20,000.00	S . 3.000.00
	Landscape Gas Lights (piping										
2950	only)	\$ -	\$ 12,500.0		\$ 12,500.00			\$ 12,500.00	100%	\$	\$ 1,250.00
2980	Joint Trench	\$ 25,000.0			S 85,000.00			5 85,000,00	100%	<u> </u>	\$ 8,500.00
3050	Rebar/Mash, Shotcrete & CIP	\$ 1,245,000.0	0,827,07 \$ (0 \$ 1,315,728.00	\$ 1,315,728.00	\$ -		\$ 1,315,728,00	100%	\$ -	\$ 5,329.43
3070	Struct, Excavation, Backfill & Offhaul.	\$ 151,000.0	5 \$ (4,721.3	6) \$ 146,278.64	\$ 146,278.64	\$ -		\$ 146,278,64	100%	\$ -	\$ 14,523.51
3100	On Grade Site Concrete (Hardscape)	\$ 50,000,0	5 25,000.0	0 \$ 75,000.00	\$ 70,815,67	8 -		\$ 70,815,67	94%	\$ 4,184,33	\$ 7.031.57
	Offsite Concrete	\$ 50,000.0		\$ 50,000,00	\$ 28,864,00	\$ -		\$ 28,864.00	58%	\$ 21,136,00	\$ 288640
3910	Misc. Concrete	\$ 50,000.0				\$ -		\$ -	100%	S	5 -
1 1 1 1 1 1 1 1	SUBTOTALS PAGE 1	\$ 3,316;820 <u>:</u> 0	F 733 894.7	4. \$ \$ 4.050,714.74	\$1.3793,498,88	\$ (150.079.68)	300 C 18 C	\$4.3,943,578.56	············· 97%	\$ 77.107,136.18	\$ 99,643.20

CONTINUATION SHEET

APPLICATION AND CERTIFICATION FOR PAYMENT. CONTAINING CONTRACTOR'S SIGNED CERTIFICATION IS ATTACHED

IN TABULATIONS BELOW, AMOUNTS ARE STATED TO THE NEAREST DOLLAR.

APPLICATION NO : APPLICATION DATE :

1/31/2018 1/1/2018

PERIOD FROM : PERIOD TO : 1/31/2018

JOB#: 1600

CONTRACT DATE:

JOB #1600 - 1401 Howard Street, San Francisco, CA

5050 St			Scheduled Value		·Change Orders				D Wark Comp	alak	<u>E.</u>	F Materials	-	. G Total	%	<u> </u>	Н)		<u> </u>
NO. 4900 M 5050 St	vlasonry			•	- 1		Į.		Work Come	alate	arl . l	Matariala	1	Total	1 67	ı	•		
NO. 4900 M 5050 St	vlasonry			•	Orders -					JICE			1			1	. 1		
4900 M 5050 St	vlasonry		Value .		~ (MVIM		·New		Previous		This	Presently		Completed	Complete	'.	Balance to	F	Refainage
5050 St					To :	5	Scheduled		Applications		Period	Stored		and Stored	}		Finish		al 10%
5050 St					Dale		Value			W	ork in Place	(Not in D or	1	to Date		1			
5050 St				(Th	ITU PCCO#11)		1		(D+E)		(F-D)	E)	1	(D + E + F)	(G/C)		(C-G)		
	State of the second Character	\$	20,000.00	\$	(20,000,00)	S	-			,			-\$	×	. 100%	\$		\$	-
5070 SI	Structural Steel	\$.275,000.00	-\$	(40,000,00)	\$ 4	9 235,000.00	S	235,000,00				\$	235,000,00	100%	\$	-	\$	23,500,00
	Structural Steel Installation	\$	400,000.00	\$	(88,158,91)	5 4	£ 311,841.09	\$	311,841.09	\$	-		\$	311,841.09	100%	\$	-	\$	31,184 11
5080 M		\$	401,143,00	:\$	(84,000,00)	\$	317,143.00	\$	317,143.00	\$	-		\$	317,143.00	100%	\$	-	\$	31,714 30
5090 M	Mezzenine Bridge	\$.20,000.00			\$ 6	50,000.00	\$	50,000.00				5	50,000.00	100%	5	-	\$.	5,000.00
5100 M	Mezzanine Glass Rail System	\$	205,000.00	\$	(117,500,00)	\$ 4	€ 87,500.00	\$	83,696.20	\$	<u> </u>		-5	83,696.20	96%	S	3,803.80	S	8,369,62
5110 5	Stairs	\$	80,000.00	\$	(17,500,00)	. \$ <i>\$</i>	\$ 62,500.00	ş	31,250.00	\$	± '		S	31,250.00	50%	\$	31.250.00	.5,	3 125.00
5120 M	Visc. Steel	\$	25,000.00			\$ 8	25,000.00	43	11,812,50	\$	-		\$	11,812,50	47%	\$	13,187.50	5	1,181,25
5130 St	Supports for the 700 lb, Trough sink	\$	-	\$	7,500,00	\$ 8	7,500.00	\$	7,500.00				\$	7,500,00	100%	\$	-	\$	7.50 00
6050 C	Cabinets	\$	10,000,00	\$.	(10,000,00)	\$	-						\$		100%	\$		\$.	
6100 R	Retrofit Carpentry	\$	560,000,00	\$.77,701,97	\$	637,701.97	\$	568,219,74	\$	44,482.00		\$	812;701.74	96%	\$	25,000.23	\$.	61,270,17
6150 W	Window Stop Repair	\$	00,000,00	\$	46,867,00	\$16	7,96,867.00	\$		\$			\$	96,867,00	100%	\$	-	\$	9,886.70
6160 B	Bell Tower Rot Repair	\$		\$	151,458.96	\$	151,458,96	35	151,458.96	\$.	-		\$	151,458.96	100%	\$.		-5	15.145,90
6200 T	Trim Carpentry	\$	50,000.00		,	\$	50,000.00	.8	21,895.57	3	.50,000.00		\$	41,895,57	84%	\$	8,104.43	Ş	4,189,56
6250 5	Scaffolding	\$	175,000.00	\$	1.74,060,84	\$	349,060,84	-\$	349,060,84	:\$	-		3	349,060.84	100%	\$	<u>.</u> .	\$	33,406,08
6250 B	Bell Tower Scaffolding	\$	-	\$	165;000,00		185,000.00	S	165,000.00	\$			S	165,000.00	100%	\$	-	\$	16,500,00
6500 C	Counterlops	\$	5,000.00	. \$	(5,000,00)	\$							S		100%	\$		\$	
	Additional under slab insulation	\$	-	\$	35,000,00			S	35,000.00				\$	35,000.00	100%	\$	• .	\$	3,500 00
7300 S	Slate Tile Roof	\$	267,960,00				258,950.00	\$	258,950.00	S	18th -		\$	258,950,00	100%	\$:\$	25,895 00
	Lower Roof System	Ş.	35,000,00		(6;890.00)		28,110,00	\$	28,110.00		<u>, </u>		\$	28,110.00	100%	\$	-	\$	2,811.00
	Flashing & Sheetmetal	\$	200,000.00	\$	234,323,47		4434,323.47	S	434,323.47				\$	434,323.47	100%	\$	- .	\$	43,432,35
	Sealants & Caulking	\$	10,000.00	_		\$	10,000.00	\$	10,000.00		· · ·		\$	10,000,00	100%	\$		S	1,000.00
	Windows	\$	545,000.00				15 269,576.22	\$	269,576.22				\$	269,678,22	100%	\$	-	\$	25.957.02
8070 S	Stain Glass Repair	\$	120,000.00	S			€2 81,260.67	\$	81,260,67				\$	81,260.67	100%	3		\$	8,126.07
	Skylight Repair	\$		\$	39,010,08		39,010,08	\$	39,010.06		-		\$	39,010.06	100%	\$		\$	3,901.01
	Doors/Milwork & Finish Hardware	\$	284,000.00				€269,000.00	\$	264,631,12				\$	264,631,12.	.98%	\$	4,368,88	\$	26,463,11
	Plaster Repair	\$	775,000,00					15	1,350,577.80		-		\$		100%	\$	-		135.057.78
	Metal Studs & Drywall	\$	110,000,00	\$	(40,000,00)	\$	70,000,00	\$	70,000,00	\$	_		. \$	70,000.00	100%	\$		S	7.000.00
	Soffitt below Transept Cafe,	1		1		-													
9200 G	Green Rm Stage Metal Framing	\$	-	\$	17,000.00		17,000.00	\$	17,000,00				\$	17;000,00	100%	S	-	3	1;700,00
	Ceramic Tile	\$	30,000.00		(30,000,00)				-4070, To A				\$		100%	S	-	\$	
9630 (F	Flooring - Carpel Tile	\$	78,000.00		(78,000.00)			1	Poleto	4	P		\$		100%	\$		\$	
	Painting	\$	234,900.00	\$			293,850.00/		279,213,41				\$	279,213.41	95%	. 35	14,636.59	\$	27,921 34
	Gold Leaf at Dome	\$		5					00,000,08				\$	60,000.00	%0ar	\$	-	\$	6,000.00
At Some	SUBTOTALS PAGE 26	1.5	/8,312,813,00	\$	1,501,132,82	·\$ 1-3	9,813,945,82	38"	9,391,896,53	4.4	214,564,68	第 第四四年	1.5	9,606,458:21	98%	\$	207,487,61	\$.	664,431.16

CONTINUATION SHEET

APPLICATION AND CERTIFICATION FOR PAYMENT, CONTAINING CONTRACTOR'S SIGNED CERTIFICATION IS ATTACHED IN TABULATIONS BELOW, AMOUNTS ARE STATED TO THE NEAREST DOLLAR.

APPLICATION NO : APPLICATION DATE :

1/31/2018

PERIOD FROM : PERIOD TO :

1/1/2016 1/31/2018

JOB#: 1600

CONTRACT DATE:

JOB #1600 -	. 4404	Howard	Strout.	San	Francis	co CA	

											······································	**********	·		,				
A	В		C						D		E	F'	_	G	·		H		1
				_	Change	-			Work Com	plete		Materials		Total	%				
.ITEM	Description of work		Scheduled		Orders		New	_	Previous		This	Presently		Completed	Complete	e	Balance to	F	lelamago
NO.			Value		To		Scheduled		Applications		Period	Stored	ŀ	and Stored		1	Finish	•	al 10%
					Date		Value			W	ork in Place	(Not in D or	1	lo Date			·		
				lπ	ru PCCO#11)		· · ·		(D + E)		(F~D)	E)	1	(D + E + F)	(G/C)	1	(C-G)		
10320	Fire Extinguishers	\$	1,800.00	_		\$	1,600.00			\$	1,600.00		\$	1,600.00	100%	\$	- 1	5	160.00
10400	Signage	S	6,500,00	-		\$	6,500,00	\$	6,500.00	\$			\$	0,500,00	100%	\$	-	\$	850.00
10450	Mirrors	S	2,000,00			\$	2,000.00			\$	2,000.00		\$	2,000,00	100%	\$	-	\$	200 00
10530	Access Doors & Ladders	S	12,000,00			35	12,000.00	\$	12,000.00	\$	-		.\$	12,000.00	100%	\$.	-	\$	1,200.00
10600	Tollet Perlitions	S	11,500.00			\$	11,500.00		11,500.00		- 1		\$	11,500.00	100%	\$	-	\$	1,150 00
10800	Bath Accessories	រង	1,500.00			\$	1,500,00		1,500.00		-		\$	1,500.00	100%	\$		\$	150 00
10910	Misc. Specialties/Bike Racks	Ş	1,500.00			\$	1,500.00	\$	1,500,00	Ş	·_		\$	1,500.00	100%	\$	-	\$	150.00
11010	Appliances	\$.	2,500.00	\$	(2,500.00)	\$	•						F	-	100%	\$	-	\$	-
12050	Window Coverings	55	-	<u> </u>		\$	-						\$		100%	,\$	- 1	\$	-
13170	Interior Plaster/Paint Lead Abatement	\$\$	100,000.00	\$	(97,870.27)	\$,	\$	2,129.73	\$			\$	2,129.73	100%	\$	(0.00)	\$	212.97
13180	Bird Guano Abalement	\$	12,500.00	\$	(3,200,00)			\$					\$	9,300.00	100%	5	-	5	
13190	Asbestos Abatement	\$	16,000.00	\$.	(1,543,00)		14,457.00		14,457.00	\$.			\$	14,457.00	100%	\$	-	.5	
14200	Wheel Chair Lift	55	25,000.00	\$	20,000.00	\$ 1	45,000.00 مسلمارًا	3	45,000;00	\$	-		Ş	45,000.00	100%	\$	-	\$	4,500.00
15050	Plumbing	\$	105,000.00	\$	(21,000.00)			8	00.000,08		4,000,00		S	84,000.00	100%	\$	-	\$	8,400 00
15150	Rediant Floor Heat	\$	145,000.00	\$	7,500.00			Ş	152,500,00	\$			\$	152,500.00	100%	\$	-		15,260 00
15400	Ventilation	\$	185,000.00	\$	10,000.00		195,000.00	5	181,171.20	\$	5,200.80		\$	186,372.00	86%	\$	8,628.00	\$	18,637.20
16050	Electrical	\$	353,000.00	\$.	643,000.00	\$	996,000.00	\$	968,728.38	5	17,385.65		\$	986,114.03	99%	- 3	9,885.97	\$	98,611,40
	Fixtures	\$	50,000,00	\$			T2135,281.00	\$	126,327.00				\$	126,327.00	93%	·S	8,954,00	5	12,632 70
16080	Site Lighting Flxtures	\$		\$	92,625,00			\$	78,693.00		6,179.00		\$	84,872.00	92%	5	7,753,00	\$	8,487,20
16090	Access Control / Intercom	\$		\$	27,469.00		27,469.00		-1	5	19,228.30		\$	27,469.00	100%	\$	-	\$	2,746,90
	CCTV System	\$		\$	15,484,00		15,484.00		4,645,20		10,838,80		S	15,484.00	100%	\$	-	\$	1,548.40
	WIFi System	\$.		\$	18,360,00	\$	18,360.00		9,180.00	ş	9,180,00		\$	18,360,00	100%	\$	-	\$	1,836.00
16160	Music Speaker System	\$		\$	51,248,00			S	51,248.00				S	51,248,00	100%	\$		\$	5,124,50
	Commisary Service Upgrade	\$	·-	\$	6,000,00		6,000.00	5	6,000.00		-		Ş	6,000.00	100%	\$	-	\$	00.00
16180		\$.\$	9,975,00			5	9,975.00				\$	9,975,00	100%	\$	-	\$	997.50
16200	Low Vollage	\$	150,000.00	\$	(60,000,00)	\$	90,000.00	5	83,072,13				\$	83,072.13	92%	\$	6,927.87	\$	8,307.21
16300	Telephone Data .	\$		\$	41-1-10-1	\$		\$	6,248.00	\$	-		\$	6,248.00	100%	5	<u>.</u>	9	524 80
15400	Lighting Control System	\$		V:	124,700,00		124,790.00	\$		\$	12,181.90		\$	121,819,00	98%	5	2,971,00	\$	12 151 90
	Englneering	\$		\$	27,500.00		27,500.00	ş	27,500.00				\$. 27,500.00	100%	\$	-	\$	2,750.00
	Additional Tenant Improvements	S	240,000.00	\$	(240,000.00)		-						\$	-	100%	\$		\$	-
		S	-	\$	40,749,25	\$	40,749.25		40,749,25	8			\$	40,749,25	100%	\$	-	\$	4,074.93
	West Tower - X brace & spiral stair			Si		. \$i	40,000.00			\$	10,000,00		\$	30,000.00	75%	\$	10,000.00	S.	3,000.00
	East Tower - X brace	\$	_	S		\$	20,000.00			Ş	-		\$	20,000.00	100%	\$	-	\$	2,000,00
# 2 W.	SUBTOTALS PAGE 3	\$	9,733,413.00	\$.5	321 248 80	\$1,5	1,2,054,661,80	\$.	11,479,698,22	\$	3,12,356;13	\$ 7.00	\$:1	1,792,054.35	98%	130	262,607,45	\$ · 8	80,615,08
			<u> </u>						- Indeed and the state of the s						السين ترسع			سائست	

CONTINUATION SHEET

APPLICATION AND CERTIFICATION FOR PAYMENT, CONTAINING CONTRACTOR'S SIGNED CERTIFICATION IS ATTACHED

IN TABULATIONS BELOW, AMOUNTS ARE STATED TO THE NEAREST DOLLAR.

APPLICATION NO: APPLICATION DATE:

DATE: 1/31/2018

PERIOD FROM: 1/1/2018 PERIOD TO: 1/31/2018

JOB#: 16

1600

CONTRACT DATE:

JOB #1600 - 1401 Howard Street, San Francisco, CA

A	В	¢			D	E	F	G		Н	1
			Change		Work Com	pleted	Materials	Total	%		
ITEM	Description of work	Scheduled	Orders	New	Previous	This	Presently	Completed	Complete	Balance to	Relainage
NO.		Value	To	Scheduled	Applications	Period	Stored	and Stored	{	Finish	al 10%
	j .		Date.	Value		Work In Place	(Not in D or	to Date			
			(Thru PCCO#11)		(D + E)	(F-D)	E)	(D+E+F)	(G/C)	(C-G)	
	DIRECT COSTS:										
	Oivision 1 - General Requirements	\$ 935,000,00						\$ 1,254,009,24	98%	\$ 20,446,74	\$ 13,068.75
	Division 2 - Site improvements .	\$ 835,820.00						\$ 1,127,883.01	95%		\$ 58,753,54
	Division 3 - 17 Bidg. Improvements		\$1,628,380.70					S . 9,410,162.10	98%		\$ 810,792.79
<u></u>	TOTAL DIRECT COST	\$ 9,733,413.00	\$2,321,248.80	\$ 12,054,661.80	\$ 11,479,698.22	\$ 312,356,13	\$ -	\$ 11,792,064.35	98%	\$ 262,607.45	\$ 880,615.08
				y							
9000	OVERHEAD & PROFIT	\$ 632,672.00			\$ 722,925.28	S 12,613.91		\$ 735,539,19	98%	\$ 16,380.36	S 73,553.92
8000	CONSTRUCTION CONTINGENCY 1.8%				\$ -			\$ -	100%	\$	\$
102	CCIP INSURANCE	\$ 259,152.00	\$ 48,056.38	\$ 307,208.38	\$ 282,631.70	\$ 15,360.42		\$ 297,992,12	97%	\$ 9,216.26	\$ 3,884.01
	TOTAL GUARANTEED MAXIMUM PRICE	\$ 11,111,908.00	\$2,001,881.74	\$ 13,113,789.73	\$ 12,485,255.20	\$ 340,230.46	\$ -	\$ 12,825,585.66	98%	\$ 288,204.07	\$ 958,053.01

				Three Way Value Comparison			Lesser of the 3 Comparisons					
APN	Address	Property Type	Owner Occupied	Year Bullt	Square Feet	2019 Factored Base Year Value		Market Value	Taxable Mills Act Value	Reduction in Assessed Value	Percentage % Reduction From FBYV	
05-0612-001A	2251 Webster	Single Family	Yes	1900	1,586	\$ 1,837,603	\$ 618,000	\$ 1,840,000	\$ 618,000	\$ (1,219,603)	-66,37%	•
06-0866-014	64 Potomac	Single Family	Yes	1900	1,750	\$ 2,550,000	\$ 600,000	\$ 2,500,000	\$ 600,000	\$ (1,950,000)	-76.47%	_
23-3517-035	1401 Howard	Office	Νo.	1913	21,943	\$ 18,458,740	\$12,700,000	\$13,700,000	\$ 12,700,000	\$ (5,758,740)	-31.20%	_
23-3542-062	2168-2174 Market	Retail·	No	1907	17,132	\$ 684,218	\$ 4,030,000	\$ 6,850,000	\$ 684,218	\$ -	0.00%	
24-3640-031	2731-2735 Folsom	3-units	Yes / No	1900	5,200	\$ 6,170,997	\$ 3,119,000	\$ 6,500,000	\$ 3,119,000	\$ (3,051,997)	-49,46%	_

2018 Property Tax Rate 1.1630% 1.1630% 1.1630% 1.1630%

Estimated Property Tax Savings (\$14,184) (\$22,679) (\$66,974) \$0 (\$35,495)



DEDARTMENT 2019 OCT 15 PM 2: 25

Y AK

October 15, 2018

Ms. Angela Calvillo, Clerk Board of Supervisors City and County of San Francisco City Hall, Room 244 1 Dr. Carlton B. Goodlett Place San Francisco, CA 94102

Re:

Transmittal of Planning Department Case Numbers: 2019-006323MLS; 2019-006384MLS; 2019-006322MLS; 2019-005831MLS; 2019-006455MLS

Six Individual Mills Act Historical Property Contract Applications for the following addresses: 2251 Webster Street; 1401 Howard Street; 64 Potomac Street; 2168 Market Street; 2731-2735 Folsom Street

BOS File Nos: _____ (pending)

Historic Preservation Commission Recommendation: Approval

Dear Ms. Calvillo,

On October 2, 2019 the San Francisco Historic Preservation Commission (hereinafter "Commission") conducted a duly noticed public hearing at a regularly scheduled meeting to consider the proposed Mills Act Historical Property Contract Applications. At the October 2, 2018 hearing, the Commission voted to approve the proposed Resolutions.

The Resolutions recommend the Board of Supervisors approve the Mills Act Historical Property Contracts as each property is a historical resource and the proposed Rehabilitation and Maintenance plans are appropriate and conform to the Secretary of the Interior's Standard for the Treatment of Historic Properties. Please refer to the attached exhibits for specific work to be completed for each property.

The Project Sponsors submitted the Mills Act applications on May 1, 2019. As detailed in the Mills Act application, the Project Sponsors have committed to Rehabilitation and Maintenance plans that will include both annual and cyclical scopes of work. The Mills Act Historical Property Contract will help the Project Sponsors mitigate expenditures and enable the Project Sponsors to maintain their historic properties in excellent condition in the future.

The Planning Department will administer an inspection program to monitor the provisions of the contract. This program will involve a yearly affidavit issued by the property owner verifying compliance with the approved Maintenance and Rehabilitation plans as well as a cyclical 5-year site inspection.

www.sfplanning.org

.

1650 Mission St. Suite 400

San Francisco, CA 94103-2479

Reception:

415.558.6378

415.558.6409

Planning

Information: 415.558.6377

Transmittal Materials Mills Act Historical Property Contracts

The Mills Act Historical Property Contracts are time sensitive. Contracts must be recorded with the Assessor-Recorder by December 30, 2019 to become effective in 2020. We respectfully request these items be introduced at the next available hearing date. Your prompt attention to this matter is appreciated.

If you have any questions or require further information, please do not hesitate to contact me.

Sincerely,

Aaron D. Starr

Manager of Legislative Affairs

cc:

John Carroll, Office of the Clerk of the Board Andrea Ruiz-Esquide, City Attorney's Office

Attachments:

Mills Act Contract Case Report, dated October 2, 2019 Assessor Valuation Table

2251 Webster Street

Historic Preservation Commission Resolution
Draft Mills Act Historical Property Contract
Draft Rehabilitation & Maintenance Plans
Draft Mills Act Valuation provided by the Assessor-Recorder's Office
Mills Act Application

1401 Howard Street

Historic Preservation Commission Resolution
Draft Mills Act Historical Property Contract
Draft Rehabilitation & Maintenance Plans
Draft Mills Act Valuation provided by the Assessor-Recorder's Office
Mills Act Application
Historic Structure Report

64 Potomac Street

Historic Preservation Commission Resolution
Draft Mills Act Historical Property Contract
Draft Rehabilitation & Maintenance Plans
Draft Mills Act Valuation provided by the Assessor-Recorder's Office
Mills Act Application

2168 Market Street

Historic Preservation Commission Resolution

SAN FRANCISCO PLANNING DEPARTMENT

2

Transmittal Materials Mills Act Historical Property Contracts

Draft Mills Act Historical Property Contract
Draft Rehabilitation & Maintenance Plans
Draft Mills Act Valuation provided by the Assessor-Recorder's Office
Mills Act Application
Historic Structure Report

2731-2735 Folsom Street

Historic Preservation Commission Resolution
Draft Mills Act Historical Property Contract
Draft Rehabilitation & Maintenance Plans
Draft Mills Act Valuation provided by the Assessor-Recorder's Office
Mills Act Application

SAN FRANCISCO PLANNING DEPARTMENT