Scope: # 1		Building Feature:	Roof
☐ Maintenance	ration 🛛 Completed	☐ Proposed	
Contract year work completion: 20)23		
Total Cost: \$ 27,000			
on anything visible from		ades of imprope	er maintenance. No work was performed
Permit #202302081643			

Scope:# 2			Building Feature:	Exterior door to back yard
☐ Maintenance	▼ Rehab/Restoration	☐ Completed	☒ Proposed	
Contract year work	completion: 2023			
Total Cost: \$ 2,00	00			
Description of wor	k:			
	the back yard on falling apart and i			is in need of repair or replacement. The

Scope:# 3			Building Feature: Windows on all sides of house
☐ Maintenance	☒ Rehab/Restoration	☐ Completed	☑ Proposed
Contract year work	completion: 2024		
Total Cost: \$ 187	,385		
Description of wor	k:		
Windows are	e broken througho	ut the house	e. They will be repaired or replaced in kind.

Scope:# 4			Building Feature:	All sides of building exterior
☐ Maintenance	☑ Rehab/Restoration	☐ Completed	☒ Proposed	
Contract year wor	k completion: 2033			
Total Cost: \$ 21,	900			
Description of wor	k:			
Exterior pain well.	t is peeling and no	eeds to be re	epainted. Any d	amage to the facade will be repaired as

Scope: # 5			Building Feature:	All sides of exterior of building
☑ Maintenance	☐ Rehab/Restoration	☐ Completed	☒ Proposed	
Contract year work	completion: Annually			
Total Cost: \$ 800)			
Description of wor	k:			
Inspection ar	nd perform necess	ary repairs for	r sidings.	

Scope: # 6	Building Feature: Windows on all sides of house
☐ Maintenance ☐ Rehab/Restoration ☐ Completed	☑ Proposed
Contract year work completion: Annually	
Total Cost: \$ 1100	
Description of work:	
Inspection and perform necessary repairs fo	or all windows.
Professionally wash exterior windows annua	ally.

Scope:# 7	Building Feature: Roof
☐ Maintenance ☐ Rehab/Restoration ☐ Completed	☑ Proposed
Contract year work completion: Annually	
Total Cost: \$ 500	
Description of work:	
Inspection and perform necessary repairs for	roof. Roof will be inspected at least once a year.

Scope:# 8			Building Feature:	Front porch
X Maintenance	☐ Rehab/Restoration	☐ Completed	☒ Proposed	
Contract year work	completion: Annually			
Total Cost: \$ 600)			
Description of wor	k:			
Inspect for w	ater damage and o	dry rot on fron	t porch, and ma	ke in-kind repairs as necessary.

Scope:# 9	Building Feature: Front door	
	X Proposed	
Contract year work completion: Annually		
Total Cost: \$ 800		
Description of work:		
Inspect for water damage and dry rot on from	door, and make repairs and p	paint as necessary.